

REPAIR ESTIMATE

VEHICLE NO: SH 9710H

29/10/2019 14:02

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>X Repair</i>			\$ 1,126.60
REAR TRUNK LID COVER TRIM BOARD <i>X</i>			\$ 254.40
REAR TRUNK LID GLASS (BLACK COLOR) <i>X</i>			\$ 733.50
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>X Repair</i>			\$ 889.70
REAR TRUNK LID LOGO (PRIUS) <i>/</i>			\$ 52.90
REAR TRUNK LID LOGO (HYBRID) <i>/</i>			\$ 52.90
REAR TRUNK LID LOGO (TOYOTA STAR) <i>/</i>			\$ 47.00
REAR BUMPER <i>/</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT <i>?</i>			\$ 318.80
REAR BUMPER UNDER COVER <i>/</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>?</i>			\$ 112.70
REAR BUMPER TOWING COVER <i>/</i>			\$ 82.70
REAR BUMPER CLIPS <i>/</i>			\$ 22.00
REAR END PANEL <i>X Repair</i>			\$ 602.10
REAR END PANEL GARNISH <i>X</i>			\$ 165.80
REAR WINDSCREEN GLASS WITH MOULDING <i>X</i>			\$ 1,778.30
SUB TOTAL			\$ 7,250.60
LESS 25%			\$ 1,812.65
DISCOUNTED TOTAL			\$ 5,437.95
REAR NO. PLATE WITH TRIM COVER <i>X</i>			\$ 100.00
REAR TRUNK LID APPS STICKER <i>/</i>			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>/</i>			\$ 60.00
REAR BUMPER REVERSE SENSOR <i>/</i>			\$ 135.70
REAR BUMPER RUBBER MAT <i>(Mod.)</i>			\$ 50.00
REAR WINDSCREEN SEALANT <i>X</i>			\$ 46.00
			\$ 431.70
LABOUR CHARGE			
Panel Beating			\$ 850.00
Spray Painting Charge			\$ 750.00
Wiring Charge			\$ 50.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor			\$ 80.00
TOWING FEE			\$ 60.00
TOTAL LABOUR			\$ 1,780.00
ESTIMATE TOTAL			\$ 7,649.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kahua 1 (11/11)

29/10/19

3 P/P

Before Part p.L.L.

NETT
NETT
NETT
NETT
NETT
NETT

600
20
30
X

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.