LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. From: LKK Auto Consultants Pte Ltd 6 Temasek Boulevard 51 Ubi Ave 1 #01-25 #18-01 Suntec Tower 4 Singapore 038986 Paya Ubi Industrial Park Singapore 408933

Attn: Eileen Bay Date: 31 Oct 2019

Preliminary Advice

Vehicle No : SLF7325T Accident Date : 26/10/2019

Make : KIA CERATO K3 Policy No. : PNCV2019-00000387

Assignment Date : 30/10/2019 Excess : S\$1,000.00

Date of Inspection : 31/10/2019 Est. Duration of Repair : 6 days

Inspection At : Progressive Car Care Pte Ltd (HQ)

Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,321.00
Revised Amount	:S\$	6,494.00
Check Items (Estimated)	:S\$	2,293.00
Total	:S\$	8,787.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 63,000.00

 COE / PARF Rebate
 :S\$ 49,734.00

Salvage Value :S\$

Margin for Repair :S\$ 13,266.00

Remarks

()	())	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
())	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(,)	Other comments :