

REPAIR ESTIMATE*

VEHICLE NO : SHC 8493Y (Supplementary)


DATE : 31.10.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) <i>monstrous crack</i>			\$ 1,388.00
	SUB TOTAL			\$ 1,388.00
	LESS 20%			\$ 277.60
	DISCOUNTED TOTAL			\$ 1,110.40
	 Ryan 31/10/19 LK Auto 		main estimate 6152.08 Supp 1110.40 <hr/> 7262.48 L/s 5800/-	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.