



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI19019286/Eqf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 15-05-2020



Code : UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 4446B	Veh. Inspected	SJD 9322Y
Policy No.		Coverage (\$)	0.00
Claim No.	M12D11981911	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	31/10/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA2E320805B45637	Colour	BLUE
Odometer	53526	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R17	BRIDGESTONE	5 mm
L/H Front Tyre	205/55 R17	BRIDGESTONE	5 mm
R/H Rear Tyre	205/55 R17	BRIDGESTONE	5 mm
L/H Rear Tyre	205/55 R17	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2019	Inspection Date	01/11/2019
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**