

孫亞弟汽車燒焊私人有限公司  
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com  
RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005290

UNITED OVERSEAS INSURANCE LTD

3 ANSON ROAD #28-01  
SPRINGLEAF TOWER (S) 079909

ATTENTION :  
CONTACT : -

FAX NO: 63273869

DATE : 31/10/2019  
ACCIDENT DATE : 19/10/2019  
VEHICLE NO : SJD9322Y  
CHASSIS/ENG.NO : WBA2E320805B45637  
VEHICLE MODEL : B.M.W. 216D  
CLAIM NO :  
POLICY NO :  
REMARK : 9322 TP UOI AGST  
SKQ4446B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER / CUT	880.00	10	792.00	792.00/
2	10	PC	FRT BUMPER CLIPS / MC	2.00	10	1.80	18.00/
3	1	PC	FRT SIDE RETAINER (RH) / BR	12.00	10	10.80	10.80/
4	1	PC	FRT BUMPER SPONGE X	65.00	10	58.50	58.50X
5	1	PC	FRT FOG LAMP COVER RH / CUT	75.00	10	67.50	67.50/
6	1	PC	FRT FOG LAMP CHROME RH / CRA	45.00	10	40.50	40.50/
7	1	PC	FRT BUMPER SENSOR OUTER RH ?	160.00	10	144.00	144.00X
8	1	PC	FRT HEADLAMP RH / CUT	1,850.00	10	1,665.00	1,665.00/
9	1	PC	FRT FENDER RH / OD	360.00	10	324.00	324.00/
10	1	PC	FRT FENDER LOGO LUXURY RH / MC	65.00	10	58.50	58.50/
11	1	PC	FRT RIM RH 205/55/17 / CUT	780.00	10	702.00	702.00/

-----  
SUB-TOTAL: 3,880.80  
\$3678.30

\*\* WORK LABOUR \*\*

TO CHECK WIRING / MC	30.00	30.00
TO DIAGNOSE & CLEAR FAULT CODE / MC	50 80.00	80.00
TO DO WHEEL ALIGNMENT / MC	60 80.00	80.00

JOYCE

Anti Rust coat

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.  
Quotation is only valid for 14 days.

# 孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

**EST/QUOTE NO. SQ005290**

UNITED OVERSEAS INSURANCE LTD

3 ANSON ROAD #28-01  
SPRINGLEAF TOWER (S) 079909

ATTENTION :

CONTACT : -

FAX NO: 63273869

DATE : 31/10/2019  
ACCIDENT DATE : 19/10/2019  
VEHICLE NO : SJD9322Y  
CHASSIS/ENG.NO : WBA2E320805B45637  
VEHICLE MODEL : B.M.W. 216D  
CLAIM NO :  
POLICY NO :  
REMARK : 9322 TP UOI AGST  
SKQ4446B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	400		500.00	500.00
			TO PUTTY & RESPRAY PAINTING ON FRT DOOR RIGHT & AFFECTED AREAS	450		700.00	700.00
SUB-TOTAL							1,390.00

*Steve (LKK)  
83228813  
Steve Chen @ LKK auto. com*

*with Mel 1/11/19, 11.39am  
3 days  
P/P  
By DPF spy*

*\$990+*

*total \$4288.30  
less 20% = \$3814.64  
余 \$3800 45  
of? pls revert.  
Shawn 7/2/2020*

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,270.80  
ADD 7% GST. S\$ 368.96  
GRAND TOTAL : S\$ 5,639.76

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

# SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Our Ref:

Date :

07/02/2020

**ATTN:THE MOTOR CLAIMS DEPT**  
UNITED OVERSEAS INSURANCE LTD

## SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No. SJD9322Y

Model / Year

BMW 216

Date of Accident 19-Oct-19

Policy No.

Type of Claim TP UOI

Prepared By

Survey By \_\_\_\_\_

Chassis No.

S/NO	Description	Qty	Cost	Price	Amount
1	TO APPLY ANTI-RUST COATING		\$	100.00	30 ✓ NEC

Steve

11/05/20