

EROFIA MOTOR TRADING PTE LTD

A16

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Lim Khoon Him

Accident Date : 14-Jun-19

Vehicle No : FBJ 5748 S

Vehicle Model : Sym Joyride 200

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Top cowling	\$ One 75.00 —
1	Front fairing	\$ One 450.00 —
1	Front fairing inner panel	\$ One 265.00 —
1	Front lower fairing	\$ One 210.00 —
1	Headlamp	\$ One 225.00 —
2	Front signals	\$ 015500 210.00 —
1	Front mudguard	\$ One 155.00 —
1	Front fork assy	\$ 850.00 ?
1	Fork under bracket	\$ 220.00 ?
1	Front rim	\$ n 310.00 X
1	Front brake disc	\$ One 165.00 X
1	Lower belly panel	\$ One 285.00 —
1	Front rim shaft	\$ n 45.00 X
1	Centre inner cowling	\$ One 175.00 —
1	Centre inner cowling top cover	\$ One 110.00 —
1	Windshield	\$ SUC 165.00 X
1	Side mirror - R/H	\$ One 80.00 —
1	Handle bar	\$ 125.00 ?
1	Handle bar end	\$ SUC 25.00 —
1	Brake lever	\$ SUC 32.00 —
1	Handle bar top cover	\$ One 100.00 —
1	Handle bar lower cover	\$ n 68.00 X
1	Rear fairing - R/H	\$ n 355.00 X
1	Footstep panel	\$ One 105.00 —
1	Exhaust assy	\$ 0124 550.00 —
1	Exhaust protector	\$ Two 55.00 —
1	Main stand	\$ n 120.00 X
1	Rear footrest - R/H	\$ One 65.00 —
1	Rear taillamp	\$ n 320.00 X
1	Rear mudguard	\$ n 165.00 X
		\$ 6,080.00
Less 10%		\$ 608.00
		\$ 5,472.00

not about
down
n/s
31/10/19
SUC
Wheeler
None

c/f: \$ 5,472.00

		\$ 11	28.00	X
1	Number plate (1 set)	\$	30.00	?
2	Fork oils	\$	56.00	?
2	Fork oil seals	\$	85.00	?
1	Steering cone (1 set)	\$	M.S 250.00	✓
1	Rear box	\$	CR 100.00	✓
1	Rear box bracket	\$	SR 55.00	✓
1	" Joyride 200 " emble	\$	604.00	

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	35	45.00
2	To provide labour.	\$	300	380.00
3	To respray painting	\$	400	600.00
4	To straighten body frame to the original position	\$?	400.00
5	To check wiring and reset headlamp focusing	\$	112	80.00
		\$		1,505.00

Grand Total \$ 7,581.00



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: