

AIG Tel = 64191947

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO 8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 31/10/2019
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

Owner : ONG AH TEE
QBE INSURANCE (SINGAPORE) PTE LTD

Certificate Number : 08-VX020568-MVA Accident Date : 27/10/2019

Vehicle Number : SKL1819E

Make & Model : MERCEDES -BENZ E250

Not Allowed
2/5 #4700
3 days
R 1/1/18
change of things

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	FRONT BUMPER	1	1,980.60	X
2	FRONT BUMPER RETAINER RH	1	120.00	X
3	FRONT BUMPER RETAINER LH	1	120.00	X
4	FRONT BUMPER CLIPS	10	70.00	X
5	FRONT BUMPER WASHER COVER	1	95.00	X
6	FRONT BUMPER TOWING COVER	1	95.00	X
7	HEADLAMP	1	2,950.60	X
8	FRONT BUMPER FOG LAMP GARNISH	1	200.00	X
9	FRONT BUMPER FOG LAMP GARNISH CHROME	1	200.00	X
	Sub Total		5,801.20	
	DISCOUNT 10% on Parts		580.12	
	Total		5,221.08	
Special Nett Item				
1	FRONT BUMPER SENSOR	1	350.00	X
Labour & Misc				
1	LABOUR TO FACILITATE REPAIR		1,200.00	X
2	R & R AIR CONDENSER AND TOP UP GAS		250.00	X
4	RUST PROOF ON AFFECTED AREAS		150.00	X
5	TO SPRAY PAINT BONNET		250.00	X
6	TO SPRAY PAINT FRONT BUMPER		250.00	X
7	TO SPRAY PAINT FRONT FENDER H		250.00	X
8	TO SPRAY PAINT FRONT FENDER RH		250.00	X
9	TO SPRAY PAINT FRONT SUPPORT PANEL		250.00	X
10	TO SPRAY PAINT GRILLE		250.00	X
	Sub Total		2,850.00	
	Grand Total		8,421.08	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party is on a "Without Prejudice" basis
- No litigation(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

P-5425.72
102
7489214
L-1000.00
5892.04
202
4713.

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 8/11/2019

To : AIG AISA PACIFIC INSURANCE PTE LTD

Attn : Motor Claim Department

QTY	DESCRIPTION	TY	REPAIR AMOUN	SURVEYOR APP.
<u>List Item</u>				
1	FRONT BUMPER BRACKET RH	2w1	\$ 150.00	✓
2	RH HEADLAMP TOP PANEL	3w1	\$ 95.60	✓
3	RH HEADLAMP LOWER PANEL	2w1	\$ 295.00	✓
4	LH HEADLAMP LOWER BRACKET	1 1	\$ 95.00	X
5	FRONT BUMPER SPONGE	105 7101	\$ 180.00	✓
6	RH WASHER MOTOR (head lamp)	185 CNE	\$ 516.80	✓
Sub Total			\$ 1,332.40	
Discount 10% on Parts			\$ 133.24	
			\$ 1,199.16	

PAGE : 1