

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

25th OCT 2019

TPA14.

Jia Le

Accident date: 24th OCT 2019

Estimated repair cost for vehicle no: SMM1748Y HONDA GRACE 1.5 '2019

S/n	Qty	Items	U/price	Amount
1	1	Front R/H fender <i>Dented</i>		\$655.00 ✓
2	1	Front R/H fender cowlings <i>3x4</i>		\$188.00 +
3	10	Front R/H fender cowlings clips <i>5 re</i>	\$5.00	\$50.00 +
4	1	Front R/H fender hybrid logo <i>new</i>		\$45.00 ✓
5	1	Front RH side mirror assy <i>Repair</i>		\$855.00 X

Subtotal :- \$1,793.00

700

560

Labour charges

To Check Wiring System

\$60.00 30

Tuff Kote

\$100.00 +

Panel beating

\$400.00 200

Spray painting

\$400.00 200

Subtotal :- \$960.00

Total:- \$2,753.00

total: 980

4/5: 800

02 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: