

## Prime Auto Claims Service Pte Ltd

GST Reg. No: 201606560M 6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948

Date: 05.11.2019

China Taiping Insurance (S) Pte Ltd 2 Anson Road #16-00 Springleaf Tower Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2616U TOYOTA ALPHARD HYBRID 2.5 (2018)

## To Supply

To Supply			
1 ) 1pc	Tail gate		\$ 1,956.20 bt -
2 ) 1pc	Tail gate "Toyota" emblem		\$ 90.00ner
3 ) 1pc	Tail gate "Alphard" emblem		\$ 80.00 re
4 ) 1pc	Tail gate "Hybrid Synergy Drive" emble	m	\$ 85.10 ne
5 ) 1pc	Tail gate "E-Four" emblem		\$ 59.10
		Sub total parts	\$ 2,270.40
		Less: 25% discount	\$ (567.60)
			\$ 1,702.80
To Supply S.Ne	tt Parts		
1 ) 1set	Rear glass inner seal		\$ 65.00 M
2) 1tube	Rear glass sealant		\$ 40.00 ue
		Sub total S.Nett Parts	\$ 105.00
L/charge			
1 ) To remove & refit rear glass.			\$ 120.00 ✓

2 ) To transfer tail gate trim board, handle & mechanism part.

3 ) To remove & replace tail gate. Align & adjust tail gate.

80.00 60.

300.00 200

\$

4 ) To putty, respray painting tail gate inlet & outer. To polish.

300.00

Sub total L/charges	\$ 800.00
Estimated Grand	\$ 2,607.80

\$

Prepared by: Chrissy

Taufhin 9749549
4/11/1983pm
hungsum
perrang sper repair
02 days
Swc/blanto.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: