

Past to vic, thanks

ARC Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1910-127
DATE : 29-Oct-2019
POLICY NO. : PNPV2019-00009866
VEHICLE REG. NO. : SMA3202E
VEHICLE MAKE : SUBARU FORESTER-2.0 I-L CVT AWD SR 6

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper X R	1	\$ 780.00	\$ 780.00
2	Rear Bumper Clip X SVC	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH X SVC	1	\$ 20.00	\$ 20.00
4	Rear Bumper Retainer LH X SVC	1	\$ 20.00	\$ 20.00
5	Rear Bumper Bracket Corner RH X SVC	1	\$ 30.00	\$ 30.00
6	Rear Bumper Bracket Corner LH X SVC	1	\$ 30.00	\$ 30.00
7	Rear Bumper Reflector RH X SVC	1	\$ 40.00	\$ 40.00
8	Rear Bumper Reflector LH X SVC	1	\$ 40.00	\$ 40.00
Total Spare Parts				\$ 1,010.00
SPECIAL NETT				
9	Reverse Sensor X SVC	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
LABOUR				
10	Spray painting Rear Bumper and Rear Boot Cover under bumper.	1	\$ 500.00	\$ 500.00
11	Remove, Replace and Repair Accident Affected Area	1	\$ 500.00	\$ 500.00
12	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
13	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
14	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 1,210.00
Amount Before Excess	\$ 2,420.00
Add GST @ 7%	169.40
Total Amount Payable	\$ 2,589.40

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Repair days - 1 day

P/p Repair.

Sun Pin (LKK)

12/11/2017

Sunpin@lkkauto.com

TP without prejudice

Page 1 of 1

Labour

300
+ 200
500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Oi Sun Pin (LKK Auto)

From: ARC Ken <kenguan@automotiverepaircentre.com.sg>
Sent: Friday, 15 November, 2019 9:04 AM
To: Oi Sun Pin (LKK Auto)
Cc: Vic (LKKAuto); ARC Raymond; ARC ShuJuan
Subject: RE: SMA3202E - TP Claim SJN2922J *** LKK REF: CC6/CTI19019423/ha3

Dear Sun Pin

We confirm the finalize amount at \$500, (P/P repair, before gst). Repair day 1 days.

Thank you!

With best regards,
Ken Ng

From: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Thursday, 14 November 2019 5:59 PM
To: kenguan@automotiverepaircentre.com.sg
Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: SMA3202E - TP Claim SJN2922J *** LKK REF: CC6/CTI19019423/ha3

Dear Ken,

We confirm the finalize amount at \$500, (P/P repair, before gst). Repair day 1 days.
If agree please reply ASAP.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ARC Ken [<mailto:kenguan@automotiverepaircentre.com.sg>]
Sent: Wednesday, 13 November, 2019 12:58 PM
To: Oi Sun Pin (LKK Auto)
Cc: ARC Raymond; ARC ShuJuan
Subject: SMA3202E - TP Claim SJN2922J *** LKK REF: CC6/CTI19019423/ha3

Dear SunPin

Attached completion photos for finalisation (SMA3202E).
Can we close at \$500?

Thank you for your attention.

With best regards,
Ken Ng

Automotive Repair Centre Pte Ltd