Automotive Repair Centre Pte Ltd CO. Reg. No.: 201312913C GST Reg. No.: 201312913C

Estimate

38 Woodlands Industrial Park E1 #05-18, Singapore 757700 Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO.: EST1910-127 DATE: 29-Oct-2019

POLICY NO.: PNPV2019-00009866

VEHICLE REG. NO.: SMA3202E

VEHICLE MAKE: SUBARU FORESTER-2.0 I-L CVT AWD SR (/

Motor Claim Department China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR						

ESTIMATE REPAIR COST

ESTIMATE REPAIR COST								
NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST				
	SPARE PARTS							
1	Rear Bumper	1	\$ 780.00	\$ 780.00				
2	Rear Bumper Clip	10	\$ 5.00	\$ 50.00				
3	Rear Bumper Retainer RH	1	\$ 20.00	\$ 20.00				
4	Rear Bumper Retainer LH	1	\$ 20.00	\$ 20.00				
5	Rear Bumper Bracket Corner RH	1	\$ 30.00	\$ 30.00				
6	Rear Bumper Bracket Corner LH	1	\$ 30.00	\$ 30.00				
7	Rear Bumper Reflector RH	1	\$ 40.00	\$ 40.00				
8	Rear Bumper Reflector LH	1	\$ 40.00	\$ 40.00				
	Total Spare Pari							
	SPECIAL NETT							
9	Reverse Sensor	1	\$ 200.00	\$ 200.00				
	Total Special Nett							
	LABOUR							
10	Spray painting Rear Bumper and Rear Boot Cover	1	\$ 500.00	\$ 500.00				
11	Remove, Replace and Repair Accident Affected Area	1	\$ 500.00	\$ 500.00				
12	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00				
13	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00				
14	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00				
Estimate prepared by: Raymond Tan Total Labour								
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first								
						inspection. Because of this, the above price are not guaranteed. Quotation on parts Total Amount Payable		
and labour are current and subject to change.								

Please arrange this vehicle to be surveyed soonest possible. Thank you.