

REG. NUMBER:

SLC 323K

MAKE/MODEL:

Nissan Qashqai 2.0

CHASSIS MEMBER:

SJNJBNJ1047024380

14 days

nett 10%

QUANTITY	SPARE PARTS		
1 PC		Front Bumper	cm
1 PC 0287	1/5	" " side retainers	cm
10 PC		" " clips	mm
1 PC 0391		" " & Lower Rubber Lid	
0343 PC 0387	1/5	" " Fog Cover Chrome	
1 PC 0637	"	" " Fog Lamp	cm
PC 99	"	" " Bracket	
1 PC 0409		Front Grille	
6 PC		" " clips	
PC			
2 PC		Headlamp Assy (LH/RH)	mm
2 PC 0515/0516		" " Lower Bracket (LH/RH)	
PC			
1 PC	1/5	Front Fender	Bu
1 PC 0883	"	" " wheel arch garnish	
1 PC	"	" " inner bracket	
1 PC 0844	"	" " inner shield	
8 PC	"	" " clips	
1 PC 99	"	" " Lamp	
1 PC	"	" " mud flap	Bu
1 PC 99	"	" " inner Vertical sponge	
1 PC 0891	"	" " Lower Garnish	
PC 1421		Front Front windscreen Glass moulding	
PC		" " sealant	
PC	1/5	Door Front A Pillar	R
PC	1/5	Front Door	Bu
PC	"	" " weatherstrip	R
2 PC	"	" " Hinges (Top/Lower)	

LIST

777.10N ✓
 35.20N ✓
 2.60N X 10 ✓
 80.30N Bu/10N ✓
 70 130.10N 2112 ✓
 327.30N ✓
 53.80N ?
 422.10N ?
 21 5.50N X 6 ?
 672.20N X 2 ✓
 41.70N X 2 ?
 753.50N ✓
 654N m.i ✓
 156.10N cm ✓
 2.60N X 8 mm ✓
 60.10N ?
 123.20SN ✓
 22.10N ?
 39.20N ?
 155.50N ?
 40.5N SN ?
 1566.50N X
 1282.80N ✓
 181.60N X
 69.10N X 2 ?

COST

K. KIM HIN AUTO PTE LTD

FAX: 64583895

NUMBER:

SLC 323K

/MODEL:

MASSIS MEMBER:

QUANTITY	SPARE PARTS	
1 PC 1505	n/s	Front Door checker R
1 PC 1681	"	" " Protector M
1 PC		Air Reserator
1 PC	n/s	Front Door Lower Garnish
1 PC		
1 PC 99		Air Reserator CMA
1 PC		
1 PC	n/s	Front tyre Pn
1 PC	"	" " Sport rim P1 R1
1 PC	"	" " Knuckle Arm B1
1 PC 7131	"	" " " " Bearing M
1 PC	"	" " Bearing Hub
1 PC	"	" " Drive Shaft R1
1 PC 7053	"	" " Lower Arm R1
1 PC	"	" " Rotor Disc
1 PC 7133	"	" " " " Back Plate
1 PC 7165	"	" " Brake Hose
1 PC 7185	"	" " " " Pipe
1 PC	"	" " Brake Sensor
1 PC	"	" " tie rod
1 PC 7311	"	" " tie rod end R1
1 PC	"	" " stabilizer Bar Linkage
1 PC	"	" " shock absorber R1
1 PC 7103	"	" " " " stopper (LWR)
1 PC 7095	"	" " " " mounting
1 PC 7097	"	" " " " Bearing
1 PC 7115	"	" " " " coil spring
1 PC 7099	"	" " " " " Lower
1 PC 7101	"	" " " " stopper (UPP)

LIST

50.90N X

382.10N

134.40SN

280SN John

850SN

557SN

336.50SN

1159.80SN

232.80N

205.20SN

196.90SN

64.80SN

55N

383.10SN

140.20SN

44.30N M1

431SN

51SN

103.10N

133.30SN

248.10SN

33N

51SN

K. KIM HIN AUTO PTE LTD

FAX: 64583895

NUMBER: SLC 323K
 E/MODEL: _____
 CHASSIS MEMBER: _____

QUANTITY	SPARE PARTS		LIST
1 PC	Front steering cross member		17.80N x 2
2 PC	Front stabilizer Bar Bush		353.60SN 7
1 PC	" " Bar		1617.90SN ✓
1 PC	Steering rack & pinion B/L		817.80SN 7
1 PC roll	Engine sub Frame		17.40SN 7
4 PC	" " " screw	1	250SN 7
1 PC	Tyre Pressure sensor		151.10SN 7
1 PC 8915	Engine Mounting - LH		243.70SN 7
1 PC	" " - RH		95.10SN 7
1 PC 8641	" " - Rear	K42	120
1 PC		K11	1600
1 PC		K16	120
1 PC		K20	150
1 PC		K01	300
1 PC		K24	300
1 PC		K26	80
1 PC		K41	300
1 PC		K04	80
1 PC	To remove and refit front windscreen		1400
1 PC	and conduct water leak test		120
1 PC			50
1 PC			
1 PC			
1 PC			
1 PC			
1 PC			
1 PC			
1 PC			

K. KIM HIN AUTO PTE LTD

FAX: 64583895