

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email: ben@allswellmotor.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To survey damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(3rd party claim against Lapac insured)

Acknowledged by Repairer

Signature:

Date:

POA 01-11-2019

Estimate repair

Vehicle No.

SUK 4366T

Submitted by

Ben

Make & Model

Vezel 1.5 CVT

COE expiry

16-01-2027

Chassis No.

Engine No.

Date of survey

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	RH side mirror <i>cracked</i>	01	\$795.00	✓	
02	RH door fnt <i>cracked</i>	01	\$950.00	✓	
03	RH door rear <i>cracked</i>	01	\$910.00	✓	
04	RH rear fender <i>cracked</i>	01	\$1,100.00	✓	931
05	RH door handle <i>cracked</i>	01	\$280.00	✓	
06	RH door centre pillar outer case <i>Rep</i>	01	\$580.00	+	
07	RH rear door window panel (vertical) <i>cracked</i>	01	\$180.00	✓	
08	Weather strip exterior RH door <i>ut</i>	01	\$98.00	✓	
09	RH rear arc <i>missing</i>	01	\$125.00	✓	
10	RH rear inner shield <i>men</i>	01	\$240.00	+	
11	RH skirting <i>deland</i>	01	\$691.00	2	5155
12	RH fnt door lock mechanism <i>2Hr</i>	01	\$920.00	*	4124
13	Rear bumper <i>Side Pad RH 2Hr</i>	01	\$1,619.00	2	185
<i>Special note</i>					
01	Clips / retainers studs \$120/prt for door panel trims, skirting & etc.	60			
<i>Labour Description</i>					
01	Dismantle / Assembly of all affected part including 2 door elements windows and etc	01	\$180.00	180	
02	Panel beating, welding, cutting of rear fender, RH centre pillar	01	\$250.00	1000	2040
03	Spray painting of all affected parts (2 door x 4), RH skirting, centre pillar, rear bumper, RH rear fender	01	\$180.00	800	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Total: 6164 Admin Lj 96893735.
CP/P) P/P 04/11/19.
07 Days.