

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

Bok Seng Logistics Pte Ltd
No 5 Tuas Ave 3
Singapore 639405
No 6 Tuas Ave 5 Gate 4
Attention : Motor Claim Department
Contact : 6416 1975 Fax No. : 6861 3508

Estimate : ES002996

Date : 04/11/2019
Vehicle Num. : SJD9668A
Make/Model : HONDA FIT 1.3A
Chassis/Eng# :
Accident Date : 01/11/2019
Claim No. :
Reference : SKR1995Y
Policy No. : D18MPC0001414_01

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BUMPER		823.50 <i>Orig</i>
2.	2	BUMPER SIDE BRACKET	105.20	210.40 <i>de</i>
3.	6	BUMPER CLIP	5.00	30.00 <i>new</i>
4.	1	HEADLAMP, RHS		985.20 <i>Orig</i>
5.	1	HEADLAMP BRACKET RH		198.50 <i>Orig</i>
6.	1	BUMPER REINFORCEMENT		431.20 <i>bt</i>
7.	1	MUDGUARD, RHS		381.20 <i>Rp</i>
8.	1	MUDGUARD INNER GARNISH		167.30 <i>de</i>
9.	6	MUDGUARD INNER GARNISH CLIP	5.00	30.00 <i>new</i>
10.	1	FRONT DOOR, RHS		1,348.20 <i>bt</i>
11.	1	SIDE MIRROR, RHS		551.20 <i>3 photo</i>
12.	1	LOWER GARNISH		345.20 <i>Rp</i>
13.	1	WASHER TANK		198.20 <i>de</i>
14.	1	AIR-CON CONDENSER		762.20 <i>?</i>
15.	1	BUMPER SPOTLAMP		198.20 <i>?</i>
16.	1	HEADLAMP, LHS		985.20 <i>Orig</i>
List TotalS\$:				7,645.70
<i>20%</i> 15.00% Discount S\$:				1,146.86
				6,498.84
LABOUR :				<i>700.</i>
TO PANEL BEAT AND REPAIR FRONT BODY				850.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

Bok Seng Logistics Pte Ltd
No 5 Tuas Ave 3
Singapore 639405
No 6 Tuas Ave 5 Gate 4
Attention : Motor Claim Department
Contact : 6416 1975 Fax No. : 6861 3508

Estimate : ES002996

Date : 04/11/2019
Vehicle Num. : SJD9668A
Make/Model : HONDA FIT 1.3A
Chassis/Eng# :
Accident Date : 01/11/2019
Claim No. :
Reference : SKR1995Y
Policy No. : D18MPC0001414_01

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
--	--	---	--	--

		TO DISMANTLE/REPLACE AIR-CON CONDENSER		150.00 <i>100? pick</i>
		TO TOP-UP GAS		

		TO SPRAY PAINTING		750.00 <i>750-</i>
--	--	-------------------	--	--------------------

		TOWING CHARGES		950.00
--	--	----------------	--	--------

		LOSS OF USE : 7 DAYS @ S\$120/DAY		60.00 <i>60.00? towing receipt</i>
--	--	-----------------------------------	--	------------------------------------

		Labour Total S\$:		2,010.00
--	--	--------------------	--	----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SIN SHENG ENGINEERING SERVICES

Total S\$: 8,508.84

=====

Tan Jia 92445249
'wp'
5/11/19 @ 220/12
Resurvey after repair
5 days
suu@lkkauto.com



YISHUN TOWING PTE LTD

Blk 4015 Ang Mo Kio Industrial Park 1, #01-502, Singapore 569631

Tel: 6458 8480 HP: 9628 8480 Fax: 6288 8480

Website: www.yishuntowing.com

Reg. No. 200106908W GST No. 200106908W

M/s Sin Cheng Engineering

WORK ORDER

No. 293227

Order By:

AT 1730 DT 1950

Date: 1/11/19

車牌
Vehicle No.

SJD 9668A

車型
Model

From:

2 Kaki Bukit Ave 2

To:

8 Tuas Ave 18 LV 5

Remarks:

Day/Night

SNA  1/11/19
Customer Signature & Company Stamp


Authorised Signature

Tow Truck No.: 1H8056

All business transactions with Yishun Towing Pte Ltd are subject to its Standard Conditions in so far as these Conditions are applicable. Copies of these conditions may be obtained upon request. Note: Please see terms & conditions on the reverse side.

