

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 07 Nov 2019

Preliminary Advice

Insured Vehicle No : SLE7355L

TP Vehicle No : SGN4365P

Make : HONDA CIVIC

Date of Inspection : 06/11/2019

Inspection At : Mova Automotive Pte Ltd (FAN YOONG BRANCH)
15 Fan Yoong Road, CNG Singapore Centre
Singapore 629792

Accident Date : 05/11/2019

Assignment Date : 06/11/2019

Est. Duration of Repair : 10 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body, o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,943.20
Revised Amount	:S\$	7,208.80
Check Items (Estimated)	:S\$	1,598.00
Total	:S\$	8,806.80

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.