

AST REC BY:

REF: CS/ICS 1901605/ AY f307

Special Instruction:

Surveyor: Adrian ASSIGNMENT (Office)

From (Person): Crystabelle Tan of ECICS Date/Time: 6.11.19 12.22 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 5914S Insured:

at Workshop n/z: Verve Motorclinic Tel: 67022990

of NO 25 kaki Bukit Road 4 #103-39

Policy No: MP19A00139500 Claim No: DMPC19002764/ CT

Sum Insured: Excess:

Make of Veh: D.O.A. 31.10.19

(Client's Record)

CA (REV) REP. / REV 24 HRS

Date/Time: 6.11.19 1.13 p.m Person Contacted: VOVO

H.O.D. Endorsement:

Vehicle (IN) OUT

Date/Time Action/Instruction (✓) Estimate

SLD 5914 S-X

11/11/19 Pere approved \$8500 from Crystabelle by merimen

4/11/19 Informed BoBen c/A LS not exceeding \$8500 & \$0 by email

11/11/19 @358pm Informed BoBo arrange to take photos after print

photo ok

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Velt: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLD5914S Regn: 2007 Sept
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Accord C.C. 1998
 Colour: White A/C: Insured / Std / NI / NA
 Sp Reading: 184121 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: CL73302098

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18
 R: 225/45R18

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 06/11/19

Survey held at: Yerve

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Frnt O/S, u/c, N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD ELICS.
6/11/19	Co Repair limit \$8500/- inform workshop.
	MV: 23k Depreciation @ 7.5k x 3 = 23k
	PV: 14.4k
	Nett: 8.6k.
	8/11/19 Confirm by workshop \$8500/- Below
	8/11/19 Revert Via Merimen

Date/Time: File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time: File Return to?

3/12/19 Typist

Days Of Repair: 10

Resurvey No. of Trip: 2

Print Fee: ☐ : Site Insp. \$

☐ : Interview \$

☐ : Tech. Insp. \$

☐ : (Final) Insp. \$

Survey Fee:

Transportation:

3 - Ho. \$

Phone

Other

Total

Report Format:

Using Stamp ID: \$8500/-

450

11

461

...CLAIM SUBFOLDER...(New Assignment)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2019 17:47 Sendback Est	05 Nov 2019 18:29 S\$25,360.30	06 Nov 2019 12:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TAN JUN JIE EDDIE, ID: S8704674E, Email: VERVEMOTORCLNIC@GMAIL.COM		
Vehicle Reg. No.:	SLD5914S	Date of Loss:	31/10/2019 00:00 - :59 [145 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1900276H/CT	Policy/Cover Note No.:	MPC19A00139500 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Verve Motorclinic Pte Ltd (Kaki Bukit) No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB, 417800 Kaki Bukit - Tel: 67022990		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/11/2019]		
Driver/Custodian:	TAN JUN JIE EDDIE (), NRIC: S8704674E Email: VERVEMOTORCLNIC@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 11 November 2019 11:16 AM
To: SUR; vervemotorclinic@gmail.com
Subject: SLD 5914S-DOA: 31/10/19 (ECICS OD)

Dear Bo Bo,

As instructed by our client , please proceed to repair the **insured vehicle SLD 5914S on LUMP SUM NOT EXCEEDING \$8500/- (Excess \$0/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler on behalf of Yvonne

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLD5914S (DMPC1900276H/CT)

OD

Oct 31 2019 12:00AM

[TAN JUN JIE EDDIE]

Verve Motorclinic Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 11/11/2019 10:29 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8500.00) - SLD5914S - Claim Handler: Crystabelle Tan

Approved:8500.00:Please update photos

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 08 Nov 2019

Preliminary Advice

Vehicle No	: SLD5914S	Accident Date	: 31/10/2019
Make	: HONDA ACCORD	Policy No.	: MPC19A00139500
Assignment Date	: 06/11/2019	Excess	: S\$0.00
Date of Inspection	: 06/11/2019	Est. Duration of Repair	: 10
Inspection At	: VERVE MOTORCLINIC PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s,n/c,n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,360.30
Revised Amount	:S\$	10,245.50
Check Items (Estimated)	:S\$	9,355.10
Total	:S\$	19,600.60
Lump Sum Repair	:S\$	8,500.00 (Estimate)

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	23,000.00
COE / PARF Rebate	:S\$	14,435.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,565.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2019 14:20
Date Of Accident	31/10/2019 04:35
Exact Location Of Accident	ALONG HOLLAND ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD5914S
Insured/Policyholder	
Name Of Registered Owner	TAN JUN JIE EDDIE
NRIC No	S8704674E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85696340
Alternative Phone No	OTHERS-85696340

Vehicle Particulars

Manufacturer	HONDA
Model	ACCORD-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MPC19A00139500
Cover Note Number	

Driver

Name of Driver	TAN JUN JIE EDDIE
NRIC No	S8704674E
Date Of Birth	20/02/1987
Occupation	INDOOR
Date Of Driving Pass	23/04/2008
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85696340
Fax Number	
Contact Number	OTHERS-85696340
Email Address	NOEMAIL

Address 121D SENGKANG EAST WAY #04-73

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident NO COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 1

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name SENGKANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE . POSTCODE: 545025 . COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800 - 3438999 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)


Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to PMS Report.

DECLARATION

I/We declare the foregoing particulars are true to every detail.

Investigator's Signature
Date & Time

Driver's Signature
If driver is not the complainant
Date & Time

Reporting Constable/Personnel's Signature
Name
Rank/Title etc.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo





Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/10/2019 06:43	Vide Report No.: D/20191031/0029	Station Diary No.: 16
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TAN JUNJIE, EDDIE			Address: APT BLK 121D SENGKANG EAST WAY #04-73 SINGAPORE 544121		
ID Type / ID No.: NRIC NO / S8704674E			Contact No.: Home/Office: Mobile: 85696340		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 32	Date of Birth: 20/02/1987	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: VALET			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 31/10/2019 05:00	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 HOLLAND ROAD HOLLAND GROVE ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLD5914S	Car	HONDA	ACCORD 2.0 A	White	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLD5914S	ECICS LIMITED	MPC19A00139500	19/09/2019	18/09/2020



**SINGAPORE
POLICE FORCE**



T/20191031/2017

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 3

Report No. T/20191031/2017

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN JUNJIE, EDDIE	ID No.	S8704674E
Related Vehicle	SLD5914S (Car)	Contact No.	85696340
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 31/10/2019 at about 0500hrs, I was driving my car, vehicle number: SLD5914S, along Holland Road. At the T-junction of Holland Road and Holland Grove Road, when I was making a left turn, suddenly my car skidded, and mounted on a kerb of the road divider. My car also hit the speed limit sign which was at the road divider, resulting to some damage on it.

Due to the accident, my car was seriously damaged. However I was not injured. There were no other road users as well. I called for police, and they came soon after. My car was towed away to my workshop.

I was advised to make this police report, reference D/20191031/0029, TP/IO Ivan Ho, tel: 65476170.



**SINGAPORE
POLICE FORCE**



T/20191031/2017

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No. T/20191031/2017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt NORASHIKIN BINTE KAMSANI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

31/10/2019 06:43

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Classification Of Case:

SN 085

Authentication Stamp

NP168



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	674E
Vehicle Details	
Vehicle No.:	SLD59145
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.0 A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	K20A6052416
Chassis No.:	CL73302098
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$20,034.00
Original Registration Date:	19 Sep 2007
First Registration Date:	19 Sep 2007
Transfer Count:	6
Actual ARF Paid:	\$22,038.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,178.00
COE Rebate Amount:	\$14,435.00
Total Rebate Amount:	\$14,435.00
Disclaimer	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Nov 2019

OK

Google Pixel 4

Get your hands on Pixel 4 at the Google Store today. Shop now

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A

 2.88% P.A. \$0 Down, \$0 Admin,
Monthly from \$468, 2 Years
Warranty Engine, Gear
StarAd

Republic Auto **CERTIFIED PRE-OWNED**
MERCEDES BENZ

 [View Our Cars](#)

Browse by Category  Save Search  Print [Back \(1 2 \) Next >](#) Sort by Date Posted 20 results/page

22 vehicles	Search	accord	Advanced Search	Search	View All
Make	Model	Price	Depreciation	Reg Date	Eng Cap
Mileage	Veh Type	Status			
Search Selection	accord	Any	Any	> 10 year(s) old	Any
		Any	Any	Any	Any
					Available



☐ **Honda Accord Euro R 2.0M (COE till 05/2026)** **\$58,800** **\$9,030 /yr** **11-May-2006** **1,998 cc** **-** **Sports** **Available**

Maintained In Pristine Condition, White Paintwork Matched With Full Black Interior, Full Original Condition, Consignment Unit, Please Call Now To Arrange A Viewing.

Autoline Pte Ltd

 [Home](#) [Contact Us](#) [About Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#)



☐ **Honda Accord 2.0A (COE till 05/2021)** **\$12,500** **\$8,170 /yr** **13-Jul-2006** **1,998 cc** **-** **Luxury** **Available**

Excellent Condition. Well Maintained By Previous Owner. Good For Short Term Drive. View To Believe. Different Loan Schemes To Suit Your Purchase. Call Our Friendly Sales Executive For Viewing And Test Drive.

Trust Motoring

 [Home](#) [Contact Us](#) [About Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#)



☐ **Honda Accord Euro R 2.0M (COE till 12/2021)** **\$23,800** **\$11,340 /yr** **12-Dec-2006** **1,998 cc** **-** **Sports** **Available**

Consignment Unit. One Of The Cleanest And Most Well Maintained CL7R In Town. Whole List Of Parts And Mods Will Be Introduced During Viewing. Seriously No Expenses Spared. Fully Forged Rebuilt Engine, 5.1 Final Drive, No Worries On Loan Paperwork, High Loan...

 [Home](#) [Contact Us](#) [About Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#)



☐ **Honda Accord Euro R 2.0M (COE till 01/2027)** **\$68,000** **\$9,450 /yr** **15-Jan-2007** **1,998 cc** **301,000 km** **Sports** **Available**

Engine Fully Overhaul At 273000km At Skm. Just Replaced Both Drive Shafts And 4 Piece Potenza Re003 Tyres Last Two Months. Come With Full Aluminium Rads, All Wear And Tear Done At Skm Only. Whatsapp Me To Know More About The Car. Not In A Rush To Sell The...

 [Home](#) [Contact Us](#) [About Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#)

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Honda Accord 2.0A JDM (COE till 01/2022)** **\$18,900** **\$8,600 /yr** **17-Jan-2007** **1,998 cc** **180,000 km** **Luxury** **Available**

Superb Condition Accord, Priced To Sell, Done Up Nicely, New Candy Red Sprayed And Groom Regularly, Pioneer HU, Full Steg Sound System, Full Wear And Tear Replaced With Receipt, High Loan Available, Consignment Unit, Call Now For A Viewing.

Prem Roy Motoring

 [Home](#) [Contact Us](#) [About Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#)



☐ **Honda Accord 2.0A JDM (COE till 01/2022)** **\$20,800** **\$9,400 /yr** **23-Jan-2007** **1,998 cc** **-** **Luxury** **Available**

AA Trust Certified Quality Pre Owned Vehicle! Well Maintained By Previous Owner! Honda Accord JDM Model! Beautiful Silver Exterior With Leather Interior Seats! Highly Recommended Sedan With Comfortable Legroom Space And Ample Boot Space For Everything And Anyth...

AA Trust Automotive

 [Home](#) [Contact Us](#) [About Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#)

[Compare](#)



☐ **Honda Accord Euro R 2.0M (COE till 08/2027)** **\$64,888** **\$8,370 /yr** **07-Aug-2007** **1,998 cc** **181,000 km** **Sports** **Available**

Well Taken Care By Seller, Many Wear And Tear Replaced Including New Engine Mounts, Interior Roof Lining, Undercarriage Parts, Genuine Mileage, Full Original Factory Alcantara Interior With Recaro Semi Bucket Seats, Workshop Inspection Welcomed, High Loan With High Tr...

PREMIUM ED

Posted: 30-Sep-2019 Tags: 2007 Honda Accord, 2007 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord Euro R 2.0M (COE till 09/2027)** **\$70,888** **\$9,030 /yr** **11-Sep-2007** **1,998 cc** **-** **Sports** **Available**

Car Overhaul And Fully Maintained By SKM, Powerful Legendary Street Legal Beast, Negotiable For Genuine Buyer, Buy With A Peace Of Mind, Well Taken Care CL7R, Consignment Unit, Trade In Welcome, Loan And Insurance Available, Call Now For Viewing Appointment!

From Roy Motoring

Posted: 20-Oct-2019 Tags: 2007 Honda Accord, 2007 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord Euro R 2.0M (COE till 02/2028)** **\$116,000** **\$13,980 /yr** **21-Feb-2008** **1,998 cc** **138,000 km** **Sports** **Available**

Consignment Unit. Ready For Viewing, In Hus Loan Available. Hurry Call To To View The Car! K20 Fd2r Crankshaft FD2R Conrod Wisco Forge Piston Fd2r Oil Pump Hardrace Camber Kit Mitin Coilover Fd2r Rrc Intake Manifold Skunk2 Intake Hondata Kpro Hls Exhaust With...

Posted: 23-Oct-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord 2.0A JDM (COE till 04/2028)** **\$45,700** **\$5,410 /yr** **18-Apr-2008** **1,998 cc** **172,029 km** **Luxury** **Available**

Super Reliable Workhorse, Owned By Pilot Owner For 6 Years. All Servicing Records Kept And Condition Can Be Verified At Workshop. Selling To Get A Bigger Car As Family Is Growing. No Problems/Repairs. Extremely Reliable Point A To B Car With A Lot Of Space And Pe...

RECOMMEND

Posted: 24-Oct-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



Find the right car through consignment.

Purchase pre-loved, owner consigned cars at affordable prices through our dedicated consignment agents. Arrange a test drive today.

Find out more!



☐ **Honda Accord 2.4A (COE till 11/2022)** **\$28,500** **\$9,290 /yr** **22-Apr-2008** **2,354 cc** **180,000 km** **Luxury** **Available**

Practically One Owner Only.

DIRECT OWNER

Posted: 07-Oct-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord 2.0A (COE till 04/2028)** **\$58,800** **\$6,930 /yr** **30-Apr-2008** **1,997 cc** **138,506 km** **Luxury** **Available**

Genuine Mileage. Rare 2.0L Unit, Reliable Car/Low Maintenance. Well Maintained/Groomed. New Paintwork. Beige Leather Interior. Biggest/Most Spacious 2.0L Luxury Sedan Ever Built (Length 4.95m). Good Fuel Economy Of 11km/L. Petrol Tank 75L. 0 To 100km/H In...

DIRECT OWNER

Posted: 14-Sep-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord 2.0A JDM (COE till 05/2023)** **\$27,500** **\$7,720 /yr** **30-May-2008** **1,998 cc** **145,000 km** **Luxury** **Available**

Malay Owner. Car In Very Good Condition, 6 Months Warranty Engine And Gearbox, Clean And Neat Interior. High Loan Available! Trade In Welcome. Please Call For Viewing Now!

PREMIUM ED

Posted: 04-Nov-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord Euro R 2.0M (COE till 06/2028)** **\$73,800** **\$8,600 /yr** **03-Jun-2008** **1,998 cc** **-** **Sports** **Available**

Consignment Unit. One Of The Cleanest And Most Well Maintained CL7R In Town. Whole List Of Parts And Mods Will Be Introduced During Viewing. Seriously No Expenses Spared. Fully Forged Rebuilt Engine, FD2R 5.1 Final Drive, DCSR 4.5.6 Gears. Teln Collovers. Mu...

PREMIUM ED

Posted: 14-Sep-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord 2.0A (COE till 07/2028)** **\$50,800** **\$5,870 /yr** **02-Jul-2008** **1,998 cc** **140,000 km** **Luxury** **Available**

Newly Replaced Aircan Extremely Important For The Hot Weather In This Sunny Island! Well Maintained By Fussy Owner, Wear And Tear Replaced, Honda Well Known For Reliability, Drive To End Of COE Without Any Worry, Consignment Unit, Viewing Via Appointment Only...

PREMIUM ED

Posted: 18-Sep-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda



☐ **Honda Accord 2.0A JDM (COE till 05/2028)** **\$47,800** **\$5,580 /yr** **11-Jul-2008** **1,998 cc** **-** **Luxury** **Available**

New Arrival! Sporty White In Black Leather Interior Honda Accord 2.0A JDM Model! Reliable And Low Maintenance Cost. Own By Careful Owner And 100% Accident Free And In Original Condition And No Modifications Done! Road Tax Till Jan 2020! Call Us Now, Do Not Miss!

Posted: 10-Oct-2019 Tags: 2008 Honda Accord, 2008 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Used Honda

SHORTLISTED 16/10/19

Compare

Verve Motorclinic Pte Ltd (Co.Reg.No:201800568H)

No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB

Singapore 417800

Tel: 67022990 Email: jaronranz92@gmail.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC19A00139500	Date of Loss:	31/10/2019
Vehicle Reg. No.:	SLD5914S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN JUN JIE EDDIE		
Driver:	TAN JUN JIE EDDIE		

Make/Model:	HONDA ACCORD, 2.0 (A)	Vehicle Reg. Date:	19/09/2007
Vehicle Colour:	WHITE		
Engine No:	K20A6052416	Chassis No:	CL73302098
Odometer:	184121 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location:	VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)
-------------------	--

COST OF CLAIMS

	Amount
Parts	21,950.30
Miscellaneous Items	0.00
Labour	3,410.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	25,360.30

This claim is handled by: THAM WEI CHUEN KENNETH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Nov 2019)

Parts: 143 HONDA ACCORD 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>distorted</i>	0.00	0.00	*580.00 F ✓
2	1		*BONNET HINGE RH <i>new</i>	0.00	0.00	*50.00 F +
3	1		*BONNET HINGE LH	0.00	0.00	*50.00 F +
4	1		*FRT GRILLE BASE ?	0.00	0.00	*215.00 F ?
5	1		*FRT GRILLE CHROME (CENTRE) <i>new</i>	0.00	0.00	*150.00 F ✓
6	1		*FRT GRILLE CHROME (TOP)	0.00	0.00	*65.00 F +
7	1		*FRT GRILLE CHROME (BOTTOM)	0.00	0.00	*65.00 F +
8	1		*FRT BUMPER <i>distorted</i>	0.00	0.00	*1,050.00 F ✓
9	8		*FRT BUMPER CLIPS <i>new</i>	0.00	0.00	*64.00 F ✓
10	1		*FRT BUMPER LOWER SPOILER ?	0.00	0.00	*1,100.00 F ?
11	1		*FRT BUMPER RETAINER RH <i>new</i>	0.00	0.00	*20.00 F ✓
12	1		*FRT BUMPER RETAINER LH <i>new</i>	0.00	0.00	*20.00 F ✓
13	1		*FRT BUMPER BEAM RH <i>Bent</i>	0.00	0.00	*35.00 F ✓
14	1		*FRT BUMPER REINFORCEMENT ?	0.00	0.00	*220.00 F ?
15	1		*WASHER TANK <i>distorted</i>	0.00	0.00	*65.00 F ✓
16	1		*WASHER TANK MOTOR <i>new</i>	0.00	0.00	*36.00 F +
17	1		*FRT SUPPORT PANEL ?	0.00	0.00	*420.00 F ?
18	1		*FRT FENDER RH <i>distorted</i>	0.00	0.00	*420.00 F ✓
19	1		*FRT FENDER LH <i>distorted</i>	0.00	0.00	*420.00 F ✓
20	12		*FRT FENDER CLIPS <i>new</i>	0.00	0.00	*36.00 F ✓
21	1		*FRT FENDER COWLING RH <i>torn</i>	0.00	0.00	*100.00 F ✓
22	1		*FRT FENDER COWLING LH <i>new</i>	0.00	0.00	*100.00 F ✓
23	1		*SIDE SKIRT LH <i>new</i>	0.00	0.00	*650.00 F ✓
24	1		*FRT WHEEL HUB RH ?	0.00	0.00	*150.00 F ?
25	1		*FRT WHEEL HUB LH <i>new</i>	0.00	0.00	*150.00 F ?
26	1		*FRT WHEEL BEARING RH ?	0.00	0.00	*55.00 F ?
27	1		*FRT WHEEL BEARING LH <i>new</i>	0.00	0.00	*55.00 F ?
28	1		*FRT KNUCKLE ARM RH ?	0.00	0.00	*250.00 F ?
29	1		*FRT KNUCKLE ARM LH <i>new</i>	0.00	0.00	*250.00 F ✓
30	1		*FRT KNUCKLE LOWER BALL JOINT RH ?	0.00	0.00	*50.00 F ?
31	1		*FRT KNUCKLE LOWER BALL JOINT LH <i>new</i>	0.00	0.00	*50.00 F ✓
32	1		*FRT SHOCK ABSORBER RH ?	0.00	0.00	*180.00 F ?
33	1		*FRT SHOCK ABSORBER LH <i>Bent</i>	0.00	0.00	*180.00 F ✓
34	1		*FRT SHOCK ABSORBER FORK RH ?	0.00	0.00	*100.00 F ?
35	1		*FRT SHOCK ABSORBER FORK LH <i>Bent</i>	0.00	0.00	*100.00 F ✓
36	1		*FRT UPPER ARM RH ?	0.00	0.00	*120.00 F ?
37	1		*FRT UPPER ARM LH <i>Bent</i>	0.00	0.00	*120.00 F ✓
38	1		*FRT LOWER ARM RH ?	0.00	0.00	*230.00 F ?
39	1		*FRT LOWER ARM LH ?	0.00	0.00	*230.00 F ?
40	1		*FRT STABILISER BAR ?	0.00	0.00	*250.00 F ?
41	1		*FRT STABILIZER LINK RH ?	0.00	0.00	*70.00 F ✓
42	1		*FRT STABILIZER LINK LH <i>new</i>	0.00	0.00	*70.00 F ✓
43	1		*FRT DRIVE SHAFT RH ? <i>new</i>	0.00	0.00	*1,060.00 F ✓
44	1		*FRT DRIVE SHAFT LH <i>new</i>	0.00	0.00	*1,060.00 F ✓
45	1		*FRT SUBFRAME ASSY <i>Bent</i>	0.00	0.00	*980.00 F ✓

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*P/STERRING RACK ASSY	0.00	0.00	*2,800.00 F?
47	1		*P/STEERING TIE ROD RH	0.00	0.00	*75.00 F?
48	1		*P/STEERING TIE ROD LH	0.00	0.00	*75.00 F?
49	1		*P/STEERING TIE ROD END RH	0.00	0.00	*75.00 F?
50	1		*P/STEERING TIE ROD END LH	0.00	0.00	*75.00 F?
51	1		*RR WHEEL HUB C/W BEARING RH	0.00	0.00	*220.00 F?
52	1		*RR WHEEL HUB C/W BEARING LH	0.00	0.00	*220.00 F?
53	1		*RR KNUCKLE ARM RH	0.00	0.00	*420.00 F?
54	1		*RR KNUCKLE ARM LH	0.00	0.00	*420.00 F?
55	1		*RR TRAILING ARM RH	0.00	0.00	*95.00 F?
56	1		*RR TRAILING ARM LH	0.00	0.00	*95.00 F?
57	1		*RR LOWER ARM RH	0.00	0.00	*105.00 F?
58	1		*RR LOWER ARM LH	0.00	0.00	*105.00 F?
59	1		*RR UPPER ARM RH	0.00	0.00	*130.00 F?
60	1		*RR UPPER ARM LH	0.00	0.00	*130.00 F?
61	1		*RR LEADING ARM RH	0.00	0.00	*78.00 F?
62	1		*RR LEADING ARM LH	0.00	0.00	*78.00 F?
63	1		*RR CONTROL ARM RH	0.00	0.00	*85.00 F?
64	1		*RR CONTROL ARM LH	0.00	0.00	*85.00 F?
65	1		*RR STABILIZER BAR	0.00	0.00	*180.00 F?
66	1		*RR STABILIZER LINK RH	0.00	0.00	*68.00 F?
67	1		*RR STABILIZER LINK LH	0.00	0.00	*68.00 F?
68	1		*FRT WHEELHOUSE RH (REPAIR)	0.00	0.00	-
69	1		*FRT CHASSIS MEMBER RH (REPAIR)	0.00	0.00	-
70	1		*FRT WINDSCREEN PILLAR LH (REPAIR)	0.00	0.00	-
71	1		*FRT DOOR LH (REPAIR)	0.00	0.00	-
72	1		*FLOOR PANEL (REPAIR)	0.00	0.00	-
73	1		*ALLOY RIM (SET)	0	0.00	*1,600.00 FS
74	1		*TIRE (SET)	0	0.00	*1,200.00 FS
75	1		*BRAKE FLUID	0	0.00	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	20,213.00
+ Margin on L,N Items 10.00% (S\$)	1,737.30
Total Parts (S\$)	21,950.30

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING	New	120.00 ✓
2	TO REMOVE, CHECK AND REPLACE REAR UNDERCARRIAGE PARTS	New	400.00 ?
3	TO REMOVE, CHECK AND REPLACE FRONT UNDERCARRIAGE PARTS	New	500.00 ✓
4	TO CONDUCT WHEEL ALIGNMENT (X2)	New	120.00 ✓
5	TO REMOVE AND REINSTALL A/C CONDENSER FOR NECESSARY	New	120.00 ?
6	TO REMOVE AND REINSTALL RADIATOR ASSY FOR NECESSARY	New	100.00 ?
7	TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00 ⁸⁰⁰
8	TO SPRAY PAINT ON AFFECTED AREA	New	1,000.00 ⁹⁰⁰
9	TO CHECK ELECTRICAL SYSTEM AND FOCUS LAMP	New	50.00 ³⁰
Gross Labour Cost (S\$)			3,410.00

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Lj
H/s 06/10/19.

Not Authorised

Excurs : To be advised

10 Days.

96893735.

Verve Motorclinic Pte Ltd (Co.Reg.No:201800568H)

No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB

Singapore 417800

Tel: 67022990 Email: jaronranz92@gmail.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC19A00139500	Date of Loss:	31/10/2019
Vehicle Reg. No.:	SLD5914S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN JUN JIE EDDIE		
Driver:	TAN JUN JIE EDDIE		

Make/Model:	HONDA ACCORD, 2.0 (A)	Vehicle Reg. Date:	19/09/2007
Vehicle Colour:	WHITE		
Engine No:	K20A6052416	Chassis No:	CL73302098
Odometer:	184121 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location:	VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)
-------------------	--

COST OF CLAIMS	Amount
Parts	21,950.30
Miscellaneous Items	0.00
Labour	3,410.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	25,360.30

This claim is handled by: THAM WEI CHUEN KENNETH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Nov 2019)

Parts: 143 HONDA ACCORD 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>Distorted</i>	0.00	0.00	✓580.00 F ✓
2	1		*BONNET HINGE RH <i>new</i>	0.00	0.00	X*50.00 F +
3	1		*BONNET HINGE LH <i>new</i>	0.00	0.00	X*50.00 F +
4	1		*FRT GRILLE BASE <i>new</i>	0.00	0.00	X*215.00 F +
5	1		*FRT GRILLE CHROME (CENTRE) <i>new</i>	0.00	0.00	X*150.00 F +
6	1		*FRT GRILLE CHROME (TOP)	0.00	0.00	X*65.00 F +
7	1		*FRT GRILLE CHROME (BOTTOM)	0.00	0.00	X*65.00 F +
8	1		*FRT BUMPER <i>Distorted</i>	0.00	0.00	1,050.00 F ✓
9	8		*FRT BUMPER CLIPS <i>new</i>	0.00	0.00	✓64.00 F ✓
10	1		*FRT BUMPER LOWER SPOILER <i>new</i>	0.00	0.00	X*1,100.00 F +
11	1		*FRT BUMPER RETAINER RH <i>new</i>	0.00	0.00	✓20.00 F ✓
12	1		*FRT BUMPER RETAINER LH <i>new</i>	0.00	0.00	X*20.00 F +
13	1		*FRT BUMPER BEAM RH <i>Bent</i>	0.00	0.00	✓35.00 F ✓
14	1		*FRT BUMPER REINFORCEMENT <i>new</i>	0.00	0.00	X*220.00 F +
15	1		*WASHER TANK <i>Distorted</i>	0.00	0.00	✓65.00 F ✓
16	1		*WASHER TANK MOTOR <i>new</i>	0.00	0.00	X*36.00 F +
17	1		*FRT SUPPORT PANEL <i>new</i>	0.00	0.00	X*420.00 F +
18	1		*FRT FENDER RH <i>Distorted</i>	0.00	0.00	✓420.00 F ✓
19	1		*FRT FENDER LH <i>Distorted</i>	0.00	0.00	✓420.00 F ✓
20	12		*FRT FENDER CLIPS <i>new</i>	0.00	0.00	✓36.00 F ✓
21	1		*FRT FENDER COWLING RH <i>new</i>	0.00	0.00	✓100.00 F ✓
22	1		*FRT FENDER COWLING LH <i>new</i>	0.00	0.00	✓100.00 F ✓
23	1		*SIDE SKIRT LH <i>new</i>	0.00	0.00	✓650.00 F ✓
24	1		*FRT WHEEL HUB RH <i>new</i>	0.00	0.00	✓150.00 F ✓
25	1		*FRT WHEEL HUB LH <i>new</i>	0.00	0.00	✓150.00 F ✓
26	1		*FRT WHEEL BEARING RH <i>new</i>	0.00	0.00	✓55.00 F ✓
27	1		*FRT WHEEL BEARING LH <i>new</i>	0.00	0.00	✓55.00 F ✓
28	1		*FRT KNUCKLE ARM RH <i>new</i>	0.00	0.00	✓250.00 F ✓
29	1		*FRT KNUCKLE ARM LH <i>new</i>	0.00	0.00	✓250.00 F ✓
30	1		*FRT KNUCKLE LOWER BALL JOINT RH <i>new</i>	0.00	0.00	X*50.00 F +
31	1		*FRT KNUCKLE LOWER BALL JOINT LH <i>new</i>	0.00	0.00	✓50.00 F ✓
32	1		*FRT SHOCK ABSORBER RH <i>Bent</i>	0.00	0.00	✓180.00 F ✓
33	1		*FRT SHOCK ABSORBER LH <i>Bent</i>	0.00	0.00	✓180.00 F ✓
34	1		*FRT SHOCK ABSORBER FORK RH <i>Bent</i>	0.00	0.00	✓100.00 F ✓
35	1		*FRT SHOCK ABSORBER FORK LH <i>Bent</i>	0.00	0.00	✓100.00 F ✓
36	1		*FRT UPPER ARM RH <i>new</i>	0.00	0.00	X*120.00 F +
37	1		*FRT UPPER ARM LH <i>new</i>	0.00	0.00	X*120.00 F +
38	1		*FRT LOWER ARM RH <i>Bent</i>	0.00	0.00	✓230.00 F ✓
39	1		*FRT LOWER ARM LH <i>Bent</i>	0.00	0.00	✓230.00 F ✓
40	1		*FRT STABILISER BAR <i>new</i>	0.00	0.00	X*250.00 F +
41	1		*FRT STABILIZER LINK RH <i>new</i>	0.00	0.00	X*70.00 F +
42	1		*FRT STABILIZER LINK LH <i>new</i>	0.00	0.00	✓70.00 F ✓
43	1		*FRT DRIVE SHAFT RH <i>new</i>	0.00	0.00	X*1,060.00 F +
44	1		*FRT DRIVE SHAFT LH <i>new</i>	0.00	0.00	✓1,060.00 F ✓
45	1		*FRT SUBFRAME ASSY <i>Bent</i>	0.00	0.00	✓980.00 F ✓

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*P/STERRING RACK ASSY	0.00	0.00	X *2,800.00 F
47	1		*P/STEERING TIE ROD RH	0.00	0.00	X *75.00 F
48	1		*P/STEERING TIE ROD LH	0.00	0.00	X *75.00 F
49	1		*P/STEERING TIE ROD END RH	0.00	0.00	X *75.00 F
50	1		*P/STEERING TIE ROD END LH	0.00	0.00	X *75.00 F
51	1		*RR WHEEL HUB C/W BEARING RH	0.00	0.00	X *220.00 F
52	1		*RR WHEEL HUB C/W BEARING LH	0.00	0.00	X *220.00 F
53	1		*RR KNUCKLE ARM RH	0.00	0.00	X *420.00 F
54	1		*RR KNUCKLE ARM LH	0.00	0.00	X *420.00 F
55	1		*RR TRAILING ARM RH	0.00	0.00	X *95.00 F
56	1		*RR TRAILING ARM LH	0.00	0.00	X *95.00 F
57	1		*RR LOWER ARM RH	0.00	0.00	X *105.00 F
58	1		*RR LOWER ARM LH	0.00	0.00	X *105.00 F
59	1		*RR UPPER ARM RH	0.00	0.00	X *130.00 F
60	1		*RR UPPER ARM LH	0.00	0.00	X *130.00 F
61	1		*RR LEADING ARM RH	0.00	0.00	X *78.00 F
62	1		*RR LEADING ARM LH	0.00	0.00	X *78.00 F
63	1		*RR CONTROL ARM RH	0.00	0.00	X *85.00 F
64	1		*RR CONTROL ARM LH	0.00	0.00	X *85.00 F
65	1		*RR STABILIZER BAR	0.00	0.00	X *180.00 F
66	1		*RR STABILIZER LINK RH	0.00	0.00	X *68.00 F
67	1		*RR STABILIZER LINK LH	0.00	0.00	X *68.00 F
68	1		*FRT WHEELHOUSE RH (REPAIR)	0.00	0.00	-
69	1		*FRT CHASSIS MEMBER RH (REPAIR)	0.00	0.00	-
70	1		*FRT WINDSCREEN PILLAR LH (REPAIR)	0.00	0.00	-
71	1		*FRT DOOR LH (REPAIR)	0.00	0.00	-
72	1		*FLOOR PANEL (REPAIR)	0.00	0.00	-
73	1		*ALLOY RIM (SET) Front LH	0	0.00	1,600.00 FS
74	1		*TIRE (SET) Rear LH	0	0.00	X *1,200.00 FS
75	1		*BRAKE FLUID	0	0.00	/ *40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	20,213.00
+ Margin on L,N Items 10.00% (\$\$)	1,737.30
Total Parts (\$\$)	21,950.30

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING	New	120.00 ✓
2	TO REMOVE, CHECK AND REPLACE REAR UNDERCARRIAGE PARTS	New	X 400.00 ✓
3	TO REMOVE, CHECK AND REPLACE FRONT UNDERCARRIAGE PARTS	New	500.00 ✓
4	TO CONDUCT WHEEL ALIGNMENT (X2)	New	120.00 ✓
5	TO REMOVE AND REINSTALL A/C CONDENSER FOR NECESSARY	New	X 120.00 ✓
6	TO REMOVE AND REINSTALL RADIATOR ASSY FOR NECESSARY	New	X 100.00 ✓
7	TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00 <i>800</i>
8	TO SPRAY PAINT ON AFFECTED AREA	New	1,000.00 <i>200</i>
9	TO CHECK ELECTRICAL SYSTEM AND FOCUS LAMP	New	50.00 <i>30</i>
Gross Labour Cost (S\$)			3,410.00

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/s 06/11/19.

Not Authorised

Excess : To be advised

10 Days.
96893735.

Verve Motorclinic Pte Ltd (Co.Reg.No:201800558H)

No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB

Singapore 417800

Tel: 67022990 Email: jaronranz92@gmail.com

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC19A00139500	Date of Loss:	31/10/2019
Vehicle Reg. No.:	SLD5914S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN JUN JIE EDDIE		
Driver:	TAN JUN JIE EDDIE		

Make/Model:	HONDA ACCORD, 2.0 (A)	Vehicle Reg. Date:	19/09/2007
Vehicle Colour:	WHITE		
Engine No:	K20A6052416	Chassis No:	CL73302098
Odometer:	184121 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location:	VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)
-------------------	--

COST OF CLAIMS	Amount
Parts	21,950.30
Miscellaneous Items	0.00
Labour	3,410.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	25,360.30

This claim is handled by: THAM WEI CHUEN KENNETH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 05 Nov 2019)
Parts:	143	HONDA ACCORD 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>Distorted</i>	0.00	0.00	*580.00 F ✓
2	1		*BONNET HINGE RH <i>new</i>	0.00	0.00	*50.00 F ✓
3	1		*BONNET HINGE LH <i>new</i>	0.00	0.00	*50.00 F ✓
4	1		*FRT GRILLE BASE <i>new</i>	0.00	0.00	*215.00 F ✓
5	1		*FRT GRILLE CHROME (CENTRE) <i>new</i>	0.00	0.00	*150.00 F ✓
6	1		*FRT GRILLE CHROME (TOP)	0.00	0.00	*85.00 F ✓
7	1		*FRT GRILLE CHROME (BOTTOM)	0.00	0.00	*65.00 F ✓
8	1		*FRT BUMPER <i>Distorted</i>	0.00	0.00	*1,050.00 F ✓
9	8		*FRT BUMPER CLIPS <i>new</i>	0.00	0.00	*64.00 F ✓
10	1		*FRT BUMPER LOWER SPOILER <i>new</i>	0.00	0.00	*1,100.00 F ✓
11	1		*FRT BUMPER RETAINER RH <i>new</i>	0.00	0.00	*20.00 F ✓
12	1		*FRT BUMPER RETAINER LH <i>new</i>	0.00	0.00	*20.00 F ✓
13	1		*FRT BUMPER BEAM RH <i>new</i>	0.00	0.00	*35.00 F ✓
14	1		*FRT BUMPER REINFORCEMENT <i>new</i>	0.00	0.00	*220.00 F ✓
15	1		*WASHER TANK <i>new</i>	0.00	0.00	*65.00 F ✓
16	1		*WASHER TANK MOTOR <i>new</i>	0.00	0.00	*30.00 F ✓
17	1		*FRT SUPPORT PANEL <i>new</i>	0.00	0.00	*420.00 F ✓
18	1		*FRT FENDER RH <i>Distorted</i>	0.00	0.00	*420.00 F ✓
19	1		*FRT FENDER LH <i>Distorted</i>	0.00	0.00	*420.00 F ✓
20	12		*FRT FENDER CLIPS <i>new</i>	0.00	0.00	*36.00 F ✓
21	1		*FRT FENDER COWLING RH <i>new</i>	0.00	0.00	*100.00 F ✓
22	1		*FRT FENDER COWLING LH <i>new</i>	0.00	0.00	*100.00 F ✓
23	1		*SIDE SKIRT LH <i>new</i>	0.00	0.00	*650.00 F ✓
24	1		*FRT WHEEL HUB RH <i>new</i>	0.00	0.00	*150.00 F ✓
25	1		*FRT WHEEL HUB LH <i>new</i>	0.00	0.00	*150.00 F ✓
26	1		*FRT WHEEL BEARING RH <i>new</i>	0.00	0.00	*55.00 F ✓
27	1		*FRT WHEEL BEARING LH <i>new</i>	0.00	0.00	*55.00 F ✓
28	1		*FRT KNUCKLE ARM RH <i>new</i>	0.00	0.00	*250.00 F ✓
29	1		*FRT KNUCKLE ARM LH <i>new</i>	0.00	0.00	*250.00 F ✓
30	1		*FRT KNUCKLE LOWER BALL JOINT RH <i>new</i>	0.00	0.00	*50.00 F ✓
31	1		*FRT KNUCKLE LOWER BALL JOINT LH <i>new</i>	0.00	0.00	*50.00 F ✓
32	1		*FRT SHOCK ABSORBER RH <i>new</i>	0.00	0.00	*180.00 F ✓
33	1		*FRT SHOCK ABSORBER LH <i>new</i>	0.00	0.00	*180.00 F ✓
34	1		*FRT SHOCK ABSORBER FORK RH <i>new</i>	0.00	0.00	*100.00 F ✓
35	1		*FRT SHOCK ABSORBER FORK LH <i>new</i>	0.00	0.00	*100.00 F ✓
36	1		*FRT UPPER ARM RH <i>new</i>	0.00	0.00	*120.00 F ✓
37	1		*FRT UPPER ARM LH <i>new</i>	0.00	0.00	*120.00 F ✓
38	1		*FRT LOWER ARM RH <i>new</i>	0.00	0.00	*230.00 F ✓
39	1		*FRT LOWER ARM LH <i>new</i>	0.00	0.00	*230.00 F ✓
40	1		*FRT STABILISER BAR <i>new</i>	0.00	0.00	*250.00 F ✓
41	1		*FRT STABILIZER LINK RH <i>new</i>	0.00	0.00	*70.00 F ✓
42	1		*FRT STABILIZER LINK LH <i>new</i>	0.00	0.00	*70.00 F ✓
43	1		*FRT DRIVE SHAFT RH <i>new</i>	0.00	0.00	*1,060.00 F ✓
44	1		*FRT DRIVE SHAFT LH <i>new</i>	0.00	0.00	*1,060.00 F ✓
45	1		*FRT SUBFRAME ASSY <i>new</i>	0.00	0.00	*980.00 F ✓

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*P/STERRING RACK ASSY	0.00	0.00	*2,800.00 F
47	1		*P/STEERING TIE ROD RH	0.00	0.00	*75.00 F
48	1		*P/STEERING TIE ROD LH	0.00	0.00	*75.00 F
49	1		*P/STEERING TIE ROD END RH	0.00	0.00	*75.00 F
50	1		*P/STEERING TIE ROD END LH	0.00	0.00	*75.00 F
51	1		*RR WHEEL HUB C/W BEARING RH	0.00	0.00	*220.00 F
52	1		*RR WHEEL HUB C/W BEARING LH	0.00	0.00	*220.00 F
53	1		*RR KNUCKLE ARM RH	0.00	0.00	*420.00 F
54	1		*RR KNUCKLE ARM LH	0.00	0.00	*420.00 F
55	1		*RR TRAILING ARM RH	0.00	0.00	*95.00 F
56	1		*RR TRAILING ARM LH	0.00	0.00	*95.00 F
57	1		*RR LOWER ARM RH	0.00	0.00	*105.00 F
58	1		*RR LOWER ARM LH	0.00	0.00	*105.00 F
59	1		*RR UPPER ARM RH	0.00	0.00	*130.00 F
60	1		*RR UPPER ARM LH	0.00	0.00	*130.00 F
61	1		*RR LEADING ARM RH	0.00	0.00	*78.00 F
62	1		*RR LEADING ARM LH	0.00	0.00	*78.00 F
63	1		*RR CONTROL ARM RH	0.00	0.00	*85.00 F
64	1		*RR CONTROL ARM LH	0.00	0.00	*85.00 F
65	1		*RR STABILIZER BAR	0.00	0.00	*180.00 F
66	1		*RR STABILIZER LINK RH	0.00	0.00	*60.00 F
67	1		*RR STABILIZER LINK LH	0.00	0.00	*60.00 F
68	1		*FRT WHEELHOUSE RH (REPAIR)	0.00	0.00	-
69	1		*FRT CHASSIS MEMBER RH (REPAIR)	0.00	0.00	-
70	1		*FRT WINDSCREEN PILLAR LH (REPAIR)	0.00	0.00	-
71	1		*FRT DOOR LH (REPAIR)	0.00	0.00	-
72	1		*FLOOR PANEL (REPAIR)	0.00	0.00	-
73	1		*ALLOY RIM (SET) Front LH	0	0.00	*1,500.00 FS
74	1		*TIRE (SET)	0	0.00	*1,200.00 FS
75	1		*BRAKE FLUID	0	0.00	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 20,213.00
+ Margin on L,N Items 10.00% (\$\$) 1,737.30
Total Parts (\$\$) 21,950.30

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING	New	120.00 ✓
2	TO REMOVE, CHECK AND REPLACE REAR UNDERCARRIAGE PARTS	New	400.00 ✓
3	TO REMOVE, CHECK AND REPLACE FRONT UNDERCARRIAGE PARTS	New	500.00 ✓
4	TO CONDUCT WHEEL ALIGNMENT (X2)	New	120.00 ✓
5	TO REMOVE AND REINSTALL A/C CONDENSER FOR NECESSARY	New	120.00 ?
6	TO REMOVE AND REINSTALL RADIATOR ASSY FOR NECESSARY	New	100.00 ?
7	TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00 8W
8	TO SPRAY PAINT ON AFFECTED AREA	New	1,000.00 901
9	TO CHECK ELECTRICAL SYSTEM AND FOCUS LAMP	New	50.00 30
Gross Labour Cost (S\$)			3,410.00

Verve Motorclinic Pte Ltd/SLD5914S/05/11/2019 18:29. Not valid without reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parts = \$7010.00

Total = \$7711.00

20% = \$1542.20

Labour = \$2370.00

\$10,921.00

4% - 20% = \$8,736.80

\$8,500.00Adrian Lj
H/s 06/19/19.

Not Authorized

Excess: To be advised

10 Days.

96893735.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2019 17:47 Sendback Est	05 Nov 2019 18:29 \$25,360.30	06 Nov 2019 12:22 Edit Adj Rpt	\$48,500.00 Edit Estimates	\$48,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TAN JUN JIE EDDIE , ID: S8704674E, Email: VERVEMOTORCLNIC@GMAIL.COM									
Vehicle Reg. No.: SLD5914S		Date of Loss: 31/10/2019 00:00 - :59 [145 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DMPC1900276H/CT		Policy/Cover Note No.: MPC19A00139500 (Comprehensive) Excess: S\$0.00							
Repairer: Verve Motorclinic Pte Ltd (Kaki Bukit) No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB, 417800 Kaki Bukit - Tel: 67022990									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 15/11/2019]									
Driver/Customer: TAN JUN JIE EDDIE () , NRIC: S8704674E Email: VERVEMOTORCLNIC@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- ECICS (11/11/2019): Alert - Adj Mandate Approved (\$48500.00) - SLD5914S - Claim Handler: Crystabelle... - ECICS (08/11/2019): Alert - Adj Mandate Maintained - SLD5914S - Claim Handler: Crystabelle Tan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLD5914S (DMPC1900276H/CT)

OD

Oct 31 2019 12:00AM

[TAN JUN JIE EDDIE]

Verve Motorclinic Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Verve Motorclinic Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	05/11/19 18:29	Repairer Estimates	 Load HTM	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/19 15:24	Adjuster Immediate Advice	 Load HTM	☒
Photos/Images			3 per page	☒
No	Finalized On	Verve Motorclinic Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	21/11/19 15:56	Accident Photo	 Load JPG	☒
2	21/11/19 15:56	Accident Photo	 Load JPG	☒
3	21/11/19 15:56	Accident Photo	 Load JPG	☒
4	21/11/19 15:56	Accident Scene Photo	 Load JPG	☒
5	21/11/19 15:56	Accident Photo	 Load JPG	☒
6	21/11/19 15:56	Accident Photo	 Load JPG	☒
7	21/11/19 15:56	Accident Photo	 Load JPG	☒
8	21/11/19 15:56	Accident Photo	 Load JPG	☒
9	21/11/19 15:56	Accident Photo	 Load JPG	☒
10	21/11/19 15:56	Accident Photo	 Load JPG	☒
11	21/11/19 15:56	Accident Photo	 Load JPG	☒
12	21/11/19 15:56	Accident Photo	 Load JPG	☒
13	21/11/19 15:56	Accident Photo	 Load JPG	☒
14	21/11/19 15:56	Accident Photo	 Load JPG	☒
15	21/11/19 15:56	Accident Photo	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/19 17:18	General View	 Load JPG	☒
2	08/11/19 17:18	General View	 Load JPG	☒
3	08/11/19 17:18	General View	 Load JPG	☒
4	08/11/19 17:18	General View	 Load JPG	☒
5	08/11/19 17:18	General View	 Load JPG	☒
6	08/11/19 17:18	General View	 Load JPG	☒
7	08/11/19 17:18	General View	 Load JPG	☒
8	08/11/19 17:18	General View	 Load JPG	☒
9	08/11/19 17:18	General View	 Load JPG	☒
10	08/11/19 17:18	General View	 Load JPG	☒
11	08/11/19 17:18	General View	 Load JPG	☒
12	08/11/19 17:18	General View	 Load JPG	☒
13	08/11/19 17:18	General View	 Load JPG	☒
14	08/11/19 17:18	General View	 Load JPG	☒
15	08/11/19 17:18	General View	 Load JPG	☒
16	08/11/19 17:18	General View	 Load JPG	☒
17	08/11/19 17:18	General View	 Load JPG	☒
18	08/11/19 17:18	General View	 Load JPG	☒
19	08/11/19 17:18	General View	 Load JPG	☒
20	08/11/19 17:18	General View	 Load JPG	☒
21	08/11/19 17:18	General View	 Load JPG	☒
22	08/11/19 17:18	General View	 Load JPG	☒
23	08/11/19 17:18	General View	 Load JPG	☒
24	08/11/19 17:18	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Verve Motorclinic Pte Ltd (Kaki Bukit)	Thumbnail	Print
25	08/11/19 17:18	General View	 Load JPG	☒
26	08/11/19 17:18	General View	 Load JPG	☒
27	08/11/19 17:18	General View	 Load JPG	☒
28	08/11/19 17:18	General View	 Load JPG	☒
29	08/11/19 17:18	General View	 Load JPG	☒
30	08/11/19 17:18	General View	 Load JPG	☒
31	08/11/19 17:18	General View	 Load JPG	☒
32	08/11/19 17:18	General View	 Load JPG	☒
33	08/11/19 17:18	General View	 Load JPG	☒
34	08/11/19 17:18	General View	 Load JPG	☒
35	08/11/19 17:18	General View	 Load JPG	☒
36	08/11/19 17:18	General View	 Load JPG	☒
37	08/11/19 17:18	General View	 Load JPG	☒
38	08/11/19 17:18	General View	 Load JPG	☒
39	08/11/19 17:18	General View	 Load JPG	☒
40	08/11/19 17:19	General View	 Load JPG	☒
41	08/11/19 17:19	General View	 Load JPG	☒
42	08/11/19 17:19	General View	 Load JPG	☒
43	08/11/19 17:19	General View	 Load JPG	☒
44	08/11/19 17:19	General View	 Load JPG	☒
45	08/11/19 17:19	General View	 Load JPG	☒
46	08/11/19 17:19	General View	 Load JPG	☒
47	08/11/19 17:19	General View	 Load JPG	☒
48	08/11/19 17:19	General View	 Load JPG	☒
49	08/11/19 17:19	General View	 Load JPG	☒
50	08/11/19 17:19	General View	 Load JPG	☒
51	08/11/19 17:19	General View	 Load JPG	☒
52	08/11/19 17:19	General View	 Load JPG	☒
53	08/11/19 17:19	General View	 Load JPG	☒
54	08/11/19 17:19	General View	 Load JPG	☒
55	08/11/19 17:19	General View	 Load JPG	☒
56	08/11/19 17:19	General View	 Load JPG	☒
57	08/11/19 17:19	General View	 Load JPG	☒
58	08/11/19 17:19	General View	 Load JPG	☒
59	08/11/19 17:19	General View	 Load JPG	☒
60	08/11/19 17:19	General View	 Load JPG	☒
61	08/11/19 17:19	General View	 Load JPG	☒
62	08/11/19 17:19	General View	 Load JPG	☒
63	08/11/19 17:19	General View	 Load JPG	☒
64	08/11/19 17:19	General View	 Load JPG	☒
65	08/11/19 17:19	General View	 Load JPG	☒
66	08/11/19 17:19	General View	 Load JPG	☒
67	08/11/19 17:19	General View	 Load JPG	☒
68	08/11/19 17:19	General View	 Load JPG	☒
69	08/11/19 17:19	General View	 Load JPG	☒
70	08/11/19 17:19	General View	 Load JPG	☒
71	08/11/19 17:19	General View	 Load JPG	☒
72	08/11/19 17:19	General View	 Load JPG	☒
73	08/11/19 17:19	General View	 Load JPG	☒
74	08/11/19 17:19	General View	 Load JPG	☒
75	08/11/19 17:19	General View	 Load JPG	☒
76	08/11/19 17:19	General View	 Load JPG	☒
77	08/11/19 17:19	General View	 Load JPG	☒
78	08/11/19 17:19	General View	 Load JPG	☒
79	08/11/19 17:19	General View	 Load JPG	☒
80	28/11/19 15:41	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Verve Motorclinic Pte Ltd (Kaki Bukit)	Thumbnail	Print
81	28/11/19 15:41	Reinspection Photo		☒
82	28/11/19 15:41	Reinspection Photo		☒
83	28/11/19 15:41	Reinspection Photo		☒
84	28/11/19 15:41	Reinspection Photo		☒
85	28/11/19 15:41	Reinspection Photo		☒
86	28/11/19 15:41	Reinspection Photo		☒
87	28/11/19 15:41	Reinspection Photo		☒
88	28/11/19 15:41	Reinspection Photo		☒
89	28/11/19 15:41	Reinspection Photo		☒
90	28/11/19 15:41	Reinspection Photo		☒
91	28/11/19 15:41	Reinspection Photo		☒
92	28/11/19 15:41	Reinspection Photo		☒
93	28/11/19 15:41	Reinspection Photo		☒
94	28/11/19 15:41	Reinspection Photo		☒
95	28/11/19 15:41	Reinspection Photo		☒
96	28/11/19 15:41	Reinspection Photo		☒
97	28/11/19 15:41	Reinspection Photo		☒
98	28/11/19 15:41	Reinspection Photo		☒
99	28/11/19 15:41	Reinspection Photo		☒
100	28/11/19 15:41	Reinspection Photo		☒
101	28/11/19 15:41	Reinspection Photo		☒
102	28/11/19 15:41	Reinspection Photo		☒
103	28/11/19 15:41	Reinspection Photo		☒
104	28/11/19 15:41	Reinspection Photo		☒
105	28/11/19 15:41	Reinspection Photo		☒
106	28/11/19 15:41	Reinspection Photo		☒
107	28/11/19 15:41	Reinspection Photo		☒
108	28/11/19 15:41	Reinspection Photo		☒
109	28/11/19 15:41	Reinspection Photo		☒
110	28/11/19 15:41	Reinspection Photo		☒
111	28/11/19 15:41	Reinspection Photo		☒
112	28/11/19 15:41	Reinspection Photo		☒
113	28/11/19 15:41	Reinspection Photo		☒
114	28/11/19 15:41	Reinspection Photo		☒
115	28/11/19 15:41	Reinspection Photo		☒
116	28/11/19 15:41	Reinspection Photo		☒
117	28/11/19 15:41	Reinspection Photo		☒
118	28/11/19 15:41	Reinspection Photo		☒
119	28/11/19 15:42	Reinspection Photo		☒
120	28/11/19 15:42	Reinspection Photo		☒
121	28/11/19 15:42	Reinspection Photo		☒
122	28/11/19 15:42	Reinspection Photo		☒
123	28/11/19 15:42	Reinspection Photo		☒
124	28/11/19 15:42	Reinspection Photo		☒
125	28/11/19 15:42	Reinspection Photo		☒
126	28/11/19 15:42	Reinspection Photo		☒
127	28/11/19 15:42	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	Verve Motorclinic Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	01/11/19 17:50	Police Report		☐
2	21/11/19 15:57	Driver's Driving License		☐
3	21/11/19 15:57	E-filed GIA report		☐
4	21/11/19 16:05	Signed DV		☐
No	Finalized On	ECICS Limited (HQ)	Thumbnail	Print
1	06/11/19 10:42	SAS		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS19019605/AYF3E2

Date: 10/12/2019

REFERENCE

Insured/Claimant: TAN JUN JIE EDDIE Policy No: MPC19A00139500
Date of Loss: 31/10/2019 Nature of Claim: OD Claim No: DMPC1900276H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD5914S**
Make & Model: HONDA ACCORD, 2.0 (A) Engine No: K20A6052416
Reg. Date: 19/09/2007 (Man. Year: 2007) Chassis No: CL73302098
Colour: White Odometer: 184121 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$23,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,950.30	8,551.00	13,399.30	61.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	2,370.00	1,040.00	30.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,360.30	10,921.00	14,439.30	56.94
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	25,360.30	8,500.00	16,860.30	66.48

INSPECTION

Date of Assignment: 06/11/2019 Present Location: Verve Motorclinic Pte Ltd (Kaki Bukit)
Date Inspected: 06/11/2019 Inspected At: Verve Motorclinic Pte Ltd (Kaki Bukit)
No. 25 Kaki Bukit Road 4, #03-39
Synergy@KB
Singapore 417800

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2019)
Parts:	143	HONDA ACCORD 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD5914S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Distorted	580.00 F	*580.00 F
2	1		*BONNET HINGE RH (WCP)	Not Necessary	50.00 F	*- F
3	1		*BONNET HINGE LH (WCP)	Not Necessary	50.00 F	*- F
4	1		*FRT GRILLE BASE (WCP)	Not Necessary	215.00 F	*- F
5	1		*FRT GRILLE CHROME (CENTRE) (WCP)	Not Necessary	150.00 F	*- F
6	1		*FRT GRILLE CHROME (TOP) (WCP)	Not Necessary	65.00 F	*- F
7	1		*FRT GRILLE CHROME (BOTTOM) (WCP)	Not Necessary	65.00 F	*- F
8	1		*FRT BUMPER (WCP)	Distorted	1,050.00 F	*680.00 F
9	8		*FRT BUMPER CLIPS (WCP)	Necessary	64.00 F	*64.00 F
10	1		*FRT BUMPER LOWER SPOILER (WCP)	Not Necessary	1,100.00 F	*- F
11	1		*FRT BUMPER RETAINER RH (WCP)	Damaged	20.00 F	*20.00 F
12	1		*FRT BUMPER RETAINER LH (WCP)	Not Necessary	20.00 F	*- F
13	1		*FRT BUMPER BEAM RH (WCP)	Bent	35.00 F	*35.00 F
14	1		*FRT BUMPER REINFORCEMENT (WCP)	Not Necessary	220.00 F	*- F
15	1		*WASHER TANK (WCP)	Deformed	65.00 F	*65.00 F
16	1		*WASHER TANK MOTOR (WCP)	Not Necessary	36.00 F	*- F
17	1		*FRT SUPPORT PANEL (WCP)	Repair	420.00 F	*- F
18	1		*FRT FENDER RH (WCP)	Distorted	420.00 F	*420.00 F
19	1		*FRT FENDER LH (WCP)	Dented	420.00 F	*420.00 F
20	12		*FRT FENDER CLIPS (WCP)	Necessary	36.00 F	*36.00 F
21	1		*FRT FENDER COWLING RH (WCP)	Torn	100.00 F	*100.00 F
22	1		*FRT FENDER COWLING LH (WCP)	Torn	100.00 F	*100.00 F
23	1		*SIDE SKIRT LH (WCP)	Cracked	650.00 F	*400.00 F
24	1		*FRT WHEEL HUB RH (WCP)	Damaged	150.00 F	*150.00 F
25	1		*FRT WHEEL HUB LH (WCP)	Damaged	150.00 F	*150.00 F
26	1			Necessary	55.00 F	*55.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRT WHEEL BEARING RH (WCP)			
27	1		*FRT WHEEL BEARING LH (WCP)	Damaged	55.00 F	*55.00 F
28	1		*FRT KNUCKLE ARM RH (WCP)	Damaged	250.00 F	*250.00 F
29	1		*FRT KNUCKLE ARM LH (WCP)	Bent	250.00 F	*250.00 F
30	1		*FRT KNUCKLE LOWER BALL JOINT RH (WCP)	Not Necessary	50.00 F	*- F
31	1		*FRT KNUCKLE LOWER BALL JOINT LH (WCP)	Damaged	50.00 F	*50.00 F
32	1		*FRT SHOCK ABSORBER RH (WCP)	Bent	180.00 F	*180.00 F
33	1		*FRT SHOCK ABSORBER LH (WCP)	Bent	180.00 F	*180.00 F
34	1		*FRT SHOCK ABSORBER FORK RH (WCP)	Bent	100.00 F	*100.00 F
35	1		*FRT SHOCK ABSORBER FORK LH (WCP)	Bent	100.00 F	*100.00 F
36	1		*FRT UPPER ARM RH (WCP)	Not Necessary	120.00 F	*- F
37	1		*FRT UPPER ARM LH (WCP)	Not Necessary	120.00 F	*- F
38	1		*FRT LOWER ARM RH (WCP)	Bent	230.00 F	*230.00 F
39	1		*FRT LOWER ARM LH (WCP)	Bent	230.00 F	*230.00 F
40	1		*FRT STABILISER BAR (WCP)	Not Necessary	250.00 F	*- F
41	1		*FRT STABILIZER LINK RH (WCP)	Not Necessary	70.00 F	*- F
42	1		*FRT STABILIZER LINK LH (WCP)	Damaged	70.00 F	*70.00 F
43	1		*FRT DRIVE SHAFT RH (WCP)	Not Necessary	1,060.00 F	*- F
44	1		*FRT DRIVE SHAFT LH (WCP)	Damaged	1,060.00 F	*1,060.00 F
45	1		*FRT SUBFRAME ASSY (WCP)	Bent	980.00 F	*980.00 F
46	1		*P/STERRING RACK ASSY (WCP)	Not Necessary	2,800.00 F	*- F
47	1		*P/STEERING TIE ROD RH (WCP)	Not Necessary	75.00 F	*- F
48	1		*P/STEERING TIE ROD LH (WCP)	Not Necessary	75.00 F	*- F
49	1		*P/STEERING TIE ROD END RH (WCP)	Not Necessary	75.00 F	*- F
50	1		*P/STEERING TIE ROD END LH (WCP)	Not Necessary	75.00 F	*- F
51	1		*RR WHEEL HUB C/W BEARING RH (WCP)	Not Necessary	220.00 F	*- F
52	1		*RR WHEEL HUB C/W BEARING LH (WCP)	Not Necessary	220.00 F	*- F
53	1		*RR KNUCKLE ARM RH (WCP)	Not Necessary	420.00 F	*- F
54	1		*RR KNUCKLE ARM LH (WCP)	Not Necessary	420.00 F	*- F
55	1		*RR TRAILING ARM RH (WCP)	Not Necessary	95.00 F	*- F
56	1		*RR TRAILING ARM LH (WCP)	Not Necessary	95.00 F	*- F
57	1		*RR LOWER ARM RH (WCP)	Not Necessary	105.00 F	*- F
58	1			Not Necessary	105.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*RR LOWER ARM LH (WCP)			
59	1		*RR UPPER ARM RH (WCP)	Not Necessary	130.00 F	*- F
60	1		*RR UPPER ARM LH (WCP)	Not Necessary	130.00 F	*- F
61	1		*RR LEADING ARM RH (WCP)	Not Necessary	78.00 F	*- F
62	1		*RR LEADING ARM LH (WCP)	Not Necessary	78.00 F	*- F
63	1		*RR CONTROL ARM RH (WCP)	Not Necessary	85.00 F	*- F
64	1		*RR CONTROL ARM LH (WCP)	Not Necessary	85.00 F	*- F
65	1		*RR STABILIZER BAR (WCP)	Not Necessary	180.00 F	*- F
66	1		*RR STABILIZER LINK RH (WCP)	Not Necessary	68.00 F	*- F
67	1		*RR STABILIZER LINK LH (WCP)	Not Necessary	68.00 F	*- F
68	1		*FRT WHEELHOUSE RH (REPAIR) (NPA)	Repair	-	-
69	1		*FRT CHASSIS MEMBER RH (REPAIR) (NPA)	Repair	-	-
70	1		*FRT WINDSCREEN PILLAR LH (REPAIR) (NPA)	Repair	-	-
71	1		*FRT DOOR LH (REPAIR) (NPA)	Repair	-	-
72	1		*FLOOR PANEL (REPAIR) (NPA)	Repair	-	-
73	1		*ALLOY RIM (SET)	Damaged (Front N/s & Rear N/s)	1,600.00 FS	*800.00 FS
74	1		*TIRE (SET)	Not Necessary	1,200.00 FS	*- FS
75	1		*BRAKE FLUID	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNetl.

Sub Total (S\$) **20,213.00** **7,850.00**
+ Margin on L,N Items 10.00/10.00% (S\$) **1,737.30** **701.00**

Total Parts (S\$) 21,950.30 8,551.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	120.00	120.00
2	TO REMOVE, CHECK AND REPLACE REAR UNDERCARRIAGE PARTS	New	400.00	0.00
3	TO REMOVE, CHECK AND REPLACE FRONT UNDERCARRIAGE PARTS	New	500.00	500.00
4	TO CONDUCT WHEEL ALIGNMENT (X2)	New	120.00	120.00
5	TO REMOVE AND REINSTALL A/C CONDENSER FOR NECESSARY	New	120.00	0.00
6	TO REMOVE AND REINSTALL RADIATOR ASSY FOR NECESSARY	New	100.00	0.00
7	TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	800.00
8	TO SPRAY PAINT ON AFFECTED AREA	New	1,000.00	800.00
9	TO CHECK ELECTRICAL SYSTEM AND FOCUS LAMP	New	50.00	30.00
Gross Labour Cost (S\$)			3,410.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >