

22/03/2002

ASS. REC. BY:

REF: CS/CTI 190196201 As f30p

Special Instruction:

SUNAJOR Adhan

ASSIGNMENT (Office)

From (Person): Chong Bunn Sen

of CTI

Date/Time: 6/11/19 8.39am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SLX 445G

Insured: GBD 7022x

at Workshop m/s Kah motor

Tel: 81006306

of 15 Ubi Road 4

Policy No: DMXVSN30211419000

Claim No: SNM 19D705218C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 6/11/19 9.47am

Person Contacted: Any chua

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 445G x
	GBD 7022x - CS3/LP(150B284/ H11611 - D.O.A - 24/10/2019

ASS. REC. BY

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: \_\_\_\_\_

Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Colour: \_\_\_\_\_

Sp. Reading: \_\_\_\_\_

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

mm

R/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

D.O.A. \_\_\_\_\_

D.O.I. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China.
	Adrian Confirmed P/P \$ 4,323.66 @ 4 day with Any.
	( \$ 17,234.69 Ltd - 80% )
	MV:
	PV:
	Nett.
RECEIVED 12 DEC 2019	

Date/Time, File Pass to?

12/12/19

☐

Preli. Report

1) Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week end (\$

Survey Fee:

Transportation:

S - PS - SI

Photos

Others

TOTAL

Report Format:

Lump Sum P/P: \$ 4,323.66 P/P

270

270

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Nov 2019		06 Nov 2019 10:59 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ERIC NG SZE KIANG (HUANG SIQIANG), ID: S1563168F		
Vehicle Reg. No.:	SLX445G	Date of Loss:	04/11/2019 14:00 - :59
Claim Type:	TP / SNM19D205218C02	Policy/Cover Note No.:	DMCVSN30211419000
Vehicle Reg. No. (Insured):	GBD7022X	Policy No. (Claimant):	10819042
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/11/2019]		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shirley Hiew (LKK Auto)

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Thursday, 12 December 2019 11:55 am  
**To:** Ary Chua; Adrian Ling (LKKAuto); Admin A; Admin-D (LKKAuto)  
**Cc:** Liew Thye Wui; Faeaz  
**Subject:** RE: Finalize TPDS-CT: SLX445G DOA: 04/11/2019@14.25PM

Dear Ary,

Finalize amount confirmed.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

*"Best Wishes for Merry Christmas & Happy New Year 2020"*

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ary Chua <arychua@honda.com.sg>  
**Sent:** Friday, 29 November 2019 10:48 am  
**To:** Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>  
**Subject:** Finalize TPDS-CT: SLX445G DOA: 04/11/2019@14.25PM

Dear Adrian Ling,  
Kindly Finalize TPDS-CT: SLX445G DOA: 04/11/2019@14.25PM

<b>Final Repair Costs (include GST)</b>	<b>\$4,323.66 + (\$302.66) = \$4,626.32</b>
<b>Repair Period* (Working Day)</b>	<b>04</b>

Please examine the above information carefully. If no discrepancy is reported within 7 days (\*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

**Ary Chua Wai Ngee**

**Kah Motor Co. SDN BHD** 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

**Veron Chen (LKKAuto)**

**From:** Ary Chua <arychua@honda.com.sg>  
**Sent:** Friday, 29 November 2019 10:48 AM  
**To:** Adrian Ling (LKKAuto); Admin A; Admin-D (LKKAuto)  
**Cc:** Liew Thye Wui; Faeaz  
**Subject:** Finalize TPDS-CT: SLX445G DOA: 04/11/2019@14.25PM  
**Attachments:** 2043\_001.pdf

Dear Adrian Ling,

Kindly Finalize TPDS-CT: SLX445G DOA: 04/11/2019@14.25PM

<b>Final Repair Costs (include GST)</b>	<b>\$4,323.66 + (\$302.66) = \$4,626.32</b>
<b>Repair Period* (Working Day)</b>	<b>04</b>

Please examine the above information carefully. If no discrepancy is reported within 7 days (\*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

**Ary Chua Wai Ngee**

**Kah Motor Co. SDN BHD** 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : [arychua@honda.com.sg](mailto:arychua@honda.com.sg)



**Confidential Note:** The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Wednesday, 6 November 2019 8:39 AM  
**To:** Ary Chua; Jeffrey Tay  
**Cc:** Liew Thye Wui; Faeaz; assignments  
**Subject:** RE: OUR REF: SNM19D205218-GBD7022X-CBS- TPDS-CT: SLX445G & GBD7022X  
DOA: 04/11/2019@14.25PM

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s lkk AUTO CONSULTANTS to survey your client's vehicle.

Aside to lkk AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Ary Chua [mailto:[arychua@honda.com.sg](mailto:arychua@honda.com.sg)]

**Sent:** Wednesday, November 6, 2019 8:21 AM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>;  
Claims Dept of CTI <claimsdept@sg.cntaiping.com>

**Cc:** Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

**Subject:** RE: OUR REF: SNM19D205218-GBD7022X-CBS- TPDS-CT: SLX445G & GBD7022X DOA:  
04/11/2019@14.25PM

Dear Chong BS,

We Choose LKK Auto Marcus Chua as our Car Surveyor.

Please Establish this Case Status Liability?

Thank you.

Best Regards,

Ary Chua Wai Ngee

**Kah Motor Co. SDN BHD** 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : [arychua@honda.com.sg](mailto:arychua@honda.com.sg)

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Sent:** Tuesday, 5 November 2019 6:17 PM

**To:** Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; Ary Chua <arychua@honda.com.sg>

**Subject:** RE: OUR REF: SNM19D205218-GBD7022X-CBS- TPDS-CT: SLX445G & GBD7022X DOA: 04/11/2019@14.25PM

Without prejudice

Dear Sir,

LKK

STA

LBS

**Chong Boon Sen**

Claims Executive

Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Claims Dept of CTI

**Sent:** Tuesday, November 5, 2019 5:17 PM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; Ary Chua <arychua@honda.com.sg>

**Subject:** OUR REF: SNM19D205218-GBD7022X-CBS- TPDS-CT: SLX445G & GBD7022X DOA: 04/11/2019@14.25PM

Dear Boon Sen,

Please conduct PRS for SLX445G.

Note : officer in charge – Boon Sen 63896171.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Ary Chua [<mailto:arychua@honda.com.sg>]

**Sent:** Tuesday, November 05, 2019 1:49 PM

**To:** Claims Dept of CTI

**Cc:** Liew Thye Wui; Faeaz

**Subject:** TPDS-CT: SLX445G & GBD7022X DOA: 04/11/2019@14.25PM

Dear OIC-China Taiping,

Kindly Establish this case Liability Status Before Arrange for Car Survey. Car Not In Ubi Bodyshop.

Our Client got Front Video Footage.

Thank you.


Best Regards,

Ary Chua Wai Ngee

**Kah Motor Co. SDN BHD** 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : [arychua@honda.com.sg](mailto:arychua@honda.com.sg)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/11/2019 12:56
Date Of Accident	04/11/2019 14:25
Exact Location Of Accident	LRG 21 GEYLANG (L/P 71)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX445G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ERIC NG SZE KIANG (HUANG SIQIANG)
NRIC No	S1563168F
Email Address	ERICNGSZEKIANG@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-96676133
Alternative Phone No	OFFICE-67479633

### Vehicle Particulars

Manufacturer	HONDA
Model	CR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10819042
Cover Note Number	

### Driver

Name of Driver	ERIC NG SZE KIANG (HUANG SIQIANG)
NRIC No	S1563168F
Date Of Birth	22/06/1962
Occupation	INDOOR
Date Of Driving Pass	11/04/1983
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96676133
Fax Number	
Contact Number	OFFICE-67479633
EMail Address	ERICNGSZEKIANG@OUTLOOK.COM

Address	BLK 544 PASIR RIS ST 51 #03-07
Postcode	S510544
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WIFE GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

NOBODY INJURY DURING THE ACCIDENT & REFER TO OWNER ATTACHMENT REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD7022X
Vehicle Make/Model/Colour	LORRY/SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


## Sketch Plan Pg. 1

Vehicle Number: SLX 445 G


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

11:11am  
05 NOV 2019  
  
Reporting Centre Personnel's Signature  
Name: **ARY CHUA**  
NRIC/FIN No.:

# Sketch Plan Pg. 2

Vehicle Number: SLX445G

## SKETCH PLAN



A = SLX445G  
B = GBD7022X

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 4th Nov 2019 at around 1425 hrs I was on the way back to my office at Lor 23 Geylang I was travelling along Lor 21 Geylang and at the junction into Sims Ave the front vehicle GBD7022X suddenly reversed towards my direction. I sounded my horn to alarm the driver but he did not hear the alarm and hit into the front of my vehicle and caused damage to the front. No body was injured in the incident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

*[Signature]* 5/11/2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

11:11am  
05 NOV 2019  
Reporting Centre Personnel's Signature  
Name: ARY CHUA  
NRIC/FIN No.:



POLICY NO.: 10819042

PERIOD OF INSURANCE  
(both dates inclusive)

FROM: 14-Mar-2018 00:00hours  
TO: 13-Mar-2020 23:59hours

AGENT'S DETAILS

CODE: 54000011  
NAME: XIU HUI OW-YEONG  
COMPANY NAME: Kah Motor Company Sdn Bhd

#### POLICYHOLDER

INSURED:  
FAMILY NAME Nig  
GIVEN NAME Sze Kiang

#### COVER

TYPE OF COVER: Comprehensive  
TYPE OF PLAN: Dual-Year Plan  
TYPE OF PROGRAM: Kah Motor Scheme  
OWN DAMAGE POLICY EXCESS \$1,000.00  
YOUNG AND/OR INEXPERIENCED DRIVER EXCESS: \$2,500.00  
(Aged 24 and below and/or has held a valid driving license for less than 1 year.)  
**note: in addition to Own Damage Policy Excess if applicable**  
WINDSCREEN EXCESS: \$100.00  
All excess subject to GST if applicable

#### USE INSURED AGAINST

Use for social, domestic and pleasure purposes and for use in connection with the policyholders own business. The policy does not cover use for (i) Hire and rewards, (ii) Racing, pace making, reliability trial or speed testing, (iii) Driving tuition, (iv) The carriage of goods for hire and reward, (v) Any purpose in connection with the motor trade.

#### PREMIUM CALCULATION

PREMIUM \$1,641.81  
GST @ 7.00% \$114.93  
TOTAL DUE \$1,756.74  
DATE ISSUED 16-Mar-2018 at 16:22hours

#### SPECIAL CLAUSE

#### CAR INSURED

MAKE & TYPE OF BODY: HONDA CR-V 1.5 1498cc  
REGISTRATION NO.: SLX445G  
CHASSIS NO.: MRHRW1880JP00061  
ENGINE NO.: L158G1115677  
SUM INSURED: Market Value inclusive of COE  
YEAR OF REGISTRATION: 2018  
OFF-PEAK CAR: No  
PERIOD OF OWNERSHIP OF CAR TO BE INSURED: 0 to <1 year  
MODIFICATIONS TO YOUR CAR: No  
WHICH DO NOT COMPLY WITH AND/OR ARE NOT APPROVED BY LTA:

#### ADDITIONAL COVERS

Free Loss of Keys\*  
Free Loss of Use\*  
Free NCD Protector\*  
Free Waiver of Excess\*

#### WHO MAY DRIVE YOUR CAR

Any driver

#### NO CLAIMS DISCOUNT

NCD%: 50

#### BREAKDOWN ASSISTANCE

If your car breakdown and you need assistance, please call our hotline at 6841 3838

#### POLICY OWNERS' PROTECTION SCHEME (PPF)

This policy is protected under the Policy Owners' Protection Scheme which is administered by the Singapore Deposit Insurance Corporation (SDIC). Coverage for your policy is automatic and no further action is required from you. For more information on the types of benefits that are covered under the scheme as well as the limits of coverage, where applicable, please contact us or visit the GIA or SDIC web-sites ([www.gia.org.sg](http://www.gia.org.sg) or [www.sdic.org.sg](http://www.sdic.org.sg)).

ORIGINAL

Aviva Ltd 4 Shenton Way #01-01 SGX Centre 2 Singapore 068807 • Tel: (65) 6827 9966 • Website: [www.aviva.com.sg](http://www.aviva.com.sg)  
Company Reg. No.: 196900499K GST Reg. No.: MR-8500166-8

&gt; Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 05 Nov 2019 / 11:17:30

Receipt Date/Time : 05 Nov 2019 / 11:17:30

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-191105-000950

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - GBD7022X As at 04 Nov 2019/14:25:25 Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD			
1	Insurance Enquiry - GBD7022X Enquiry Fee 20191105111540616767	7.00	0.49	7.49
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
	<b>Paid By</b>			
	xxxxxxxxxxxx7145 Credit Card: Visa/MasterCard			7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT19004823	Page	1
	3 ANSON ROAD #16-00	Date	: 5. Nov 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SLX445G	Engine No	: L15BG1115677		
Chassis No	: MRHRW1880JP000061	Date   Time	: 5. Nov 2019 11:56:03 AM		
Model	: CRV 1.5L TURBO YM2018 (7 SEATER)	Surveyor Name	:		
Owner's Name	: ERIC NG SZE KIANG	Survey Date	: DID : +65 6846 5673		
Ins Policy No.	: 10819042	Authorisation Date	: HP : +65 8100 6306		
Date of Accident	: 4/11/2019		: Email : arychua@honda.com.sg		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73737)						
	OWNER: ERIC NG SZE KIANG						
	OWNER INSURER: AVIVA LTD						
	ACC DATE: 04/11/2019@14.25PM						
	ACC: LRG 21 GEYLANG (L/P 71)						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE PTE LTD						
	TP VEH: GBD7022X - LORRY/SILVER						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>Red</i>	1	45.00		45.00	3.15	48.15
33100-TLA-T11	HEADLIGHT ASSY, R. <i>new</i>	1	1836.50	5	1744.67	122.13	1866.80
19043-5AA-E00	LABEL, COOLANT INFORMATION <i>new</i>	1	10.00	5	9.50	0.67	10.17
71123-TME-T00	MOLDING B, R. FR. GRILLE <i>curled</i>	1	52.90	5	50.25	3.52	53.77
71121-TME-T00	BASE, FR. GRILLE <i>curled</i>	1	154.00	5	146.30	10.24	156.54
71122-TME-T00	MOLDING, FR. GRILLE	1	105.40	5	100.13	7.01	107.14
75700-SZW-000	EMBLEM MARK <i>new</i>	1	29.50	5	28.02	1.96	29.98
90301-ST0-003	NUTPUSH 3MM <i>new</i>	2	2.10	5	3.99	0.28	4.27
71127-TLA-A00	STAY ASSY, FR. GRILLE <i>new damaged</i>	1	18.90	5	17.95	1.26	19.21
04711-TMC-U10ZZ	FACE ASSY,FR.BUMPER <i>Debond</i>	1	9999.99	5	9499.99	665.00	10164.99
71102-TME-T00	FACE, FR. BUMPER LOWER <i>new</i>	1	530.40	5	503.88	35.27	539.15
71145-TMC-U00	BASE, FR. LICENSE PLATE <i>hit</i>	1	95.50	5	90.72	6.35	97.07
71130-TME-T12	BEAM COMP,FR. BUMPER <i>new</i>	1	480.80	5	456.76	31.97	488.73
71140-TME-T01	BEAM,FR.BUMPER R.CORNER UPP <i>new</i>	1	35.80	5	34.01	2.38	36.39
71190-TME-T01	BEAM,FR.BUMPER L.CORNER UPP <i>new</i>	1	42.50	5	40.37	2.83	43.20
71193-TME-T01	SPACER, R. FR. BUMPER SIDE <i>new</i>	1	11.90	5	11.30	0.79	12.09
71198-TME-T01	SPACER, L. FR. BUMPER SIDE <i>new</i>	1	11.90	5	11.30	0.79	12.09
91505-TM8-003	CLIP,BUMPER <i>new</i>	14	2.30	5	30.59	2.14	32.73
04714-TME-305	BULKHEAD ASSY,FR. <i>Repair</i>	1	470.00	5	446.50	31.26	477.76

Printed on 5/11/2019 1:35:52 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
Registration No : SLX445G  
Chassis No : MRHRW1880JP000061  
Model : CRV 1.5L TURBO YM2018 (7 SEATER)  
Owner's Name : ERIC NG SZE KIANG  
Ins Policy No. : 10819042  
Date of Accident : 4/11/2019

Document No. : SQT19004823 Page 2  
Date : 5. Nov 2019  
Customer No. : WZC008  
Svc Advisor : ARY CHUA WAI NGEE  
Engine No : L15BG1115677  
Date | Time : 5. Nov 2019 11:56:03 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
80100-TMC-Q01	CONDENSER ASSY	1	857.50	5	814.62	57.02	871.64
19010-SPD-U01	RADIATOR COMP	1	1347.30	5	1279.93	89.60	1369.53
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	5	132.24	9.26	141.50
Sum Item					15498.02	1,084.88	16,582.90
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00		140.00	9.80	149.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BKBOR	REMOVE & RENEW BONNET & RENEW DAMAGE PARTS1	1	2500.00		2500.00	175.00	2675.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1800.00		1800.00	126.00	1926.00
Sum Labor					4940.00	345.80	5,285.80

Survey By : Adrian Ly  
Date & Time : 26/11/19.  
Excess :  
Status : Not Authorized  
Signature : [Signature]

Total Amount 20,438.02 1,430.68 21,868.70  
Total (Inclusive of GST) 21,868.70

21558.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 5/11/2019 1:35:52 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.





# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** CU0043894 / ERIC NG SZE  
**Chassis No:** MRHRW1880JP000061  
**License No:** SLX445G  
**Mileage:** 41124  
**Engine No:** L15BG1115677

**Document No:** SVO19075506  
**Printed By:** ARYCHUA  
**Order Date:** 26. November 2019  
**Order Time:** 11:56:03 AM  
**Service Advisor:** ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Incd Amount	GST
SUPPLIMENTARY ITERM PARTS & LABOR							
60100-TLC-A00ZZ	HOOD COMP, ENGINE <i>perked</i>	1	1,011.00	5	960.45	67.23	1,027.68 ✓
71121-TME-T00	BASE, FR. GRILLE <i>cracked</i>	1	168.30	5	159.88	11.19	171.07 ✓
SUM PARTS:					1,120.33	78.42	1,198.75
TOTAL SGD					1,120.33	78.42	1,198.75

**Total Payable (SGD) 1,198.75**

GST Amount is calculated from individual line(s)

*Supp*



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer: CU0043894 / CHINA TAIPING  
Chassis No: MRHRW1880JP000061  
License No: SLX445G  
Mileage: 41124  
Engine No: L15BG1115677

Document No: SVO19075506  
Printed By: ARYCHUA  
Order Date: 26. November 2019  
Order Time: 11:56:03 AM  
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 73737) OWNER: ERIC NG SZE KIANG OWNER INSURER: AVIVA LTD ACC DATE: 04/11/2019@14.25PM ACC: LRG 21 GEYLANG (L/P 71) SURVEYED BY: ARIAN LING(LKKAUTO)26/11/2019@11.11AM REF NO: SNM19D205218-GBD7022X-CBS-TPDS-CT TP INSURER: CHINA TAIPING INSURANCE PTE LTD TP VEH: GBD7022X - LORRY/SILVER						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
19043-5AA-E00	LABEL, COOLANT INFORMATION	1	10.00	5	9.50	0.67	10.17
71123-TME-T00	MOLDING B, R. FR. GRILLE	1	52.90	5	50.25	3.52	53.77
71121-TME-T00	BASE, FR. GRILLE	1	154.00	5	146.30	10.24	156.54
71122-TME-T00	MOLDING, FR. GRILLE	1	105.40	5	100.13	7.01	107.14
75700-SZW-000	EMBLEM MARK	1	29.50	5	28.02	1.96	29.98
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27
71127-TLA-A00	STAY ASSY, FR. GRILLE	1	18.90	5	17.95	1.26	19.21
71100-TMC-U10ZZ	FACE ASSY, FR. BUMPER	1	548.30	5	520.88	36.46	557.34
71145-TMC-U00	BASE, FR. LICENSE PLATE	1	95.50	5	90.72	6.35	97.07
91505-TM8-003	CLIP, BUMPER	14	2.30	5	30.59	2.14	32.73
60100-TLC-A00ZZ	HOOD COMP, ENGINE	1	1,011.00	5	960.45	67.23	1,027.68
71121-TME-T00	BASE, FR. GRILLE	1	168.30	5	159.88	11.19	171.07
	<b>SUM PARTS:</b>				<b>2,163.66</b>	<b>151.46</b>	<b>2,315.12</b>
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML01I	0760 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	120.00		120.00	8.40	128.40
BKBOR	1863 REMOVE & RENEW BONNET & RENEW DAMAGE PARTS ON ATTACHEMNT ITEMS	1	1,120.00		1,120.00	78.40	1,198.40
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	900.00		900.00	63.00	963.00
	<b>SUM LABOUR:</b>				<b>2,160.00</b>	<b>151.20</b>	<b>2,311.20</b>
	<b>TOTAL SGD</b>				<b>4,323.66</b>	<b>302.66</b>	<b>4,626.32</b>

Total Payable (SGD)

**4,626.32**

GST Amount is calculated from individual line(s)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Nov 2019		06 Nov 2019 10:59 <a href="#">Edit Adj Rpt</a>	<b>S\$4,323.66</b> <a href="#">Edit Estimates</a>	<b>S\$4,323.66</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>ERIC NG SZE KIANG (HUANG SIQIANG)</b> , ID: S1563168F								
Vehicle Reg. No.:	<b>SLX445G</b>	Date of Loss:	04/11/2019 14:00 - :59 [19 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D205218C02</b>	Policy/Cover Note No.:	DMCVSN30211419000						
Vehicle Reg. No. (Insured):	<b>GBD7022X</b>	Policy No. (Claimant):	10819042						
		Excess:	S\$0.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (Ubi)</b> 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>Aviva Ltd (HQ)</b> - Tel: (65) 6827 9966								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 15/11/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLX445G (SNM19D205218C02)  
[GBD7022X]  
TP  
ERIC NG SZE KIANG (HUANG SIQIANG)  
Nov 4 2019 2:00PM  
[-]  
Kah Motor Co Sdn Bhd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	05/11/19 13:09	<b>Video - Accident</b> [Linked Accident Report Documents]		Load MP4	

Assessment Reports

1 per page

























No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	05/11/19 13:10	<b>Accident Statement</b>		Load HTM	

Photos/Images
















3 per page

No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
2	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
3	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
4	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
5	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
6	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
7	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
8	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
9	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
10	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
11	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	
12	05/11/19 13:09	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/12/19 15:08	<b>General View</b>		Load JPG	
2	06/12/19 15:08	<b>General View</b>		Load JPG	
3	06/12/19 15:08	<b>General View</b>		Load JPG	
4	06/12/19 15:08	<b>General View</b>		Load JPG	
5	06/12/19 15:08	<b>General View</b>		Load JPG	
6	06/12/19 15:08	<b>General View</b>		Load JPG	
7	06/12/19 15:08	<b>General View</b>		Load JPG	
8	06/12/19 15:08	<b>General View</b>		Load JPG	
9	06/12/19 15:08	<b>General View</b>		Load JPG	
10	06/12/19 15:08	<b>General View</b>		Load JPG	
11	06/12/19 15:08	<b>General View</b>		Load JPG	
12	06/12/19 15:08	<b>General View</b>		Load JPG	
13	06/12/19 15:08	<b>General View</b>		Load JPG	
14	06/12/19 15:08	<b>General View</b>		Load JPG	
15	06/12/19 15:08	<b>General View</b>		Load JPG	
16	06/12/19 15:08	<b>General View</b>		Load JPG	
17	06/12/19 15:08	<b>General View</b>		Load JPG	
18	06/12/19 15:08	<b>General View</b>		Load JPG	
19	06/12/19 15:08	<b>General View</b>		Load JPG	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
20	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	06/12/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/11/19 13:09	Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/19 14:10	Supplementary	 Load PDF	

## Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/11/19 13:09	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/11/19 13:10	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	05/11/19 13:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/11/19 13:09	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019620/ASF3E2

Date: 18/12/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30211419000

Claimant  
Vehicle No : SLX445GInsured  
Vehicle No : GBD7022X

Date of Loss: 04/11/2019

Nature of Claim: TP

Claim  
No: SNM19D205218C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLX445G

Make &amp; Model: HONDA CR-V, 1.5 (A)

Engine No: L15BG1115677

Reg. Date: 14/03/2018 (Man. Year: 2018)

Chassis No: MRHRW1880JP000061

Colour: White

Odometer: 41123 km

Engine Capacity: 1498 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18  
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,668.35	2,183.66	14,484.69	86.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,890.00	2,140.00	2,750.00	56.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,558.35</b>	<b>4,323.66</b>	<b>17,234.69</b>	<b>79.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,509.08</b>	<b>302.66</b>	<b>1,206.42</b>	<b>79.94</b>
<b>Nett Amount (S\$)</b>	<b>23,067.43</b>	<b>4,626.32</b>	<b>18,441.11</b>	<b>79.94</b>

## INSPECTION

Date of Assignment: 06/11/2019

Date Inspected: 26/11/2019 Inspected At:

Kah Motor Co Sdn Bhd (Ubi)  
15 Ubi Road 4  
Singapore 408610

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 18 Dec 2019)	
<b>Parts:</b>	N/A	HONDA CR-V 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLX445G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH CASING - L	Deformed	45.00 FS	*45.00 FS
2	1		*HEADLIGHT ASSY,R.	Not Necessary	1,744.67 FS	*- FS
3	1		*LABEL, COOLANT INFORMATION	Necessary	9.50 FS	*9.50 FS
4	1		*MOLDING B,R.FR. GRILLE	Cracked	50.25 FS	*50.25 FS
5	1		*BASE, FR.GRILLE	Cracked	146.30 FS	*146.30 FS
6	1		*MOLDING,FR.GRILLE	Cracked	100.13 FS	*100.13 FS
7	1		*EMBLEMH MARK	Necessary	28.02 FS	*28.02 FS
8	1		*NUTPUSH 3MM (2PCS)	Necessary	3.99 FS	*3.99 FS
9	1		*STAY ASSY, FR.GRILLE	Damaged	17.95 FS	*17.95 FS
10	1		*FACE ASSY,FR.BUMPER	Deformed	9,499.99 FS	*520.88 FS
11	1		*FACE,FR.BUMPER LOWER	Not Necessary	503.88 FS	*- FS
12	1		*BASE,FR.LICENSE PLATE	Cut	90.72 FS	*90.72 FS
13	1		*BEAM COMP,FR.BUMPER	Not Necessary	456.76 FS	*- FS
14	1		*BEAM,FR.BUMPER R.CORNER UPP	Not Necessary	34.01 FS	*- FS
15	1		*BEAM,FR.BUMPER L.CORNER UPP	Not Necessary	40.37 FS	*- FS
16	1		*SPACER,R.FR.BUMPER SIDE	Not Necessary	11.30 FS	*- FS
17	1		*SPACER,L.FR.BUMPER SIDE	Not Necessary	11.30 FS	*- FS
18	1		*CLIP, BUMPER (14PCS)	Necessary	30.59 FS	*30.59 FS
19	1		*BULKHEAD ASSY, FR.	Repair	446.50 FS	*- FS
20	1		*CONDENSER ASSY	Not Necessary	814.62 FS	*- FS
21	1		*RADIATOR COMP	Not Necessary	1,279.93 FS	*- FS
22	6		*COOLANT ANTI-FREEZE TYPE 2	Not Necessary	132.24 F	*- F
23	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
24	1		*HOOD COMP, ENGINE	Dented	960.45 FS	*960.45 FS
25	1		*BASE,FR.GRILLE	Cracked	159.88 FS	*159.88 FS
					<b>Total Parts (S\$)</b>	<b>16,668.35      2,183.66</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	BODY UNDERSIDE COATING	New	100.00	0.00
2	BODY JOINT SEALANT	New	100.00	0.00
3	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	140.00	120.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	0.00
5	REMOVE & RENEW BONNET & RENEW DAMAGE PARTS	New	2,500.00	1,120.00
6	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	New	1,800.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,890.00</b>	<b>2,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >