From (Pernor	Melvin Yora	AGDIGITUD.	ENT (Office)	Date	Time: 5/11/19@ 5.46pt
Estimated Co	out:		Bill to:	1,0000	Time: 31/1-10 - 1-1
OD (TP) W	STTP RES / OD RES / E	VA/INV/MV/	28		45
To Inspect V	chicle No:	SMJIE	YF18	Insured:	FBK 1294E
at Workshop	m/s	Hc Auto		Tel: 9	457 0678 .
oflo	160) Sin Ming [)ive # 05.	-09	
Policy No:)			05135/7HE
Sum Insued			Excess:		
Make of Veh (Client's Recen				D.O./	3/11/2019
CA / REV	/ REP. / REV 24 HRS			Ito	.D. Eudopement;
Date/Time;	9.30am@ 6/11/19	Person Contagted:	mr Jue	Vehicl	
Date/Time	Action/Instruction Vo	limida 5			
	AN - YEISI TME	INCIGO124	18/03		21A:13/2/2019
	FBK IZVIAE - X				
1411/2014	9@ 3.41am Rev	red	mali advi	0	

ASSIGNMENT

From	Date: 6/11/2019	Veh No: SMJ 1817	ZyrrRegn: 0	2 19
Estimated Cost		Type: M.Car / M.Cycle / Bus / Van / L	.orry / Taxi / Prime Mov	er/
OD TP WS / TP RES / OD RES	S/EVA/INV/MV	Truck / Trailer or (A)	w	gan .
To inspect Vehicle No.	SMJ1817Y	Make / tonds	Shuttle as	188
	· C Auto	Colour M. Coras	A/C: Insured / S	td / NI / NA
	9 DAVE # 05-09	Sp.Reading 59787	T/Radio: Insured / \$	Std / NL / NA
insured:		Eng/No:		
Policy No.		C/No:	P7 . 12	16641
Claims No.		Gen. Cond: Good / Fair / Poor / Burn	nt	
Sum Insured:	Excess	Steering: Inoder / Jammed / Leaked	I/Bumt or	
(Client's Record)		Brake: Inoder / Janumed / Leaked	I/Bumt or	
Make of Veh:		Modi: Nill S/Rim / STD A/Rim o		
		Tyte Size: Figvanti	185/60R	15
(Policy Condition)		R: -2		_
Remark: The veh had commence	ed its N/S O/S	BS / DUN / EXNEVA / GY / FS / LIZA	/ MIC / OHTSU / PIR / S	SUMI /
repair at the time of in	spection.	TOYO POKO or		
Ball or Market Value:		Front 0	Rear	-
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 0 nm	R/Bal.	∠ mm
GIA / PR Seen:	Consistent?: Yes or No	L/Bal. of mm	L/Bal.	Z mm
Est Repairs: da	ys Res: Yes or No	D.O.A. 3 /11 /19	D.O.L 6	/11/19
Lum Sum: 1-31%	3 Val.: Yes or No	Survey held at	4	
0. DEV DED 2418	ne luip)	Des. of Damages : Frt / Rear / O/S	/ N/S / U/C / Roofto	p or
CA / REV / REP. / 24 HI	Vehicle: IN / OUT	Rec N/	5	
Date: Person C	ontacled:	The U/C / Chassis frame / Boo	dy Structure affected de	ue to collision.
Date / Time Action / Instru	clion			
	BECEN	'ED 1 3 JAN 2020		
	RECEIV	ED 13 Jan 2020		
Oute/Time: File Pass to7	Prefi, Report	Days Of Repair: 5		
	Final Report	Resurvey No. of Trip: 3	Survey Fee:	250
Districtions, File Platered to	r man respect	nesurvey no. or trip.	Transportation:	250
ā	Add Fe	e: Site Insp (\$) 3+RS_34	
		: Interview (\$) Heim	
Report Formet: TP		Tech love to	1 CSBott	
Lung Om / LB Fr H30		Westerd C		
430	00			250
			1521/01	250

Yvonne Wong (LKK Auto)

From:

Yvonne Wong (LKK Auto)

Sent:

Monday, November 11, 2019 8:41 AM

To:

MotorSurvey@sompo.com.sg; 'Ye, Yong Kang Melvin'

Cc:

'Henry, Irene James'; SUR

Subject:

RE: PRE-REPAIR SURVEY --- YOUR REF: FBK 1294 E | ACCIDENT INVOLVING SMJ 1817 Y

& FBK 1294 E ON 03 NOVEMBER 2019 ALONG STEVEN ROAD JUNCTION OF ANDERSON ROAD AT ABOUT 0950 HOURS Our ref : CMTD1905135/THE

Attachments:

SMJ 1817Y PRELI ADVISE pdf

Re send/attached

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SMJ1817Y

Date of survey : 06/11/2019 Number of days : 5 days

Thank you.

Best Regards,

Denise on behalf of Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Wong (LKK Auto)

Sent: Friday, November 08, 2019 5:32 PM

To: MotorSurvey@sompo.com.sg; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: PRE-REPAIR SURVEY --- YOUR REF: FBK 1294 E | | ACCIDENT INVOLVING SMJ 1817 Y & FBK 1294 E ON 03

NOVEMBER 2019 ALONG STEVEN ROAD JUNCTION OF ANDERSON ROAD AT ABOUT 0950 HOURS Our ref :

CMTD1905135/THE

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SMJ1817Y

Date of survey: 06/11/2019 Number of days: 5 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

Nivitha (LKK Auto)

From:

Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Sent:

Tuesday, 5 November 2019 5:46 PM

To:

assignments@lkkauto.com; sur@lkkauto.com

Cc:

Henry, Irene James; Elaine Toh

Subject:

RE: PRE-REPAIR SURVEY --- YOUR REF: FBK 1294 E || ACCIDENT INVOLVING SMJ 1817 Y & FBK 1294 E ON 03 NOVEMBER 2019 ALONG STEVEN ROAD JUNCTION OF ANDERSON ROAD AT ABOUT 0950 HOURS Our ref : CMTD1905135/THE

Hi LKK Auto.

Please make arrangement to conduct the survey for SMJ1817Y.

Best Regards Melvin Ye Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission1 & Product Purchase2 via Sompo SG

Download now @





¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Elaine Toh < Elainetoh@visionlawllc.com> Sent: Tuesday, 5 November, 2019 4:08 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> Cc: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: FBK 1294 E | | ACCIDENT INVOLVING SMJ 1817 Y & FBK 1294 E ON 03

NOVEMBER 2019 ALONG STEVEN ROAD JUNCTION OF ANDERSON ROAD AT ABOUT 0950 HOURS Our ref:

CMTD1905135/THE Importance: High

Our Ref: SMJ 1817 Y (et) WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of KENNETH KONG (NORTH AREA) LKK AUTO CONSULTANTS PTE LTD as the Single Joint Expert for this matter.

Venue:

H C Auto Pte Ltd

160 Sin Ming Drive

#05-09 Sin Ming Auto City

Singapore 575722

Contact:

Mr. Joe @ 9457-0678 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.

Thank you.

F

Regards.

Elaine Toh (Secretary) Vision Law LLC

Tel: 65342811 (Ext. 122)

Fax: 65356802

Appointed surveyor (Name & Signature)

Date & Time of Inspection :

cc:

SMJ 1817 Y - By fax: 64578287 only

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]

Sent: Tuesday, 5 November, 2019 10:13 AM

To: Elaine Toh

Cc: Henry, Irene James

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: FBK 1294 E | | ACCIDENT INVOLVING SMJ 1817 Y & FBK 1294 E ON 03

NOVEMBER 2019 ALONG STEVEN ROAD JUNCTION OF ANDERSON ROAD AT ABOUT 0950 HOURS Our ref:

CMTD1905135/THE

Our Reference: CMTD1905135/THE Your Reference: SMJ 1818 Y (YL)

Without Prejudice

Date: 04 November 2019

Attention:

VISION LAW LLC

Dear Sir / Mdm,

ACCIDENT INVOLVING SMJ1817Y & FBK1294E ON 03.11.2019

We refer to your Notice of Accident dated 04/11/2019.

The handler for this case is Ms Thelma Choo.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

Raleigh Services	The state of the s	
10010 (D10.000121000)	Andrew Ow Yong	
	Vincent Ng	
LKK Auto Consultants	Kenneth Kong (North area)	
	Marcus Chua (East area)	
	Mohd Rasul (West area)	
	Mohd Taufikh (West area)	
Priority Services	Jimmy Lee	
	Lawrence Ng	
	Jeffery Ong	
		Kenneth Kong (North area) Marcus Chua (East area) Mohd Rasul (West area) Mohd Taufikh (West area) Priority Services Jimmy Lee Lawrence Ng

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert

Best Regards Melvin Ye Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG





Download now @

For Travel, Personal Accident & Home Insurance | For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Elaine Toh < Elainetoh@visionlawllc.com > Sent: Monday, 4 November, 2019 11:43 AM

To: Claims - Motor Survey < Motor Survey@sompo.com.sg>

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: FBK 1294 E | | ACCIDENT INVOLVING SMJ 1817 Y & FBK 1294 E ON 03

NOVEMBER 2019 ALONG STEVEN ROAD JUNCTION OF ANDERSON ROAD AT ABOUT 0950 HOURS

Importance: High

Our Ref: SMJ 1817 Y (YL) WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by <u>HENG LEASING PTE LTD</u> to notify you of a road traffic accident on 03 November 2019 at about 0950 hours along Steven Road Junction of Anderson Road involving our client's motor vehicle registration number SMJ 1817 Y and motor vehicle registration number FBK 1294 E driven by you/your insured at the material time.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Thank you.

Regards, Elaine Toh Vision Law LLC

Tel: 65342811 (Ext. 122)

Fax: 65356802

cc: SMJ 1817 Y - By fax: 64578287 only

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413 Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref:

Date: 11 nov 2019

Our Ref: CS/SMO19019637/Kyd3

The Motor Claims Department SOMPO INSURANCE SINGAPORE PL


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMJ 1817Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on <u>06/11/2019</u> at the premises of M/s <u>H C AUTO PTE LTD</u> and have the following to report:-

Workshop Estimate Amount	: S\$	11,438.24
Revised Estimate Amount	: S\$	4,915.04 .
"Check" Items Amount	: S\$	196.00
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: SS	-

Description of Damage: The vehicle sustained damages at the rear n/s body.



Yours faithfully

Kenneth Kong Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	603E
Vehicle No.:	SMJ1817Y
Vehicle to be Exported:	No
intended Deregistration Date:	13 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	LEB6560230
Chassis No.:	GP71216641
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$20,554.00
Original Registration Date:	25 Feb 2019
First Registration Date:	25 Feb 2019
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$10,776.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2029
PARF Rebate Amount: Intended COE Rebate Details	\$8,082.00
COE Expiry Date:	24 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$31,458.00
Total Rebate Amount:	\$39,540.00

The information contained herein is correct as at 13 Jan 2020

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

mforesaid.	
	ACCIDENT STATEMENT
Date Of Report	04/11/2019 15:08
Date Of Accident	03/11/2019 09:50
Exact Location Of Accident	STEVEN ROAD JUNCTION OF ANDERSON ROAD
Country/State of Loss	SINGAPORE
C	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SMJ1817Y
Insured/Policyholder	
Name Of Registered Owner	HENG LEASING PTE LTD
Co Reg No	201840603E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96779813
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994242
Cover Note Number	
Driver	
Name of Driver	PATRICK PAK YEW HUN

Name of Driver PATRICK PAK YEW HUN
NRIC No S2590096J

 Date Of Birth
 28/08/1966

 Occupation
 OUTDOOR

 Date Of Driving Pass
 17/02/1989

Driving Experience 30 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96779813

Fax Number

Contact Number

EMail Address NOEMAIL

Address

BLK 44 CHAI CHEE STREET #11-102

Postcode

461044

OTHER - HIRER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO 2

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO 2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: GRAB PASSENGER

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

CHAI CHEE NPP

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN / POLICE REPORT NO: T/20191103/2043

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO WITH HC AUTO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBK1294E

Vehicle Make/Model/Colour

APRILIA ISTX 150

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

EZRA JESUDASON GIDEON

NRIC/Passport Number

S9315906C

Contact Number

94195202

Address

Postcode

Insurance Company Name

DETAILS OF INJURED PERSON 1

Name EZRA JESUDASON GIDEON

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBK1294E

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 2. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The name and acceptance of this form by insurance companies is not as sometimes of policy subjects on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- fi. The report will be forwarded by the insurers of the GriA Facords Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent as the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose's) of:
 - processing, handling and/or dealing with my clasms including the settlement of the claims and any necessary investigations relating to the claims;
 - (iii) investigating the accident and/or my claims.
 - [iii] carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about desvery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all material who have insured whiches i involved in this ecodent and the insurers lawyers/law forms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that asset in evaluating, investigating controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, by

(iii) for complying with requestioners under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

- 4 NOV 2019

Driver Signature of driver a not the policy to sent

GNOV ENT 4:50 AM

NHCJENNO

According Contre Pers

Jenny Lim

III COMP service to a service of

- 4 NOV 2019

SKETCH PLAN				
S A TIT			A smj	1817 -
AT			Timi-	F
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	111111111	0	
Offer pose	1090H OHlached no	T/XXPIIOS/T	3.	
	71 . S			
DECLARATION UWe Sectore the foregoin (20)	cultural and course respect		M	· ·
Policyholder's Signature Oate & Time:	Driver's Signature (If driver is not the policetion	deri Name	ng Centre Personne 's I	nny Lim
- 4 NOV 2019	4 May edby som	An secu	N No	,

Police Report Pg. 1





Police Station Of Origin: Chai Chee NPP 35 Chai Chee Avenue #01-256 SINGAPORE 461035 Tel No: 1800-4459999 1 of 3 Report No. T/20191103/2043

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/11/2019 12:33			Vide Report No.:	Station Diary No.:	
Interna	nt's Pions	No. Contract	STEP ME STANDARD	可是是我们在那些大学 名中	
	f Informant: K PAK YEV		Address: APT BLK 44 CHAI CHEE STI 461044	REET #11-102 SINGAPORE	
ID Type / ID No.: NRIC NO / \$2590096J			Contact No.: Home/Office: Mobile: 96779813		
National MALAY:			Email:		
Sex: Age: Date of Birth: Male 53 28/08/1966			Type of Informant: Driver		
Race: Chinese		-	Language: Institution / School Na		
Occupation: Private Driver			Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Injury Conveyed By Ambulance		Drink Drive: No	Date/Time of Accident: 03/11/2019 09:5	. 1	Type of Location Straight Road
Location: Along Road 1 STEVENS RO	DAD	terson Ros	ad.			
Along Stevens Road junction of Anderson Road Weather: Road Clear Dry		Surface:		Road	Speed Limit:	
Traffic Flow: Traffic		c Control: c Light - Working		Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Rear					Anyon	e conveyed by ance:

TO BE ADD	THE PERSON		
FBK1294E	Motorcycle	Slightly	O CONTRACTOR
SMJ1817Y	Car	Damaged Slightly Damaged	1

2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report Pg. 2





Police Station Of Origin: Chai Chee NPP 35 Chai Chee Avenue #0

Report No. T/20191103/2043

2 of 3

35 Chai Chee Avenue #01-256 SINGAPORE 461035

CONTINUATION OF REPORT

Tel No: 1800-4459999

HUR DATE BY	ALL DOOR SEAL OF THE PERSON NAMED IN COLUMN	建筑建筑 越			2,000	
Name	Ezra Jesudason Gideon			ID No	20	S9315906C
Related Vehicle	FBK1294E (Motorcy	rcle)		Conta	ct No.	94895202
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days granted Medical Leave N		NIL	Degree of	Injury	NIL	
Name	PATRIČK PAK YEWHUN			ID No.		S2590096J
Related Vehicle	SMJ1817Y (Car)			Contact No.		96779813
Hospital/Clinic	NIL			Class Driving Licens Expiry	g e &	Class: 3 Date of Expiry: NIL
Date Treatment	te Treatment NIL			harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	

Brief Details.

On the 03/11/2019 at about 0950hrs, I was travelling along Stevens Road towards Orchard Road on the first lane which I reach the junction of Stevens Road and Anderson Road using my vehicle SMJ1817Y. There was a traffic light at the junction at it was red at that time, thus I stop my vehicle outside the yellow box of the junction and wait for the traffic light to turn green. While waiting, suddenly I heard a loud bang at the rear of my vehicle and when I look at the rear of my vehicle, I saw a motorcycle on the ground of next to my vehicle. I proceed to make a check on him and call for the police for assistance. The said rider FBK1294E was conveyed to TTSH hospital by ambulance. My vehicle suffer damages to the rear left bumper valued unknown.

At the same time Traffic Police attended to us vide incident E/20191103/0093 and my in car camera SD card was taken by Traffic police Sgt(2) T130056 Siti Zahriah under in charge case IO Sufyan.



Police Report Pg. 3





Police Station Of Origin:
Chai Chee NPP
35 Chai Chee Avenue #01-256 SINGAPORE
461035 CONTINUATION OF REPORT

3 of 3 Report No. T/20191103/2043

Tel No: 1800-4459999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / SI CHEN ZHICHANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/11/2019 12:33
Officer In Charge Of Case: TP / GIT / Staff Sgt SUFIYAN BIN HARRAPORE Contact No.: 6547639	Classification Of Case:
Authentication Stamp	

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel: 6457 0678 Fax: 6457 8287 Co. and GST Reg. No.: 200820153N

Date: 04 / 11 / 2019

COSTS OF REPAIR ESTIMATE Not Notharing Phenomy Bepary 4-5day USny 8 4300/ M/s Heng Leasing Pte Ltd C/o 160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722 Dear Sir / Madam .

Vehicle no.

SMJ 1817 Y

Honda Shuttle Hybrid 1.5 Auto

Accident date :

03 / 11 / 2019

	Quantity	Descriptions	Amount (S\$)
ı	l pc	tail gate	s ₹ 1,193.00 ¥
2	1 pc	tail gate weather strip	5 / 168.50 X
3	1 pc	tail gate inner lock	S 1 180.00 Z
4	1 pc	tail gate Honda Logo	s ac 38.00 x
5	1 pc	tail gate 'SHUTTLE' emblem	S An 55.00 -
6	1 pc	tail gate "Hybrid" emblem	s 1s 75.50 -
7	1 pc	n/s tail gate reflector 340.80	s as 340.80 -
8	1 pc	n/s tail lamp 520-50	SCM 520.50 -
9	1 pc	rear bumper fascia 986-50	S & 1,200.00 L
0	2 pes	rear bumper spare 1 @ 56.50	S In 113.00 7
1	1 pc	n/s rear bumper reflector	S 4/7 86.40 ~
2	1 pc	n/s rear bumper reflector garnish	S MIT 45.00 -
3	1 pc	n/s rear bumper side retainer	S Dr7 42.50 -
4	1 pc	n/s rear bumper bracket	s em 42.50 7
5	1 pc	n/s rear bumper sponge	SCM 220.00 L
6	1 pc	rear bumper tow cover	S 16.50 X
7	1 pc	n/s rear bumper lower side garnish	S cm 89.50 7
8	1 pc	rear windscreen glass molding	s ~~ 130.00 X
9	1 pc	rear end panel inner garnish	s 🖺 155.50 X
0	1 pc	rear end panel	S 1 685.00 8
1	1 pc	n/s rear fender 1010.90	S B 1,010.90
2	1 pc	n/s rear fender inner garnish 706-20	CMS Fox 755.00 X
3	1 pc	n/s rear fender air duct	S PIV 28.70 Z
4	1 pc	fender side bracket	S P17 178.00 Z
5	1 pc	n/s tools box	Dehna 128.00 2
		Less 20%	\$ 7,497.80 \$ 1,499.56
		Balance C/FD	\$ 5,998.24

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722 Tel: 6457 0678 Fax: 6457 8287

Co. and GST Reg. No.: 200820153N

		Balance B/FD (SMJ 1817 Y)	\$ 5,998.24
26 27 28 29	1 set 1 pc 1 pc 1 pc	rear bumper reverse sensor rear panel inner seal rear windscreen inner seal rear windscreen inner gum	S ~ 350.00 sn X S ~ 250.00 sn X S ~ 60.00 sn X
	1992.	allowed that the content of the cont	\$ 6,718.24
		Labour charges	s 2,200.00 801 s 1,600.00 809
		To putty and spray painting	s 1,600.00 log
		To check,repair wiring	s 120.00 200
		Re-seal anti rust	s 120.00 3a
		To transfer tail gate	80 120.00 X
		Remove and refix cushion seat, garnish, carpet	s 280.00 601
		Remove and refix rear windscreen glass & quarter glass	\$ 280.00 X 601
		Plus : GST 7%	\$ 800.68
		Sub-total	\$ 12,238.92

LRIS Auto Committees hence natify
the Pepaint of the following:

• To receive between a very painty

• To deptay demanded parts using energy

• Parts prices are subject to continue

• Third party survey or a "Visitnet Projects" take

• No deptay and committees

• Incommy world tool to marray and a lease is subject to that appears

• Experience of the law appears for the state of the party.

Actions the law appears

Equilibrium.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS/SMO19019637/Kyd3e2

50 RAFFLES PLACE

#05-01/06

Date: 15-01-2020

5 Working Days



SINGAPORE LAND TOWERSINGAPORE 048623

ESTIMATED NORMAL PERIOD FOR REPAIR:

1.	Policy Particul	ars :- THIRD PARTY CLA	.IM
Insured Veh.	FBK 1294E	Veh. Inspected	SMJ 1817Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905135/THE	Excess (\$)	0.00
Assign From	MELVIN YONG	Assign Date	05/11/2019
2.	Vehicle P	articulars & Condition	
Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP71216641	Colour	METALLIC GREY
Odometer	59767	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3.	Cor	nditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	185/60 R15	DAVANTI	8 mm
L/H Front Tyre	185/60 R15	DAVANTI	8 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
k	Descr	ription of Damages	TO FORKER
THE VEHICLE SU DAMAGES SEE D	STAINED DAMAGES AT THE ETAILS.	E REAR N/S PORTION.	
5.	Ger	neral Information	
Accident Date	03/11/2019	Inspection Date	06/11/2019
Survey held at Repairer	160 SIN MING DRIVE# 05-0 H C AUTO PTE LTD	09	
5a.	HUNDIOFIEED	Remarks	
A)THE INSPECTION	ON WAS CONDUCTED ON A	"WITHOUT PREJUDICE" BA	SIS.
DJIN ACCORDAN	OF TO TOOK INSTRUCTION	S, WE HAVE NOT AUTHUR	OLD NEPAINO.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 1817Y

aty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	TO REPAIR SEE LABOUR	1,193.00	
1	TAIL GATE WEATHER STRIP	SERVICEABLE	168.50	
1	TAIL GATE INNER LOCK	TO REPAIR SEE LABOUR	180.00	9
-1	TAIL GATE HONDA LOGO	NOT NECESSARY	38.00	
1	TAIL GATE 'SHUTTLE' EMBLEM	NECESSARY	55.00	55.00
-1	TAIL GATE "HYBRID" EMBLEM	NECESSARY	75.50	75.50
1	N/S TAIL GATE REFLECTOR	CUT	340.80	340.80
1	N/S TAIL LAMP	CRACKED	520.50	520.50
1	REAR BUMPER FASCIA	BENT	1,200.00	986.50
2	REAR BUMPER SPARE @\$56.50	SERVICEABLE	113.00	
1	N/S REAR BUMPER REFLECTOR	MISSING	86.40	86.40
1	N/S REAR BUMPER REFLECTOR GARNISH	MISSING	45.00	45.00
1	N/S REAR BUMPER SIDE RETAINER	DISTORTED	42.50	42.50
1	N/S REAR BUMPER BRACKET	CRACKED	42.50	42.50
1	N/S REAR BUMPER SPONGE	CRACKED	220.00	220.00
1	REAR BUMPER TOW COVER	SERVICEABLE	16.50	
1	N/S REAR BUMPER LOWER SIDE GARNISH	CRACKED	89.50	89.50
1	REAR WINDSCREEN GLASS MOLDING	NOT NECESSARY	130.00	
1	REAR END PANEL INNER GARNISH	SERVICEABLE	155.50	
1	REAR END PANEL	TO REPAIR SEE LABOUR	685.00	
1	N/S REAR FENDER	BENT	1,010.90	1,010.90
1	N/S REAR FENDER INNER GARNISH	CRACKED	755.00	706.20
1	N/S REAR FENDER AIR DUCT	DISTORTED	28.70	28.70
1	FENDER SIDE BRACKET	DISTORTED	178.00	178.00
1	N/S TOOLS BOX	DEFORMED	128.00	128.00
	LESS 20% DISCOUNT		-1,499.56	-911.20
			5,998.24	3,644.80

Report Ref No. CS/SMO19019637/Kyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	350.00	
1	REAR PANEL INNER SEAL (SN)	NOT NECESSARY	250.00	
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	60.00	
1	REAR WINDSCREEN INNER GUM (SN)	NOT NECESSARY	60.00	
			720.00	
	LABOUR			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF TAIL GATE, TAIL GATE INNER LOCK AND REAR END PANEL.		2,200.00	800.00
	TO PUTTY AND SPRAY PAINTING.		1,600.00	800,00
	TO CHECK, REPAIR WIRING.		120.00	20.00
	RE-SEAL ANTI RUST.		120.00	30,00
	TO TRANSFER TAIL GATE	NOT NECESSARY	120.00	
	REMOVE AND REFIX CUSHION SEAT, GARNISH, CARPET.		280.00	60.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS & QUARTER GLASS.		280.00	60.00
			4,720.00	1,770.00
	GRAND TOTAL		11,438.24	5,414.80

RECOMMENDED COST OF LUMP SUM REPAIRS	4,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO19019637/Kyd3e2

MSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.