

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300



TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/11/2019
Vehicle Reg. No.:	SHC3098M	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	22/10/2019
Vehicle Colour:	BLUE		
Engine No:	G4LEKU397525	Chassis No:	KMHC851CVLU186848
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,384.74
Miscellaneous Items	0.00
Labour	770.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,154.74
+ GST 7.00% (S\$)	150.83
Nett Amount (S\$)	2,305.57

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2019)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC3098M/04/11/2019 16:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER DEF <i>DEF</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CENTER MOULDING <i>cra</i>	20.00	0.00	*451.25 FL
3	1		*REAR BUMPER LOWER CENTER MOULDING <i>cut</i>	20.00	0.00	*155.00 FL
4	2		*REAR BUMPER BEAM STAY RH / LH <i>xnn</i>	20.00	0.00	*276.20 FL
5	2		*REAR BUMPER SIDE BRKT RH / LH <i>xnn</i>	20.00	0.00	*66.20 FL
6	10		*REAR BUMPER CLIPS <i>xnn</i>	20.00	0.00	*22.00 FL
7	1		*REAR BUMPER MAT DEF <i>xnn</i>	0.00	0.00	*50.00 F
8	1		*REVERSE SENSOR <i>xnn</i>	0.00	0.00	*135.70 F
9	1		*REAR NO.PLATE WITH TRIM COVER DEF <i>cra</i>	0.00	0.00	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **1,670.75** *\$1087.65*

- List Item Discount on L Items (S\$) **286.01** *\$217.53*

Total Parts (S\$) **1,384.74** *\$870.12*

ComfortDelGro Engineering Pte Ltd/SHC3098M/04/11/2019 16:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

\$975
+ \$184.1

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6/11/19
1600hrs

Ram(LKK)

88622778 (HP)

Parasram @ LKK Auto @m

Part by Part

aff repair photo

2 repair days

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350.00 320
2	SPRAY PAINTING	New	250.00 200
3	WIRING CHECK	New	50.00 20
4	R/I REVERSE SENSOR	New	120.00 20
Gross Labour Cost (S\$)			770.00

ComfortDelGro Engineering Pte Ltd/SHC3098M/04/11/2019 16:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1069

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2019)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3098M/08/11/2019 15:00**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER FOGLAMP	20.00	0.00	*201.50 FL
2	1		*REAR BUMPER LOWER COVER	20.00	0.00	*28.70 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						230.20
- List Item Discount on L Items (S\$)						46.04
Total Parts (S\$)						184.16

ComfortDelGro Engineering Pte Ltd/SHC3098M/08/11/2019 15:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS