

Surveyor:

MARCUS

DOI: 07/11/2019

Date / Time : 07/11/2019

Registered in Merimen: 07/11/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SLR 613U

Claim No. : 6223378441SG

Name of Insured : NG THIAM HOE

Policy No. : 1700033743

Insured Tel No. : HP: +65-96824658

Make / Model : SUBARU FORESTER-2.0 I-L (SJ) (A)

Excess Sec II :SS D.O.A. : 07/11/2019 07:30

Place of Accident : BKE AFTER MANDAI EXIT

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SFN 3666P



INSRS:
WSP: FASTECH
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st)	
	Non-Reporting ltr (2nd)	
	Non-Reporting ltr (Final)	
	Notification ltr (if non-pickup)	
	Call OI	
	After call ltr to OI	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: Email Call

Repair Cost: 45 S\$ 6,000 (5 days) Reduction: 63% Email Call

FINAL SETTLEMENT Date/Time: 5/3/2020 Confirm with: ONG Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 0

Repair Cost: (w/ GST) S\$ 6,420 (2 VEH C.C. (1) 2 NO VEH)

Loss of Rental (LOR): S\$ - (- days) COPY SENT 11/3/2020

Loss of Use (LOU): S\$ 160 (580 x 2 days)

Loss of Income (LOI): S\$ - (- x - days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: S\$ 2.00

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost: S\$ -

Total: S\$ 6,582 Global Sum S\$:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 6,582 Name 1: FASTECH AUTO PTE LTD

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

ASS. REC. BY: *Mc/MS* K

112:

Alu/

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SFN 3666P*
 at Workshop no: *PP.*
 of _____
 Insured: *SLR 6134*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: *SFN 3666P* Yr Regn: *5108*
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA*
 Make: *Honda stream* cc *1799*
 Colour: *Blue* A/C: _____ Insured / Std / NI / NA
 Sp. Reading: *272609* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *RN 61068304*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: *205/55-R16*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Tourador*
 Front R/Bal. *6* mm Rear R/Bal. *6* mm
 L/Bal. *6* mm U/Bal. *6* mm
 D.O.A. *7/11/19* D.O.I. *7/11/19*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: *24*
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: *5* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS *095H*
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<i>Syrs Gal.</i>
	<i>LTA 13694 21-5-2023</i>
	<i>Nett 10306</i>
<i>11/11/19</i>	<i>L/S \$6000 confirmed with Alu.</i>
	<i>ced \$10,079 (63%)</i>

Date/Time, File Pass to? Prel. Report
 Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to? _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Wash (\$)

Survey Fee:	
Transportation:	
S+P&C	
Photos	
Other:	
TOTAL	

Equip Form: _____
 Lump Sum / U.C.: _____

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

not allowed
 7/11/19
 1/5 @ 6000/
 Safety.

Qty	Particular	Amount S\$
	<u>List Item:</u> SFN3666P	
1PCS	REAR WINDSCREEN MOULDING	RM \$48.50 ✓
1PCS	TAILGATE	Body DD \$903.20 ✓
1PCS	TAILGATE 'H' LOGO	RM \$35.20 ✓
1PCS	TAILGATE 'STREAM' EMBLEM	RM \$32.60 ✓
1PCS	TAILGATE 'RSZ' EMBLEM	RM \$38.80 X
1PCS	TAILGATE OUTER GARNISH	RM \$184.50 X
1PCS	TAILGATE INNER LOCK	DD \$109.50 ✓
1PCS	TAILGATE INNER TRIM BOARD	RM/CN \$341.50 ✓
1SET	TAILGATE INNER TRIM BOARD CLIPS	RM \$50.00 ✓
1PCS	TAILGATE WEATHERSTRIP	RM \$116.90 ✓
1PCS	TAILGATE Top spoiler [black] 450	RM/CN \$490.20 ✓
1PCS	REAR BUMPER	DD \$665.40 ✓
2PCS	REAR BUMPER SIDE RETAINERS @\$25.50	17 \$51.00 X
1SET	REAR BUMPER CLIPS	RM \$39.00 ✓
1PCS	REAR END PANEL	Body DD \$306.10 ✓
1PCS	REAR END PANEL LOWER MEMBER	RM \$182.30 ✓
1PCS	REAR END PANEL TOP GARNISH	RM \$225.60 ✓
1PCS	REAR FLOOR PANEL	RM \$912.30 X
2PCS	REAR FLOOR PANEL TOP BOARDS @\$266.50	17 \$533.00 X
2PCS	REAR taillamps @ 891.10 384.50 x 2 = 769.00	RM \$1782.20 ✓
2PCS	REAR FENDER INNER TRIM BOARDS @\$395.20	RM/To.n \$790.40 ✓
1SET	REAR FENDER INNER TRIM BOARD CLIPS	17 \$50.00 X
1PCS	REAR EXHAUST	RM \$689.30 X

20%

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
------------	-------------------	-------------------

List Item:

2PCS	REAR EXHAUST MOUNTINGS @\$45.00	11 \$90.00 X
1PCS	REAR SPARE TYRE BRACKET	11 \$285.10 X
2PCS	REAR BUMPER LOWER BRACKETS @\$25.50	301 \$51.00 ✓
1PCS	CENTRE EXHAUST PIPE	(202) 11 \$685.40 X
List Item Total:		\$9689.00

5116.20
202
4092.96

Special Nett Item:

1SET	REAR BUMPER REVERSE SENSOR	shardh \$280.00 220
1PCS	REAR END PANEL SEALANT	ner \$50.00 ✓
1PCS	REAR FLOOR PANEL INSULATOR	11 \$180.00 X
1PCS	REAR WINDSCREEN SEALANT	ner \$50.00 40
1PCS	REAR QUARTER GLASS SEALANT	11 \$50.00 X
1SET	REAR REVERSE CAMERA	shardh \$480.00 380
<u>Special Nett Total:</u>		\$1090.00

Labour Charge:

TO CHECK WIRING.	\$80.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR.	\$80.00 50
TO DISMANTLE & REPLACING REVERSE CAMERA.	\$80.00 50
TO DISMANTLE & REFIX REAR WINDSCREEN.	\$150.00 120
TO TRANSFER TAILGATE COMPONENTS.	\$100.00 60
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.	\$150.00 80
TO DISMANTLE & REPLACING REAR EXHAUST.	\$180.00 60

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular	Amount S\$
<u>Labour Charge:</u>		
	TO SPRAY RUST PROOFING.	\$150.00 80
	TO MOUNT VEHICLE ON JIG BENCE.	17 \$380.00 X
	TO SPRAY RUST PROOFING.	Repair \$150.00 X
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.	\$1800.00 1000
	TO PUTTY & SPRAY PAINTING.	\$2000.00 1200
	Labour Charge Total:	\$5300.00

7512.96

6010

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$16,079.00

LKK Auto Consultants hence notify the Receiver of the following:

- * To receive beneficial spray painting
- * To display damaged parts during recovery

Authorised by Repairer:

Signature:

Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	095H
Vehicle Details	
Vehicle No.:	SFN3666P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	R18A1775699
Chassis No.:	RN61068304
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,394.00
Original Registration Date:	22 May 2008
First Registration Date:	22 May 2008
Transfer Count:	2
Actual ARF Paid:	\$17,394.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$19,356.00
COE Rebate Amount:	\$13,694.00
Total Rebate Amount:	\$13,694.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Nov 2019

Home > Used Cars > StarBright Auto > Honda Stream 1.8A (COE till 04/2023)

Honda Stream 1.8A (COE till 04/2023)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$24,800		
Depreciation	\$7,170 /yr	Reg Date	23-Apr-2008 (3yrs 5mths 15days COE left)
Mileage	138,000 km (12k /yr)	Manufactured	2008
Road Tax	\$1,076 /yr	Transmission	Auto
Dereg Value	\$14,135 as of today (change)	OMV	\$21,018
COE	\$20,441	ARF	\$21,018
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight	1,370 kg	No. of Owners	4
Type of Vehicle	MPV		

Features

1.8L I-VTEC Engine, Leather Seats, Airbags, ABS, Climatic Control Aircon, Sport Rims, HID Headlights, Knockdown Rear Seats. View specs of the Honda Stream (2007-2014)

Accessories

Auto Climatic Air-con, Leather Seats, Sports Rims, Reverse Sensors And Reverse Camera, LCD Player, Arm Rest, Knockdown Rear Seats.

Description

1 Year Warranty, Excellent Condition, Accident Free, Bank Loan/In House Loan Available, Trade In Welcome.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

[Shortlist](#)
[Report Error](#)
[Compare](#)
[More Actions](#)
[Add note](#)

Seller Information

Company	StarBright Auto = dealer's pricelist = 95 vehs sold 40 vehs available
Address	1 Bukit Batok Crescent #02-13/14 Search cars nearby this location
Location	WCEGA Plaza
Office No	67930080
Contact Person(s)	Soh 97955598 Richard 81667779

Posted on: 05-Nov-2019 | Last updated on: 05-Nov-2019

Upfront Payment

[» more Financial info](#)

Transfer Fee \$25

FREE VALUATION,
Be informed don't get lowballed.

Completely FREE!

Find out your car's worth today!



[Advanced Search](#)

Home > Used Cars > G.S.T. Automobile Trading > Honda Stream 1.8A X (COE till 01/2023)

Honda Stream 1.8A X (COE till 01/2023)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$22,800		
Depreciation	\$7,060 /yr	Reg Date	30-Jan-2008 (3yrs 2mths 22days COE left)
Mileage	165,000 km (14k /yr)	Manufactured	2007
Road Tax	\$1,076 /yr	Transmission	Auto
Dereg Value	N.A.	OMV	\$17,471
COE	N.A.	ARF	\$19,219
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight	1,350 kg	No. of Owners	5
Type of Vehicle	MPV		



Location Map

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Features

View specs of the Honda Stream (2007-2014)

Description

COE Till Jan 2023, Road Tax Till Jan 2020, Economical MPV.

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Seller Information

Company	G.S.T. Automobile Trading	
	<ul style="list-style-type: none"> • dealer's pricelist • 7 vets sold 3 vets available 	
Address	22 Woodlands Link #04-47/48/49 Woodlands East Industrial Estate Search cars nearby this location	
Office No	67589559	
Contact	Mr Goh	97579559
Person(s)	Xiao Wei	96889543

Posted on: 02-Nov-2019 | Last Updated on: 02-Nov-2019

Upfront Payment

[» more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$6,840 (change)	Maximum 70% Loan
1st Instalment	\$470	Based on 3.75% interest rate

[Compare](#)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	07 Nov 2019 14:33	Cim Dtl Modified	Claimant's Name: -> -.	[A] HOW MEI KWAN
2	07 Nov 2019 14:33	Cim Veh Model Changed	(202358) HONDA STREAM 1.8 X (A).	[A] HOW MEI KWAN
3	07 Nov 2019 14:33	Cim Created	Reg No: SFN3666P. Acct Date: 2019/11/07. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Fastech Auto Pte Ltd (HQ)	[A] HOW MEI KWAN
4	07 Nov 2019 14:33	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	07 Nov 2019 14:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/11/18	[A] HOW MEI KWAN
6	07 Nov 2019 14:33	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	07 Nov 2019 14:33	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	07 Nov 2019 14:33	Label Added	(19):Fastlane.	[A] HOW MEI KWAN
9	07 Nov 2019 14:33	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
10	08 Nov 2019 15:16	Cim Dtl Modified	Claimant's Name: - -> ONG WEE LEE. Claimant's ID: -> S8218095H.	[A] HOW MEI KWAN
11	11 Nov 2019 10:30	Cim Registration Modified	Acct Time:00:00:00->07:00:00.	[I] AIG OneClaim Integration User
12	07 Feb 2020 15:41	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	07 Feb 2020 15:41	Cim Dtl Modified	Claim Conclusion: -> 3.	[A] JOANNE LEE KHANG MIN
14	07 Feb 2020 15:41	Cim Dtl Modified	JPJ Reg. Date: -> 2008/05/22.	[A] JOANNE LEE KHANG MIN
15	07 Feb 2020 15:41	Cim Details Notified		[A] JOANNE LEE KHANG MIN
16	12 Feb 2020 12:09	Adj Mandate Request	Cur.Req:6582.00:3 vehicle chain collision,01 2nd. BOLA 2B. ** 5 days recommendation for repair	[A] Khanchna Pothuraj

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Bill To)	Ref 1	Ref 2	Amount
2339491	08 Nov 2019 10:49:29	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SFN3666P	SLR613U	11.77
2431643	07 Feb 2020 15:41:21	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFN3666P	SLR613U	11.77

Print Received Message

This mail is associated with :

*SFN3666P (6223378441SG)
[SLR613U]
TP
ONG WEE LEE
Nov 7 2019 7:00AM
[NG THIAM HOE,]
Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/02/2020 10:42 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6582.00) - SFN3666P - Claim Handler: MdNoor, Norsiah

Approved:6582.00.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 5 March 2020 3:09 PM
To: Ong Shiying
Cc: Jason; Lina Pang; Admin A
Subject: RE: Our Ref : SFN 3666P DOA: 07.11.2019 Your Ref : SLR 613U *** LKK REF: CC6/AIG19019728/Uka3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 6,420.00
2. Loss of Use (2 days x \$80)	\$ 160.00
3. LTA Search Fee	\$ 2.00
Total	\$ 6,582.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Shiying <shiyong.ong@fastechauto.com.sg>

Sent: Wednesday, 26 February 2020 10:37 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Admin A <admin-a@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: RE: Our Ref : SFN 3666P DOA: 07.11.2019 Your Ref : SLR 613U *** LKK REF: CC6/AIG19019728/Uka3

Without Prejudice

Dear Khanchna,

Please refer to our Letter of Demand dated 09/01/2020.

We have yet to receive an offer from your good office.

We await your reply.

Best Regards,

Shiying

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: Monday, January 20, 2020 2:06 PM

To: Ong Shiying <shiying.ong@fastechauto.com.sg>; Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref : SFN 3666P DOA: 07.11.2019 Your Ref : SLR 613U *** LKK REF: CC6/AIG19019728/Uka3

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Khanchna,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

*Wishing you a Happy and Prosperous Lunar New Year**



Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Shiying <shiyong.ong@fastechauto.com.sg>
Sent: Monday, 20 January, 2020 12:31 PM
To: Admin A <admin-a@lkkauto.com>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>
Subject: Our Ref : SFN 3666P DOA: 07.11.2019 Your Ref : SLR 613U

Without Prejudice

Dear Sir / Madam,

Kindly refer to our Letter of Demand dated 09/01/2020.

Please provide us with the name of OIC.

Thank you.

Best Regards,

Shiyong

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 6 March 2020 6:26 PM
To: Ong Shiyong
Cc: Jason; Lina Pang; Admin A
Subject: RE: Our Ref : SFN 3666P DOA: 07.11.2019 Your Ref : SLR 613U *** LKK REF: CC6/AIG19019728/Uka3
Attachments: DV AND ATA.pdf

Without Prejudice
(save as to costs)

Dear Shiyong,

Thank you for the acceptance.

Please affix chop and sign the ATA & DV and e-mail them back to us.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>
Sent: Thursday, 5 March 2020 4:47 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our Ref : SFN 3666P DOA: 07.11.2019 Your Ref : SLR 613U *** LKK REF: CC6/AIG19019728/Uka3

Without Prejudice

Dear Khanchna,

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2019 Edit Reg		07 Nov 2019 00:00 Edit Adj Rot	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	NG THIAM HOE , ID: S8105184D								
Main Claimant:	ONG WEE LEE , ID: S8218095H								
Vehicle Reg. No.:	SFN3666P	Date of Loss:	07/11/2019 07:00 - :59 [137 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6223378441SG	Policy/Cover Note No.:	1700033743 (Comprehensive) Coverage: 29/07/2019 - 28/07/2020						
Vehicle Reg. No. (Insured):	SLR613U	Policy No. (Claimant):	5100780279-01						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/11/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG_EXPRESS (24/02/2020): Alert - Adj Mandate Approved (S\$6582.00) - SFN3666P - Claim Handler: MdNoor, Nor... AIG_SG (08/11/2019): Request To Upload TP GIA Report AIG_SG (08/11/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFN3666P (6223378441SG)
[SLR613U]
TP
ONG WEE LEE
Nov 7 2019 7:00AM
[NG THIAM HOE,]
Fastech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Letters/Correspondences											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	{Draft}	Third Party Express Settlement – Payment Breakdown							Edit			
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	07/11/19 17:50	Chassis Number							Load JPG	<input checked="" type="checkbox"/>		
2	07/11/19 17:50	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
3	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
4	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
5	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
6	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
7	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
8	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
9	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
10	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
11	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
12	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
13	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
14	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
15	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
16	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
17	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
18	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
19	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
20	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
21	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
22	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
23	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
24	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
25	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
26	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
27	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
28	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
29	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
30	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
31	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
32	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
33	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
34	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
35	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
36	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
37	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
38	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
39	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		
40	07/11/19 17:53	General View							Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
59	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
60	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
61	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
62	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
63	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
64	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
65	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
66	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
67	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
68	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
69	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
70	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
71	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
72	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
73	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
74	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
75	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
76	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
77	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
78	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
79	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
80	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
81	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
82	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
83	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
84	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
85	07/11/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 09:46	TP GIA REPORT	 Load PDF	
2	08/01/20 11:10	EMAIL TO OI	 Load PDF	
3	10/02/20 12:23	GIA SEARCH	 Load PDF	
4	10/02/20 12:23	LOD	 Load PDF	
5	12/03/20 11:00	WORKSHOP INVOICE	 Load PDF	
6	12/03/20 11:00	AUTHORISATION TO ACT FORM	 Load PDF	
7	12/03/20 11:00	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/11/19 13:32	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLR613U (Insd veh)	Model:	HONDA STREAM 1.8 X (A)
	SFN3666P (TP veh)		
Date of Accident:	07/11/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	17,204.53
Final Repair Cost	:	\$	6,420.00
Loss of Use	:	\$	160.00 2.00 days at \$80.00 per day
Rental (if any)	:	\$	0.00 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,582.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 6,582.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

12 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019728/UKA3Q2
Date: 12/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700033743
Claimant SFN3666P **Insured Vehicle No :** SLR613U
Vehicle No : SFN3666P
Date of Loss: 07/11/2019 Nature of Claim: TP Claim No: 6223378441SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFN3666P** Engine No: R18A1775699
Make & Model: HONDA STREAM, 1.8 X (A) Chassis No: RN61068304
Reg. Date: 22/05/2008 (Man. Year: 2008) Odometer: 272609 km
Colour: Blue
Engine Capacity: 1799 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	10,779.00	4,782.96	5,996.04	55.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	2,730.00	2,570.00	48.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,079.00	7,512.96	8,566.04	53.27
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	16,079.00	6,000.00	10,079.00	62.68
+ GST 7.00/7.00% (S\$)	1,125.53	420.00	705.53	62.68
Nett Amount (S\$)	17,204.53	6,420.00	10,784.53	62.68
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,582.00		

INSPECTION

Date of Assignment: 07/11/2019
Date Inspected: 07/11/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	48.50 F	*48.50 FL
2	1		*TAILGATE	Badly Dented	903.20 F	*903.20 FL
3	1		*TAILGATE H LOGO	Necessary	35.20 F	*35.20 FL
4	1		*TAILGATE STREAM EMBLEM	Necessary	32.60 F	*32.60 FL
5	1		*TAILGATE RSZ EMBLEM	Not fitted	38.80 F	*- FL
6	1		*TAILGATE OUTER GARNISH	Serviceable	184.50 F	*- FL
7	1		*TAILGATE INNER LOCK	Dented	109.50 F	*109.50 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	341.50 F	*341.50 FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	116.90 F	*116.90 FL
11	1		*TAILGATE TOP SPOILER BLACK	Cracked / Necessary	490.20 F	*450.00 FL
12	1		*REAR BUMPER	Distorted	665.40 F	*665.40 FL
13	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	51.00 F	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
15	1		*REAR END PANEL	Badly Dented	306.10 F	*306.10 FL
16	1		*REAR END PANEL LOWER MEMBER	Bent	182.30 F	*182.30 FL
17	1		*REAR END PANEL TOP GARNISH	Twisted	225.60 F	*225.60 FL
18	1		*REAR FLOOR PANEL	Repair	912.30 F	*- FL
19	2		*REAR FLOOR PANEL TOP BOARDS	Not Necessary	533.00 F	*- FL
20	2		*REAR TAILLAMPS	Cracked	1,782.20 F	*769.00 FL
21	2		*REAR FENDER INNER TRIM BOARDS	Deformed / Torn	790.40 F	*790.40 FL
22	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
23	1		*REAR EXHAUST	Repair	689.30 F	*- FL
24	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
25	1		*REAR SPARE TYRE BRACKET	Not Necessary	285.10 F	*- FL
26	2		*REAR BUMPER LOWER BRACKETS	Bent	51.00 F	*51.00 FL
27	1		*CENTRE EXHAUST PIPE	Not Necessary	685.40 F	*- FL
28	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*220.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
30	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*REAR QUARTER GLASS SEALANT	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR REVERSE CAMERA	Shorted	480.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	10,779.00	5,806.20
- List Item Discount on L Items 0.00/20.00% (\$\$)		0.00	1,023.24
	Total Parts (\$\$)	10,779.00	4,782.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REVERSE CAMERA	New	80.00	50.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO TRANSFER TAILGATE COMPONENTS	New	100.00	60.00
6	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
7	TO DISMANTLE & REPLACING REAR EXHAUST	New	180.00	60.00
8	TO SPRAY RUST PROOFING	New	150.00	80.00
9	TO MOUNT VEHICLE ON JIG BENCE	New	380.00	0.00
10	TO SPRAY RUST PROOFING	New	150.00	0.00
11	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS	New	1,800.00	1,000.00
12	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			5,300.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >