

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

not authorized
7/11/19
1/5 4100
527

VEHICLE NO: SLT 7827M

| QTY | PARTICULAR | |
|-------|--|-----------------------|
| 1 PCS | REAR WINDSCREEN W/MOULDING | 11 \$1,855.30 X |
| 2 PCS | REAR WINDSCREEN INNER SIDE GARNISH @\$165.00 | 11 \$330.00 X |
| 1 PCS | TAILGATE | 12 \$3,066.20 X |
| 1 PCS | TAILGATE OUTER GARNISH | 11 \$450.00 X |
| 1 PCS | TAILGATE REAR LOGO | 11 \$38.50 X |
| 1 PCS | TAILGATE 'ASHVAI' EMBLEM | 11 \$78.50 X |
| 2 PCS | TAILGATE REFLECTORS @\$650.00 | 11 \$1,300.00 X |
| 1 PCS | TAILGATE REAR WIPER ARM | 11 \$166.00 X |
| 1 PCS | TAILGATE REAR WIPER MOTOR | 11 \$966.00 X |
| 1 PCS | TAILGATE INNER LOCK | 11 \$292.00 X |
| 1 PCS | TAILGATE INNER TRIM BOARD | 11 \$595.30 X |
| 1 SET | TAILGATE INNER TRIM BOARD CLIPS | 11 \$30.00 X |
| 1 PCS | TAILGATE WEATHERSTRIP | 11 \$166.20 X |
| 1 PCS | TAILGATE REVERSE CAMERA | 11 \$485.00 X |
| 2 PCS | TAILGATE LICENCE PLATE LAMPS @\$53.00 | 11 \$106.00 X |
| 1 PCS | REAR BUMPER | 11 \$891.00 X |
| 1 PCS | REAR BUMPER TOW COVER | 11 \$22.00 X |
| 2 PCS | REAR BUMPER REFLECTORS @\$68.00 | 01/5cm \$136.00 1PC |
| 2 PCS | REAR BUMPER SIDE RAIN TAINERS @\$35.00 | 11 \$70.00 X |
| 1 SET | REAR BUMPER CLIPS | 11 \$35.00 X |
| 1 PCS | REAR BUMPER SPONGE | 11 \$185.00 X |
| 1 PCS | REAR BUMPER REINFORCEMENT | 11 \$721.00 X |
| 2 PCS | REAR BUMPER REINFORCEMENT BRACKETS @\$150.00 12/00 | 01/5cm \$300.00 1PC |
| 1 PCS | REAR END PANEL | 11 \$720.00 X |
| 1 PCS | REAR SUPPORT PANEL TOP GARNISH | 11 \$408.00 X |
| 1 PCS | REAR FLOOR PANEL | 11 \$1,288.00 X |
| 1 PCS | REAR FLOOR PANEL TOP BOARD | 11 \$622.00 X |
| 2 PCS | REAR FLOOR PANEL TOOLS SPONGES @\$305.00 | 11 \$610.00 X |
| 1 PCS | REAR END PANEL LOCK SENSOR | 11 \$265.00 X |
| 1 PCS | REAR FLOOR PANEL TOP BOARD SPONGE | 11 \$495.00 X |
| 1 PCS | REAR EXHAUST | 11 \$1,122.30 X |
| 2 PCS | REAR EXHAUST MOUNTINGS @\$60.00 | 11 \$120.00 X |
| 2 PCS | TAILLAMPS @\$580.00 | 01/5cm \$1,160.00 1PC |
| 2 PCS | REAR FENDERS @\$1150.00 | 11 \$2,300.00 X |
| 2 PCS | REAR FENDER OUTER PROTECTORS @\$541.00 | 01/5cm \$1,082.00 1PC |
| | | \$22,477.30 |
| | S.NETT | |
| 1 PCS | REAR LICENCE PLATE W/HOLDER | 11 \$50.00 X |
| 1 PCS | REAR WINDSCREEN SEALANT | 11 \$50.00 X |

717.20

619.20

482.60

323.70

107

p- 38242
102
3261.78

1 SET
1 PCS
1 SET

REAR BUMPER REVERSE SENSOR
REAR END PANEL SEALANT
REAR FLOOR PANEL INSULATOR

shahl \$280.00 200
nu \$50.00 ✓
11 \$50.00 X

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO DISMANTLE & REPLACING REAR WINDSCREEN
TO DISMANTLE & REFIX REAR EXHAUST
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO SPRAY RUST PROOFING
TO MOUNT VEHICLE ON CAR O-LINER
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30
\$80.00 50
11 \$150.00 X
11 \$150.00 X
\$100.00 80
\$120.00 30
11 \$380.00 X
\$1,500.00 600
\$1,500.00 850
TOTAL \$27,017.30

5111.28

UK... the Consultants hence notify
the Repairer of the following
... after spray painting
... part(s) during resurvey
... information
... on the "as is" basis
... as follows
... must be resurveyed and
... Company
... by Repairer
... re: