

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED
 10 EUNOS ROAD 8
 #09-04A SINGAPORE POST CENTRE
 SINGAPORE 408600
TEL: 63374779 **FAX:** 63389267
ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439
Date: 11 Dec 2019
Policy No: GA027739
Veh Reg No: SDS839A
Make/Model: TOYOTA VELLFIRE
 2.4Z GOLDEN EYES II
 2WD
Chassis No: ANH208346738
Engine No: 2AZG444066
Reg. Date: 27-03-2015

Your Ref No: TP 1119-5741
Claim Type: Third Party
Accident Date: 03-11-2019
TP Veh Reg No: SLR 3612 C

Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Supplementary Parts to Repair				
Spare Parts				
1 RETAINER FRONT FENDER LINER <i>nu</i>	5.00	1 PCS	5.00	5.00 ✓
	Add 10%		0.50	5.50
			Total	S\$ 5.50
			GST Amount	S\$ 0.39
			Total Amount payable	S\$ 5.89

SUPP 5.50
PARTS 2502.50
SN 95.00
V&B 2200.00

4803.00

For Progressive Car Care Pte Ltd



 AUTHORISED SIGNATURE