

Date: 06/11/2019

To: AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

**Estimate Cost Of Repair For Toyota Estima Hybrid 2.4X A (SFJ9688H)**

To supply the following parts:

		Amount
1	Rear Bumper Assy <i>x R</i>	\$ 2,560.56
2	Rear Bumper Retainer <i>/ CR4</i>	\$ 86.50
3	Rear Bumper clip 12pcs @2.60 <i>/ Nec</i>	\$ 31.20
<b>Sub Total</b>		<b>\$ 2,678.26</b>
Less 10%		\$ 267.83
<b>Total on Parts</b>		<b>\$ 2,410.43</b>

Labour Charges:

1	Being remove and replace new Bumper, <i>Repair bumper and door</i>	\$ 400.00	<i>300</i>
2	Being plastic primer coat on the bumper and painting on replacing and repair parts	\$ 800.00	<i>400</i>

**Total on Labour** \$ 1,200.00

**Total Repair Cost** **\$ 3,610.43**

Prepare By

  
Pang Tian Hook

*Repair days. - 2days.*

*Lump Sum. Repair.  
After spray photo.*

*Sun Pin.  
7/11/2019.*

*TP without prejudice.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: