

ESTIMATE TO REPAIR

VEHICLE NO. : SKH 7988 G
 MAKE : SUZUKI
 MODEL : SX4 SEDAN 1.6
 YEAR : 2009
 CHASSIS NO : JSAGYC21S00320010

SURVEYOR NAME : Lkk keneph
 DATE OF SURVEY :
 TIME OF SURVEY : 11 NOV 2019

DATE : 7-Nov-19
 DATE OF ACCIDENT : 5-Nov-19
 THIRD PARTY REF : SJV 6289 K
 THIRD PARTY REF : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$ 675.25
1 pc	rear bumper bean				\$ 227.50
1 pc	rear end panel				\$ 319.50
10 pcs	rear bumper clips		\$ 3.00		\$ 30.00
	Less 15%				\$ 1,252.25
					\$ 187.84
					\$ 1,064.41
	To putty & spray paint.				\$ 500.00
	labour charges.				\$ 600.00
TG/VL	TOTAL				\$ 2,164.41

Not Not hash
 6/12/19
 Puttying After Paint
 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: