Simeuor El. REF: SMO	·
ASSI	GNMENT
D-1	Veh No: SJU1771S Yr Regn: 15 Dec 2014
om: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
timated Cost:	Truck / Trailer or
OD (TR) WS / TP RES / OD RES / EVA / INV / MV	Make: BMW 535i c.c 2879
o Inspect Vehicle No:	Colour Gney A/C: Insured / Std / NI / NA
Workshop m/s ferfarmane Motors	Sp.Reading 66638 T/Radio: Insured / Std / NI / NA
	Eng/No:
sured:	C/No: WBA5B12010D327516
olicy No.	Gen. Cond: Good / Fair / Poor / Burnt
laims No.	Steering: Inorder / Jammed / Leaked / Burnt or
um Insured: Excess:	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	Tyre Size: F: 275/35 ZR19
	1 lyle Size. 1
(Policy Condition) N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	TOYO / YOKO or
Chlor ()	D
Bal. or Market Value: Consistent?: Yes or No	Front R/Bal. 6 mm R/Bal. 6 mm
2 - 1 - 12 - V No	L/Bal. 6 mm L/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No Est Renairs: days Res.: Yes or No	D.O.A. D.O.I. 08-11-19
SV-1. Vec es No	W/C
Lum Sum: % _ 3 Val.: Yes or No	Des. of Damages : Frt / Rear) / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	<u> </u>
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	Milay do
	- / A \
RECEIVED 2 6 DE	2019
KEOLIVED	2011-1-0
3-	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) 36/12 Typist : Final Report	Resurvey No. of Trip: Survey Fee: 490
Date/Time, File Return to?	Transportation:
2) Add Fe	ee: : Site Insp (\$)S+RS,SI
	: Interview (\$) Photos
Report Format : TP	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ \2,673.56)	. : Weekend (\$) .
	ΤΟΤΑL 490

Nivitha (LKK Auto)

From:

Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Sent:

Friday, 8 November 2019 10:18 AM

To:

PBSP; assignments; SUR

Cc:

Henry, Irene James; Hwang, Shiang Yi

Subject:

RE: SURVEY ARRANGEMENT - REQUEST FOR DIRECT SETTLEMENT - SJV1771S &

SCW6228P ON 07/11/2019 Our ref : CMTD1905199/SYH

Without Prejudice

Hi Caroline,

We acknowledged receipt of your claim documents.

Please be informed that Ms Hwang Shiang Yi is the handler of this case.

We regret to inform that we are unable to revert on liability as we have yet to receive our insured's accident report.

We have appointed LKK AUTO to conduct the survey on a without prejudice basis.

Aside to LKK,

Please make arrangement to conduct the survey for SJV1771S.

Best Regards
Melvin Ye
Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG





Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: PBSP <pml-pbsp@simedarby.com.sg> Sent: Thursday, 7 November, 2019 5:33 PM

To: Claims - Motor Survey < Motor Survey@sompo.com.sg>
Cc: Ye, Yong Kang Melvin < melvin.ye@sompo.com.sg>

Subject: SURVEY ARRANGEMENT - REQUEST FOR DIRECT SETTLEMENT - SJV1771S & SCW6228P ON 07/11/2019

Dear Sirs.

We refer to the above matter and as spoken this afternoon, please arrange survey tomorrow between 9am - 5pm as our customer will collect the vehicle by tomorrow evening. We will email the estimates to you / surveyor by tomorrow morning.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards, Caroline C/o Performance Motors Limited - Body and Paint 303 Alexandra Road Singapore 159941 DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Monday, 11 November 2019 11:12 AM

To:

Admin-D (LKKAuto); 'Ye, Yong Kang Melvin'; assignments;

MotorSurvey@sompo.com.sg

Cc:

'Henry, Irene James'; 'Hwang, Shiang Yi'; SUR

Subject:

RE: SURVEY ARRANGEMENT - REQUEST FOR DIRECT SETTLEMENT - SJV1771S &

SCW6228P ON 07/11/2019 Our ref : CMTD1905199/SYH

Attachments:

PRELI ADVISED OF SJV 1771S.pdf

Dear Sir/Madam,

Enclosed preliminary revised of SJV 1771S

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Friday, 8 November 2019 10:48 AM

To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; SUR

<sur@lkkauto.com>

Subject: RE: SURVEY ARRANGEMENT - REQUEST FOR DIRECT SETTLEMENT - SJV1771S & SCW6228P ON 07/11/2019

Our ref: CMTD1905199/SYH

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]

Sent: Friday, 8 November 2019 10:18 AM

To: PBSP <pml-pbsp@simedarby.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: CMTD1905199/SYH

Date:11/11/2019

Our Ref: CS/SMO19019837/Gtd3

The Motor Claims Department SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SJV 1771S .

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 08/11/2019 at the premises of M/s Performance and have the following to report: -

Workshop Estimate Amount	: <u>S\$</u>	14,588.55
Revised Estimate Amount	: <u>S\$</u>	11,969.45
"Check" Items Amount	: <u>S</u> \$	424.10
Market Value	: <u>S</u> \$	
LTA Reimbursement Value	: <u>S</u> \$	-
Nett Value	: <u>S\$</u>	

Description of Damage:


The vehicle sustained damages at the n/s front portion.

Repair days: 6

Comments/ Present Status:

Damages Consistent.

Yours faithfully Guo Qiang Automotive Assessor



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	9561
Vehicle Details	
Vehicle No.:	SJV1771S
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	535I M SPORT D/AB NAV DSC LED SR HUD
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	08649063N55B30A
Chassis No.:	WBA5B12010D327516
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$70,293.00
Original Registration Date:	15 Dec 2014
First Registration Date:	15 Dec 2014
Transfer Count:	1
Actual ARF Paid:	\$98,528.00
Intended PARF Rebate Details	克勒克克斯克斯特斯克斯克斯克斯克斯克斯 克斯克克斯克斯克斯克斯克斯克斯克斯克斯克斯克
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2024
PARF Rebate Amount:	\$73,896.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,904.00
COE Rebate Amount:	\$37,874.00
Total Rebate Amount:	\$111,770.00

The information contained herein is correct as at 11 Nov 2019

OK



bmw 535i Used Vehicle List (5 vehicles)

Car Model Price Depreciation **Reg Date** Eng Cap Mileage Company Availabi BMW 5 Series 535i Sunroof \$145,000 \$19,250 /yr 2,979 cc 31-Oct-2014 42,442 km Munich Alpina Pte Ltd Availal

Offer Loan Interest At 2.28%, Extremely Well Maintained, Comes With Agent Warranty 5 Years, Up To 70% Financing Possible! It's 100% Accident Free. View To Believe! Trade In Welcome Call/SMS To Arrange...

Office No. - -

Andrew - 92481159 | Ben - 91849182

BMW 5 Series 535i M-Sport \$138,800 \$18,870 /yr 27-Jun-2014 2,979 cc 46,000 km RS Autohub Pte Ltd Availal

Fully Maintained By PML, 100% Accident Free, Lowest Mileage And Highest Specs In The Market, Due To Number Retention x 1 Transfer, Original Factory Fitted M-Sports Package, M Aerodynamics Package, M-S...

Office No. - 67424232

Randy - 98892929 | James - 82232202

BMW 5 Series 535i Sunroof \$137,800 \$19,770 /yr 31-Mar-2014 2,979 cc 85,123 km Straits Drive Pte Ltd Availal

F10 Latest Facelift. High Loan Available, Well Maintained. Trade In And Auto Financing Available. Call Now For Viewing. Welcome Workshop Inspection.

Office No. - 62545817

Heng - 94456168 | Foo - 83081193

BMW 5 Series 535i Luxury \$133,800 \$19,230 /yr 24-Mar-2014 2,979 cc 81,000 km Dickson Automobile Availal

PML Facelifted 535i Luxury F10 Model, Digital Instrument Panel, Restyled Light Clusters With BMW Adaptive LED Headlight. Very Well Maintained! Extended Warranty Available! Professional Evaluation By S...

\$18,650 /yr

Office No. - 68447667

BMW 5 Series 535i Luxury

Steven Lee - 83832206 | Ricky Eng - 91853390 | Beatrice Teo - 81287619

\$128,777

Cheapest & Last Batch F10 New Face-lift Adaptive LED Headlights With Digital Speedometer Display Luxury Model With Full Serviced History

24-Feb-2014 2,979 cc

68,000 km HTS Motor

PML, Well Maintained With Genuine Low Mileage Done. 1 Years ...

Office No. - 64752126

Ken Tee - 86110661 | Jayson - 90298853

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sal even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, ca reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart, All rights reserved.

Availal

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.		
	ACCIDENT STATEMENT	
Date Of Report	07/11/2019 16:37	
Date Of Accident	07/11/2019 13:20	
Exact Location Of Accident	PIE FILTERING TO UPPER SERANGOON ROAD	
Country/State of Loss	SINGAPORE	
MCS CAN BE STORY	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJV1771S	
Insured/Policyholder		
Name Of Registered Owner	LARRY TEO SEOW PHO	

NRIC No S1200956I

Email Address LARRY.TEO@SIGNATUREFOOD.SG

Mobile Phone No (LOCAL) +65-94557117

Alternative Phone No OTHERS-93638260

Vehicle Particulars

Manufacturer BMW

Model 535I M SPORT D

Exact Purpose for which vehicle was being used at

time of accident

NORMAL USAGE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number VA1/GA336451

Cover Note Number

Driver

Name of Driver LARRY TEO SEOW PHO

 NRIC No
 \$1200956I

 Date Of Birth
 29/05/1956

 Occupation
 INDOOR

 Date Of Driving Pass
 11/06/1977

Driving Experience 42 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-94557117

Fax Number

Contact Number OTHERS-93638260

EMail Address LARRY.TEO@SIGNATUREFOOD.SG

Address 34 FLORA DRIVE #01-30

Postcode 506893

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

NO

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCW6228P

Vehicle Make/Model/Colour

VW GREY

Details Of Properties

Vehicle Category PRIVATE CAR
Name of Driver HEMAN FUNG

NRIC/Passport Number

Contact Number 91066006

Address

Postcode

Insurance Company Name SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

Page 2 of 30

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Sienzture

Date & Time: 7 NOV 2019

@1530 HPS

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Sime Darby Performance Centre Singapore 159941

erformence Motors Limited

Reporting Centre Personnel's Signature

NRIC/FIN No 303 Alexandra Road

Namel



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 7 Nov 2019, I was disting along DIE + filtering into ME (change) Upper
Savangoon Road ground 1318 hrs. Infront of me, there were many cars driving
around bokmH + I saw from my mirror, a car disting very fast betiesed
me. I kept my distant from the can infront of me, but the can behind
me just hit hard on my rear of the vehicle.
I came down to inspect the accident and the driver of the car that
hit my rear kept apologing to me that he was display too fact. We
exchanged particulars as pillows;
Name: Heman Fung Vetocle NO; SCN 6228P Mobile NO: 9106 6006
CI: DIAMTPUDIDISSAG SOMPO INSURANCE SINGAPORE PTE LTD

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 7 NOV 2019

@1530 HPS

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Name:

Reporting Centre Personnel's Signature 3 Alexandia Road NRIC/FIN Notice Darby Performance Centre

Singapore 159941

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 64796624 (AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

08 NOV 2019

ESTIMATE

Estimate No. Page No. : 1 of 5 : b1 53371

Date Estimated : 08/11/2019

Singapore 506893

Prepared By : Inthiran A/L Thurasamy

GUIDE CENTRE REAR (M)

GUIDE BOTTOM CENTRE (M)

COVERING TOWING RR PRIMED (M) / MIS

- ESTIMATE REPAIR FOR -- ACCOUNT -509 Sompo Insurance Singapore Pte Ltd Larry Teo Seow Pho 34 Flora Drive 50 Raffles Place #01-30 #05-01/06 Singapore Land Tower Singapore 048623 Singapore

REGN. NO.	CHASSIS NO. REGN	N. DATE	MODEL		MILEAG	E
SJV1771S	WBA5B12010D327516 15/	12/2014	535iA		0	
	DESCRIPTION To replace rear bumper,boot lid and repair Painting rear bumper,boot lid and tail pane		§ 3		035	VALUE 4,250.00 2,819.00
	To remove and install boot compartment control to facilitate repairs.		nish		230/	271.00
	To remove old PDC assembly, replace dar reconnect to new bumper including conduct proper function.		and		150	177.00
	To check electrical wiring systems and ligh rear section for proper function.	ntings at the			150	177.00
	To replace bootlid smart opener control un bottom sensor lines including program and proper function.		cks for		561	661.00
	To carry out body cavity preservation. (Per panel).				100	118.00
	Sundries.				?	150.00
				Total Labour	1:	8,623.00
	TAILPIPE TIP BLACK CHROME / Lat BOOTLID / DD SET MOUNTS PDC SENSOR RR (M) / RR BUMPER CARRIER / BT ADAPTOR / COVER BUMPER REAR (M) / Suttern COVER BUMPER REAR (M)		-	QTY PRIC 1 161.90 1 1,650.65 1 58.90 1 775.95 1 109.35 1 187.20		VALUE 161.90 1,650.65 1,650.65 1,775.95 109.35 187.20

80.95

69.90

57.40

80.95

69.90

₹ 57.40

1

1



A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSa: 64796624 (Motorrad



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 53371 Page No. : 2 of 5

Date Estimated

: 08/11/2019

: Inthiran A/L Thurasamy

Prepared By

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

REGN. NO. SJV1771S

WBA5B12010D327516

15/12/2014

535iA

0

DESCRIPTION PRIC VALUE QTY REAR BUMPER PANEL PRIMED (M PDC) / DE 1,768.50 1,768.50 193.15 193.15 ADAPTER (M) PLUG BLACK D=5MM 0.95 6.65 SENSOR WIRE FOR SMART OPENER TOP 43.15 43.15 SENSOR WIRE FOR SMART OPENER BOTTOM 41.50 41.50 DECOUPLING RING PDC TORQUE CONVERTE 5.10 20.40 740.00 BUMPER PDC SENSOR (A90 SOPHISTOGRAU 370.00 DM Total Parts 5,965.55



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after soray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor's Name

ano (Xil

No. of Working Days Recommend

19094.20

Labour 1 8,623.00 Parts 5,965.55 Labour 2 0.00 Excess 0.00 Total GST @ 7% 1,021.20 Grand Total 15,609.75

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. :

b1 53371

Date Estimated :

08/11/2019

Prepared By :

Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

- ACCOUNT -509

Larry Teo Seow Pho

Sompo Insurance Singapore Pte Ltd

34 Flora Drive #01-30

50 Raffles Place

Singapore

#05-01/06 Singapore Land Tower

Singapore 506893

Singapore 048623

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SJV1771S

WBA5B12010D32751 15/12/2014

535iA

0

ORIGI	NAL PRICE	DISC. %	NETT
od tail t. To	2,550.00	0	2,550.00
	2,537.00	0	2,537.00
	230.00	0	230.00
nnect	150.00	0	150.00
ion	150.00	0	150.00
ensor	561.00	0	561.00
	100.00	0	100.00
	150.00	0	150.00
UNIT PRICE	QTY	DISC. %	NETT
161.90 1,650.65 1.00 775.95 187.20 80.95 69.90 1,768.50 193.15 1.10 0.95	1.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	161.90 1,650.65 2.00 (A) 775.95 187.20 80.95 69.90 1,768.50 193.15 6.60 (A) 6.65 43.15
	UNIT PRICE 161.90 1,650.65 1.00 775.95 187.20 80.95 69.90 1,768.50 193.15 1.10	2,537.00 230.00 230.00 230.00 230.00 230.00 230.00 250.00	2,550.00 0 2,537.00 0 230.00 0 230.00 0 230.00 0 230.00 0 230.00 0 200.00 0

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

SENSOR WIRE FOR SMART OPENER BOTTOM	41.50	1.00	0	41.50
	497.05	1.00	0	497.05 (4)
# CONTROL UNIT SMART OPENER DECOUPLING RING PDC TORQUE CONVERTE	5.10	4.00	0	20.40
BUMPER PDC SENSOR (A90 SOPHISTOGRAU	370.00	2.00	0	740.00

SUPPLEMENTARY ITEMS

1	0.0	יידח לא רברי	DATE	0.113
FAY TO FAX NO		GWaian	12/12/19	6
FAX TO FAX HO				
F.3.10 F.3.10				
CONFIRME				

Total Labour : 6,428.00
Total Parts : 6,245.55
Total Labour & Parts : 12,673.55
GST @7%: 887.15
Grand Total : 13,560.70

LOSS OF USE = \$120 X 8 DAYS

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No.

b1 53371

Date Estimated:

08/11/2019

Prepared By :

Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

- ACCOUNT -

50 Raffles Place

509

Sompo Insurance Singapore Pte Ltd

Larry Teo Seow Pho

34 Flora Drive

#01-30

#05-01/06 Singapore Land Tower Singapore 048623

Singapore

Singapore 506893

REGN. DATE

MODEL

MILEAGE

REGN. NO. SJV1771S

WBA5B12010D32751

CHASSIS NO.

15/12/2014

535iA

UNIT PRICE

0

DESCRIPTION

ORIGINAL PRICE

DISC. %

DISC. %

0

0

0

NETT

NETT

DESCRIPTION # EXPANDING NUT # EXPANDING RIVET D=8MM # CONTROL UNIT SMART OPENER

1.00 1.10 497.05 2.00 6.00 1.00

QTY

2.00 6.60 497.05

SUPPLEMENTARY ITEMS

Total Labour:

Total Parts:

505.65

Total Labour & Parts:

505.65



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS/SMO19019837/Gtd3e2

50 RAFFLES PLACE

#05-	AFFLES PLACE 01/06 SAPORE LAND TO	OWERSINGAPORE 048623	Date: 13-01-2020	
אווע	SAFORE DAND IN	SWENGINGAL ONE 040025	Code: SMO	
		Policy Particulars	:- THIRD PARTY CLA	M
	Insured Veh.	SCW 6228P	Veh. Inspected	SJV 1771S
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD1905199/SYH	Excess (\$)	0.00
	Assign From	YONG KANG MELVIN	Assign Date	08/11/2019
		Vehicle Part	iculars & Condition	
	Make & Model	B.M.W. 535I	c.c	2979
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WBA5B12010D327516	Colour	GREY
	Odometer	60638	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
		Condit	tions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	275/35Z R19	DUNLOP	6 mm
	L/H Front Tyre	275/35Z R19	DUNLOP	6 mm
	R/H Rear Tyre	275/35Z R19	DUNLOP	6 mm
	L/H Rear Tyre	275/35Z R19	DUNLOP	6 mm
		Descript	ion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	EAR PORTION.	
	DAMAGES SEE D	ETAILS.		
i. ·		Genera	al Information	
	Accident Date	07/11/2019	Inspection Date	08/11/2019
	Survey held at	PERFORMANCE MOTORS LT	D	
		303 ALEXANDRA ROAD SINGAPORE 159941		
ia.			Remarks	ARL PROPERTY THE PROPERTY OF
	A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"WI CE TO YOUR INSTRUCTIONS, V	THOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
b.		Estimate	Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Day	/S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 1771S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	TAILPIPE TIP BLACK CHROME (SN)	CUT	161.90	161.90
1	BOOTLID (SN)	DENTED	1,650.65	1,650.65
1	SET MOUNTS PDC SENSOR RR (M) (SN)	NOT NECESSARY	58.90	
1	RR BUMPER CARRIER (SN)	BENT	775.95	775.95
1	ADAPTOR (SN)	NOT NECESSARY	109.35	
1	COVER BUMPER REAR (M) (SN)	CUT	187.20	187.20
1	GUIDE CENTRE REAR (M) (SN)	CRACKED	80.95	80.95
1	GUIDE BOTTOM CENTRE (M) (SN)	CRACKED	69.90	69.90
1	COVERING TOWING RR PRIMED (M) (SN)	NOT NECESSARY	57.40	
1	REAR BUMPER PANEL PRIMED (M PDC) (SN)	DEFORMED	1,768.50	1,768.50
1	ADAPTER (M) (SN)	CRACKED	193.15	193.15
7	PLUG BLACK D=5MM (SN)	NECESSARY	6.65	6.65
1	SENSOR WIRE FOR SMART OPENER TOP (SN)	DAMAGED	43.15	43.15
1	SENSOR WIRE FOR SMART OPENER BOTTOM (SN)	DAMAGED	41.50	41.50
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY	20.40	20.40
2	BUMPER PDC SENSOR (A90 SOPHISTOGRAU (SN)	DAMAGED	740.00	740.00
2	EXPANDING NUT (SN) (ADDITIONAL)	NECESSARY	2.00	2.00
6	EXPANDING RIVET D=8MM (SN) (ADDITIONAL)	NECESSARY	6.60	6.60
1	CONTROL UNIT SMART OPENER (SN) (ADDITIONAL)	DAMAGED	497.05	497.05
			6,621.20	6,395.55
	LABOUR			
	TO REPLACE REAR BUMPER, BOOT LID AND REPAIR TAIL PANEL.		4,250.00	2,550.00
	PAINTING REAR BUMPER, BOOT LID AND TAIL PANEL.		2,819.00	2,537.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	230.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNC		177.00	150.00

Report Ref No. CS/SMO19019837/Gtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

12,673.55

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.		661.00	561.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
			8,473.00	6,278.00
	GRAND TOTAL		15,094.20	12,673.55

RECOMMENDED COST OF REPAIRS

Report Ref No. CS/SMO19019837/Gtd3e2

8

XING GUO QIANG

M.MATAI, AMSAE-A

K.S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.