

#### **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2003884

INV Date 14/05/2020

Reference CC3/CTI19019854/Fea3n2

Code CT



Vehicle No. SHC 1042L

Insured Veh. SJN 5949M

Claim No. SNM19D205284C02/9

Policy No. DMPCSN3059001900

Accident Date 05/11/2019

Inspection Date 07/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile						
CHIN	HINA TAIPING INSURANCE (S) PTE LTD Ref : CC3/CTI19019854/Fea3n2						
	SON ROAD #16-0 NGLEAF TOWER	0 SINGAPORE 079909	Date: 14-05-2020 Code: CTI				
1.	1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJN 5949M	Veh. Inspected	SHC 1042L			
	Policy No.	DMPCSN3059001900	Coverage (\$)	0.00			
	Claim No.	SNM19D205284C02/9	Excess (\$)	0.00			
	Assign From		Assign Date	07/11/2019			
2.		Vehicle Partic	culars & Condition				
	Make & Model	TOYOTA PRIUS	<b>c.c</b> 1798				
	Engine No.	HIDDEN	Year of Reg. 2017				
	Chassis No.	JTDKB3FU603563924	Colour	BLUE			
	Odometer	-	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	FAIR					
3.	3. Conditions of Tyres						
-		Size	Make	Balance			
	R/H Front Tyre	195/65 R16	DAVANTI	6 mm			
	L/H Front Tyre	195/65 R16	DAVANTI	6 mm			
	R/H Rear Tyre	195/65 R16	DAVANTI	6 mm			
	L/H Rear Tyre	195/65 R16	DAVANTI	6 mm			
4.							
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S	BODY.				
	DAMAGES SEE DI						
5.			I Information				
	Accident Date	05/11/2019	Inspection Date	07/11/2019			
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969					
5a.			emarks				
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		REPAIRS.			
5b.	Estimate Days of Repair						
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	5 Working Days				



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1042L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER,RH	BUCKLED	836.70	836.70
1	REAR FENDER SHIELD (RH)	NOT NECESSARY	134.20	-
1	PANEL SUB-ASSY,FRONT DOOR,RH	DENTED	1,264.00	1,264.00
1	PANEL SUB-ASSY,REAR DOOR,RH	BUCKLED	1,258.30	1,258.30
1	REAR DOOR HINGE UPPER	NOT NECESSARY	82.30	-
1	REAR DOOR HINGE LOWER	NOT NECESSARY	82.30	-
1	REAR DOOR CHECK	NOT NECESSARY	153.00	-
1	CENTRE ROCKER PANEL (GARNISH)	CRACKED	576.00	576.00
1	REAR TYRE RIM,RH	CRACKED	1,555.08	1,555.08
1	REAR RH KNUCKLE ASSY (ADDITIONAL)	DAMAGED	810.60	810.60
1	REAR RH UPPER ARM (ADDITIONAL)	JAMMED	356.80	356.80
1	RH WHEEL BEARING HUB (ADDITIONAL)	DAMAGED	610.20	610.20
	LESS 25% DISCOUNT		-1,929.87	-1,816.92
			5,789.61	5,450.76
	SPECIAL NETT ITEMS			
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT & APPS STICKER (SN)	NECESSARY	80.00	80.00
			155.00	155.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,000.00	800.00
	SPRAY PAINTING CHARGE.		800.00	700.00
	TUFF KOTE.		50.00	30.00
	TOWING CHARGE.		60.00	60.00
	TRANSFER OF DOOR.		160.00	120.00
	REAR WHEEL ALIGNMENT.		80.00	60.00
	REMOVE/REFIX RR SUSPENSION ASST REPAIR. (ADDITIONAL).		80.00	80.00
			2,230.00	1,850.00
	GRAND TOTAL		8,174.61	7,455.76

Report Ref No. CC3/CTI19019854/Fea3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS       / 455 /6		RECOMMENDED COST OF REPAIRS			7,455.76
--	--	-----------------------------	--	--	----------

Report Ref No. CC3/CTI19019854/Fea3n2

PARASURAM S/O SHANMUGAM

**Asst. Automotive Assessor** 

mont

**HO LEONG CHUAN** 

**Automotive Assessor**