

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Yew Ah Chye

Accident Date : 25-Oct-19

Vehicle No : FBJ 895 H

Vehicle Model : Yamaha 125

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy	\$ 820 640.00 X
1	Fork under bracket	\$ 177 185.00 X
1	Front rim shaft	\$ 45 45.00 X
1	Front rim bearing	\$ 38 38.00 X
1	Front brake disc	\$ 155 155.00 X
1	Handle-bar	\$ 88 88.00 ✓
2	Handle-bar ends	\$ 32 64.00 1pc
1	Hand grip (1 set)	\$ 55 55.00 ✓
1	Handle-bar inner bracket	\$ 68 68.00 X
2	Side mirrors	\$ 55 110.00 1pc
1	Clutch lever	\$ 30 30.00 X
1	Brake lever	\$ 32 32.00 ✓
2	Front signals	\$ 140 140.00 ✓
1	Headlamp	\$ 285 285.00 ✓
1	Fairing assy (1 set)	\$ 580 580.00 ✓
1	Radiator grille cover	\$ 125 125.00 X
1	Rear footrest -R/H	\$ 40 40.00 ✓
1	Exhaust assy	\$ 485 485.00 X
1	Exhaust protector	\$ 60 60.00 ✓
1	Step board panel	\$ 285 285.00 ✓
1	Rear fender	\$ 120 120.00 X
		\$ 3,630.00
	Less 10%	\$ 363.00
		\$ 3,267.00

not Afford
2/5 \$1550/
4 day
7/11/19
take photo Afford

21512
10%
1360.80

c/f:	\$	3,267.00
------	----	----------

Special Nett Items

1	Number plate (1 set)	\$ 28.00	10
2	Fork oils	\$ 15.00	X
2	Fork oil seals	\$ 28.00	X
1	Steering cone (1 set)	\$ 90.00	X
1	Rear box	\$ 250.00	1ft
1	Rear box bracket	\$ 100.00	✓
1	ERP IU	\$ 175.00	X
1	Sticker (1 set)	\$ 95.00	✓
1	Delivery bag	\$ 600.00	DX
		\$ 1,424.00	

<u>S/No.</u>	<u>Labour</u>
--------------	---------------

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing	\$	80.00	17 X
3	To provide labour.	\$	380.00	280
4	To repair body frame.	\$	350.00	17 X
		\$	<u>860.00</u>	

Grand Total	\$	5,551.00
-------------	----	----------

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairs of the following:

- * The resurvey before/after spray painting
- * The damaged/damaged parts during resurvey
- * The resurvey subject to confirmation on a "Without prejudice" basis
- * The resurvey is allowed
- * The preliminary repairs must be resurveyed and subject to final approval of Insurer's Company

Warranted by Repairer

100