

INS. CASE OWNER: **NORSIAH**

CC4/AIG19019916/da3

LKK:
IDAC:

ASSIGNMENT

Surveyor: **MARCUS**

DOI: **11/11/2019**

Date / Time: **11.11.2019**

Registered in Merimen: **11.11.2019**

Pre-assign / CCU / FTE



Insured Vehicle No. : **SGJ 4009P**

Claim No. : **9772314680SG**

Name of Insured : **LIM LAY CHENG JESSLYN (LIN LIQING)**

Policy No. : **1800127905**

Insured Tel No. : **HP: _____**

Make / Model : **AUDI A4 SEDAN 2.0 TFSI**

Excess Sec II :SS **D.O.A: 07/11/2019 18:30**

Place of Accident : **ANG MO KIO AVE 5 JUNCTION OF CTE**

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : **HO SWEE WEE KELVIN (HE CHUIWEI)**

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : **+65-97486511 (V/L- YES / NO)**

Insured Liability : % **Final ? Yes / No**

SKP 6758T



INSRS:
WSP: **STK AUTO**
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SKP 6758T - X	SGJ 4009P - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	<input type="checkbox"/>
			After call ltr to OI:	<input checked="" type="checkbox"/>
			Authorisation To Act:	<input checked="" type="checkbox"/>
			Release Voucher:	<input checked="" type="checkbox"/>
			Final Repair Bill:	<input checked="" type="checkbox"/>
			Car Rental Invoice:	<input type="checkbox"/>
			Towing Invoice:	<input type="checkbox"/>
			LTA / GIA :	<input checked="" type="checkbox"/>
			Medical Bill:	<input type="checkbox"/>
			PIR:	<input type="checkbox"/>
			Mandate/Reject Instruction:	<input type="checkbox"/>
			LOD	<input checked="" type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/>
			Post-Repair Photos:	<input type="checkbox"/>
			Others:	<input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time:	Sent By:		
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	SS	(days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 12/12/19	Confirm with Tan Guohua	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia :	
Repair Cost:	SS 4708.00			
Loss of Rental (LOR):	SS -	(days)		
Loss of Use (LOU):	SS 480.00	(5 120 x 4 days)		
Loss of Income (LOI):	SS -	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	SS 7.45			
Medical	SS -	1) Claim status: Normal/Reject/Private Settle		
Disbursement:	SS -	(e.g. Tow/ Independent)	2) Report Format: TP	
Legal Cost	SS -	3) Survey fee: \$320		
Total:	SS 5195.45	Global Sum SS:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS 5195.45	Name 1: Stk Auto (s) pte Ltd		
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT
12/12/19

ISS. REC. BY:

REF:

Acc.

AGC/CS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKP 6758
 at Workshop m/s: STW
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKP 6758 Yr Regn: 9114
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: BMW 520i cc 1997
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 78417 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W3A5A 32060.D 335206
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/R / STD A/Rim or
 Tyre Size: F: 245/40 R19
 R: 275/35 R19

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 95
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 1953
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO
 Front 6 mm Rear 6 mm
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 7/10/19 D.O.I. 11/10/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>LTA 69989</u>
	<u>43 - \$4400 (Red \$ 6722.16 / 60%)</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Wash & Dry (\$ _____)
 Survey Fee: _____
 Transportation: _____
 S + PS \$ _____
 Phone _____
 Other _____
 Total _____

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

officer

Tel: 6256 3561

Date: 8/11/2019
To: AIG AISA PACIFIC INSURANCE PTE LTD
Attn: Motor Claim Department
Owner: LI YUAN BO

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Certificate Number: 5109233388 Accident Date: 7/11/2019
Vehicle Number: SKP6768T
Make & Model: BMW 520I

not approved
M/L

The photo after repair
4/5 @ 4460

4 days
11/11/19

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	BOOTLID <i>27/suc</i>		\$ 1,650.65	---
2	BOOT LID LOGO <i>neu</i>		\$ 75.25	---
3	BOOT LID EMBLEM ".520I" <i>neu</i>		\$ 69.45	---
4	BOOT LID LOCK <i>neu</i>		\$ 218.20	---
5	REAR BUMPER <i>7.5</i>		\$ 1,571.95	---
6	REAR BUMPER RETAINER RH <i>17</i>		\$ 193.15	X
7	REAR BUMPER RETAINER LH <i>17</i>		\$ 193.15	X
8	REAR BUMPER REINFORCEMENT <i>17</i>		\$ 775.95	X
9	REAR BUMPER REFLECTOR RH <i>17</i>		\$ 45.75	X
10	REAR BUMPER REFLECTOR LH <i>17</i>		\$ 45.75	X
11	REAR END PANEL <i>lower 2 X</i>		\$ 850.90	X
12	REAR END PANEL TOP GARNISH <i>neu</i>		\$ 120.00	X
13	EXHAUST MUFFLER <i>17</i>		\$ 1,300.90	X
	Sub Total		\$ 7,111.05	4481.45
	DISCOUTN 10% on Parts		\$ 711.11	448.15
	Total		\$ 7,822.16	4033.30
Special Nett Item				
1	REAR BUMPER SENSOR <i>should</i>		\$ 350.00	270.5.2
1	REAR BUMPER CLIPS <i>neu</i>		\$ 50.00	
1	REAR END PANEL CLIPS <i>17</i>		\$ 50.00	X 270.00
	Sub Total		\$ 450.00	
Labour & Misc				
1	LABOUR TO FACILIATE REPAIR		\$ 1,200.00	600
2	R & R REAR BOOT LID COMPAREMENT		\$ 250.00	60
4	RUST PROOF ON AFFECTED AREAS		\$ 150.00	50
5	TO SPRAY PAINT BOOT LID		\$ 250.00	
6	TO SPRAY PAINT REAR BUMPER		\$ 250.00	
7	TO SPRAY PAINT REAR FENDER RH <i>17</i>		\$ 250.00	600
8	TO SPRAY PAINT REARFENDER LH <i>17</i>		\$ 250.00	
9	TO SPRAY PAINT REAR END PANEL		\$ 250.00	
	Sub Total		\$ 2,850.00	1310.00
	Grand Total		\$ 11,122.16	5613.30 - 20% = 4490.64
				= 4400.00

- Only damaged part(s) to be surveyed
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	195B
Vehicle Details	
Vehicle No.:	SKP6758T
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	520I AT D/AB 2WD 4DR LED NAV
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	A7170668N20B20B
Chassis No.:	WBA5A32060D335206
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$44,831.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	2
Actual ARF Paid:	\$49,764.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$34,834.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,801.00
COE Rebate Amount:	\$35,155.00
Total Rebate Amount:	\$69,989.00

The information contained herein is correct as at 11 Nov 2019

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Wish For Sale



The Most Affordable!
 Depreciation For A Popular Family MPV
 Direct Owner

Browse by Category

Sort by Date Posted 40 results/page

19 vehicles

bmw 520

Advanced Search

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection bmw 520 Any Any 2014 Any Any Any Available								
	BMW 5 Series 520i Luxury	\$93,800	\$14,830 /yr	30-May-2014	1,997 cc	93,922 km	Luxury	Available
(BMW Adaptive LED Headlights With Digital Speedometer Display). Easy And Flexible In-House Loan And Balloon Scheme Available, No... Posted: 10-Nov-2019 Tags: 2014 BMW 520i, 2014 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	BMW 5 Series 520i	\$97,800	\$14,690 /yr	23-Sep-2014	1,997 cc	71,600 km	Luxury	Available
1 Owner, Agent Unit. Facelift Model. Well Maintained Interior With Immaculate Paintwork. Buy With Added Peace Of Mind From Vantage... Vantage Pre-Owned Posted: 10-Nov-2019 Tags: 2014 BMW 520i, 2014 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	BMW 5 Series 520i	\$93,800	\$14,620 /yr	26-Jun-2014	1,997 cc	55,000 km	Luxury	Available
1 Owner, Low Mileage Agent (PML) Unit, Low Depreciation, 1.98% Interest, Buy From Reputed Company, All Credit Profile Welcome, 10... Hamilton Autohub Pte Ltd Posted: 09-Nov-2019 Tags: 2014 BMW 520i, 2014 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	BMW 5 Series 520i Luxury	\$102,777	\$15,330 /yr	27-Nov-2014	1,997 cc	70,000 km	Luxury	Available
1000% Guarantee Tip-Top Condition, Super Good Deal Not To Miss. 1 & Only Real Luxury Model In Market Now, 1 & Only Unit Still Warr... HTS Motor Posted: 09-Nov-2019 Tags: 2014 BMW 520i, 2014 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	Juzz Performance Pte Ltd - Specialist for Bmw Car repair, servicing & maintenance							
Juzz Performance, a modern car garage filled with motorheads of over 20 years of experience in maintenance, repair & tuning of European makes. More info about this shop								
	BMW 5 Series 520i	\$94,500	\$14,030 /yr	31-Oct-2014	1,997 cc	85,417 km	Luxury	Available
2014 Facelift Model Come With Digital Cluster! Road Tax Until April 2020! 1 Year Warranty For Gearbox And Engine Provided.No Chests... Posted: 08-Nov-2019 Tags: 2014 BMW 520i, 2014 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	BMW 5 Series 520i	\$94,700	\$14,030 /yr	31-Oct-2014	1,997 cc	95,874 km	Luxury	Available
1 Owner Unit. 2014 Facelift Model Come With Digital Cluster! Full Agent Service Record. Road Tax End Apr 2020! 1 Year Warranty For G... Posted: 08-Nov-2019 Tags: 2014 BMW 520i, 2014 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	BMW 5 Series 520i Luxury	\$91,800	\$14,190 /yr	18-Jun-2014	1,997 cc	108,000 km	Luxury	Available
The Facelifted 520i Luxury With Digital Speedometer Display! Sleek Grey Unit With Only 1 Owner! Very Well Maintained Interior And Ext... ST Carz Pte Ltd Posted: 08-Nov-2019 Tags: 2014 BMW 520i, 2014 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW								
	BMW 5 Series 520i	\$97,000	\$15,470 /yr	23-May-2014	1,997 cc	58,000 km	Luxury	Available

Compare

Available DIRECT DRIVE

PLEASE ARRANGE TO SURVEY VEHICLE AT
 NO.8 KAKI BUKIT AVE 4 GATE 2
 #03-21
 SINGAPORE 415875

LINDA LIAO
 STK AUTO (S) PTE LTD

Date : 8/11/2019
 To : AIG AISIA PACIFIC INSURANCE PTE LTD
 Attn : Motor Claim Department

Owner : LI YUAN BO
 NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Certificate Number : 5109233388 Accident Date : 7/11/2019

Vehicle Number : SKP6758T

Make & Model : BMW 520I

Not Approved
After Repair
4/5
4 days
11/11/19

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	BOOTLID <i>27/suc</i>		\$ 1,650.65	/
2	BOOT LID LOGO <i>neu</i>		\$ 75.25	/
3	BOOT LID EMBLEM "520I" <i>neu</i>		\$ 69.45	/
4	BOOT LID LOCK <i>neu</i>		\$ 218.20	/
5	REAR BUMPER <i>7.5</i>		\$ 1,571.95	/
6	REAR BUMPER RETAINER RH <i>11</i>		\$ 193.15	X
7	REAR BUMPER RETAINER LH <i>11</i>		\$ 193.15	X
8	REAR BUMPER REINFORCEMENT		\$ 775.95	?
9	REAR BUMPER REFLECTOR RH <i>11</i>		\$ 45.75	X
10	REAR BUMPER REFLECTOR LH <i>11</i>		\$ 45.75	X
11	REAR END PANEL		\$ 850.90	?
12	REAR END PANEL TOP GARNISH		\$ 120.00	?
13	EXHAUST MUFFLER <i>11</i>		\$ 1,300.90	X
	Sub Total		\$ 7,111.05	
	DISCOUTN 10% on Parts		\$ 711.11	
	Total		\$ 7,822.16	
	Special Nett Item			
1	REAR BUMPER SENSOR <i>should</i>		\$ 350.00	220 s.w
1	REAR BUMPER CLIPS <i>neu</i>		\$ 50.00	/
1	REAR END PANEL CLIPS <i>11</i>		\$ 50.00	X
	Sub Total		\$ 450.00	
	Labour & Misc			
1	LABOUR TO FACILIATE REPAIR		\$ 1,200.00	600
2	R & R REAR BOOT LID COMPAREMENT		\$ 250.00	50
4	RUST PROOF ON AFFECTED AREAS		\$ 150.00	50
5	TO SPRAY PAINT BOOT LID		\$ 250.00	50
6	TO SPRAY PAINT REAR BUMPER		\$ 250.00	50
7	TO SPRAY PAINT REAR FENDER RH <i>11</i>		\$ 250.00	50
8	TO SPRAY PAINT REARFENDER LH <i>11</i>		\$ 250.00	50
9	TO SPRAY PAINT REAR END PANEL		\$ 250.00	50
	Sub Total		\$ 2,850.00	
	Grand Total		\$ 11,122.16	

• This estimate is based on the information provided.
 • The actual cost may vary depending on the condition of the vehicle.
 • Repairs are subject to confirmation.
 • Third party liability is on a "Without Prejudice" basis.
 • No illegal modification(s) is allowed.
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Officer

Tel: 6256 3561

Date: 8/11/2019
To: AIG AISA PACIFIC INSURANCE PTE LTD
Attn: Motor Claim Department

Owner: LI YUAN BO
NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Certificate Number: 5109233388 Accident Date: 7/11/2019

Vehicle Number: SKP6758T

Make & Model: BMW 520I

Not Approved
Mela

The photo after repair
4/5

4 days
11/11/19

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	BOOTLID <i>27/suc</i>		\$ 1,650.65	---
2	BOOT LID LOGO <i>rec</i>		\$ 75.25	---
3	BOOT LID EMBLEM ".520I" <i>rec</i>		\$ 69.45	---
4	BOOT LID LOCK <i>TW1</i>		\$ 218.20	---
5	REAR BUMPER <i>7.5</i>		\$ 1,571.95	---
6	REAR BUMPER RETAINER RH <i>17</i>		\$ 193.15	X
7	REAR BUMPER RETAINER LH <i>17</i>		\$ 193.15	X
8	REAR BUMPER REINFORCEMENT		\$ 775.95	X
9	REAR BUMPER REFLECTOR RH <i>17</i>		\$ 45.75	X
10	REAR BUMPER REFLECTOR LH <i>17</i>		\$ 45.75	X
11	REAR END PANEL		\$ 850.90	?
12	REAR END PANEL TOP GARNISH		\$ 120.00	?
13	EXHAUST MUFFLER <i>17</i>		\$ 1,300.90	X
	Sub Total		\$ 7,111.05	
	DISCOUTN 10% on Parts		\$ 711.11	
	Total		\$ 7,822.16	
Special Nett Item				
1	REAR BUMPER SENSOR <i>should</i>		\$ 350.00	220 s.w
1	REAR BUMPER CLIPS <i>rec</i>		\$ 50.00	---
1	REAR END PANEL CLIPS <i>17</i>		\$ 50.00	X
	Sub Total		\$ 450.00	
Labour & Misc				
1	LABOUR TO FACILIATE REPAIR		\$ 1,200.00	600
2	R & R REAR BOOT LID COMPAREMENT		\$ 250.00	60
4	RUST PROOF ON AFFECTED AREAS		\$ 150.00	50
5	TO SPRAY PAINT BOOT LID		\$ 250.00	
6	TO SPRAY PAINT REAR BUMPER		\$ 250.00	
7	TO SPRAY PAINT REAR FENDER RH <i>17</i>		\$ 250.00	
8	TO SPRAY PAINT REARFENDER LH <i>17</i>		\$ 250.00	
9	TO SPRAY PAINT REAR END PANEL		\$ 250.00	
	Sub Total		\$ 2,850.00	
	Grand Total		\$ 11,122.16	

- ordinary damaged part(s) on the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

- Re: SKP6758T Against SGJ4009P DOA : 07/11/2019

19916/d.

From: AIG SGP, Claims-Survey

To:

Cc: Fong, Andy-SY

Sent: 11/11/2019 8:34:39 AM

Attachments:  LTA SERACH.pdf  SKP6758T BMW 520i.jpeg  SAS2699596.PDF

Hi LKK,

9.32am @ 11/11/19

Kindly assist to survey.

p: Linda

v: Natln

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: STK STK [mailto:stkautosg@gmail.com]

Sent: Saturday, November 09, 2019 11:02 AM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] Re: SKP6758T Against SGJ4009P DOA : 07/11/2019

This message is from an external sender; be cautious with links and attachments.

Dear Motor Claim Department

Please arrange survey before repair .

Thank you

Yours sincerely

Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER

View Received Message

This mail is associated with :

***SKP6758T (9772314680SG)**
[SGJ4009P]
TP
LI YUANBO
Nov 7 2019 6:30PM
[LIM LAY CHENG JESSLYN (LIN LIQING),]
Stk Auto (s) Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/11/2019 10:50 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5115.45) - SKP6758T - Claim Handler: MdNoor, Norsiah

Approved:5115.45.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKP6758T (9772314680SG)**
[SGJ4009P]
TP
LI YUANBO
Nov 7 2019 6:30PM
[LIM LAY CHENG JESSLYN (LIN LIQING),]
Stk Auto (s) Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/12/2019 11:32 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5195.45) - SKP6758T - Claim Handler: MdNoor, Norsiah

Approved:5195.45.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Nov 2019 Edit Reg		11 Nov 2019 00:00 Edit Adj Rpt	S\$4,400.00 Edit Estimates	S\$4,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIM LAY CHENG JESSLYN (LIN LIQING), ID: 57716013B								
Main Claimant:	LI YUANBO, ID: S9181195B								
Vehicle Reg. No.:	SKP6758T	Date of Loss:	07/11/2019 18:00 - :59 [61 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9772314680SG	Policy/Cover Note No.:	1800127905-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGJ4009P	Policy No. (Claimant):	5109233388						
Repairer:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21, 415875 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (11/12/2019): Alert - Adj Mandate Approved (S\$5195.45) - SKP6758T - Claim Handler: MdNoor, Nor... AIG_SG_EXPRESS (20/11/2019): Alert - Adj Mandate Approved (S\$5115.45) - SKP6758T - Claim Handler: MdNoor, Nor... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP6758T (9772314680SG)
[SGJ4009P]
TP
LI YUANBO
Nov 7 2019 6:30PM
[LIM LAY CHENG JESSLYN (LIN LIQING),]
Stk Auto (s) Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
Assessment Reports															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	20/11/19 09:57	Adjuster Immediate Advice											Load HTM				
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
2	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
3	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
4	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
5	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
6	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
7	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
8	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
9	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
10	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
11	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
12	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
13	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
14	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
15	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
16	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
17	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
18	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
19	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
20	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
21	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
22	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
23	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
24	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
25	11/11/19 17:35	General View											Load JPG <input checked="" type="checkbox"/>				
26	11/11/19 17:35	Odometer Reading											Load JPG <input checked="" type="checkbox"/>				
27	11/11/19 17:35	Chassis Number											Load JPG <input checked="" type="checkbox"/>				
28	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
29	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
30	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
31	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
32	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
33	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
34	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
35	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
36	13/11/19 18:00	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	13/11/19 18:00	Reinspection Photo		<input checked="" type="checkbox"/>
38	13/11/19 18:00	Reinspection Photo		<input checked="" type="checkbox"/>
39	13/11/19 18:00	Reinspection Photo		<input checked="" type="checkbox"/>
40	13/11/19 18:00	Reinspection Photo		<input checked="" type="checkbox"/>
41	13/11/19 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
42	13/11/19 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
43	13/11/19 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
44	13/11/19 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
45	13/11/19 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
46	13/11/19 18:01	Reinspection Photo		<input checked="" type="checkbox"/>
47	19/11/19 16:56	After Repair Photo		<input checked="" type="checkbox"/>
48	19/11/19 16:56	After Repair Photo		<input checked="" type="checkbox"/>
49	19/11/19 16:56	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/11/19 11:57	EMAIL FROM AIG DD 11.11.19		<input type="checkbox"/>
2	11/11/19 11:57	LTA SERACH		<input type="checkbox"/>
3	11/11/19 11:57	TP ESTIMATE		<input checked="" type="checkbox"/>
4	11/11/19 11:57	TP GIA REPORT		<input type="checkbox"/>
5	14/11/19 11:31	TP ESTIMATE - MARKED		<input type="checkbox"/>
6	20/11/19 09:45	TP ESTIMATE - MARKED (FINAL)		<input type="checkbox"/>
7	20/11/19 09:45	LOD		<input type="checkbox"/>
8	20/11/19 09:45	LTA SERACH		<input type="checkbox"/>
9	31/12/19 09:55	WORKSHOP INVOICE		<input type="checkbox"/>
10	31/12/19 09:55	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
11	31/12/19 09:55	Release Voucher		<input type="checkbox"/>
12	31/12/19 09:55	LETTER TO OI		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/11/19 10:17	OI GIA REPORT		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SGJ4009P (Insd veh)	Model:	BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A)
	SKP6758T (TP veh)		
Date of Accident:	07/11/2019		

Global Sum Settlement	:	[] Yes	[X] No		
Repair Estimate	:			\$ 10,378.94	
Final Repair Cost	:			\$ 4,708.00	
Loss of Use	:			\$ 480.00	4.00 days at \$120.00 per day
Rental (if any)	:			\$ 0.00	days
LTA / GIA Search Fee	:			\$ 7.45	
Others:	:			\$ 0.00	
	:			\$	
Final Settlement Sum	:			\$ 5,195.45	
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ___100___(%)			
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	STK Auto (S) Pte Ltd	:	\$ 5,195.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

31 Dec
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019918/UDA3Q2

Date: 31/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800127905-01
Claimant
Vehicle No : SKP6758T **Insured Vehicle No :** SGJ4009P
Date of Loss: 07/11/2019 **Nature of Claim:** TP **Claim No:** 9772314680SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP6758T**
 Make & Model: BMW 520i, 2.0 AT D/AB 2WD 4DR LED NAV (A) Engine No: A7170668N20B20B
 Reg. Date: 30/09/2014 (Man. Year: 2013) Chassis No: WBA5A32060D335206
 Colour: Blue Odometer: 78417 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 275/35 R19
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	6,849.94	4,303.30	2,546.64	37.18	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,850.00	1,310.00	1,540.00	54.04	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	9,699.94	5,613.30	4,086.64	42.13	
Approved Total (Overridden) (S\$)		4,400.00			
	(S\$)	9,699.94	4,400.00	5,299.94	54.64
+ GST 7.00/7.00% (S\$)	679.00	308.00	371.00	54.64	
Nett Amount (S\$)	10,378.94	4,708.00	5,670.94	54.64	
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00			
+ Doc/Search Fee (S\$)		7.45			
Nett Liability (S\$)		5,195.45			

INSPECTION

Date of Assignment: 11/11/2019
 Date Inspected: 11/11/2019 Inspected At: Stk Auto (s) Pte Ltd (HQ)
 8 kaki bukit ave4, #03-21
 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,650.65 FL	*1,650.65 FL
2	1		*BOOT LID LOGO	Necessary	75.25 FL	*75.25 FL
3	1		*BOOT LID EMBLEM 520I	Necessary	69.45 FL	*69.45 FL
4	1		*BOOT LID LOCK	Twisted	218.20 FL	*218.20 FL
5	1		*REAR BUMPER	Distorted	1,571.95 FL	*1,571.95 FL
6	1		*REAR BUMPER RETAINER RH	Not Necessary	193.15 FL	*- FL
7	1		*REAR BUMPER RETAINER LH	Not Necessary	193.15 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Deformed	775.95 FL	*775.95 FL
9	1		*REAR BUMPER REFLECTOR RH	Not Necessary	45.75 FL	*- FL
10	1		*REAR BUMPER REFLECTOR LH	Not Necessary	45.75 FL	*- FL
11	1		*REAR END PANEL LOWER GARNISH	Necessary	120.00 FL	*120.00 FL
12	1		*REAR END PANEL	Repair	850.90 FL	*- FL
13	1		*EXHAUST MUFFLER	Not Necessary	1,300.90 FL	*- FL
14	1		*REAR BUMPER SENSOR	Shorted	350.00 FS	*220.00 FS
15	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
16	1		*REAR END PANEL CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,561.05	4,751.45
- List Item Discount on L Items 10.00/10.00% (\$\$)	711.11	448.15
Total Parts (\$\$)	6,849.94	4,303.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	600.00
2	R&R REAR BOOT LID COMPARTMENT	New	250.00	60.00
3	RUST PROOF ON AFFECTED AREAS	New	150.00	50.00
4	TO SPRAY PAINT BOOT LID }	New	250.00	600.00
5	TO SPRAY PAINT REAR BUMPER }	New	250.00	0.00
6	TO SPRAY PAINT REAR END PANEL }	New	250.00	0.00
7	TO SPRAY PAINT REAR FENDER RH	New	250.00	0.00
8	TO SPRAY PAINT REAR FENDER LH	New	250.00	0.00
Gross Labour Cost (S\$)			2,850.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >