

Surveyor: Taufikn ASSIGNMENT (Office)From (Person): Sahara of FCI Date/Time: 11.11.2019 1.24p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 1301A Insured: SHB 3041Gat Workshop m/s: Sng Ah Tu Tel: 62686183of Blk 3 Pioneer road nush #01-18Policy No: _____ Claim No: D19007010 mfs4

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3.11.2019
(Client's Record)CA / REV / REP. / REV 24 HRS ^{mp} H.O.D. Endorsement: _____Date/Time: 11.11.19 1.38p.m Person Contacted: Samantha Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 1301A - X
	SHB 3041G - X
13/11/19 @ 11.47am	revised to Sahara by email.
	Part by Part \$ 1793.30 (Red. 2830.90; 61%)


Tan/mi
ASS. REG. BY:

REF: P C 1

ASSIGNMENT

From: _____ Date: 12-11-2019
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SMD 1301A
at Workshop m/s Sng An Tee
of Blk 3 Pioneer road North #01-18
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: Audi 1000

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS mp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD1301A Yr Regn: 2018, My
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mercedes Benz C180 c.c. 1595
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 36451 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD205402K 401022
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 12/11/19
Survey held at Sng An Tee
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 DEC 2019

Date/Time, File Pass to?

1) 16/12 Typist
Date/Time, File Return to?

2)

Rep. Formet: TP

Lump Sum / Fee: 1793.30

Days Of Repair: 3

Resurvey No. of Trip: 1+1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: 135

Transportation: 50

\$ + RS. SI 50 + 50

Photos: 25

Others: _____

TOTAL

308



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007010MFSH

Date: 13 November 2019

Our Ref: CS/FCI19019927/T1tf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 1301A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/11/2019 at the premises of M/s SNG AH TEE. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,624.20</u> .
Revised Estimate Amount	: S\$ <u>2,693.30</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the n/s body.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-11-2019	Our Ref No. D19007010MFSH
Accident Date	03-11-2019	Claim Type. Third Party
Insured Vehicle	SHB3041G	Third Party Vehicle. SMD1301A
Survey Location	BLK 3 PIONEER ROAD NORTH #01-18	
Contact Person.	SAMANTHA TAN	
Contact No.	62686183/ 0	Fax No. 62681429
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 13 November 2019 11:47 AM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19007010MFSH/1
Attachments: CSFCI19019927T1tf3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SMD 1301A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 11 November 2019 1:39 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007010MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 11 November, 2019 1:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007010MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	643B

Vehicle Details

Vehicle No.:	SMD1301A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	27491031395409
Chassis No.:	WDD2050402R401022
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$37,480.00
Original Registration Date:	03 Aug 2018
First Registration Date:	03 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$44,472.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Aug 2028
PARF Rebate Amount:	\$33,354.00

Intended COE Rebate Details

COE Expiry Date:	02 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,989.00
COE Rebate Amount:	\$33,199.00
Total Rebate Amount:	\$66,553.00

Message

Transfer of ownership or deregistration is not allowed for this vehicle.

The information contained herein is correct as at 06 Nov 2019

OK

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD.

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005306

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE : 08/11/2019
 ACCIDENT DATE : 03/11/2019
 VEHICLE NO : SMD1301A
 CHASSIS/ENG.NO : WDD2050402R401022
 VEHICLE MODEL : MERCEDES C180
 CLAIM NO :
 POLICY NO :
 REMARK : 1301FIRST TP AGST SHB3041G

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** LIST PRICE **

SUB-TOTAL: 0.00

** NETT PRICE **

1	1	PC	FRT FENDER LH	937.00	10	843.30	843.30
2	1	PC	FRT FENDER INNERSHIELD LH @ FRT	130.00	10	117.00	117.00
3	1	PC	FRT FENDER INNERSHIELD LH @ RR	123.00	10	110.70	110.70
4	1	PC	FRT DOOR LH	1,850.00	10	1,665.00	1,665.00
5	2	PC	FRT DOOR HINGE	137.00	10	123.30	246.60
6	1	PC	FRT DOOR RUBBER	324.00	10	291.60	291.60
SUB-TOTAL							3,274.20

** WORK LABOUR **

TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS

TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS

650.00 650.00

700.00 700.00

SUB-TOTAL 1,350.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SAM

PAGE: 1 of 1

Acknowledged by Repairer
 Signature:

SUB-TOTAL : S\$ 4,624.20
 ADD 7% GST. S\$ 323.69
 GRAND TOTAL : S\$ 4,947.89

ON BEHALF OF SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

EST/QUOTE NO. SQ005306

DATE 08/11/2019

ACCIDENT DATE : 03/11/2019

VEHICLE NO : SMD1301A

CHASSIS/ENG.NO : WDD2050402R401022

VEHICLE MODEL : MERCEDES C180

CLAIM NO :

POLICY NO :

REMARK 1301FIRST TP AGST
SHB3041G

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** LIST PRICE **

SUB-TOTAL: 0.00

** NETT PRICE **

1	1	PC	FRT FENDER LH	937.00	10	843.30	843.30
2	1	PC	FRT FENDER INNERSHIELD LH @ FRT	130.00	10	117.00	117.00
3	1	PC	FRT FENDER INNERSHIELD LH @ RR	123.00	10	110.70	110.70
4	1	PC	FRT DOOR LH	1,850.00	10	1,665.00	1,665.00
5	2	PC	FRT DOOR HINGE	137.00	10	123.30	246.60
6	1	PC	FRT DOOR RUBBER	324.00	10	291.60	291.60

SUB-TOTAL 3,274.20

\$843.30

** WORK LABOUR **

TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS

650.00 400 650.00

TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS

700.00 450 700.00

SUB-TOTAL 1,350.00

\$950 + \$100 (additional for windscreen pillar LH)

total: \$1893.30

part by part

Please revert Elgin 06/12/2019

SAM

PAGE: 1 of 1

SUB-TOTAL : S\$ 4,624.20

ADD 7% GST. S\$ 323.69

GRAND TOTAL : S\$ 4,947.89

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19019927/T1f3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-12-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3041G	Veh. Inspected	SMD 1301A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007010MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	11/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2050402R401022	Colour	BLACK	
Odometer	36451	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/11/2019	Inspection Date	12/11/2019	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 1301A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT FENDER LH (SN)	DENTED	843.30	843.30
1	FRT FENDER INNERSHIELD LH @ FRT (SN)	NOT NECESSARY	117.00	-
1	FRT FENDER INNERSHIELD LH @ RR (SN)	NOT NECESSARY	110.70	-
1	FRT DOOR LH (SN)	TO REPAIR SEE LABOUR	1,665.00	-
2	FRT DOOR HINGE 123.30 (SN)	NOT NECESSARY	246.60	-
1	FRT DOOR RUBBER (SN)	NOT NECESSARY	291.60	-
			3,274.20	843.30
LABOUR				
	TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRT DOOR LH.		650.00	450.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		700.00	500.00
			1,350.00	950.00
GRAND TOTAL			4,624.20	1,793.30
RECOMMENDED COST OF REPAIRS				1,793.30

Report Ref No. CS/FCI19019927/T1tf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.