

SIAC

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

08/11/2019 17:40

OWNER'S PARTICULARS

JOB-NO: 50112180

NAME: CityCab PTE LTD (Fleet)  
ADDRESS: 383 SIN MING DRIVE  
SINGAPORE 575717 0

CONTACT: 65533880  
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA9567Y TRANS: AUTO  
MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT  
OWNER'S INSURER: MS First Capital Insurance Limited  
JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: JTDKB3FU903563271  
ENGINE: 2ZRS061147

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND.	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	500
2 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00		Y	60
3 R&R BOOTLID UPPER WINDSCREEN TO TRANSFER	1.00	150.00	0.00	150.00		Y	120
4 RUST PROOFING	1.00	80.00	0.00	80.00		Y	40
5 SUNDRIES	1.00	60.00	0.00	60.00		Y	20
6 RESPRAY BOOTLID	1.00	250.00	0.00	250.00		Y	200
7 RESPRAY BOOTLID SPOILER	1.00	250.00	0.00	250.00		Y	100
8 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
TOTAL:		2,190.00	0.00	2,190.00			

1240  
+  
100.00  
1340

MATERIALS

1 BOOTLID <del>bt</del>	1.00	1,113.40	278.35	835.05	L	Y	
2 BOOTLID RUBBER BEADING <del>acc</del>	1.00	389.81	97.45	292.36	L	Y	
3 BOOTLID EMBLEM-LOGO <del>new</del>	1.00	56.70	14.18	42.52	L	Y	
4 BOOTLID EMBLEM-PRIUS <del>new</del>	1.00	56.70	14.18	42.52	L	Y	
5 BOOTLID EMBLEM-HYBRID <del>new</del>	1.00	56.70	14.18	42.52	L	Y	
6 BOOTLID SPOILER <del>repair</del>	1.00	1,206.00	301.50	904.50	L	Y	2123.64
7 BOOTLID LOCK <del>X SUV</del>	1.00	452.21	113.05	339.16	L	Y	
8 BOOTLID CATCH <del>X SUV</del>	1.00	28.02	7.01	21.01	L	Y	631.04
9 BOOTLID HINGE LHS <del>X SUV</del>	1.00	89.41	22.35	67.06	L	Y	suppl
10 BOOTLID HINGE RHS <del>X SUV</del>	1.00	89.41	22.35	67.06	L	Y	2754.98
11 BOOTLID BOARD INNER GARNISH <del>cut</del>	1.00	302.30	75.58	226.72	L	Y	
12 BOOTLID WINDSCREEN BOTTOM <del>bro</del>	1.00	725.90	181.48	544.42	L	Y	
13 BOOTLID WINDSCREEN BOTTOM MLDG <del>new</del>	1.00	65.00	16.25	48.75	L	Y	
14 BOOTLID WINDSCREEN UPPER MLDG <del>new</del>	1.00	65.00	16.25	48.75	L	Y	
15 BOOTLID CARPLATE LAMP LHS <del>3x SUV</del>	1.00	160.90	40.23	120.67	L	Y	
16 BOOTLID CARPLATE LAMP RHS <del>3x SUV</del>	1.00	160.90	40.23	120.67	L	Y	
17 ADS STICKER-BOOK NOW <del>new</del>	1.00	80.00	20.00	60.00	L	Y	
18 ADS STICKER-COMFOTDELGRON <del>new</del>	1.00	80.00	20.00	60.00	L	Y	120.00
19 ADS STICKER-65521111 <del>new</del>	1.00	80.00	20.00	60.00	L	Y	180
20 REPAIR REAR BUMPER <del>R</del>	1.00	250.00	62.50	187.50	L	Y	
21 BOOTLID WINDSCREEN BOTTOM SEALANT <del>new</del>	1.00	50.00	0.00	50.00	S	Y	30
22 BOOTLID WINDSCREEN UPPER SEALANT <del>new</del>	1.00	50.00	0.00	50.00	S	Y	30
TOTAL:		5,608.36	377.12	4,231.24			

TOTAL PARTS & LABOUR : 7,798.36 1,377.12 6,421.24

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:\$ 0.00

No. Of Day: 5 days

RE-SURVEY: ~~BEFORE~~ AFTER PAINTING

~~PART-BY-PART OR LUMP SUM~~ \$

DATE OF SURVEY: 11, 11, 19 @ 1620

SURVEYED BY: RASUL

CONTACT NO: 90010068 FAX NO: \_\_\_\_\_

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED  
DAuto002  
Ding Auto User 2

ESTIMATOR  
STA AUTOCENTRE  
TEL: \_\_\_\_\_ FAX: \_\_\_\_\_

# DING AUTOMOTIVE PTE LTD

Blk 10, #01-20  
 Sin Ming Industrial Est. Sec C  
 Singapore 575645  
 Tel: 6452 1208  
 Fax: 6452 0614

Vehicle:	SHA9567Y
Model:	TOYOTA PRIUS
Chassis:	JTDKB3FU903563271

### PARTS SUPPLEMENTARY & QUOTATION FORM

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	TAIL GATE REGISTERED GARNISH <i>cr</i>	1	\$ 841.79	25%	\$ 631.34	
					PARTS \$ 631.34	

	LABOUR		PRICE	SURVEYOR MARKING
1	RESPRAY TAIL GATE REGISTERED GARNISH		\$ 250.00	<i>100</i>
TOTAL:			\$ 250.00	

PARTS	\$	631.34	
LABOUR	\$	250.00	
TOTAL	\$	881.34	

Part By Part

Labour = \$ 1340  
 S/M = \$ 180  
 Parts = \$ 2754.95  
 Lts + P = \$ 4274.95  
Final Amount = \$ 4274.95

5 days  
P/P