

11am - 12/11/19

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
 160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
 TEL: 6475 2112 FAX: 6475 4666
 WEBSITE: <http://www.ricardo.com.sg>

**QUOTATION**

M/S : HUANG WEI MING RUSSELL
 308B PUNGGOL WALK #16-388
 SINGAPORE 822308

NO: WQT0801016
 DATE: 11 Nov 2019
 A/C CODE: C014947

H/P: 96741109

YOUR REF: SMD8001U
 VEH REG NO: SMD8001U
 MAKE/MODEL: VOLVO V40 T2 (A)
 SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		S\$		S\$
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE. DOA: 11/01/2019 ACCIDENT INVOLVING: SMD8001U & SLX7821H CLAIM TYPE: 3RD PARTY CLAIM AGAINST SLX7821H (INSURED WITH AIG)				
1 TO PANEL BEAT AND SPRAY PAINT ON FRONT BUMPER.	1 SVC	400.00		400.00
Total				S\$ 400.00
Add GST @ 7%				28.00
Grand Total				S\$ 428.00

25d

TOTAL: SINGAPORE DOLLAR FOUR HUNDRED TWENTY EIGHT ONLY

HUANG WEI MING RUSSELL

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

Not Authorised
 1 day
 12/11/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: