

REF: CC3/A19/19019950/ATf3n2

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100395861

Claims No. 635006516SG

Sum Insured: _____ Excess: 0

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 87K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05/18 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFE1310B- Yr Regn: 2014 / Dec

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6. c.c. 1984.

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 62089. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU22246XEN134238.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35R20.

R: 255/35R20.

BS / DUN / EXNOVA / GY / FS / LIZA / M/C / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 11/11/19.

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD A/G.
	SFE 1310B - X
	12/11 - Revert via menmen
	MV: 87K 12/11 @ 16:01 - mandate approval set by Victor Koh
	PV: 72.8K 12/11 @ 4:05pm Inform authorise repair excess \$4007.
	Nett. 14.2K

RECEIVED 12 MAR 2020

Part by Part \$7396.16; (Red. 25365.84; 779.)

Date/Time, File Pass to?

12/13 Typist

Date/Time, File Return to?

3

Report Format: OD

Lump Sum / ①: 7396.16

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp \$☐ : Interview \$☐ : Tech. Insp \$☐ : Wheel end \$

Survey Fee:

Transportation:

S + PG \$

Flares

Others

Total

200

11

211

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 12 November 2019 4:05 PM
To: 'Claims'; Admin-D (LKKAuto); Admin A; SUR
Subject: RE: OD CLAIM FOR SFE 1310 B ON 8/11/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SFE 1310B (Excess \$0.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 12 November 2019 2:58 PM
To: Claims <claims@premiumauto.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SFE 1310 B ON 8/11/2019

Dear Calvin,

As spoken, we are still awaiting for authorization from AIG.

Enclosed estimate marking for your reference

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 12 November 2019 8:53 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

View Received Message

This mail is associated with :

***SFE1310B (68500655165G)**

OO

Nov 8 2019 9:00AM

[SUSAN SEOK CHUN YANAGIHARA]

Premium Automobiles Pte Ltd.

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/11/2019 16:01 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8379.00) - SFE1310B - Claim Handler: Chan, Yoke Shi

Approved:8379.00:Why LH rear door and handle need spray painting? No damage photos. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.



☐ Audi A6 2.0A TFSI MU \$87,800 \$13,460 /yr 30-Oct-2014 1,984 cc 44,488 km Luxury Available

Up To 100% Loan. 1 Owner. New 6 Months Roadtax. Fully Serviced By Premium Automobile Since Day 1. Receipts Attached. Original Condition. Beautiful White On Brown Interior. View To Believe It. Please Call For Viewing/Test Drive Now!

PREMIUM AD

Esteem Performance Pte Ltd

Posted: 30-Oct-2015 Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$87,800 \$13,340 /yr 28-Nov-2014 1,984 cc - Luxury Available

FIRE SALE! Price Reduced By \$3k! 1 Owner Only. Trade-In/Loan/Cash Deal Are Welcomed!

PREMIUM AD

Posted: 08-Oct-2015 Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$93,800 \$13,710 /yr 27-Feb-2015 1,984 cc 35,013 km Luxury Available

Powerful And Fuel Efficient Audi A6 Luxury Sedan Equipped With A 2L Turbo Engine And With 4 Different Driving Modes To Cater To Your Mood And Style Of Driving! Spacious And Quiet Cabin For Passengers To Travel In Luxury And Comfort! Large Boot Provide Ample Load...

PREMIUM AD

Select By Performance Premium Selection

Posted: 05-Nov-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



That's a fine looking car interior

Customise your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.

Find out more!



☐ Audi A6 2.0A TFSI MU \$89,000 \$12,800 /yr 27-Feb-2015 1,984 cc 93,000 km Luxury Available

Well Agent Maintain 1 Owner Unit. Very Smooth And Responsive Drive. Great For Everyday Driven Cars. Our Cars Comes Will Comes With New Coat Paint. Call Now To View And Test Before IT'S GONE. Trade In And Loan Available.

Posted: 26-Oct-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$89,800 \$12,900 /yr 27-Mar-2015 1,984 cc 58,000 km Luxury Available

6 Months Warranty, Excellent Condition, Accident Free, Bank Loan/In House Loan Available, Trade In Welcome.

Posted: 11-Oct-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$93,900 \$13,540 /yr 14-Apr-2015 1,984 cc 69,000 km Luxury Available

Sexy Executive Sedan! Very Well Maintained By Owner Who Is Selling Due To Upgrade, Agent Unit! Service Regularly. Owner's Second Car. Very Nice Number Plate 999x U Comes Along With It! Loan And Insurance Available, Trade Ins Always Welcome, Consignment Unit...

Prem Roy Motoring

Posted: 04-Oct-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$93,777 \$13,470 /yr 21-Apr-2015 1,984 cc 54,000 km Luxury Available

Agent Maintained. Lowest Depreciation. Road Tax Just Renewed. Powerful And Fuel Efficient Audi A6 Luxury Sedan Equipped With A 2L Turbo Engine Clean Interior, Well Maintained, View To Believe. Trade In/Scrap Available, Call Us For A Non Obligatory Viewing Now! By...

PREMIUM AD

Posted: 20-Nov-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$96,800 \$13,850 /yr 14-May-2015 1,984 cc 67,000 km Luxury Available

Minimum 12 Months Warranty, STA Certified, Attractive Financing Rates And Easy Ownership With Supreme Cars Leasing! Beautiful White Paintwork And Black Leather Interior! Trade In Available. View The Car At Our Leng Kee Showroom Today!

Supreme Cars Pte Ltd

Posted: 11-Nov-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$95,999 \$13,630 /yr 27-May-2015 1,984 cc 85,000 km Luxury Available

A White Audi A6. Immaculate Condition View To See Condition. Letting It Go Due To Changing Priorities. Well Kept And Agent Maintained. Bidded Number Plate.

URGENT OFFER

Posted: 11-Nov-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 1.8A TFSI S-tronic \$99,800 \$13,980 /yr 29-May-2015 1,798 cc 60,000 km Luxury Available

Minimum 12 Months Warranty, STA Certified, Attractive Financing Rates And Easy Ownership With Supreme Cars Leasing! Gorgeous White Paintwork And Brown Leather Interior! Trade In Available. View The Car At Our Leng Kee Showroom Today!

Supreme Cars Pte Ltd

Posted: 10-Nov-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi



☐ Audi A6 2.0A TFSI MU \$96,888 \$13,770 /yr 29-May-2015 1,984 cc 62,888 km Luxury Available

URGENT OFFER

Posted: 30-Oct-2015 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi A6, A6, A6, Used Audi

Model 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100 2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150 2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200 2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250 2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300 2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350 2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500 2501 2502 2503 2504 2505 2506 2507 2508 2509 2510 2511 2512 2513 2514 2515 2516 2517 2518 2519 2520 2521 2522 2523 2524 2525 2526 2527 2528 2529 2530 2531 2532 2533 2534 2535 2536 2537 2538 2539 2540 2541 2542 2543 2544 2545 2546 2547 2548 2549 2550 2551 2552 2553 2554 2555 2556 2557 2558 2559 2560 2561 2562 2563 2564 2565 2566 2567 2568 2569 2570 2571 2572 2573 2574 2575 2576 2577 2578 2579 2580 2581 2582 2583 2584 2585 2586 2587 2588 2589 2590 2591 2592 2593 2594 2595 2596 2597 2598 2599 2600 2601 2602 2603 2604 2605 2606 2607 2608 2609 2610 2611 2612 2613 2614 2615 2616 2617 2618 2619 2620 2621 2622 2623 2624 2625 2626 2627 2628 2629 2630 2631 2632 2633 2634 2635 2636 2637 2638 2639 2640 2641 2642 2643 2644 2645 2646 2647 2648 2649 2650 2651 2652 2653 2654 2655 2656 2657 2658 2659 2660 2661 2662 2663 2664 2665 2666 2667 2668 2669 2670 2671 2672 2673 2674 2675 2676 2677 2678 2679 2680 2681 2682 2683 2684 2685 2686 2687 2688 2689 2690 2691 2692 2693 2694 2695 2696 2697 2698 2699 2700 2701 2702 2703 2704 2705 2706 2707 2708 2709 2710 2711 2712 2713 2714 2715 2716 2717 2718 2719 2720 2721 2722 2723 2724 2725 2726 2727 2728 2729 2730 2731 2732 2733 2734 2735 2736 2737 2738 2739 2740 2741 2742 2743 2744 2745 2746 2747 2748 2749 2750 2751 2752 2753 2754 2755 2756 2757 2758 2759 2760 2761 2762 2763 2764 2765 2766 2767 2768 2769 2770 2771 2772 2773 2774 2775 2776 2777 2778 2779 2780 2781 2782 2783 2784 2785 2786 2787 2788 2789 2790 2791 2792 2793 2794 2795 2796 2797 2798 2799 2800 2801 2802 2803 2804 2805 2806 2807 2808 2809 2810 2811 2812 2813 2814 2815 2816 2817 2818 2819 2820 2821 2822 2823 2824 2825 2826 2827 2828 2829 2830 2831 2832 2833 2834 2835 2836 2837 2838 2839 2840 2841 2842 2843 2844 2845 2846 2847 2848 2849 2850 2851 2852 2853 2854 2855 2856 2857 2858 2859 2860 2861 2862 2863 2864 2865 2866 2867 2868 2869 2870 2871 2872 2873 2874 2875 2876 2877 2878 2879 2880 2881 2882 2883 2884 2885 2886 2887 2888 2889 2890 2891 2892 2893 2894 2895 2896 2897 2898 2899 2900 2901 2902 2903 2904 2905 2906 2907 2908 2909 2910 2911 2912 2913 2914 2915 2916 2917 2918 2919 2920 2921 2922 2923 2924 2925 2926 2927 2928 2929 2930 2931 2932 2933 2934 2935 2936 2937 2938 2939 2940 2941 2942 2943 2944 2945 2946 2947 2948 2949 2950 2951 2952 2953 2954 2955 2956 2957 2958 2959 2960 2961 2962 2963 2964 2965 2966 2967 2968 2969 2970 2971 2972 2973 2974 2975 2976 2977 2978 2979 2980 2981 2982 2983 2984 2985 2986 2987 2988 2989 2990 2991 2992 2993 2994 2995 2996 2997 2998 2999 3000 3001 3002 3003 3004 3005 3006 3007 3008 3009 3010 3011 3012 3013 3014 3015 3016 3017 3018 3019 3020 3021 3022 3023 3024 3025 3026 3027 3028 3029 3030 3031 3032 3033 3034 3035 3036 3037 3038 3039 3040 3041 3042 3043 3044 3045 3046 3047 3048 3049 3050 3051 3052 3053 3054 3055 3056 3057 3058 3059 3060 3061 3062 3063 3064 3065 3066 3067 3068 3069 3070 3071 3072 3073 3074 3075 3076 3077 3078 3079 3080 3081 3082 3083 3084 3085 3086 3087 3088 3089 3090 3091 3092 3093 3094 3095 3096 3097 3098 3099 3100 3101 3102 3103 3104 3105 3106 3107 3108 3109 3110 3111 3112 3113 3114 3115 3116 3117 3118 3119 3120 3121 3122 3123 3124 3125 3126 3127 3128 3129 3130 3131 3132 3133 3134 3135 3136 3137 3138 3139 3140 3141 3142 3143 3144 3145 3146 3147 3148 3149 3150 3151 3152 3153 3154 3155 3156 3157 3158 3159 3160 3161 3162 3163 3164 3165 3166 3167 3168 3169 3170 3171 3172 3173 3174 3175 3176 3177 3178 3179 3180 3181 3182 3183 3184 3185 3186 3187 3188 3189 3190 3191 3192 3193 3194 3195 3196 3197 3198 3199 3200 3201 3202 3203 3204 3205 3206 3207 3208 3209 3210 3211 3212 3213 3214 3215 3216 3217 3218 3219 3220 3221 3222 3223 3224 3225 3226 3227 3228 3229 3230 3231 3232 3233 3234 3235 3236 3237 3238 3239 3240 3241 3242 3243 3244 3245 3246 3247 3248 3249 3250 3251 3252 3253 3254 3255 3256 3257 3258 3259 3260 3261 3262 3263 3264 3265 3266 3267 3268 3269 3270 3271 3272 3273 3274 3275 3276 3277 3278 3279 3280 3281 3282 3283 3284 3285 3286 3287 3288 3289 3290 3291 3292 3293 3294 3295 3296 3297 3298 3299 3300 3301 3302 3303 3304 3305 3306 3307 3308 3309 3310 3311 3312 3313 3314 3315 3316 3317 3318 3319 3320 3321 3322 3323 3324 3325 3326 3327 3328 3329 3330 3331 3332 3333 3334 3335 3336 3337 3338 3339 3340 3341 3342 3343 3344 3345 3346 3347 3348 3349 3350 3351 3352 3353 3354 3355 3356 3357 3358 3359 3360 3361 3362 3363 3364 3365 3366 3367 3368 3369 3370 3371 3372 3373 3374 3375 3376 3377 3378 3379 3380 3381 3382 3383 3384 3385 3386 3387 3388 3389 3390 3391 3392 3393 3394 3395 3396 3397 3398 3399 3400 3401 3402 3403 3404 3405 3406 3407 3408 3409 3410 3411 3412 3413 3414 3415 3416 3417 3418 3419 3420 3421 3422 3423 3424 3425 3426 3427 3428 3429 3430 3431 3432 3433 3434 3435 3436 3437 3438 3439 3440 3441 3442 3443 3444 3445 3446 3447 3448 3449 3450 3451 3452 3453 3454 3455 3456 3457 3458 3459 3460 3461 3462 3463 3464 3465 3466 3467 3468 3469 3470 3471 3472 3473 3474 3475 3476 3477 3478 3479 3480 3481 3482 3483 3484 3485 3486 3487 3488 3489 3490 3491 3492 3493 3494 3495 3496 3497 3498 3499 3500 3501 3502 3503 3504 3505 3506 3507 3508 3509 3510 3511 3512 3513 3514 3515 3516 3517 3518 3519 3520 3521 3522 3523 3524 3525 3526 3527 3528 3529 3530 3531 3532 3533 3534 3535 3536 3537 3538 3539 3540 3541 3542 3543 3544 3545 3546 3547 3548 3549 3550 3551 3552 3553 3554 3555 3556 3557 3558 3559 3560 3561 3562 3563 3564 3565 3566 3567 3568 3569 3570 3571 3572 3573 3574 3575 3576 3577 3578 3579 3580 3581 3582 3583 3584 3585 3586 3587 3588 3589 3590 3591 3592 3593 3594 3595 3596 3597 3598 3599 3600 3601 3602 3603 3604 3605 3606 3607 3608 3609 3610 3611 3612 3613 3614 3615 3616 3617 3618 3619 3620 3621 3622 3623 3624 3625 3626 3627 3628 3629 3630 3631 3632 3633 3634 3635 3636 3637 3638 3639 3640 3641 3642 3643 3644 3645 3646 3647 3648 3649 3650 3651 3652 3653 3654 3655 3656 3657 3658 3659 3660 3661 3662 3663 3664 3665 3666 3667 3668 3669 3670 3671 3672 3673 3674 3675 3676 3677 3678 3679 3680 3681 3682 3683 3684 3685

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 11 Nov 2019

Preliminary Advice

Vehicle No	: SFE1310B	Accident Date	: 08/11/2019
Make	: AUDI A6	Policy No.	: 2100395861-04
Assignment Date	: 11/11/2019	Excess	: S\$0.00
Date of Inspection	: 11/11/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,170.00
Revised Amount	:S\$	7,708.00
Check Items (Estimated)	:S\$	400.00
Total	:S\$	8,108.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	87,000.00
COE / PARF Rebate	:S\$	72,803.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,197.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	265I
Vehicle Details	
Vehicle No.:	SFE1310B
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU (NAVIGATION)
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CDN407749
Chassis No.:	WAUZZZ4GXEN134238
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$42,589.00
Original Registration Date:	23 Dec 2014
First Registration Date:	23 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$46,625.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2024
PARF Rebate Amount:	\$34,968.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$74,000.00
COE Rebate Amount:	\$37,835.00
Total Rebate Amount:	\$72,803.00

The information contained herein is correct as at 11 Nov 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2651
Vehicle Particulars	
Vehicle No.:	SFE1310B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU (NAVIGATION)
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CDN407749
Chassis No.:	WAUZZZ4GXEN134238
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$42,589.00
Original Registration Date:	23 Dec 2014
First Registration Date:	23 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$46,625.00
Imported PARF Eligibility Particulars	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2024
PARF Rebate Amount:	\$34,968.00
Imported COE Rebate Particulars	
COE Expiry Date:	22 Dec 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$74,000.00
COE Rebate Amount:	\$37,835.00
Total Rebate Amount:	\$72,803.00

The information contained herein is correct as at 11 Nov 2019

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder	: SUSAN SEOK CHUN YANAGIHARA @CHAN SEOK CHI	Vehicle No.	: SFE1310B
Period of Insurance	: 23 Dec 2018 To 22 Dec 2019	Policy No.	: 2100395861-04
Engine No.	: CDN407749	Endorsement No.	:
Chassis No.	: WAUZZZ4GXEN134238	Issued Date	: 10 Dec 2018

ABOUT THE COVER

Make/Model	: AUDI A6 C7 2.0 TFSI MU (ULTRA EDITION)	First Year of Registration	: 2014
Engine Capacity/Tonnage	: 1,984.00 CC	Sum Insured	: Market Value
Driver Restriction	: NA	Off Peak Car	: No
Person or Classes of Persons Entitled to Drive*			

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

*You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

SUSAN SEOK CHUN YANAGIHARA @CHAN SEOK CHUN - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408689 83862323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125217

PREMIUM LEASING - EF

261 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : Susan Seok Chun Yanagihara
VEHICLE NUMBER : SFE 1310 B
DATE/ TIME OF ACCIDENT : 08 NOV 2019 About 9.30 - 9.45 am
PLACE OF ACCIDENT : PIE towards before
THIRD PARTY VEHICLE (IF ANY) :

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

Hillview Ave → Tampines

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?

No

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Side swipe

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

No injury

NAME:

Susan S. C. Yanagihara

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

UNDERTAKING


I, Susan Seok Chun Yanagihara (NRIC No. S7409265 I), hereby confirm that the Singapore Accident Statement lodged by me on 08 NOV 2019 at 1.12 pm hours pertaining to the accident involving motor car Reg. No: SFE1310 B, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature

:



Name of Insured / Driver

:

Susan Seok Chun Yanagihara

Nric No.

:

S7409265 I

Date

:

08 NOV 2019

Signature

:

Name of Policyholder

:

Nric No.

:

Date

:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :18688

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1334/2019/NS
Date	:	8-Nov-19

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Susan Seok Chun Yanagihara
Address	:	91 Hillview Avenue #09-20 Singapore 669625
Telephone	:	HP +65 97881825
Type of Claim	:	Own Damage Claim
Policy No.	:	2100395861-04
Vehicle No	:	SFE 1310 B
Model Code	:	Audi A6 C7 2.0 TFSI MU 4G
Model / Year	:	Dec-14
Engine No	:	CDN 407749
Chassis No	:	WAUZZZ4GXEN134238
Mileage	:	62089
Date In	:	8-Nov-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Nov-19
Place of Accident	:	Along PIE Toward Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 11/11/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 050 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 1310 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	X
6	To dismantle rear bumper, rear lid and lhs sill panel trim. To renew rear bumper. Cut out and weld lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$ 7,200.00	1250
7	To respray rear bumper, lhs rear fender, rear lid, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel, door handle and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 7,300.00	1100
8	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 18,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 1310 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>old</i>	\$	2,438.00 ✓
2	REAR BUMPER STICKY PAD <i>new</i>	4 \$	21.00 ✓
3	REAR BUMPER FIXING PARTS	\$	249.00 +
4	REAR BUMPER SPOILER	\$	316.00 ↓
5	REAR BUMPER SECURING STRIP	\$	157.00 ↓
6	REAR BUMPER CARRIER	\$	887.00 ↓
7	REAR BUMPER SEAL - LH	\$	13.00 ↓
8	REAR BUMPER SEAL - RH	\$	13.00 ×
9	REAR BUMPER GUIDE SECTION - LH LOWER	\$	48.00 ×
10	REAR BUMPER GUIDE PROFILE - LH / RH UPPER	2 \$	106.00 ↓
11	REAR BUMPER GUIDE SECTION - CENTRE	\$	96.00 ↓
12	REAR BUMPER GUIDE SECTION - LH / RH	2 \$	60.00 ✓
13	REAR BUMPER CONNECTING PIECE	2 \$	22.00 +
14	REAR PARKING AID SENSOR	2 \$	462.00 ×
15	REAR SIDE PANEL - LH <i>Repr</i>	\$	2,850.00 ×
16	REAR WINDSCREEN	\$	1,069.00 ×
17	PRIMER	\$	19.00 ×
18	SIDE WINDOW - LH	\$	286.00 ×
19	SIDE WINDOW TRIM STRIPS - LH	\$	235.00 ×
20	A6 INSCRIPTION <i>Not New</i>	\$	87.00 ↓
SUB TOTAL SPARE PARTS		:	<u>\$ 9,434.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 1310 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	AUDI EMBLEM	\$ 113.00	+
22	2.0 T INSCRIPTION	\$ 87.00	+
23	CLIP ATTACHMENT PARTS	\$ 96.00	+
24	ADHESIVE TAPE ATTACHMENT PARTS	\$ 15.00	+
25	LED TAIL LIGHT - LH OUTER	\$ 1,149.00	✓
26	TAIL LIGHT COVER - LH OUTER	\$ 43.00	+
27	LED TAIL LIGHT - LH INNER	\$ 1,149.00	✓
28	TAIL LIGHT TRIM - LH INNER	\$ 27.00	+
29	REAR WHEEL HOUSING LINER - LH	\$ 256.00	+
30	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 72.00	+
31	EXTERIOR DOOR HANDLE TRIM PLATE - LH	\$ 410.00	+
32	EXTERIOR DOOR HANDLE CAP - LH	\$ 79.00	+
33	ACRYLIC SEALANT	S/N \$ 180.00	+
34	CAVITY WAX	S/N \$ 140.00	X
35	STONE CHIP	S/N \$ 180.00	X
36	METAL FILLER POWDER	S/N \$ 280.00	X
37	REAR WINDSCREEN SEALANT	S/N \$ 200.00	+
38	1/4 GLASS SEALANT	S/N \$ 100.00	+
39	SUNDRIES	\$ 400.00	?

TOTAL SPARE PARTS	:	\$ 14,410.00
TOTAL LABOUR CHARGES	:	\$ 2,760.00
GRAND TOTAL	:	\$ 17,170.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 1310 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function	S/N	\$ 360.00 ✓	✓
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N	\$ 600.00 ✗	
3	To install rear windscreen solar film.	S/N	\$ 400.00 ✗	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00 ✗	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,760.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 1310 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N S 1,400.00	X
6	To dismantle rear bumper, rear lid and lhs sill panel trim. To renew rear bumper. Cut out and weld lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	S 7,200.00	1250
7	To respray rear bumper, lhs rear fender, rear lid, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel, door handle and end panelling. To carry out stone chip treatment and joint sealer works.	S 7,300.00	1750 / 3 x 550 = 1650 + 100 Handle = 100
8	To carry out diagnostic check.	S/N S 192.00	/
TOTAL LABOUR CHARGES		: \$ 18,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 1310 B

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
1	REAR BUMPER <i>old</i>	S	2,438.00	✓ 1950 40
2	REAR BUMPER STICKY PAD <i>new</i>	4 S	21.00	+
3	REAR BUMPER FIXING PARTS	S	249.00	+
4	REAR BUMPER SPOILER	S	316.00	+
5	REAR BUMPER SECURING STRIP	S	157.00	+
6	REAR BUMPER CARRIER	S	887.00	+
7	REAR BUMPER SEAL - LH	S	13.00	+
8	REAR BUMPER SEAL - RH	S	13.00	+
9	REAR BUMPER GUIDE SECTION - LH LOWER	S	48.00	+
10	REAR BUMPER GUIDE PROFILE - LH / RH UPPER	2 S	106.00	+
11	REAR BUMPER GUIDE SECTION - CENTRE	S	96.00	+
12	REAR BUMPER GUIDE SECTION - LH / RH	2 S	60.00	+
13	REAR BUMPER CONNECTING PIECE	2 S	22.00	+
14	REAR PARKING AID SENSOR	2 S	462.00	+
15	REAR SIDE PANEL - LH <i>new</i>	S	2,850.00	+
16	REAR WINDSCREEN	S	1,069.00	+
17	PRIMER	S	19.00	+
18	SIDE WINDOW - LH	S	286.00	+
19	SIDE WINDOW TRIM STRIPS - LH	S	235.00	+
20	A6 INSCRIPTION <i>new</i>	S	87.00	+
SUB TOTAL SPARE PARTS			<u>S 9,434.00</u>	

Premium Automobiles

55 Ulu Road 1, Singapore 408599
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 1310 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	AUDI EMBLEM	S	113.00 +
22	2.0 T INSCRIPTION	S	87.00 ✓
23	CLIP ATTACHMENT PARTS	S	96.00 +
24	ADHESIVE TAPE ATTACHMENT PARTS	S	15.00 ✓
25	LED TAIL LIGHT - LH OUTER	S	1,149.00 ✓ 919.20
26	TAIL LIGHT COVER - LH OUTER	S	43.00 ✓ 33.84
27	LED TAIL LIGHT - LH INNER	S	1,149.00 ✓ 919.20
28	TAIL LIGHT TRIM - LH INNER	S	27.00 ✓ 21.50
29	REAR WHEEL HOUSING LINER - LH	S	256.00 ✓
30	WHEEL HOUSING LINER ATTACHMENT PARTS	S	72.00 +
31	EXTERIOR DOOR HANDLE TRIM PLATE - LH	S	410.00 +
32	EXTERIOR DOOR HANDLE CAP - LH	S	79.00 +
33	ACRYLIC SEALANT	S/N S	180.00 +
34	CAVITY WAX	S/N S	140.00 ✓
35	STONE CHIP	S/N S	180.00 ✓
36	METAL FILLER POWDER	S/N S	280.00 ✓
37	REAR WINDSCREEN SEALANT	S/N S	200.00 ✓
38	1/4 GLASS SEALANT	S/N S	100.00 ✓
39	SUNDRIES	S	400.00 ✓

TOTAL SPARE PARTS

: \$ 14,410.00

TOTAL LABOUR CHARGES

: \$ 2,760.00

GRAND TOTAL

: \$ 17,170.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

33262

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan King
Surveyed Date : 11/11/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 050 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :18688

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1334/2019/NS
Date : 8-Nov-19

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Susan Seok Chun Yanagihara
Address : 91 Hillview Avenue
#09-20
Singapore 669625
Telephone : HP +65 97881825
Type of Claim : Own Damage Claim
Policy No. : 2100395861-04
Vehicle No : **SFE 1310 B**
Model Code : Audi A6 C7 2.0 TFSI MU 4G
Model / Year : Dec-14
Engine No : CDN 407749
Chassis No : WAUZZZ4GXEN134238
Mileage : 62089
Date In : 8-Nov-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Nov-19
Place of Accident : Along PIE Toward Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 1310 I

S/N	Nature of Jobs	Esti Ch
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function	S/N \$
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$
3	To install rear windscreen solar film.	S/N \$
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$
SUB TOTAL LABOUR CHARGES		: \$ 2,;

1,063.66

q

0
0.0

360.++
1,250.++
1,100.++
192.++
=
2,902.++

0.0

2,438.++
1,149.++
43.++
1,149.++
27.++
=
4,806.++
4,806.++
2,902.++
=
7,708.++

0.0

400.++

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :18688

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1334/2019/NS
Date	:	8-Nov-19

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

5 days - ok - Jy - 10 Jan 2020

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Susan Seok Chun Yanagihara
Address	:	91 Hillview Avenue #09-20 Singapore 669625
Telephone	:	HP +65 97881825
Type of Claim	:	Own Damage Claim
Policy No.	:	2100395861-04
Vehicle No	:	SFE 1310 B
Model Code	:	Audi A6 C7 2.0 TFSI MU 4G
Model / Year	:	Dec-14
Engine No	:	CDN 407749
Chassis No	:	WAUZZZ4GXEN134238
Mileage	:	62089
Date In	:	8-Nov-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Nov-19
Place of Accident	:	Along PIE Toward Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 1310 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function	S/N	\$ 360.00	\$ 360.00
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N	\$ 600.00	
3	To install rear windscreen solar film.	S/N	\$ 400.00	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	
SUB TOTAL LABOUR CHARGES		:	\$ 2,760.00	\$ 360.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 1310 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 360.00
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	
6	To dismantle rear bumper, rear lid and lhs sill panel trim. To renew rear bumper. Cut out and weld lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$	7,200.00	\$ 1,250.00
7	To respray rear bumper, lhs rear fender, rear lid, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel, door handle and end panelling. To carry out stone chip treatment and joint sealer works.	\$	7,300.00	\$ 1,750.00
8	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 18,852.00	\$ 3,552.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 1310 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,438.00	\$ 1,950.40
2	REAR BUMPER STICKY PAD	4 \$ 21.00	
3	REAR BUMPER FIXING PARTS	\$ 249.00	
4	REAR BUMPER SPOILER	\$ 316.00	
5	REAR BUMPER SECURING STRIP	\$ 157.00	
6	REAR BUMPER CARRIER	\$ 887.00	
7	REAR BUMPER SEAL - LH	\$ 13.00	
8	REAR BUMPER SEAL - RH	\$ 13.00	
9	REAR BUMPER GUIDE SECTION - LH LOWER	\$ 48.00	
10	REAR BUMPER GUIDE PROFILE - LH / RH UPPER	2 \$ 106.00	
11	REAR BUMPER GUIDE SECTION - CENTRE	\$ 96.00	
12	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 60.00	
13	REAR BUMPER CONNECTING PIECE	2 \$ 22.00	
14	REAR PARKING AID SENSOR	2 \$ 462.00	
15	REAR SIDE PANEL - LH	\$ 2,850.00	
16	REAR WINDSCREEN	\$ 1,069.00	
17	PRIMER	\$ 19.00	
18	SIDE WINDOW - LH	\$ 286.00	
19	SIDE WINDOW TRIM STRIPS - LH	\$ 235.00	
20	A6 INSCRIPTION	\$ 87.00	
SUB TOTAL SPARE PARTS		\$ 9,434.00	\$ 1,950.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 1310 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 1,950.40
21	AUDI EMBLEM	\$ 113.00	
22	2.0 T INSCRIPTION	\$ 87.00	
23	CLIP ATTACHMENT PARTS	\$ 96.00	
24	ADHESIVE TAPE ATTACHMENT PARTS	\$ 15.00	
25	LED TAIL LIGHT - LH OUTER	\$ 1,149.00	\$ 919.20
26	TAIL LIGHT COVER - LH OUTER	\$ 43.00	\$ 33.84
27	LED TAIL LIGHT - LH INNER	\$ 1,149.00	\$ 919.20
28	TAIL LIGHT TRIM - LH INNER	\$ 27.00	\$ 21.52
29	REAR WHEEL HOUSING LINER - LH	\$ 256.00	
30	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 72.00	
31	EXTERIOR DOOR HANDLE TRIM PLATE - LH	\$ 410.00	
32	EXTERIOR DOOR HANDLE CAP - LH	\$ 79.00	
33	ACRYLIC SEALANT	S/N \$ 180.00	
34	CAVITY WAX	S/N \$ 140.00	
35	STONE CHIP	S/N \$ 180.00	
36	METAL FILLER POWDER	S/N \$ 280.00	
37	REAR WINDSCREEN SEALANT	S/N \$ 200.00	
38	1/4 GLASS SEALANT	S/N \$ 100.00	
39	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		\$ 14,410.00	\$ 3,844.16
TOTAL LABOUR CHARGES		\$ 18,852.00	\$ 3,552.00
GRAND TOTAL		\$ 33,262.00	\$ 7,396.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFE 1310 B

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1334/2019/NH

From
Telephone +65 -
Telefax +65 -
Mobile +65 -
Our Dept
Email

11-Mar-2020

Date
Total Pages

Dear Sir,

RE: INSURANCE CLAIM FOR SFE 1310 B, Audi A6 C7 2.0 TFSI MU

Premium Automobiles Pte Ltd,
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SFE 1310 B**, claimant, **Ms. Susan Seok Chun Yanagihara**, please find the related document as attached.

1. A copy of the Original invoice no. 85014980 – S\$ 7,913.89
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SFE 1310 B

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 6828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:46

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014980 Date: 10/03/2020 Order: SFE1310B Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SFE1310B (V 23444)	Regn Date: 23/12/2014	Mileage: 62081	WIP No.: 18688
Model: A6 C7 2.0 TFSI MU 4G20TH (YOM	Chassis: WAUZZZ4GXEN134236	Engine: CDN 407749	Dept: U
You have been assisted by :- UB-Melvin Khoo (138)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER,REAR LID AND LHS SILL PANEL TRIM.TO RENEW REAR BUMPER. CUT OUT AND WELD LHS REAR FENDER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,LHS REAR FENDER, LHS REAR DOOR AND DOOR HANDLE.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORK	1750.00	1.00	1,750.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4G5945095A	TAIL LIGHT	1.00	1149.00	919.20
X	A4G5853267	(A) (SK)COVER 13/11/1	1.00	42.30	33.84
X	A4G5945093A	TAIL LIGHT(LAST)	1.00	1149.00	919.20
X	A4G5945255	(A) (SK)TRIM 13/11/19	1.00	26.90	21.52
X	A4G5807067B GRU	COVER	1.00	2438.00	1,950.40
Sub-Total					7,396.16
7% GST					517.73
Grand Total					7,913.89

Parts 3,844.16
Labour 0.00
Sublet 3,552.00
Menus 0.00
Lubricant 0.00



10/3

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SFE 1310 B

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1334/2019/KK
15 November 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI MU
Vehicle Chassis No. : WAUZZZ4GXEN134238
Vehicle Regn No. : SFE 1310 B
Vehicle Mileage : 62089 KM
Vehicle Owner : Ms. Susan Seok Chun Yanagihara
Certificate No : 2100395861-04
Own Damage Excess : S\$ 0.00 (inclusive 7% GST)
Accident Date : 8 Nov 2019
Place : Along PIE Towards Changi
Repair Cost : \$ 7913.89
WIP No. : 18688
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____
Time : _____
Date : _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Nov 2019 17:36		11 Nov 2019 16:30 Edit Adj Rpt	S\$7,396.16 Edit Estimates	S\$7,396.16 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	SUSAN SEOK CHUN YANAGIHARA, ID: S74092651, Tel: +6597881825, Email: YANAGI@SINGNET.COM.SG		
Vehicle Reg. No.:	SFE1310B	Date of Loss:	08/11/2019 09:00 - :59 [58 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 6850065516SG	Policy/Cover Note No.:	2100395861 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/11/2019]		
Driver/Custodian:	SUSAN SEOK CHUN YANAGIHARA (45 / Female) , NRIC: S74092651, Tel: +6597881825 Email: YANAGI@SINGNET.COM.SG		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (12/11/2019): Alert - Adj Mandate Approved (S\$8379.00) - SFE1310B - Claim Handler: Chan, Yoke ...
- AIG_SG (12/11/2019): SFE1310B / OD / 08/11/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFE1310B (6850065516SG)
OD
Nov 8 2019 9:00AM
[SUSAN SEOK CHUN YANAGIHARA]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
Video					1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print	
1	08/11/19 15:52	Video - Accident [Linked Accident Report Documents]	1	Load MP4		
Assessment Reports					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	11/11/19 17:40	Adjuster Immediate Advice	1	Load HTM		
2	12/11/19 15:38	Adjuster Immediate Advice	1	Load HTM		
Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	11/11/19 17:31	General View	1	Load JPG	☒	
2	11/11/19 17:31	General View	1	Load JPG	☒	
3	11/11/19 17:31	General View	1	Load JPG	☒	
4	11/11/19 17:31	General View	1	Load JPG	☒	
5	11/11/19 17:31	General View	1	Load JPG	☒	
6	11/11/19 17:31	General View	1	Load JPG	☒	
7	11/11/19 17:31	General View	1	Load JPG	☒	
8	11/11/19 17:31	General View	1	Load JPG	☒	
9	11/11/19 17:31	General View	1	Load JPG	☒	
10	11/11/19 17:31	General View	1	Load JPG	☒	
11	11/11/19 17:31	General View	1	Load JPG	☒	
12	11/11/19 17:31	General View	1	Load JPG	☒	
13	11/11/19 17:31	General View	1	Load JPG	☒	
14	11/11/19 17:31	General View	1	Load JPG	☒	
15	11/11/19 17:31	General View	1	Load JPG	☒	
16	11/11/19 17:31	General View	1	Load JPG	☒	
17	11/11/19 17:31	General View	1	Load JPG	☒	
18	11/11/19 17:31	General View	1	Load JPG	☒	
19	11/11/19 17:31	General View	1	Load JPG	☒	
20	11/11/19 17:31	General View	1	Load JPG	☒	
21	11/11/19 17:31	General View	1	Load JPG	☒	
22	11/11/19 17:31	General View	1	Load JPG	☒	
Documentation					1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	11/11/19 17:31	UNDER TAKING AND INTERVIEW	1	Load PDF		
2	11/11/19 17:31	Certificate of Insurance	1	Load PDF		
3	11/11/19 17:31	Driver's Driving License	1	Load PDF		
4	11/11/19 17:31	Singapore Accident Statement	1	Load PDF		
5	12/11/19 15:27	ESTIMATE	1	Load PDF		
6	13/03/20 13:21	WORKSHOP INVOICE	1	Load PDF		
7	13/03/20 13:21	DISCHARGE VOUCHER	1	Load PDF		

Linked Accident Report Documents

View [View in Browser](#)

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/11/19 15:52	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 19:15	Accident Statement	 Load HTM	
2	06/12/19 19:17	Accident Statement	 Load HTM	
3	06/12/19 19:17	Accident Statement	 Load HTM	
4	06/12/19 19:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/11/19 15:49	Accident Photo	 Load JPG	☒
2	08/11/19 15:49	Accident Photo	 Load JPG	☒
3	08/11/19 15:49	Accident Photo	 Load JPG	☒
4	08/11/19 15:49	Accident Photo	 Load JPG	☒
5	08/11/19 15:49	Accident Photo	 Load JPG	☒
6	08/11/19 15:49	Accident Photo	 Load JPG	☒
7	08/11/19 15:49	Accident Photo	 Load JPG	☒
8	08/11/19 15:49	Accident Photo	 Load JPG	☒
9	08/11/19 15:49	Accident Photo	 Load JPG	☒
10	08/11/19 15:49	Accident Photo	 Load JPG	☒
11	08/11/19 15:49	Accident Photo	 Load JPG	☒
12	08/11/19 15:49	Accident Photo	 Load JPG	☒
13	08/11/19 15:49	Accident Photo	 Load JPG	☒
14	08/11/19 15:49	Accident Photo	 Load JPG	☒
15	08/11/19 15:49	Accident Photo	 Load JPG	☒
16	08/11/19 15:49	Accident Photo	 Load JPG	☒
17	08/11/19 15:49	Accident Photo	 Load JPG	☒
18	08/11/19 15:49	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/11/19 15:53	Sketch Plan	 Load JPG	☒
2	08/11/19 15:53	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19019950/ATF3N2

Date: 13/03/2020

REFERENCE

Insured/Claimant: SUSAN SEOK CHUN YANAGIHARA

Policy No: 2100395861

Date of Loss: 08/11/2019

Nature of Claim: OD

Claim No: 6850065516SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFE1310B

Make & Model: AUDI A6, 2.0 TFSI MU (A)

Engine No: CDN407749

Reg. Date: 23/12/2014 (Man. Year: 2014)

Chassis No: WAUZZZ4GXEN134238

Colour: Black

Odometer: 62089 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$87,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35R20

Rear Tyre Size: 255/35R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,410.00	3,844.16	10,565.84	73.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,852.00	3,552.00	15,300.00	81.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,262.00	7,396.16	25,865.84	77.76
+ GST 7.00/7.00% (S\$)	2,328.34	517.73	1,810.61	77.76
Nett Amount (S\$)	35,590.34	7,913.89	27,676.45	77.76

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,438.00 FS	*1,950.40 FS
2	4		*REAR BUMPER STICKY PAD	Not Necessary	21.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	316.00 FS	*- FS
5	1		*REAR BUMPER SECURING STRIP	Not Necessary	157.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	887.00 FS	*- FS
7	1		*REAR BUMPER SEAL-LH	Not Necessary	13.00 FS	*- FS
8	1		*REAR BUMPER SEAL-RH	Not Necessary	13.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION-LH LOWER	Not Necessary	48.00 FS	*- FS
10	2		*REAR BUMPER GUIDE PROFILE-LH/RH UPPER	Not Necessary	106.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION-CENTRE	Not Necessary	96.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	60.00 FS	*- FS
13	2		*REAR BUMPER CONNECTING PIECE	Not Necessary	22.00 FS	*- FS
14	2		*REAR PARKING AID SENSOR	Not Necessary	462.00 FS	*- FS
15	1		*REAR SIDE PANEL-LH	Repair	2,850.00 FS	*- FS
16	1		*REAR WINDSCREEN	Not Necessary	1,069.00 FS	*- FS
17	1		*PRIMER	Not Necessary	19.00 FS	*- FS
18	1		*SIDE WINDOW-LH	Not Necessary	286.00 FS	*- FS
19	1		*SIDE WINDOW TRIM STRIPS-LH	Not Necessary	235.00 FS	*- FS
20	1		*A6 INSCRIPTION	Not Necessary	87.00 FS	*- FS
21	1		*AUDI EMBLEM	Not Necessary	113.00 FS	*- FS
22	1		*2.0 T INSCRIPTION	Not Necessary	87.00 FS	*- FS
23	1		*CLIP ATTACHMENT PARTS	Not Necessary	96.00 FS	*- FS
24	1		*ADHESIVE TAPE ATTACHMENT PARTS	Not Necessary	15.00 FS	*- FS
25	1		*LED TAIL LIGHT-LH OUTER	Cracked	1,149.00 FS	*919.20 FS
26	1		*TAIL LIGHT COVER-LH OUTER	Cut	43.00 FS	*33.84 FS
27	1		*LED TAIL LIGHT-LH INNER	Cracked	1,149.00 FS	*919.20 FS
28	1		*TAIL LIGHT TRIM-LH INNER	Cut	27.00 FS	*21.52 FS
29	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	256.00 FS	*- FS
30	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
31	1		*EXTERIOR DOOR HANDLE TRIM PLATE-LH	Not Necessary	410.00 FS	*- FS
32	1		*EXTERIOR DOOR HANDLE CAP-LH	Not Necessary	79.00 FS	*- FS
33	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
34	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
35	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
36	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
38	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 14,410.00 3,844.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
2	TO DISMANTLE REAR BUMPER,REAR LID AND LHS SILL PANEL TRIM,TO RENEW REAR BUMPER.CUT OUT AND WELD LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	7,200.00	1,250.00
3	TO RESPRAY REAR BUMPER,LHS REAR FENDER,REAR LID,LHS REAR DOOR,LHS SILL PANEL,DOOR ENTRANCES,ROOF CHANNEL,DRAIN PANEL,DOOR HANDLE AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	7,300.00	1,750.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
6	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
7	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	0.00
8	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
Gross Labour Cost (\$\$)			18,852.00	3,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >