

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Nov 2019)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH7012C/22/11/2019 11:51**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRT FENDER EMBLEM RH <i>new</i>	20.00	0.00	*53.50 FL	
						Sub Total (\$)	53.50
						- List Item Discount on L Items (\$)	10.70
						Total Parts (\$)	42.80

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH7012C/22/11/2019 11:51. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**