



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Attn: Taufikh
7 days Final Bill
TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ang Choon Hin 286 Bishan Street 24 #13-90 Singapore 570286
	Document No 38044833	Mobile: 96182259
	Document Date 20/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	29/07/2019	SMN9668L	1704	50408	650D/SMN9668L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004711	8ARZ161448	60	Francis Cher T S	15/11/2019 15.33	17/12/2019 16.47		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSN1930651900 ACC DATE:09.11.19 TOW/DRIVE IN: EXCESS:\$750 DATE-IN: DATE SURVEY:12.11.19 NO OF REPAIR DAYS:7 DAYS BY:TAUFIKH (LKK) AUTHORISED ON:15.11.19 2.50PM	*			50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)	*			100.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.	*			180.00
4	B	BP-MECH2 RESET AND REPROGRAMME ECU.	18			180.00
5	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, BONNET, FRT SUPPORT PANEL, L/F FENDER AND AFFECTED PORTION OF CAR.	*			2880.00
6	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			2360.00
7	V	EXC Excess element of insurance repair to be paidby the insured party	88			-750.00
8	1	T53301-48170 HOOD SUB-ASSY	1.00	1983.90		1983.90
9	2	T75770-48060 MOULDING ASSY, HOOD,	1.00	567.50		567.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128163005;
PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/12/2019
TIME 11:34

413005;

VEHICLE NO SMN9668L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ang Choon Hin 286 Bishan Street 24 #13-90 Singapore 570286
	Document No 38044833	Mobile: 96182259
	Document Date 20/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	29/07/2019	SMN9668L	1704	50408 650D/SMN9668L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004711	8ARZ161448	60	Francis Cher T S	15/11/2019 15.33	17/12/2019 16.47		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	3	T53101-48920	GRILLE SUB-ASSY,	1.00	1351.40	1351.40
11	4	T52119-4D946	COVER, FR BUMPER	1.00	811.30	811.30
12	5	S52161-0K040	PIECE, RR BUMPER	4.00	4.10	16.40
13	6	T52535-48040	RETAINER, FR BUMPER	1.00	115.20	115.20
14	7	T52536-48030	RETAINER, FR BUMPER	1.00	115.20	115.20
15	8	T53812-48190	PANEL, FR FENDER, LH	1.00	1446.30	1446.30
16	9	T53102-48081	GRILLE SUB-ASSY,	1.00	417.70	417.70
17	0	T52701-48010	MOULDING SUB-ASSY,	1.00	465.60	465.60
18	1	T52411-48050	GUARD, FR BUMPER	1.00	340.20	340.20
19	2	T89341-48040 C3	SENSOR, ULTRASONIC,	1.00	481.90	481.90
20	3	T81185-48E40	UNIT, HEADLAMP LH	1.00	6714.50	6714.50
21	4	T90467-07217	CLIP	6.00	2.50	15.00
22	5	T81145-48E40	UNIT, HEADLAMP RH	1.00	6714.50	6714.50
23	6	T52614-48050	ABSORBER, FR BUMPER	1.00	112.20	112.20
24	7	T52029-48010	REINFORCEMENT	1.00	301.10	301.10
25	8	T52612-48050	ABSORBER, FR BUMPER	1.00	49.80	49.80
26	9	T53208-48091	SUPPORT SUB-ASSY,	1.00	407.30	407.30
27	0	T52538-48040	RETAINER, FR BUMPER	1.00	117.40	117.40
28	1	T16695-36140	PLATE, RADIATOR SIDE	1.00	53.70	53.70
29	2	T16697-36070	PLATE, RADIATOR SIDE	1.00	90.90	90.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462 413005.
PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/12/2019
TIME 11:34

413005.

VEHICLE NO SMN9668L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Page 2 of 3
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ang Choon Hin 286 Bishan Street 24 #13-90 Singapore 570286
	Document No 38044833	
	Document Date 20/12/2019	Mobile: 96182259

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	29/07/2019	SMN9668L	1704	50408 650D/SMN9668L

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTEZB3GH10J004711	8ARZ161448	60	Francis Cher T S	15/11/2019 15.33	17/12/2019 16.4

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	3	T52134-48070 REINFORCEMENT, FR	1.00	69.80		69.80
31	4	T52537-48040 RETAINER, FR BUMPER	1.00	117.40		117.40
32	5	T52618-48030 ABSORBER, FR BUMPER,	1.00	172.00		172.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 23,048.20	28,048.2
		Labour 5,750.00	GST 7.00%
		Materials 0.00	1,963.3
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 30,011.5

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462
PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.


DATE 20/12/2019
TIME 11:34

413005

VEHICLE NO SMN9668L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors