

22/03/2002

ASS. REC. BY:

REF:

CS/ICS19020053/EF304

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Elizabeth Chw My Lai

of ECICS

Date/Time: 12.11.19 2.46 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMP 4080D

Insured:

SLC 7500J

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Durandray Rd

Policy No:

Claim No:

DMP C19002884

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.11.19

2.14 p.m

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMP 4080D X

SLC 7500J X

4/2-

Revert via menmen preli advise.

Part by Part \$5,151.30

RES. REC. BY: Steve

REF:

JCS

ASSIGNMENT

From:

Date:

2/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMP 40800

at Workshop m/s

performance Motor

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Han

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMP 40800

Yr Regn:

25/9/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216

C.C.

1499

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

4188

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA 6V12 0505 P00000

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R17

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

9/11/19

D.O.I.

2/12/19

Survey held at

Performance Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-119K

16/12/19 Final/le \$5151.30, 5 days Cred: 3327.05: 39%

RECEIVED 17 DEC 2019

Date/Time, File Pass to?



Preli. Report



Final Report

1) 11/12 Typist

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

290

Transportation:

S + RS. \$

Photos

Others:

TOTAL

11

261

Report Format:

TP

Lump Sum / L.B.B.:

5,151.30

Nivitha (LKK Auto)

From: Elizabeth Chew Ming Lai (ECICS, Claims) <Elizabeth_Chew@ecics.com.sg>
Sent: Tuesday, 12 November 2019 2:46 PM
To: pml-pbsp@simedarby.com.sg
Cc: Admin-D (LKKAuto); SUR; assignments
Subject: FW: REQUEST FOR DIRECT SETTLEMENT - SMP4080D & SLE7500J ON 09/11/2019
ECICS REF: DMPC1900288H
Attachments: SKM_558e19111207280.pdf; SMP4080D.PDF

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Caroline,

We refer to the above matter.

Without prejudice to any other related claims we agree to have a direct settlement with your company on behalf of our insured, subject to our surveyor's recommendation on costs of repair and number of days for LOU/LOR. As for quantum on the LOU/LOR we follow the NIMA Protocol Benchmark.

Kindly forward us all the supporting document to enable us to consider your client's claim.

Aside to LKK, please refer to the below email and conduct PRI.

We shall forward the documents to you shortly.

Thank you.

Best regards

Elizabeth Chew

AVP | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email elizabeth_chew@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Tuesday, 12 November 2019 10:08 AM
To: ECICS Claims
Subject: Fw: REQUEST FOR DIRECT SETTLEMENT - SMP4080D & SLE7500J ON 09/11/2019

From: PBSP
Sent: Tuesday, 12 November 2019 8:31 AM

To: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>

Subject: REQUEST FOR DIRECT SETTLEMENT - SMP4080D & SLE7500J ON 09/11/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

A member of the Sme Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : b1 53398
Date Estimated : 11/11/2019
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -
Huang Junhao, Willy
341 Upper Bukit Timah Road
#03-04

Singapore 588195

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P0000	25/09/2019	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including to knock out bootlid and dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,700.00	0	1,700.00 ✓
To respray rear bumper and bootlid.	1,731.00	0	1,731.00 ✓
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
Sundries.	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (BLACK)	72.20	1.00	0	72.20 ✓
REAR BUMPER PANEL PRIMED (LINES PDC	1,045.45	1.00	0	1,045.45 ✓
LETTERING 216 I	64.45	1.00	0	64.45 ✓
GROMMET	0.80	2.00	0	1.60 ✓
PLAQUE 74MM	71.60	1.00	0	71.60 ✓

Total Labour :	3,811.00
Total Parts :	1,255.30
Total Labour & Parts :	5,066.30
GST @7%:	354.64
Grand Total :	5,420.94

LOSS OF USE = \$80 X 5 DAYS
GIA SEARCH FEE - \$2.00

DATE	TIME	NAME
12/19	15:12	Steve LFK
		4

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	885D
Vehicle Details	
Vehicle No.:	SMP4080D
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	216I GRAN TOURER
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	39475754B38A15A
Chassis No.:	WBA6V120505P00000
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$31,966.00
Original Registration Date:	25 Sep 2019
First Registration Date:	25 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$36,753.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2029
PARF Rebate Amount:	\$27,564.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,759.00
COE Rebate Amount:	\$31,159.00
Total Rebate Amount:	\$58,723.00

The information contained herein is correct as at 02 Dec 2019

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 04 Dec 2019

Preliminary Advice

Insured Vehicle No	: SLE7500J	Accident Date	: 09/11/2019
TP Vehicle No	: SMP4080D	Assignment Date	: 12/11/2019
Make	: BMW 216D	Est. Duration of Repair	: 4.00
Date of Inspection	: 02/12/2019		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,393.35
Revised Amount	:S\$	5,066.30
Check Items (Estimated)	:S\$	2,188.30
Total	:S\$	7,254.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2019 11:21
Date Of Accident	09/11/2019 20:30
Exact Location Of Accident	BUKIT PANJANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP4080D
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	HUANG JUNHAO WILLY
NRIC No	S8441885D
Email Address	WILLYNMELIE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96321374
Alternative Phone No	OTHERS- 96321374 96521374

Vehicle Particulars

Manufacturer	BMW
Model	216
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V12099
Cover Note Number	

Driver

Name of Driver	HUANG JUNHAO WILLY
NRIC No	S8441885D
Date Of Birth	30/12/1984
Occupation	INDOOR
Date Of Driving Pass	15/03/2005
Driving Experience	14 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96321374
Fax Number	
Contact Number	OTHERS-96321374
Email Address	WILLYNMELIE@GMAIL.COM

Address	341 UPPER BUKIT TIMAH ROAD #03-04
Postcode	588195
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : YEONG MAY YAN MELISSA GENDER: : FEMALE
Passenger 2	NAME: : HUANG ENYA MEREDITH GENDER: : FEMALE
Passenger 3	NAME: : HUANG ENYU WYNSTAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG-BURN CD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE7500J
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG KOK YONG
NRIC/Passport Number	S7822644G

Contact Number

85884047

Address

BLK 645 WOODLANDS RING RD #10-14

Postcode

730645

Insurance Company Name

ECICS LIMITED

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
Policyholder's Signature

Date & Time:

11/11/19 (9.56am)

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 9th NOV 2019, around 8:30pm my vehicle (SMP40800) REAR WAS HIT by a Toyota AHTIS (SLE 7500J). Before the accident my car is ~~at~~ stationary waiting at a red traffic light along Bukit PANJANG Rd before Bangkit Rd travelling toward Bukit Panjang Hawker centre direction.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

11/11/19 (9.56am)

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

12 NOV 2019

E S T I M A T E

Estimate No. : b1 53398
Date Estimated : 11/11/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Huang Junhao, Willy
341 Upper Bukit Timah Road
#03-04

Singapore 588195

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P00000	25/09/2019	216i GT	0

DESCRIPTIONVALUE

To replace rear bumper & attachments including to knock out
boot lid and dented area caused by the accident

1700 2,550.00

To respray rear bumper and boot lid

1731 1,923.00

To replace bootlid smart opener top and
bottom sensor lines including program and conduct checks for
proper function.

X ? 661.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 5,568.00

DESCRIPTIONQTY PRICVALUE

REAR BUMPER CARRIER	1	460.40	460.40
SUPPORT	1	45.55	45.55
# RR BUMPER LH INNER SIDE GUID	1	61.35	61.35
# RR BUMPER RH INNER SIDE GUID	1	61.35	61.35
REAR BUMPER TOWING FLAP EYE PRIMED	1	43.05	43.05
REAR BUMPER TRIM STRIP (BLACK)	1	72.20	72.20
REAR BUMPER PANEL PRIMED (LINES PDC	1	1,045.45	1,045.45
LETTERING 216 I	1	64.45	64.45
GROMMET	2	0.80	1.60
PLAQUE 74MM	1	71.60	71.60
REAR BUMPER HEAT INSULATION	1	63.50	63.50
SENSOR WIRE FOR SMART OPENER TOP	1	43.15	43.15
SENSOR WIRE FOR SMART OPENER BOTTOM	1	41.50	41.50
DECOUPING RING PDC TORQUE CONVERTER	2	5.10	10.20
ULTRASONIC SENSOR IMPERIALBLAU(WA89	2	370.00	740.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53398**
Date Estimated : **11/11/2019**
Prepared By : **Han Kwan Yong**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P00000	25/09/2019	216i GT	0

Total Parts : **2,825.35**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Handwritten signature]
4/12/19

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 2/12/19, 11 am Excess S\$ _____

Surveyor's Name Star CLKK Sign _____

Surveyor's Tel _____ Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

intl April
5 days
P/P
Ry Bel sy

8478.35

Labour 1	:	5,568.00
Parts	:	2,825.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	8393.35 587.53
Grand Total	:	8,980.88

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53398**
Date Estimated : **11/11/2019**
Prepared By : **Han Kwan Yong**

Page No. : **3 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P00000	25/09/2019	216i GT	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53398**
Date Estimated : **11/11/2019**
Prepared By : **Han Kwan Yong**

Page No. : **4 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P00000	25/09/2019	216i GT	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53398**
Date Estimated : **11/11/2019**
Prepared By : **Han Kwan Yong**

Page No. : **5 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P00000	25/09/2019	216i GT	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pml.com.sg

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report 2 with Coating

Estimate No. : **b1 53398**
Date Estimated : **11/11/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Huang Junhao, Willy
341 Upper Bukit Timah Road
#03-04

Singapore 588195

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P0000	25/09/2019	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including to knock out bootlid and dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,700.00	0	1,700.00
To respray rear bumper and bootlid.	1,731.00	0	1,731.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00
# To carry out Paint Coating (by Owner)	85.00	0	85.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (BLACK)	72.20	1.00	0	72.20
REAR BUMPER PANEL PRIMED (LINES PDC	1,045.45	1.00	0	1,045.45
LETTERING 216 I	64.45	1.00	0	64.45
GROMMET	0.80	2.00	0	1.60
PLAQUE 74MM	71.60	1.00	0	71.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary 2

Estimate No. : **b1 53398**
Date Estimated : **11/11/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Huang Junhao, Willy
341 Upper Bukit Timah Road
#03-04

Singapore 588195

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP4080D	WBA6V120505P0000	25/09/2019	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To carry out Paint Coating (by Owner)	85.00	0	85.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	85.00
Total Parts :	
Total Labour & Parts :	85.00

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Total Labour :	3,896.00
Total Parts :	1,255.30
Total Labour & Parts :	5,151.30
GST @7%:	360.59
Grand Total :	5,511.89

Note : add in Paint Coating

		steve	15/12/19	S
		LFR		
CALC NO		steve	27/12/19	
CA				
D				
E				
F				

JERGA DETAILS

UEN: 201736810K

61 Woodlands Industrial Park E9, E9 Premium, #01-02 Singapore 757047

Invoice

Date : 18/12/19
Invoice Number : 18/12/19-9
Car Brand & Model, Colour, License Plate : Bmw 2GT, BLUE
SMP 4080D

Description	Amount
<p>1. Paint Protection Coating</p> <p><input type="checkbox"/> a. CAMUI CC4</p> <p><input type="checkbox"/> b. CAMUI Golden Expresser</p> <p><input checked="" type="checkbox"/> c. ULTIMEA Self Heal Coating <i>Both and Rear bumper</i></p>	
<p>2. Platinum99 Solar Film</p> <p><input type="checkbox"/> Full Car <input type="checkbox"/> Half Car</p> <p><input type="checkbox"/> Others</p> <p>Remarks: _____</p>	
<p>3. Transition Solar Film</p> <p><input type="checkbox"/> Full Car <input type="checkbox"/> Half Car</p> <p><input type="checkbox"/> Others</p> <p>Remarks: _____</p>	
<p>4. Paint Protection Film (ULTIMEA FusionUltra Pro)</p> <p><input type="checkbox"/> a. Full Car</p> <p><input type="checkbox"/> b. Full Front</p> <p><input type="checkbox"/> c. 4 Doors</p> <p><input type="checkbox"/> d. Others</p> <p>Remarks: _____</p>	
<p>5. Others</p> <p><input type="checkbox"/> a. Remarks: _____</p>	

Total Amount Payable: 985

JERGA PTE. LTD.
UEN REG NO.
201736810K

Company Stamp

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2019 11:21 Edit Reg		12 Nov 2019 00:00 Edit Adj Rpt	S\$5,151.30 Edit Estimates	S\$5,151.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	HUANG JUNHAO WILLY, ID: S8441885D, Email: WILLYNMELIE@GMAIL.COM								
Main Claimant:	HUANG JUNHAO WILLY, ID: S8441885D								
Vehicle Reg. No.:	SMP4080D	Date of Loss: 09/11/2019 20:00 - :59 [1 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SLE7500J	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 21/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMP4080D
[SLE7500J]
TP
HUANG JUNHAO WILLY
Nov 9 2019 8:00PM
[HUANG JUNHAO WILLY]
Performance Motors Limited

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) v

Assessment Reports				1 per page v	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/19 11:31	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	02/12/19 16:58	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
5	02/12/19 16:58	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
6	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	02/12/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	16/12/19 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
28	16/12/19 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	16/12/19 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	16/12/19 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	16/12/19 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	16/12/19 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	16/12/19 19:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/19 11:18	Singapore Accident Statement	1	Load PDF	
2	04/12/19 11:18	ESTIMATE	1	Load PDF	
3	30/12/19 12:55	Supplementary	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19020053/ETF3E2

Date: 30/12/2019

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant

Vehicle No : SMP4080D

Insured Vehicle No : SLE7500J

Date of Loss: 09/11/2019

Nature of Claim:

TP

Claim No: DMPC1900288H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMP4080D

Make & Model: BMW 216D, 1.5 D Gran Tourer (A)

Engine No: 39475754B38A15A

Reg. Date: 25/09/2019 (Man. Year: 2019)

Chassis No: WBA6V120505P00000

Colour: Blue

Odometer: 4188 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,905.35	1,335.30	1,570.05	54.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,573.00	3,816.00	1,757.00	31.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,478.35	5,151.30	3,327.05	39.24
+ GST 7.00/7.00% (S\$)	593.48	360.59	232.89	39.24
Nett Amount (S\$)	9,071.83	5,511.89	3,559.94	39.24

INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 02/12/2019 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2019)
Parts:	M1-MPV	BMW 216D 1.5 D Gran Tourer (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP4080D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Not Necessary	460.40 FS	*- FS
3	1		*SUPPORT	Not Necessary	45.55 FS	*- FS
4	1		*#RR BUMPER LH INNER SIDE GUID	Not Necessary	61.35 FS	*- FS
5	1		*#RR BUMPER RH INNER SIDE GUID	Not Necessary	61.35 FS	*- FS
6	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	43.05 FS	*- FS
7	1		*REAR BUMPER TRIM STRIP (BLACK)	Cut	72.20 FS	*72.20 FS
8	1		*REAR BUMPER PANEL PRIMED (LINES PDC	Dented	1,045.45 FS	*1,045.45 FS
9	1		*LETTERING 216 I	Necessary	64.45 FS	*64.45 FS
10	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
11	1		*PLAQUE 74MM	Necessary	71.60 FS	*71.60 FS
12	1		*REAR BUMPER HEAT INSULATION	Not Necessary	63.50 FS	*- FS
13	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	43.15 FS	*- FS
14	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	41.50 FS	*- FS
15	2		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	10.20 FS	*- FS
16	2		*ULTRASONIC SENSOR IMPERIALBLAU (WA89	Not Necessary	740.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **2,905.35** **1,335.30**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT BOOT LID AND DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	1,923.00	1,731.00
3	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	0.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO CARRY OUT PAINT COATING (BY OWNER)	New	85.00	85.00
Gross Labour Cost (\$\$)			5,573.00	3,816.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >