

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:30

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014956	Account: A0006 (T 0)
		Date : 05/03/2020	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
		Order : SGJ4009P	
		Term : 30	

Regn No: SGJ4009P (V 39487)	Regn Date: 26/10/2018	Mileage: 19746	WIP No.: 18793
Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV,	Chassis: WAUZZZF40JA231825	Engine: CVK 068777	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-550.00	1.00	-550.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHT,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND HEADLIGHT.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER. PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	960.00	1.00	960.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE FRONT BUMPER REINFORCEMENT BRACKETS RENEWAL	1000.00	1.00	1,000.00
S	BODYWORK	M: TO REPAIR RHS FRONT FENDER	250.00	1.00	250.00
S	BODYWORK	M: TO RESPRAY RHS FRONT FENDER	550.00	1.00	550.00
X	A8W0807065D GRU	(A) (SK)COVER 25/11/1	Less 020%	1.00	1999.00
X	A8W0807683 9B9	GRILLE(LAST)	Less 020%	1.00	178.00
X	A8W0853651A 3FZ	(A) (SK)GRILLE 25/11/	Less 020%	1.00	1227.00
X	A8W0807113	BRACKET	Less 020%	1.00	732.50
X	A8W0807550A	FOAM INSER(LAST)	Less 020%	1.00	113.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 16:30

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014956 Date : 05/03/2020 Order : SGJ4009P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SGJ4009P (V 39487) Regn Date: 26/10/2018 Mileage: 19746 WIP No.: 18793

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF40JA231825 Engine: CVK 068777 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	A8W0807081	COVER(SHARE) AP	Less 020%	1.00	115.50	92.40
X	A8K0010520A	STICKER AP	Less 020%	1.00	12.20	9.76
X	A8W0010515A	STICKER AP	Less 020%	1.00	6.40	5.12
X	A8W0807771	(SK)BRACKET AP	Less 020%	1.00	125.00	100.00
X	A8W0823029A	HOOD(LAST)	Less 020%	1.00	2554.00	2,043.20
X	A8W0823124	(SK) PROTECTION	Less 020%	1.00	24.70	19.76
X	A8W0823126	(SK) PROTECTION	Less 020%	1.00	24.70	19.76
X	A8W0823125	(A) (SK) PROTECTION 25	Less 020%	1.00	24.90	19.92
X	A8W0823529E	(SK)BOWD CABLE AP	Less 020%	1.00	52.10	41.68
X	A8W0941774A	HEADLIGHT AP	Less 020%	1.00	7087.00	5,669.60
X	A8W0807133	BRACKET AP	Less 020%	1.00	206.50	165.20
X	A8W0807134	BRACKET AP	Less 020%	1.00	206.50	165.20
X	AN 10036203	BOLT AP	Less 020%	4.00	12.60	40.32
X	AN 02300311	NUT AP	Less 020%	4.00	0.50	1.60
X	A8K0805399B	BOLT AP	Less 020%	4.00	1.60	5.12
X	AN 91178401	BOLT AP	Less 020%	8.00	3.80	24.32
X	AN 91093901	POP-RIVET AP	Less 020%	4.00	0.70	2.24
X	A8W0820536	BRACKET AP	Less 020%	1.00	16.30	13.04
X	A8W0121674A	AIR DUCT AP	Less 020%	1.00	10.40	8.32
X	A8W0816421J	CONDENSER AP	Less 020%	1.00	567.50	454.00
X	A3D0260749C	WASHER AP	Less 020%	1.00	4.00	3.20
X	A4E0260749A	WASHER AP	Less 020%	1.00	3.60	2.88
X	A7H0820896	SEAL RING AP	Less 020%	1.00	2.50	2.00

Parts 12,308.24
Labour 0.00
Sublet 5,822.00
Menus 0.00
Lubricant 0.00

Sub-Total 17,580.24

7% GST 1,230.62

Grand Total 18,810.86



Received by

For & on behalf of
Premium Automobiles Pte Ltd