

ASSIST. REC. BY:

Rasul

REF:

AIG

CC3/AIG19020118/Rlyf3

8304

2016 SS
\$1600f

ASSIGNMENT

From:

Date:

13. 11. 2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGL 2617L

at Workshop m/s

Premium

of 24 Benji Sector

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$1600f

(Client's Record)

Make of Veh:

mummy

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

181K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGL 2617L

Yr Regn:

2016 / MUMY SS

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A7 SB 2.0 TFSI (LED) C.C. 1984

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

27511

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAW 2224976N 094008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

255/40R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/11/19

D.O.I.

13/11/19

Survey held at

PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SGL2617L-X

14/11/19

Revert via Merimen

15/11/19

Approval Mandate by Cherry Lois - KL

15/11/19

Submit and sent to Authorise to Premium

09/6

Confirm final fig \$25881-20 sent by email / (Red \$30894-80, 54%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

9/7/20 Typist

Rep. Forms:

Lump Sum / L.B. / C.

PIP \$25881-20

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(Pending Mandate Request)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Nov 2019		13 Nov 2019 13:28		S\$0.00 View Rpt		Pending Mandate Request Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	BARRY JOSEPH O'DONNELL, ID: S2750830H, Tel: +6596559556, Email: SUZANNA@I-RESEARCH.SG		
Vehicle Reg. No.:	SGL2617L	Date of Loss:	11/11/2019 15:00 - :59 [41 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 4476788883SG	Policy/Cover Note No.:	2100466246 (Comprehensive)
		Excess:	S\$1,600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Khoo, Kay-Eng - 6419 1026] Kay-Eng.Khoo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/11/2019]		
Driver/Custodian:	BARRY JOSEPH O'DONNELL (62 / Male), NRIC: S2750830H, Tel: +6596559556 Email: SUZANNA@I-RESEARCH.SG		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (14/11/2019): SGL2617L / OD / 11/11/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 15, 2019 1:30 PM
To: Claims; SUR
Subject: RE: OD CLAIMS FOR SGL 2617 L

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SGL2617L (**excess \$1600/-**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Friday, November 15, 2019 10:24 AM
To: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR SGL 2617 L

Dear Yvonne,

Any update?

Thanks

Best Regards,

TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khoo, Kay-Eng

Date: 14 Nov 2019

Preliminary Advice

Vehicle No	: SGL2617L	Accident Date	: 11/11/2019
Make	: AUDI A7	Policy No.	: 2100466246
Assignment Date	: 13/11/2019	Excess	: S\$1,600.00
Date of Inspection	: 13/11/2019	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	56,776.00
Revised Amount	:S\$	29,878.20
Check Items (Estimated)	:S\$	2,391.00
Total	:S\$	32269.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	181,000.00
COE / PARF Rebate	:S\$	88,997.00
Salvage Value	:S\$	
Margin for Repair	:S\$	92,003.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Yvonne Wong (LKK Auto)

From: PAL Claim <claims@premiumauto.com.sg>
Sent: Friday, January 31, 2020 5:14 PM
To: Rasul (LKKAuto)
Cc: Claims
Subject: SGL 2617 L - Labour
Attachments: 2617.pdf; WhatsApp Image 2019-11-18 at 4.14.18 PM.jpeg; WhatsApp Image 2019-11-18 at 4.14.24 PM.jpeg; WhatsApp Image 2019-11-18 at 4.14.32 PM.jpeg

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Rasul,

Attached here are the damage photo for SGL 2617 L. Supplementary labour line need to mark back and sent back to us for reference.
Kindly have your approval additional 2 days repair duration.

Best Regards,

Raymond Ting
Estimator

Premium Automobiles Pte Ltd (Reg No 199902271W)
24 Benoi Sector, Singapore 629857
p. +65 6474 3323 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/11/2019 11:26
Date Of Accident	11/11/2019 15:00
Exact Location Of Accident	YOTEL HOTEL CARPARK ENTRANCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL2617L
Insured/Policyholder	
Name Of Registered Owner	BARRY JOSEPH O'DONNELL
NRIC No	S2750830H
Email Address	SUZANNA@I-RESEARCH.SG
Mobile Phone No	(LOCAL) +65-96559556
Alternative Phone No	OFFICE-96559556

Vehicle Particulars

Manufacturer	AUDI
Model	A7 SB 2.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100466246-03
Cover Note Number	

Driver

Name of Driver	BARRY JOSEPH O'DONNELL
NRIC No	S2750830H
Date Of Birth	05/01/1957
Occupation	INDOOR
Date Of Driving Pass	25/09/2007
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96559556
Fax Number	
Contact Number	OFFICE-96559556
Email Address	SUZANNA@I-RESEARCH.SG

Address	14 HOLLAND
Postcode	276137
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I ACCIDENTALLY HIT THE PILLAR WHILE I WAS TURNING RIGHT TOWARDS THE CAR PARK ENTRANCE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)



I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Wendy Lillian Seck, George
NRIC/FIN No.: G124871432

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I accidentally hit the pillar while I was turning right toward the carpark Entrance

DECLARATION

I/We declare the foregoing particulars are true in every respect.

3091

Policyholder's Signature
Date & Time:

L201C TestPlatform V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Date & Time:

Reporting Centre Personnel's Signature

Name: **WONG HONG, SENG, George**
NRIC/FIN No.: **G29871431**

NRIC/FIN No.: G2987143A



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : Barry Joseph O' Donnell
VEHICLE NUMBER : SGL 26172
DATE/ TIME OF ACCIDENT : 11/11/19 @ 1500
PLACE OF ACCIDENT : Yotel hotel, carpark Entrance
THIRD PARTY VEHICLE (IF ANY) : N/A

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

from Tanglin mall, pick up my wife at Yotel and go to
UWC Dover road.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?


NO

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

collided with the pillar and Damaged front LHS of ~~the~~ my car.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO


NAME: Barry Joseph O' Donnell

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

UNDERTAKING

I, Barry Joseph O'Donnell (NRIC No.: S27508307A), hereby confirm that the Singapore Accident Statement lodged by me on 12/11/19 at 830am hours pertaining to the accident involving my motor car no.: SG1 2617L, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I hereby confirm that I have not been subjected to any breathalyser test or blood test for alcohol in respect of this accident on 11/11/19 and no action has been taken or will be taken against me for driving whilst under the influence of alcohol in respect to this accident.

I further irrevocably undertake to absolve my insurer, AIG ASIA PACIFIC INSURANCE PTE LTD from any liability whatsoever in the event that I consciously derogate from my report which I had given to AIG ASIA PACIFIC INSURANCE PTE LTD and during any court proceedings concerning the accident involving my motor car no. SG1 2617L along Yotel hotel, carpark Entrance at about 1500 hours and in such event, hereby irrevocably undertake to indemnify my insurers from all their costs and expenses of and incidental to the matters herein.

Signature

: 

Name of Insured/Driver: Barry Joseph O'DONNELL

NRIC No

: S27508307A

Date

: 12/11/19



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : BARRY JOSEPH O'DONNELL
Period of Insurance : 17 May 2019 To 16 May 2020
Engine No. : CYP006638
Chassis No. : WAUZZZ4G7GN094008

Vehicle No. : SGL2167L
Policy No. : 2100466246-03
Endorsement No. :
Issued Date : 22 Apr 2019

ABOUT THE COVER

Make/Model : AUDI A7 (PI) SPORTBACK 2.0 TFSI
Engine Capacity/Tonnage : 1,984.00 CC Sum Insured : Market Value First Year of Registration : 2016
Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes
Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

BARRY JOSEPH O'DONNELL - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125211

PREMIUM LEASING - NC

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCFKJ

REPUBLIC OF SINGAPORE DRIVING LICENCE


Licence Number: **S2750830H**

Name: **BARRY JOSEPH O'DONNELL**

Birth Date: **06 Jan 1957**

Issue Date: **08 Aug 2011**

001989276J




YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars < 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg

25 Sep 2007

NP 428A

Licence No: S2750830H



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	830H
Vehicle Details	
Vehicle No.:	SGL2617L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Nov 2019
Vehicle Make:	AUDI
Vehicle Model:	A7 SB 2.0 TFSI (LED)
Primary Colour:	Beige
Manufacturing Year:	2015
Engine No.:	CYP006638
Chassis No.:	WAUZZZ4G7GN094008
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$56,899.00
Original Registration Date:	17 May 2016
First Registration Date:	17 May 2016
Transfer Count:	0
Actual ARF Paid:	\$74,419.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2026
PARF Rebate Amount:	\$55,814.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$33,183.00
Total Rebate Amount:	\$88,997.00

The information contained herein is correct as at 14 Nov 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1352/2019/GW
Date	:	12-Nov-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Barry Joseph O'Donnell
Address	:	14 Holland Green Singapore 276137
Telephone	:	HP +65 96559556
Type of Claim	:	Own Damage Claims
Policy No.	:	2100466246-03
Vehicle No	:	SGL 2617 L
Model Code	:	A7 SB 2.0 TFSI
Model / Year	:	May-16
Engine No	:	CYP006638
Chassis No	:	WAUZZZ4G7GNN094008
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Nov-19
Place of Accident	:	YOTEL HOTEL, CARPARK ENTRANCE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGL 2617 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlights washer assy and front parking aid.	S/N \$ 480.00 /	\$480-00
2	To remove and reinstall air cond condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 X	
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00 /	\$300-00
4	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,780.00 1500	\$1750-00
5	To respray front bumper, lhs front fender, bonnet and lhs front door.	\$ 4,800.00 2200	\$2200-00
6	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 X	
7	To carry out diagnostic check.	S/N \$ 192.00 /	\$19200
TOTAL LABOUR CHARGES		: \$ 14,202.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>den</i> ✓	\$ 2,909.00 ✓	\$2327.20
2	FRONT BUMPER GRILLE <i>X</i>	\$ 139.00 X	
3	FRONT BUMPER FIXING PARTS <i>?</i>	\$ 251.00	
4	FRONT BUMPER ADAPTER -LH <i>X</i>	\$ 34.00 ✓	\$27.12
5	FRONT BUMPER CLOSING ELEMENT <i>X</i>	\$ 191.00 X	
6	FRONT BUMPER SPOILER <i>X</i>	\$ 227.00 X	\$1164.00
7	RADIATOR GRILLE <i>Cra</i> ✓	\$ 1,455.00 ✓	
8	RADIATOR GRILLE COVER <i>X</i>	\$ 49.00 X	
9	CATCH FOR RADIATOR-LH/RH <i>X</i>	2 \$ 36.00 X	\$215.20
10	LICENCE PLATE HOLDER <i>X</i>	\$ 564.00 X	
11	FRONT BUMPER GRILLE-LH <i>sub</i> ✓	\$ 269.00 ✓	
12	FRONT BUMPER END CAP-LH <i>X</i>	\$ 53.00 ✓	\$41.92
13	FRONT BUMPER WHEEL SPOILER -LH <i>Cra</i> ✓	\$ 349.00 ✓	
14	FRONT STONE CHIP GUARD-LH <i>X</i>	\$ 66.00 ✓	\$52.72
15	ADHESIVE TAPE <i>den</i> ✓	\$ 50.00 ✓	
16	FRONT BUMPER COVER <i>Cra</i> ✓	\$ 116.00 ✓	\$92.40
17	FOAM FILLER PIECE <i>?</i>	\$ 174.00 X	
18	FRONT BUMPER REINFORCEMENT BAR <i>bt</i> ✓	\$ 754.00 ✓	\$21.20
19	FRONT BUMPER BRACE-LH <i>bt</i> ✓	\$ 27.00 ✓	
20	FRONT BUMPER GUIDE PIECE-LH <i>Cra</i> ✓	\$ 40.00 ✓	\$31.52
SUB-TOTAL SPARE PARTS		\$ 7,753.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT BUMPER HOLDER-LH ?	\$	237.00
22	AIR CONDITIONER STICKER <i>rec</i> ✓	\$	18.00 ✓ <i>\$14-00</i>
23	SIGN ' CAUTION ' STICKER <i>rec</i> ✓	\$	13.00 ✓ <i>\$9-76</i>
24	SIGNAL HORN - LOW TONE LH X	\$	262.00 X
25	SPRING SHACKLE FOR SIGNAL HORN X	\$	43.00 X
26	FRONT PARKING AID SENSOR- INNER ?	\$	231.00
27	FRONT PARKING AID SENSOR - OUTER ?	\$	210.00
28	FRONT PARKING AID SENSOR SEAL RING <i>rec</i> ✓ @4.80	\$	5,579.00 - (9.20 (4 pcs) ✓
29	FRONT FENDER-LH <i>bt</i> ✓	\$	1,558.00 ✓ <i>\$1246-40</i>
30	FRONT FENDER ATTACHMENT PARTS-LH ?	\$	92.00
31	STONE GUARD FILM FOR FRONT FENDER-LH X	\$	104.00 X <i>\$83-20</i>
32	FRONT FENDER BRACKET-LH UPPER ?	\$	17.00
33	FRONT FENDER BRACE-LH ?	\$	75.00 ✓ <i>\$59-68</i>
34	FRONT FENDER CLOSING ELEMENT-LH ?	\$	48.00
35	FRONT WHEEL HOUSING LINER SEAL-LH <i>rec</i> ✓	\$	9.00 ✓ <i>\$7-04</i>
36	FRONT WHEEL HOUSING LINER -LH <i>cut</i> ✓	\$	256.00 ✓ <i>\$204-80</i>
37	FRONT WHEEL HOUSING LINER ATTACHEMENT PART-LH ?	\$	66.00
38	BONNET <i>bt</i> ✓	\$	5,579.00 ✓ <i>\$4463-20</i>
39	BONNET ATTACHMENT PARTS ?	\$	161.00
40	BONNET LID HINGE-LH/RH X <i>LH-bt / RH-X</i>	2 \$	292.00 X
SUB-TOTAL SPARE PARTS		:	\$ 14,850.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	GAS FILLED STRUT FOR BONNET X	2 \$	217.00 X
42	BONNET EDGE PROTECTION ?	\$	25.00
43	BONNET CATCH HOOK X	\$	127.00 X
44	BONNET LOCK BAR ?	2 \$	90.00
45	BONNET LOCK LATCH HOOK X	\$	16.00 X
46	BONNET LOCK LATCH COVER X	2 \$	7.00 X
47	BONNET LID LOCK WITH MICRO SWITCH X	2 \$	391.00 X
48	BONNET MICRO SWITCH X	2 \$	133.00 X
49	BOWDEN CABLE-CENTER X	\$	53.00 X
50	BOWDEN CABLE COVER X	\$	9.00 X
51	LED HEADLIGHT COVER-LH can ✓	\$	39.00 ✓
52	LED HEADLIGHT MONTING-LH ?	\$	107.00
53	LED HEADLIGHT-LH can ✓	\$	11,694.00 ✓
54	POWER MODULE DAY DRIVING LIGHTS FOR HEADLIGHT-LH X	\$	520.00 X
55	POWER MODULE FOR MATRIX LIGHTS FOR HEADLOIGHT-LH X	\$	1,726.00 X
56	POWER MODULE FOR DIPPED BEAM FOR HEADLIGHT-LH X	\$	508.00 X
57	FAN FOR HEADLIGHT-LH X	\$	363.00 X
58	REPAIR SET OF POWER MODULE FOR DYNAMIC FLASHING X	\$	20.00 X
59	RETAINER PLATE FOR HEADLIGHTS ?	\$	36.00
60	COMPENSATING FOR HEADLIGHTS ?	3 \$	115.00
SUB-TOTAL SPARE PARTS		:	\$ 16,196.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

\$31-12

\$9355-20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
61	FAN CAP FOR HEADLIGHT <i>CR ✓</i>	\$ 52.00	<i>\$40-88</i>
62	HEADLIGHT HOSE <i>★ ?</i>	\$ 32.00	
63	LIFT CYLINDER FOR HEADLIGHT-LH <i>X</i>	\$ 216.00	
64	HOSE FOR HEADLIGHT WASHER SYSTEM <i>X</i>	\$ 466.00	
65	WASH WATER RESERVOIR <i>X</i>	\$ 174.00	
66	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR <i>X</i>	\$ 1,140.00	
67	COOLANT FOR RADIATOR <i>X</i>	4 \$ 84.00	
68	AIR GUIDE-LH <i>?</i>	\$ 24.00	
69	FRONT WHEEL RIM-LH <i>X old damage</i>	\$ 1,187.00	
70	SUNDRIES <i>?</i>	\$ 400.00	<i>\$12-00</i>
TOTAL SPARE PARTS		: \$ 42,574.00	
TOTAL LABOUR CHARGES		: \$ 14,202.00	
GRAND TOTAL		: <u>\$ 56,776.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Rasul - Hp 90010568

Surveyed Date

: 13/11/19 @ 1110

Authorised Date

: 7 days

Excess Cost

: EXCESS: TBA

Liability

:

Remarks

:

REVERT
Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1352/2019/GW

Date

18-Nov-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SGL 2617 L

Model No

A7 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Front bumper adapter RHS <i>new</i>	\$ 34.00	<i>\$27-12</i>
2	Flat contact housing with contact locking mechanism <i>new</i>	\$ 29.00	<i>\$22-72</i>
3	Front number plate <i>new</i>	\$ 40.00	<i>\$40-00</i>

TOTAL

\$ 103.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1352/2019/GW
Date 25-Nov-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SGL 2617 L
Model No A7 SB 2.0 TFSI

Quantity Description


Unit Price Amount

Labours

1	To repair lhs front fender top support.	\$ 900.00 500	\$500-00
2	To respray lhs front fender top support.	\$ 1,350.00 550	\$550-00

TOTAL

\$ 2,250.00



For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1352/2019/GW
Date : 12-Nov-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

7 day Confirm

Hi Rasul

We took 9 days exclude 1 Sunday

jb 6 Feb 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Barry Joseph O'Donnell
Address : 14 Holland Green
Singapore 276137
Telephone : HP +65 96559556
Type of Claim : Own Damage Claims
Policy No. : 2100466246-03
Vehicle No : **SGL 2617 L**
Model Code : A7 SB 2.0 TFSI
Model / Year : May-16
Engine No : CYP006638
Chassis No : WAUZZZ4G7GNN094008
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Nov-19
Place of Accident : YOTEL HOTEL, CARPARK ENTRANCE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGL 2617 L

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlights washer assy and front parking aid.	S/N \$	480.00	\$ 480.00 ✓
2	To remove and reinstall air cond condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,400.00	
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$	300.00	\$ 300.00 ✓
4	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. (Headlamp replacement \$250.00)	\$	6,750.00	\$ 1,750.00 ✓
5	To respray front bumper, lhs front fender, bonnet and lhs front door.	\$	4,800.00	\$ 2,200.00 ✓
6	To renew lhs front rim and carry out wheel alignment.	S/N \$	280.00	
7	Added labour charges - see attached	\$	2,250.00	\$ 1,050.00 ✓
8	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00 ✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 16,452.00</u></u>	<u><u>\$ 5,972.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,909.00	\$ 2,327.20 ✓
2	FRONT BUMPER GRILLE	\$ 139.00	
3	FRONT BUMPER FIXING PARTS	\$ 251.00	
4	FRONT BUMPER ADAPTER -LH	\$ 34.00	\$ 27.12 ✓
5	FRONT BUMPER CLOSING ELEMENT	\$ 191.00	
6	FRONT BUMPER SPOILER	\$ 227.00	
7	RADIATOR GRILLE	\$ 1,455.00	\$ 1,164.00 ✓
8	RADIATOR GRILLE COVER	\$ 49.00	
9	CATCH FOR RADIATOR-LH/RH	2 \$ 36.00	
10	LICENCE PLATE HOLDER	\$ 564.00	
11	FRONT BUMPER GRILLE-LH	\$ 269.00	\$ 215.20 ✓
12	FRONT BUMPER END CAP-LH	\$ 53.00	\$ 41.92 ✓
13	FRONT BUMPER WHEEL SPOILER -LH	\$ 349.00	\$ 278.80 ✓
14	FRONT STONE CHIP GUARD-LH	\$ 66.00	\$ 52.72 ✓
15	ADHESIVE TAPE	\$ 50.00	\$ 40.00 ✓
16	FRONT BUMPER COVER	\$ 116.00	\$ 92.40 ✓
17	FOAM FILLER PIECE	\$ 174.00	
18	FRONT BUMPER REINFORCEMENT BAR	\$ 754.00	
19	FRONT BUMPER BRACE-LH	\$ 27.00	\$ 21.20 ✓
20	FRONT BUMPER GUIDE PIECE-LH	\$ 40.00	\$ 31.52 ✓
SUB-TOTAL SPARE PARTS		\$ 7,753.00	\$ 4,292.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		c/f	\$	4,292.08
21	FRONT BUMPER HOLDER-LH	\$	237.00	
22	AIR CONDITIONER STICKER	\$	18.00	\$ 14.00 /
23	SIGN ' CAUTION ' STICKER	\$	13.00	\$ 9.76 /
24	SIGNAL HORN - LOW TONE LH	\$	262.00	
25	SPRING SHACKLE FOR SIGNAL HORN	\$	43.00	
26	FRONT PARKING AID SENSOR- INNER	\$	231.00	
27	FRONT PARKING AID SENSOR - OUTER	\$	210.00	
28	FRONT PARKING AID SENSOR SEAL RING	\$	5,579.00	
29	FRONT FENDER-LH	\$	1,558.00	\$ 1,246.40 /
30	FRONT FENDER ATTACHMENT PARTS-LH	\$	92.00	
31	STONE GUARD FILM FOR FRONT FENDER-LH	\$	104.00	\$ 83.20 /
32	FRONT FENDER BRACKET-LH UPPER	\$	17.00	
33	FRONT FENDER BRACE-LH	\$	75.00	\$ 59.68 /
34	FRONT FENDER CLOSING ELEMENT-LH	\$	48.00	
35	FRONT WHEEL HOUSING LINER SEAL-LH	\$	9.00	\$ 7.04 /
36	FRONT WHEEL HOUSING LINER -LH	\$	256.00	\$ 204.80 /
37	FRONT WHEEL HOUSING LINER ATTACHEMENT PART-LH	\$	66.00	
38	BONNET	\$	5,579.00	\$ 4,463.20 /
39	BONNET ATTACHMENT PARTS	\$	161.00	
40	BONNET LID HINGE-LH/RH	2 \$	292.00	
SUB-TOTAL SPARE PARTS		\$	14,850.00	\$ 10,380.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 10,380.16
41	GAS FILLED STRUT FOR BONNET	2	\$ 217.00	
42	BONNET EDGE PROTECTION		\$ 25.00	
43	BONNET CATCH HOOK		\$ 127.00	
44	BONNET LOCK BAR	2	\$ 90.00	
45	BONNET LOCK LATCH HOOK		\$ 16.00	
46	BONNET LOCK LATCH COVER	2	\$ 7.00	
47	BONNET LID LOCK WITH MICRO SWITCH	2	\$ 391.00	
48	BONNET MICRO SWITCH	2	\$ 133.00	
49	BOWDEN CABLE-CENTER		\$ 53.00	
50	BOWDEN CABLE COVER		\$ 9.00	
51	LED HEADLIGHT COVER-LH		\$ 39.00	\$ 31.12 ✓
52	LED HEADLIGHT MONTING-LH		\$ 107.00	
53	LED HEADLIGHT-LH		\$ 11,694.00	\$ 9,355.20 ✓
54	POWER MODULE DAY DRIVING LIGHTS FOR HEADLIGHT-LH		\$ 520.00	
55	POWER MODULE FOR MATRIX LIGHTS FOR HEADLOIGHT-L		\$ 1,726.00	
56	POWER MODULE FOR DIPPED BEAM FOR HEADLIGHT-LH		\$ 508.00	
57	FAN FOR HEADLIGHT-LH		\$ 363.00	
58	REPAIR SET OF POWER MODULE FOR DYNAMIC FLASHING		\$ 20.00	
59	RETAINER PLATE FOR HEADLIGHTS		\$ 36.00	
60	COMPENSATING FOR HEADLIGHTS	3	\$ 115.00	
SUB-TOTAL SPARE PARTS			\$ 16,196.00	\$ 19,766.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGL 2617 L

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f		\$ 19,766.48
61	FAN CAP FOR HEADLIGHT		\$ 52.00	\$ 40.88
62	HEADLIGHT HOSE		\$ 32.00	
63	LIFT CYLINDER FOR HEADLIGHT-LH		\$ 216.00	
64	HOSE FOR HEADLIGHT WASHER SYSTEM		\$ 466.00	
65	WASH WATER RESERVOIR		\$ 174.00	
66	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATO		\$ 1,140.00	
67	COOLANT FOR RADIATOR	4	\$ 84.00	
68	AIR GUIDE-LH		\$ 24.00	
69	FRONT WHEEL RIM-LH		\$ 1,187.00	
70	<i>Added parts - see attached</i>		\$ 103.00	\$ 89.84
71	SUNDRIES		\$ 400.00	\$ 12.00
TOTAL SPARE PARTS		:	\$ 42,677.00	\$ 19,909.20
TOTAL LABOUR CHARGES		:	\$ 16,452.00	\$ 5,972.00
GRAND TOTAL		:	\$ 59,129.00	\$ 25,881.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1352/2019/GW 18-Nov-19 Glory Tan 1 of 1 SGL 2617 L A7 SB 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Front bumper adapter RHS	\$ 34.00	\$	27.12
2	Flat contact housing with contact locking mechanism	\$ 29.00	\$	22.72
3	Front number plate	\$ 40.00	\$	40.00
TOTAL		\$ 103.00	\$	89.84

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1352/2019/GW 25-Nov-19 Glory Tan 1 of 1 SGL 2617 L A7 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To repair lhs front fender top support.	\$ 900.00	\$ 500.00
2	To respray lhs front fender top support.	\$ 1,350.00	\$ 550.00
TOTAL		\$ 2,250.00	\$1,050.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant