

e

Not Allowed
d/s 1600
13/11/19
3/17

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

e

M/S : LONPAE INSURANCE

Estimate No: EST0001048

Date: 12 Nov 2019

Policy No:

Veh Reg No: **GBA863Y**

Make/Model: TOYOTA DYNA

Chassis No: 1KD1575487

Engine No: JTFAT35Y703000353

Reg. Date: 02/02/2007

ATTN: Motor Claim Department

Your Ref No: GBA863Y

Claim Type: Third Party

Accident Date: 21/10/2019

Estimate Repair Cost to Vehicle No :GBA863Y

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 Rear Tail Gate	1,237.20	1 PC	1,237.20	X
2 Rear Tail Gate Side Lock - RH	78.20	1 PC	78.20	X
3 Rear Tail Gate Emblem (Toyota)	120.20	1 PCS	120.20	X
4 Rear Side Gate - RH	2,346.20	1 PC	2,346.20	X
			3,781.80	
	Less 25%		945.45	2,836.35
Special Net				
5 Rear Tail Gate Sticker 70 KM/H	20.00	1 PC	20.00	X
6 Rear Tail Gate Sticker - 13 Pax	20.00	1 PC	20.00	X
7 Rear Tail Gate Aluminium Plate	650.00	1 PCS	650.00	X
			690.00	690.00
Labour				
8 Panel Beating	800.00	1 PC	800.00	400
9 Spray Painting	800.00	1 PC	800.00	400
			1,600.00	1,600.00
			Total	S\$ 5,126.35

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND ONE HUNDRED TWENTY SIX AND CENTS THIRTY FIVE ONLY

For FOCUS AUTO PTE LTD
any item(s) must be resurveyed and
written approval from Insurance Company

2063.82

AUTHORISED SIGNATURE