

ASS. REC. BY:

Surveyor: Tauhid

REF:

CS/INC19020162/7/13/13

12

Special Instructions:

ASSIGNMENT (Office)From (Person): Hazalysen Bt Ibrahim

of

INC

Date/Time:

9:47am @ 13/11/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 474SH

Insured:

SJA 3340A

at Workshop w/s

TransGinkers

Tel:

9091 6581

of

27A Tanjung Penjuru

Policy No:

Claim No:

MT/1070829-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/11/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:18am @ 13/11/19

Person Contacted:

Summe

Vehicle IN/OUT

Date/Time

Action/Instruction

Initials (✓)SMD 474SH - X

Tanpin

INC

ASSIGNMENT

21/8/2018

From

Date

13/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SMD 4745H

at Workshop n/s

Turns Crookers

of

27A Tanjung Perjuna

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

3rd (working)

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum. Punc:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS up.

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMD 4745H

Regn:

2018

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda CX5

C.C.

1998

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

18715

T/Radio:

Insured / Std / NI / NA

Eng/No:

SMGKF2W7AK0227602

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

225/65R17

R:

~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

mm

R/Bal:

mm

L/Bal:

mm

L/Bal:

mm

D.O.A.

D.O.I.

13/11/19e350

Survey held at

Trans Eureka

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/12

\$5381.70, 5 days email to Service.
(\$4,597.40 Red - 46%)

RECEIVED 16 DEC 2019

16/12/2019

Date/Time: File Path to?

16/12/19

1) Typist

Date/Time: File Path to?

3)

Report Format:

Lump Sum / L.P.

\$5,381.70 AP

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Witness (\$

Survey Fee:

Transportation

F + FS (\$

Photos

Other

TOTAL

250

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Thursday, 14 November 2019 8:49 AM
To: Admin-D (LKKAuto); assignments
Cc: SUR; Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear LKK,

Re-send with complete details.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg

income
made different



in with you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 14 November 2019 7:41 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear Hazalya,

Kindly assist to provide us the complete details of the below assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalysa Binte Ibrahim (mailto:hazalysa.ibrahim@income.com.sg)

Sent: Wednesday, 13 November 2019 9:47 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Azhari	MT/1071002-001	FBH4158L	HKL LIM TEAM MOTORSPORT	BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722	James Lim (Keong) / 6275-6656		SGG1021M	23/06/19	6275-6566
2	Chryllis Quah	MT/1070958-001	SCR233P	MAXIMUS RACING PTE LTD	MR PERFORMANCE CENTRE 7 SOON LEE STREET #05-05 ISPACE SINGAPORE 627608	Arry Seah / 8858 3131	12:00-16:00	SKT7763A	11/11/19	9638 2477
3	Jared Liu	MT/1071048-001	SLL3226R	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	14:00-16:00	GBJ9737Y	11/11/19	Driver waiting
4	Eric Tang	MT/1070984-001	SLR4815C	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	10:30-16:00	XO3747D	12/11/19	

5	Muhammad Airwan	MT/1070829-002	SMD4745H	TRANS EUROKARS PTE LTD	27A TANJONG PERUURU SINGAPORE 609042	Samuel Ng /	15:00-16:00	SJA3340A	11/11/19	
6	Jeff Lin	MT/1071063-001	SMH5296J	XINYA AUTO SERVICES PTE LTD	BLK 1002 #01-75 BUKIT MERAH LANE 3 SINGAPORE 159719	/ 62703481		SKJ1748L	08/11/19	
7	Muhammad Airwan	MT/1068445-002	SMH4477K	AUTO INSURE PTE LTD	6 MARSILING LANE	Mr Sam Goh / 31572628		SLJ4787S	21/10/19	9743 6363
8	Charlotte Chew	MT/1067845-002	SML3246X	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	209 PANDAN GARDENS SINGAPORE 609339	Kevin Leong / 81680997	10:00-12:00	SKW4924G	19/10/19	6568 4501
9	Fiona Shen	MT/1055123-002	SLR758K	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	209 PANDAN GARDENS SINGAPORE 609339	Edwin Calina / 91819978	10:00-12:00	FBH1536Z	25/07/19	6568 4501
10	Helena Tan	MT/1070771-002	EM1175U	CYCLE & CARRIAGE INDUSTRIES PTE LTD	188 PANDAN LOOP SINGAPORE 128378	GO CHEE HAN / 9181 7717		SHD1108B	10/11/19	6771 4336
11	Jared Liu	MT/1065746-002	SLX4511Y	ETHOZ AUTOMOTIVE SOLUTIONS LTD	30 BUKIT BATOK CRESCENT SINGAPORE 658075	Lee Chen Sin / 8822 8339		GBJ5365M	07/10/19	6654 7520
12	Jeff Lin	MT/1071022-001	SGG5504K	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131		XE1549S	08/11/19	63161151

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto)
Sent: Monday, 16 December 2019 12:16 pm
To: jessica@eurokars.com.sg
Cc: Shirley Hiew (LKK Auto)
Subject: RE: FINALIZATION SMD4745H TP NTUC (MAZDA)

Hi Jessica,

COR \$5381.70 (before gst) , 5 days.

Regards
Taufikh
Lkk Auto

From: jessica@eurokars.com.sg [mailto:jessica@eurokars.com.sg]
Sent: Thursday, 12 December 2019 1:43 PM
To: Taufikh@lkkauto.com; admin-a@lkkauto.com
Subject: FINALIZATION SMD4745H TP NTUC (MAZDA)

Dear Taufikh,

Please find our computation attached for your agreement.

COR: \$5,758.42 include GST
05 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case

Thank you very much.

Regards,
Jessica Shastri
Admin Executive – Insurance Claims
27A, Tanjong Penjuru
Singapore 609042
Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessica@eurokars.com.sg
Website: www.eurokarsgroup.com



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2019 19:20
Date Of Accident	11/11/2019 09:30
Exact Location Of Accident	WOODLANDS AVE12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD4745H
Insured/Policyholder	
Name Of Registered Owner	LEE SEOW YEOW
NRIC No	S7421592J
Email Address	THORNRAY@YAHOO.COM
Mobile Phone No	(LOCAL) +65-94508449
Alternative Phone No	OFFICE-94508449

Vehicle Particulars

Manufacturer	MAZDA
Model	CX-5-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	NG WEI SI
NRIC No	S7835276J
Date Of Birth	19/11/1978
Occupation	INDOOR
Date Of Driving Pass	19/03/2010
Driving Experience	9 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97908449
Fax Number	
Contact Number	
EEmail Address	RAE_WS@YAHOO.COM

Address	APT BLK 230 JURONG EAST STREET
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA3340A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

x

Policyholder's Signature
Date & Time:

r 


Driver's Signature
(If driver is not the policyholder)
Date & Time: 11 Nov 5:50pm



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO. SMD H745 H

ACCIDENT DATE: 11 Nov 2019

CONTACT NUMBER: 979031149

ACCIDENT TIME: 9:30 am

EMAIL: rae_ws@yahoo.com

LOCATION: Woodlands Ave 12

I was travelling on the first ~~lane~~^{lane} of Woodlands Ave to

At the ~~cross~~^T junction of Woodlands Ave 12 and Woodlands Ave 5, the traffic light had turned amber, being the first car, I braked at the crossway, but the vehicle behind me SJA 3340 hit the rear of my vehicle.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☐ CLAIM OWN POLICY ☒ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)

Date & Time: 11 Nov 5:30 pm

Reporting Center Personnel's Signature _____

Name: _____
NRIC/FIN No.: _____



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

NTUC INCOME INSURANCE 1 MARITIME SQUARE #10-01 HARBOURFRONT CENTRE SINGAPORE 099253 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Lee Seow Yeow ADDRESS : 230 Jurong East Street 21 #16-683 Singapore 600230 TEL : 94508449		WIP : 55753 EXCESS : DATE: 11-Nov-19	
VEH NO :	SMD4745H	DATE IN :		CONTACT PERSON :	SAMUEL
CHASSIS NO :	JM6KF2W7AK0227602	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX5	DATE REG.:	21-Aug-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MKBYB-50-22XBBB	Le ✓	\$ 1,278.90
2	BRACKET CENTER	1	MKD53-50-251	8w ✓	\$ 5.40
3	STAY LHS, REAR BUMPER	1	MKB7W-52-B32A	? de ✓	\$ 25.40
4	STAY RHS, REAR BUMPER	1	MKB7W-52-B22A	? de ✓	\$ 25.40
5	TOWING COVER LHS	1	MKB8A-50-EL1 BB	cut ✓	\$ 5.20
6	REFLECTOR LHS → photo	1	MK123-51-5M0C	cm ✓	\$ 210.90
7	RETAINER CENTER, SENSOR	1 ✓	MK123-67-UC5 2Y	at ✓	\$ 31.00
8	SENSOR CENTER, ULTRASONIC	1 ✓	MGMK6-67-UC1 2Y	ms ✓	\$ 361.80
9	PAD PROTECTOR, SENSOR	3	MG001-67-061	reg ✓	\$ 23.40
10	RUBBER SEAL, SENSOR	2	MKB8A-50-2G2	nh ✓	\$ 32.80
11	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	nh ✓	\$ 10.80
12	FASTENER, REAR BUMPER	16	MB45A-56-146A	nh ✓	\$ 48.00
13	ORNAMENT, CX	1	MKB7W-51-721A	nh x nh ✓	\$ 40.30
14	MASCOT, REAR	1	MKB7W-51-731	x nh ✓	\$ 45.90
15	ORNAMENT, SKYACTIVE	1	MKB7W-51-771	x nh ✓	\$ 67.00
16	CLIP, FINISHER	4	MBHY1-51-0A6A	nh ✓	\$ 40.40
17	CLIP, FINISHER	2	MKB8A-51-SJ3	nh ✓	\$ 11.00
18	CLIP, FINISHER	4	MTK78-51-0B6	nh ✓	\$ 44.00
19	FASTENER, FINISHER	8	MKB8A-51-W24A	nh ✓	\$ 29.60
20	FASTENER, FINISHER	1	MTK80-51-W24	nh ✓	\$ 5.50
21	GROMMET, FINISHER	1	MBHN1-50-0Z1A	nh ✓	\$ 2.70
22	FASTENER, FINISHER	11	MKB8A-51-W24A	nh ✓	\$ 40.70
23	GROMMET, TAILGATE	4	MGA7B-51-146	nh ✓	\$ 13.20
24	FASTENER, TAILGATE	2	MEG21-51-146	x nh ✓	\$ 12.40
25	GASKET LHS, TAILLAMP	1	MKB8A-51-3J8A	nh ✓	\$ 13.70
26	GASKET RHS, TAILLAMP	1	MKB8A-51-3H8A	nh ✓	\$ 13.70
TOTAL PARTS					\$ 2,439.10
TOTAL PARTS COST					\$ 2,439.10

Labour Description				
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR TAILGATE, REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	660.	\$ 2,640.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	1260.	\$ 2,520.00
3	MZ-BR-REV5EN	TO TRANSFER REVERSE SENSORS.	NETT ✓	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	nn NETT X	\$ 330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	nn X	\$ 250.00
6	MZ-BR-ELECTR	FALSE Electrical check	150.	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.	\$ 350.00
8		TO SUPPLY BRILA PREMIUM COATING. → sub agreement 200.	NETT	\$ 250.00
9	MZ-BR-SUNDRI	SUNDRIES. None	10. NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 7,020.00
TOTAL PARTS	\$ -	\$ 2,439.10
TOTAL	\$ -	\$ 9,459.10
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

9979.10

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dam(a) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD



SUPPLEMENTARY ESTIMATE COST OF REPAIRS

NTUC INCOME INSURANCE 1 MARITIME SQUARE #10-01 HARBOURFRONT CENTRE SINGAPORE 099253 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Lee Seow Yeow ADDRESS : 230 Jurong East Street 21 #16-683 Singapore 600230 TEL : 94508449		WIP : 55753 EXCESS : DATE: 11-Nov-19	
VEH NO :	SMD4745H	DATE IN :		CONTACT PERSON :	SAMUEL
CHASSIS NO :	JM6KF2W7AK0227602	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX5	DATE REG.:	21-Aug-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR REINFORCEMENT	1	MKD53-50-260D	bt✓	\$ 520.00
TOTAL PARTS				\$ -	\$ 520.00
TOTAL PARTS COST				\$ -	\$ 520.00
Labour Description					
1					
TOTAL LABOUR				\$ -	\$ -
TOTAL PARTS				\$ -	\$ 520.00
TOTAL				\$ -	\$ 520.00
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

NTUC INCOME INSURANCE 1 MARITIME SQUARE #10-01 HARBOURFRONT CENTRE SINGAPORE 099253 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lee Seow Yeow ADDRESS : 230 Jurong East Street 21 #16-683 Singapore 600230 TEL : 94508449		WIP : 55753 EXCESS : DATE: 11-Nov-19	
VEH NO :	SMD4745H	DATE IN :		CONTACT PERSON :	SAMUEL
CHASSIS NO :	JM6KF2W7AK0227602	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX5	DATE REG.:	21-Aug-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MKBYB-50-22XBBB	\$ 1,278.90	\$ 1,278.90
2	BRACKET CENTER	1	MKD53-50-251		\$ 5.40
3	STAY LHS, REAR BUMPER	1	MKB7W-52-B32A	\$ 25.40	\$ 25.40
4	STAY RHS, REAR BUMPER	1	MKB7W-52-B22A	\$ 25.40	\$ 25.40
5	TOWING COVER LHS	1	MKB8A-50-EL1 BB	\$ 5.20	\$ 5.20
6	REFLECTOR LHS	1	MK123-51-5MOC	\$ 210.90	\$ 210.90
7	RETAINER CENTER, SENSOR	1	MK123-67-UC5 2Y	\$ 15.50	\$ 31.00
8	SENSOR CENTER, ULTRASONIC	1	MGMK6-67-UC1 2Y	\$ 180.90	\$ 361.80
9	PAD PROTECTOR, SENSOR	3	MG001-67-061	\$ 23.40	\$ 23.40
10	RUBBER SEAL, SENSOR	2	MKB8A-50-2G2	\$ 32.80	\$ 32.80
11	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.80	\$ 10.80
12	FASTENER, REAR BUMPER	16	MB45A-56-146A	\$ 48.00	\$ 48.00
13	ORNAMENT, CX	1	MKB7W-51-721A		\$ 40.30
14	MASCOT, REAR	1	MKB7W-51-731		\$ 45.90
15	ORNAMENT, SKYACTIVE	1	MKB7W-51-771		\$ 67.00
16	CLIP, FINISHER	4	MBHY1-51-0A6A	\$ 40.40	\$ 40.40
17	CLIP, FINISHER	2	MKB8A-51-SJ3	\$ 11.00	\$ 11.00
18	CLIP, FINISHER	4	MTK78-51-0B6	\$ 44.00	\$ 44.00
19	FASTENER, FINISHER	8	MKB8A-51-W24A	\$ 29.60	\$ 29.60
20	FASTENER, FINISHER	1	MTK80-51-W24	\$ 5.50	\$ 5.50
21	GROMMET, FINISHER	1	MBHN1-50-0Z1A	\$ 2.70	\$ 2.70
22	FASTENER, FINISHER	11	MKB8A-51-W24A	\$ 40.70	\$ 40.70
23	GROMMET, TAILGATE	4	MGA7B-51-146	\$ 13.20	\$ 13.20
24	FASTENER, TAILGATE	2	MEG21-51-146		\$ 12.40
25	GASKET LHS, TAILLAMP	1	MKB8A-51-3J8A	\$ 13.70	\$ 13.70
26	GASKET RHS, TAILLAMP	1	MKB8A-51-3H8A	\$ 13.70	\$ 13.70
SUPPLEMENTARY PARTS					
1	REAR REINFORCEMENT	1	MKD53-50-260D	\$ 520.00	\$ 520.00
TOTAL PARTS				\$ 2,591.70	\$ 2,959.10

		TOTAL PARTS COST	\$ 2,591.70	\$ 2,959.10
	Labour Description			
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT, TO REPAIR TAILGATE, REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 2,640.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	\$ 1,260.00	\$ 2,520.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ -	\$ 330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ -	\$ 250.00
6	MZ-BR-ELECTR	FALSE	\$ 150.00	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
8		TO SUPPLY BRILA PREMIUM COATING.	\$ 200.00	\$ 250.00
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 10.00	\$ 100.00
		TOTAL LABOUR	\$ 2,790.00	\$ 7,020.00
		TOTAL PARTS	\$ 2,591.70	\$ 2,959.10
		TOTAL	\$ 5,381.70	\$ 9,979.10
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ 5,381.70	
		GST 7%	\$ 376.72	\$ -
		GRAND TOTAL	\$ 5,758.42	\$ -

NUMBER OF DAYS: 5 WORKING DAYS (EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

ID:t05

INTERNAL INVOICE

CODE: I9104 I04
CUSTOMER: Mr Lee Seow Yeow
ADDRESS: 230 Jurong East Street 21
#16-683
Singapore 600230
MODEL: MAZDA CX5 IPM 2.0 PREMIUM BLAC
CHASSIS NO: JM6KF2W7AK0227602
ENGINE NO: PE31265790
DESCRIPTION: P.D.I.

PAGE NO: 1
INVOICE NO: 31002064
DEPT/POS ID: N / 12
DATE IN: 23/08/2018
DATE PRINTED: 30/08/2018
JOB NO: 21356
CSO/OP CODE: PDI - Min Yue
TEL NO:
REGN NO: SMD4745H
REGN DATE:
MILEAGE: 3
REQUISITION NO: 25814/BG

MZ-PT CX PETROL TOPPING
Std PDI Pkg CX5
MZ-PDI C PRE DELIVERY INSPECTION & INSTALL IU
Std PDI Pkg CX5
MZ-PV CX POLISH A UNIT OF VEHICLE
Std PDI Pkg CX5
MZ-RP CX SUPPLY 1 SET OF REGN PLATE
Std PDI Pkg CX5
MZ-IU CX SUPPLY 1 UNIT OF IU
Std PDI Pkg CX5
SUB SUPPLY & INSTALL CX5 SOLAR FILM (RIKECOOL)
SUBLET 137224
GEN INSTALL CX5 FRONT & REAR VIDEO CAMERA
SUB 7 CX5 BRILA PREMIUM BODY COATING
SUBLET 137225
GEN TO INSTALL ROOF RAIL
11-CARPETCX5KF CARPET MAZDA CX5 KF 1.0
11-BPDVR9 DVR,BLAUPUNKT 9.0 2- 1.0

ID:t05

INTERNAL INVOICE

CODE: I9104 I04
CUSTOMER: Mr Lee Seow Yeow
ADDRESS: 230 Jurong East Street 21
#16-683
Singapore 600230
SINGAPORE
MODEL: MAZDA CX5 IPM 2.0 PREMIUM BLAC
CHASSIS NO: JM6KF2W7AK0227602
ENGINE NO: PE31265790

PAGE NO: 2
INVOICE NO: 31002064
DEPT/POS ID: N / 12
DATE: 23/08/2018
DATE PRINTED: 30/08/2018
JOB NO: 21356
CSO/OP CODE: PDI - Min Yue
TEL NO:
REGN NO: SMD4745H
REGN DATE:
MILEAGE: 3

DESCRIPTION: P.D.I.

REQUISITION NO: 25814/BG

BJA9-66-EZ1L	SD CARD	1.0
DB2M-V6-601C	NAVI OWNER'S MANUAL	1.0
88-K123-V3-830	ROOF RAIL CX-5 KF	1.0

Parts
Surcharge
Labour
Menus

=====
Net
G.S.T. 7%
Total
Paid
Amount Due

COPY DOCUMENT

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020162/T1sd3n2

73 BRAS BASAH ROAD

Date: 26-12-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE



189556

ATTN: MUHAMMAD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJA 3340A	Veh. Inspected	SMD 4745H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1070829-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	13/11/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA CX-5	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JM6KF2W7AK0227602	Colour	GREY
Odometer	18715 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/11/2019	Inspect Date / Time	13/11/2019 (03:30 PM)
Survey held at	27A TANJONG PENJURU		
Repairer	TRANS EUROKARS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 4745H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	1,278.90	1,278.90
1	BRACKET CENTER (SN)	NOT NECESSARY	5.40	-
1	STAY LHS ,REAR BUMPER (SN)	DEFORMED	25.40	25.40
1	STAY RHS ,REAR BUMPER (SN)	DEFORMED	25.40	25.40
1	TOWING COVER LHS (SN)	CUT	5.20	5.20
1	REFLECTOR LHS (SN)	CRACKED	210.90	210.90
2	RETAINER CENTER ,SENSOR (SN)	CUT (1 PC ONLY)	31.00	15.50
2	SENSOR CENTER ,ULTRASONIC (SN)	MISSING (1 PC ONLY)	361.80	180.90
3	PAD PROTECTOR ,SENSOR (SN)	NECESSARY	23.40	23.40
2	RUBBER SEAL ,SENSOR (SN)	NECESSARY	32.80	32.80
4	GROMMET ,REAR BUMPER (SN)	NECESSARY	10.80	10.80
16	FASTENER ,REAR BUMPER (SN)	NECESSARY	48.00	48.00
1	ORNAMENT ,CX (SN)	NOT NECESSARY	40.30	-
1	MASCOT ,REAR (SN)	NOT NECESSARY	45.90	-
1	ORNAMENT ,SKYACTIVE (SN)	NOT NECESSARY	67.00	-
4	CLIP ,FINISHER (SN)	NECESSARY	40.40	40.40
2	CLIP ,FINISHER (SN)	NECESSARY	11.00	11.00
4	CLIP ,FINISHER (SN)	NECESSARY	44.00	44.00
8	FASTENER ,FINISHER (SN)	NECESSARY	29.60	29.60
1	FASTENER ,FINISHER (SN)	NECESSARY	5.50	5.50
1	GROMMET ,FINISHER (SN)	NECESSARY	2.70	2.70
11	FASTENER ,FINISHER (SN)	NECESSARY	40.70	40.70
4	GROMMET ,TAILGATE (SN)	NECESSARY	13.20	13.20
2	FASTENER ,TAILGATE (SN)	NOT NECESSARY	12.40	-
1	GASKET LHS ,TAILLAMP (SN)	NECESSARY	13.70	13.70
1	GASKET RHS ,TAILLAMP (SN)	NECESSARY	13.70	13.70
1	SUNDRIES (SN)	NECESSARY	100.00	10.00
1	REAR REINFORCEMENT (ADDITIONAL)(SN)	BENT	520.00	520.00
			3,059.10	2,601.70

Report Ref No. CS/INC19020162/T1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT .TO REPAIR TAILGATE ,REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT .		2,640.00	660.00
	TO RESPRAY REAR BUMPER ,REAR REINFORCEMENT ,REAR END PANEL AND TAILGATE.		2,520.00	1,260.00
	TO TRANSFER REVERSE SENSORS.		330.00	330.00
	TO TRANSFER REVERSE CAMERA.	NOT NECESSARY	330.00	-
	TO CARRY -OUT BODY CAVITY PRESERVATION . FALSE .	NOT NECESSARY	250.00	-
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		250.00	150.00
	TO SUPPLY BRILA PREMIUM COATING.		350.00	180.00
			250.00	200.00
			6,920.00	2,780.00
	GRAND TOTAL		9,979.10	5,381.70
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			5,381.70

Report Ref No. CS/INC19020162/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.