

Section A - Accident Details

Registration Number	SHB1063G
Case Reference Number	TAX/11/19/2028
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	POH KOK SENG
Type of Accident	Head to Rear
Accident Date and Time	10/11/2019 11:20 PM
Accident Reported Date and Time	11/11/2019 8:31 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	10/11/2019 11:21 PM
Replacement Vehicle issued?	No
Job Card Number	24104262
Special Instruction to ARC, if any	TOWED \$40 /AIG - LKK
Prepared Date and Time	12/11/2019 5:02 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$807.00	\$600.00
Total Spray Cost	\$1,956.00	\$690.00
Total Spare Part Cost	\$7,301.87	\$3,830.29
Total Other Cost	\$536.00	\$180.00
TOTAL COST	\$10,600.87	\$5,300.29 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	15/11/2019 4:49 PM	15/11/2019 5:33 PM
Signature		
Remarks	Initial estimate = 5 days SUP = 1 day	P/P Repair, Take before spray photo. send to sunpin@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1911-0533	Invoice Number	
Quotation Date	29.11.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$400.00
TO REPAIR REAR SPARE TYRE PANEL	\$300.00	\$200.00
Total Labour	\$807.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR SPARE TYRE PANEL	\$300.00	\$150.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$80.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$60.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,956.00	\$690.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIT SENSOR SYSTEM	\$120.00	\$40.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$536.00	\$180.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace ✓
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace ✓
		52462470 30	PAD, RR BUMPER, RH & LH, 1	1.00	\$3.80	25.00	\$2.85	Replace	Replace ✓
		52462470 20	PAD, RR BUMPER, RH & LH, 2	1.00	\$3.80	25.00	\$2.85	Replace	Replace ✓
		52462470 10	PAD, RR BUMPER, RH & LH, 3	1.00	\$3.80	25.00	\$2.85	Replace	Replace ✓
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	1.00	\$11.00	25.00	\$8.25	Replace	Replace ✓
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Check X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757105
FAX Number : 03855592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/12/2019

User ID : PohSuan

52576470	40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X
52591470	50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Check	X
52592470	40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Check	X
52161160	10	CLIPS PIECE, FRT & RR BUMPER	1.00	\$1.50	25.00	\$1.13	Replace	Replace	/
52453470	10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	/
52565479	00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Check	X
52566479	00	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	/
52169470	20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	/
		SENSOR REVERSE	1.00	\$180.00	25.00	\$135.00	Replace	Replace	/
89997301	00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	X
58398470	50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
58399470	30	COVER, REAR FLOOR UNDER, LH	1.00	\$234.30	25.00	\$175.73	Replace	Replace	/
66259470	10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
76801471	10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	25.00	\$668.40	Replace	Replace	/
75403480	10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	/
75441470	90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	/
75442471	30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	/
67005474	40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$929.60	25.00	\$697.20	Replace	Replace	/
58307470	90	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$629.80	25.00	\$472.35	Replace	Replace	/
81551472	81	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
81561471	51	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
81581470	10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
81591470	10	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Check	X
81497470	20	COVER, REAR COMBINATION LAMP, RH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given	X
81498470	20	COVER, REAR COMBINATION LAMP, LH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given	X
76085479	16	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/
Total				\$8,782.20		\$3,476.59			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		66259470	COVER, REAR FLOOR UNDER CENTER	1.00	\$222.60	25.00	\$166.95	Replace	Replace
		64718470	END PANEL, COVER, DECK TRIM SERVICE HOLE	1.00	\$47.00	25.00	\$35.25	Replace	Replace
		51931470	CARRIER, SPARE WHEEL	1.00	\$20.00	25.00	\$15.00	Replace	Replace
		58327470	EXHAUST HEAT SHIELD INSULATOR, MAIN	1.00	\$137.00	25.00	\$102.75	Replace	Replace
			SPARE TYPE INSULATOR SHEET	3.00	\$15.00	25.00	\$33.75	Replace	Replace
Total					441.60		353.70		

3830.29
+ 600.00
+ 870.00

5300.29

Repair day - 5 days

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/11/19/2028	Date of Collection	/ /
Vehicle No	SHB 1063 G	Date of Request	14/11/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	3 1

S/N	Part Number	Part Description	Quantity	Unit Price	
		COVER REAR FLOOR CENTER	1pc	MISSING	/ MIS.
		REAR END PANEL TOP GARNISH	1pc		/ CRA
		SPARE TYRE STUD	1pc		/ BT
		REAR EXHAUST HEAT SHIELD	1pc		/ CRU.
	Labor	to REPAIR SPARE TYRE PANEL		\$ 300	200
	Labor	to SPRAY SPARE TYRE PANEL		\$ 300	150

<<<Please submit photographs for damaged parts>>>

I, (Name) _____
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 [to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX 11/19/2018	Date of Collection	/ /
Vehicle No	SHB 1063 G	Date of Request	14/11/2019
Vehicle Model	TOYOTA PRIMS	Number of Days to Extend (If any)	3-1

S/N	Part Number	Part Description	Quantity	Unit Price
		SPARE TYRE INSULATOR COAT	3pus	/ Nec
	TO	REQUEST ADDITIONAL REPAIR DAYS		1 days

<<<Please submit photographs for damaged parts>>>

I, (Name) _____
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 [to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Pg 3/2



Case Details

Case Reference Number : TAX/11/19/2028
Type of Repair : Accident Repair
Vehicle Registration Number : SHB1063G

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-9278-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 10/11/2019 03:20 PM
Vehicle Age(In Months) : 23

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

				SMRT Recommendation						Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	1	239.10	Replace ✓ DD
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ✓ CRU
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace ✓ NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace ✓ NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace ✓ NEC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	1	11.00	11.00	25.00	8.25	Replace	1	8.25	Replace ✓ NEC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check ✓ X SRC
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give ✓ X SRC
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check ✓ X SRC
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check ✓ X SRC

Total Spare Part Cost 6,948.17

Surveyor Total 3,356.54

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,948.17

Final Sur Total 3,356.54

SMRT Recommendation										Surveyor Approval				
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	1	1.50	1.50	25.00	1.13	Replace	1	1.13	Replace	✓ NEC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	✓ CR4.
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	✗ X SVC
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	✓ CUT
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	✓ MTS
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	25.00	135.00	Replace	1	135.00	Replace	✓ Short
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Check	✗ X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	1	175.73	Replace	✓ CR4.
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	668.40	Replace	✓ SCR
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72/3	Replace	✓ NEC
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22/3	Replace	✓ NEC
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22/3	Replace	✓ NEC
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	697.20	Replace	✓ bp

Total Spare Part Cost 6,948.17

Surveyor Total 3,356.54

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,948.17

Final Sur Total 3,356.54

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	1	472.35	Replace	✓ PD
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Check	✗ X SVC
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	0	0	Not Give	✗ X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	0.00	Replace	✓ Nec
Total Spare Part Cost						6,948.17		Surveyor Total		3,356.54				
Lump Sum Discount (%)						0.00		Lump Sum Dis (%)		0				
Final Spare Part Cost						6,948.17		Final Sur Total		3,356.54				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	400	✓
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	✓
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80	✓
Total:			1,656.00	540.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO RESPRAY TAIL GATE	378.00	200	/
5	Main	TO RESPRAY REAR SPOILER	180.00	0	
6	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	60	/
7	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
Total:			1,656.00	540.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIT SENSOR SYSTEM	120.00	40	/
2	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	/
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	/
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TOWING CHARGE	56.00	0	
Total:			536.00	140.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	6,946.17	3,356.54
Total Labour Cost	507.00	400.00
Total Spray Painting	1,656.00	540.00
Other	536.00	140.00
Overall Total	9,647.17	4,436.54
Lump Sum Repair Option		
Lump Sum Total	0.00	4,436.54
Surveyor Approved Amount		4,436.54
No of Repeat Days*	5	4
Remarks	-	P/P Repair, Take before spray photo. send to sunpin@lkkauto.com

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

13/11/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: