

ASS. REC. BY:

REF: CS/SM019020270/ESf3¹⁷

Special Instruction:

Surveyor: SRVE

ASSIGNMENT (Office)

From (Person): Malin Ye yun kang of SMDDate/Time: 14.11.19 2.46 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 3255GInsured: FBH 9245Kat Workshop m/s: Ding AutomotiveTel: 96841857of BK 10 A01-20 San ming Ind Exser C

Policy No: _____

Claim No: CHTD 1905296/GPL

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 13.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 14.11.19 5.29 p.mPerson Contacted: mohanVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate Inspector: 31 Corporation Rd
	SHB 3255G - CSI FCI 1700 3159 / mlg h3m2 D.O.A. = 12/04/2017
	FBH 9245K - CCB / LCR 1700 6675 / Gd9342 D.O.A. = 13/03/2017
15/11	Sent Prel: by EMail

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 3255G

Yr Regn:

31/5/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

1798

Colour:

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

66301

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTD KB 3FU 403081338

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

13/11/19

D.O.A.

14/11/19

Survey held at

Ding Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/11/19

Finalize (20) from \$1842.76, 2 days (Guang)
(P 435.00 Red - 19%)

21/11/2019

RECEIVED 21 NOV 2019

Date/Time, File Pass to?

21/11/19

1) Typ. St

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wheel and (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

250

Rep. Form:

Lump Sum (P/P) \$1,842.76 P/P



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref:

Date: 11 nov 2019

Our Ref: CS/SMO19020270/Esd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB3255G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/11/2019 at the premises of M/s DING AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,277.76</u>
Revised Estimate Amount	: S\$ <u>1,842.76</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear body.



Yours faithfully

Steve Chen
Automotive Assessor

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 15, 2019 12:00 PM
To: Ye, Yong Kang Melvin; SUR
Cc: Henry, Irene James; Gnoh, Pau Loong
Subject: RE: ACCIDENT INVOLVING SHB3255G AND FBH9245K ON 13/11/2019 SURVEYOR ARRANGEMENT Our ref : CMTD1905296/GPL
Attachments: SHB 3255G PRELI ADVISE.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SHB3255G
Date of survey : 14/09/2019
Number of days : 2 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]
Sent: Thursday, November 14, 2019 2:46 PM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; Taxis Customer Service <taxiscs@stengg.com>; Henry, Irene James <irene.henry@sompo.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Subject: RE: ACCIDENT INVOLVING SHB3255G AND FBH9245K ON 13/11/2019 SURVEYOR ARRANGEMENT Our ref : CMTD1905296/GPL

Without Prejudice

Dear LKK Auto,

Please make arrangement to conduct the survey for SHB3255G on a without prejudice basis.

Best Regards

Melvin Ye

Claims Division



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Taxis Customer Service <taxiscs@stengg.com>

Sent: Thursday, 14 November, 2019 11:58 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg

Subject: ACCIDENT INVOLVING SHB3255G AND FBH9245K ON 13/11/2019 SURVEYOR ARRANGEMENT

Dear Officer,

Kindly please arrange survey for vehicle **SHB3255G**. Vehicle already grounded inside workshop. Survey location will be at 31 Corporation Road.

Best Regards,

VADIVELAN MOHAN

Ding Automotive Pte Ltd

Hp : 96891857 / 62657130

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Thursday, 14 November 2019 2:46 PM
To: SUR; assignments
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; Taxis Customer Service; Henry, Irene James; Gnoh, Pau Loong
Subject: RE: ACCIDENT INVOLVING SHB3255G AND FBH9245K ON 13/11/2019 SURVEYOR ARRANGEMENT Our ref : CMTD1905296/GPL

Without Prejudice

Dear LKK Auto,

Please make arrangement to conduct the survey for SHB3255G on a without prejudice basis.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



or



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Taxis Customer Service <taxiscs@stengg.com>
Sent: Thursday, 14 November, 2019 11:58 AM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: ACCIDENT INVOLVING SHB3255G AND FBH9245K ON 13/11/2019 SURVEYOR ARRANGEMENT

Dear Officer,

Kindly please arrange survey for vehicle **SHB3255G**. Vehicle already grounded inside workshop. Survey location will be at 31 Corporation Road.

Best Regards,
VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	839G
Vehicle Details	
Vehicle No.:	SHB3255G
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Yellow
Manufacturing Year:	2018
Engine No.:	2ZR2C28217
Chassis No.:	JTDKB3FU403081338
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	31 May 2019
First Registration Date:	31 May 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,309.00
COE Rebate Amount:	\$21,034.00
Total Rebate Amount:	\$31,719.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Nov 2019

OK

TRAFFIC POLICE CARD Pg. 1

	TRAFFIC INVESTIGATION BRANCH TRAFFIC POLICE 10 UBI AVENUE 3 SINGAPORE 408865 Fax: 65474749	CASE CARD
	REPORT NO. <u>E/20191113/0093</u> Traffic Accident along <u>PIE (AD) 17.5 KM, Lp/852F</u> involving vehicles <u>SHB3255G & FBH 9245K</u> on <u>13/11/19</u> at about _____ am/pm.	
With reference to the above, you are advised to lodge an accident report online via the SPF Electronic Police Centre website (http://www.police.gov.sg/epc) within 24 hours.		

You are required to be present at Traffic Police on _____ at about _____ am/pm to see the Investigation Officer to assist in the investigation to the traffic accident.

2. Please bring along you >

- a) Identity card/Passport/Work Permit
- b) Driving Licence/Vocational Licence
- c) Vehicle Insurance/Medical Certificate
- d) Any video footage
- e) Any other relevant documents/Witnesses (if any)

3. If you are unable to keep to the appointment, kindly contact the Investigation Officer:

Name: _____

Contact: _____

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

14/11/2019 15:23

OWNER'S PARTICULARS

JOB-NO: 50112198

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 1

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB3255G

TRANS: AUTO

CHASSIS: JTDKB3FU403081338

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR2C28217

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	350.00 <i>290</i>	0.00	350.00		Y	
2 RESPRAY REAR BUMPER	1.00	250.00 <i>290</i>	0.00	250.00		Y	
3 R&R REAR TAIL LAMP AND REPOSITION	1.00	100.00 <i>X</i>	0.00	100.00		Y	
4 CHECK WIRING & LIGHTING SYSTEM	1.00	80.00 <i>70</i>	0.00	80.00		Y	
TOTAL:		780.00	0.00	780.00			
MATERIALS							
1 REAR BUMPER <i>BR</i>	1.00	659.90	164.98	494.92 <i>/</i>	L	Y	
2 REAR RHS TAIL LAMP(UPPER) <i>BR</i>	1.00	523.10	130.78	392.32 <i>/</i>	L	Y	
3 REAR RHS TAIL LAMP(LOWER) <i>BR</i>	1.00	511.20	127.80	383.40 <i>/</i>	L	Y	
4 REAR RHS BUMPER RETAINER <i>BR</i>	1.00	42.83	10.71	32.12 <i>/</i>	L	Y	
5 REAR BUMPER CLIPS <i>N/C</i>	1.00	45.00 <i>30</i>	0.00	45.00	S	Y	
6 REAR BUMPER BODY STICKER (YELLOW) <i>ML</i>	1.00	150.00 <i>80</i>	0.00	150.00	S	Y	
TOTAL:		1,932.03	434.27	1,497.76			
TOTAL PARTS & LABOUR:		2,712.03	434.27	2,277.76			

EXCESS/LOADING:\$ 0.00

No. Of Day: *2 days*

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: *14/11/19, 3-15pm*SURVEYED BY: *Steve (LKK)*CONTACT NO: *8322 8813*

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

14/11/2019 15:23

JOB-NO: 50112198

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 1

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB3255G

TRANS: AUTO

CHASSIS: JTDKB3FU403081338

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR2C28217

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	350.00	770	0.00		350.00	Y
2 RESPRAY REAR BUMPER	1.00	250.00	790	0.00		250.00	Y
3 R&R REAR TAIL LAMP AND REPOSITION	1.00	100.00	X	0.00		100.00	Y
4 CHECK WIRING & LIGHTING SYSTEM	1.00	80.00	70	0.00		80.00	Y
TOTAL:		780.00	0.00	780.00			
MATERIALS							
1 REAR BUMPER / DR	1.00	659.90	164.98	494.92	L	Y	
2 REAR RHS TAIL LAMP(UPPER) / DR	1.00	523.10	130.78	392.32	L	Y	
3 REAR RHS TAIL LAMP(LOWER) / DR	1.00	511.20	127.80	383.40	L	Y	
4 REAR RHS BUMPER RETAINER / DR	1.00	42.83	10.71	32.12	L	Y	
5 REAR BUMPER CLIPS / ML	1.00	45.00	99	0.00	S	Y	
6 REAR BUMPER BODY STICKER (YELLOW) / ML	1.00	150.00	80	0.00	S	Y	
TOTAL:		1,932.03	434.27	1,497.76			

TOTAL PARTS & LABOUR :

2,712.03 434.27 2,277.76

EXCESS/LOADING:\$ 0.00

No. Of Day:

2 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

Steve (LKK)

w/ ML, 14/11/19, 3.15pm

SURVEYED BY:

CONTACT NO:

8322 8813

FAX NO:

P/P / L/S

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Part By Part

Labour = \$430

S/M = \$110

Parts = \$1302.76

L&SP = \$1842.76

Final Amount = \$1842.76



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19020270/Esf3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 25-11-2019	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBH 9245K	Veh. Inspected	SHB 3255G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905296/GPL	Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG	Assign Date	14/11/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU403081338	Colour	YELLOW
Odometer	66301	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	5 mm
L/H Front Tyre	195/65 R15	GOODYEAR	5 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	5 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/11/2019	Inspection Date	14/11/2019
Survey held at	31 CORPORATION ROAD		
Repairer	DING AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3255G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BROKEN	659.90	659.90
1	REAR RHS TAIL LAMP (UPPER)	BROKEN	523.10	523.10
1	REAR RHS TAIL LAMP (LOWER)	CUT	511.20	511.20
1	REAR RHS BUMPER RETAINER	BROKEN	42.83	42.83
	LESS 25% DISCOUNT		-434.27	-434.27
			1,302.76	1,302.76
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
1	REAR BUMPER BODY STICKER (YELLOW)(SN)	NECESSARY	150.00	80.00
			195.00	110.00
LABOUR				
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.		350.00	200.00
	RESPRAY REAR BUMPER.		250.00	200.00
	R&R REAR TAIL LAMP AND REPOSITION.	NOT NECESSARY	100.00	-
	CHECK WIRING & LIGHTING SYSTEM.		80.00	30.00
			780.00	430.00
GRAND TOTAL			2,277.76	1,842.76
RECOMMENDED COST OF REPAIRS				1,842.76

Report Ref No. CS/SMO19020270/Esf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.