

A.S. REC. BY:

REF: CS/MSG/19020206 / Uyd 3 n2 | Special Instruction:

Surveyor: MARCUSASSIGNMENT (Office)From (Person): Meumen Irene Tanof MSIGDate/Time: 14/11/19 @ 5:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 54975

Insured:

SML 5512P

at Workshop m/s

Precise Auto

Tel:

6745 7367

of

1 kaki Bukit Ave 6 # 02-34/36Policy No: 29114756MKF

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:23pm 15/11/19 Person Contacted:AineVehicle IN/OUT

Date/Time	Action/Instruction
	<u>Ishtimold /</u>
	<u>SJY 54975-X</u>
	<u>SML 5512P-X</u>

ASS. REC. BY:

M/C/W

REF:

ASSIGNMENT

From

Date

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

5JY5497S

at Workshop m/s

PAC-22

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

413,800

IDAC Accident Report:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

5JY5497S

Yr Regn:

14/9/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or C.A.

Make:

Hyundai Avante cc 1591

Colour:

S-blue

A/C:

Insured / Std / NI / NA

Sp. Reading

148419

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH DU41BMA4986776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

215/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dayton

Front:

6

Rear:

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/11/19

D.O.I.

15/11/19

*Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2nd. 0/5.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L7A 8503 10mth net \$297

RECEIVED 23 JAN 2020

22/11/19 Sent Pending Estimate to Insurance Co (Merimen)
 13/1/20 Confirmed L/S \$3600 w. the Yan Hong (Red \$2959-28, 45%)
 22/1/19 Sent Preli to Insurance Co

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

22/1/20 Typist

Report Format:

Equip. Sum / L.P. 11

\$3600/=

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Next day (\$

Survey Fee:

Transportation:

3 + RS \$

Plytes

(Other:

TOTAL

150
11
161

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 22 Jan 2020

Preliminary Advice

Insured Vehicle No	: SML5512P	Accident Date	: 13/11/2019
TP Vehicle No	: SJY5497S	Assignment Date	: 14/11/2019
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 5.00
Date of Inspection	: 15/11/2019		
Inspection At	: PRECISE AUTO SERVICE (HQ) NO 1 KAKI BUKIT AVE 6, #02-34/36 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,559.28
Revised Amount	:S\$	3,600.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,600.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2019 09:22		14 Nov 2019 17:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	JOYRIDE CAR RENTAL PTE LTD, Co. Reg. No.: 201842065H		
Vehicle Reg. No.:	SJY5497S	Date of Loss:	13/11/2019 00:00 - :59 [109 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SML5512P	Policy No. (Claimant):	
		Excess:	
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/11/2019]		
Adj Asg. Remarks:	on WP, OI:Grab, Liab: clear, Agree on SJE. Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: Arine @ 6745 7367		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SJY5497S (611753)**
[SML5512P]

TP
JOYRIDE CAR RENTAL PTE LTD
Nov 13 2019 12:00AM
[GRAB RENTALS PTE LTD]
Precise Auto Service

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **22/11/2019 18:23 PM.**
To irene_tan@sg.msig-asia.com
CC sur@lkkauto.com
Subject **VEHICLE NO SJY5497S DOA : 13/11/2019**

Hi Irene

Please be informed that we have inspected the vehicle SJY5497S on 15/11/2019.

We are still pending estimate from repairer.

Thank you

Regards
Yvonne
LKK AUTO CONSULTANTS PTE LTD

DOCUMENTS SUMMARY

There are no documents.

[Advanced Search](#)

Home > Used Cars > D&L Auto Trading > Hyundai Avante 1.6A S

Hyundai Avante 1.6A S

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$14,800		
Depreciation	\$10,100 /yr View models with similar depre	Reg Date	22-Oct-2010 (11mths 6days COE left)
Mileage	N.A.	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$8,389 as of today (change)	OMV	\$10,722
COE	\$32,415	ARF	\$10,722
Engine Cap	1,591 cc	Power	89.7 kW (120 bhp)
Curb Weight	1,264 kg	No. of Owners	4
Type of Vehicle	Mid-Sized Sedan		



Price Chart

Features

1.6L DOHC CVT Engine, 120BHP, 4 Speed Auto, Electric Power Steering, 4xABS Disc Brakes, 2xSRS Airbags, Climatic Aircon Controls, Knockdown Rear Seats [View specs of the Hyundai Avante \(2007-2011\)](#)

Accessories

Genuine Leather Seats, Sports Rims, New Tyres, Pioneer CD Audio Player, Reverse Sensors, Solar Film, Remote Key With Alarm System.

Description

Guaranteed Accident-Free, Well Maintained, Wear & Tear Replaced, 90% Loan At 2.28%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewing.

Category

PAP Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)

Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)[Click on the point to view the vehicle](#)[Shortlist](#)[Compare](#)[Add note](#)[Report Error](#)[More Actions](#)

Seller Information

D&L Auto Trading

35 vehicles for sale, 20 sold in past 3 mths

200 Jalan Sultan #04-20
Textile Centre
Tel: 62960188
[Search cars nearby](#)

Darren Low

96236322

Posted on: 01-Nov-2019 | Last Updated on: 01-Nov-2019

[Upfront Payment](#)
Compare
[» more Financial Info](#)

avante Price Range Depreciation 2010 Vehicle Type Submit

Advanced Search

Home > Used Cars > Auto Quest Singapore > Hyundai Avante 1.6A S

Hyundai Avante 1.6A S

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$16,900		
Depreciation	\$11,760 /yr View models with similar depre	Reg Date	09-Nov-2010 (11mths 24days COE left)
Mileage	130,000 km (14.4k /yr)	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$8,681 as of today (change)	OMV	\$10,673
COE	\$34,001	ARF	\$10,673
Engine Cap	1,591 cc	Power	89.7 kW (120 bhp)
Curb Weight	1,264 kg	No. of Owners	4
Type of Vehicle	Mid-Sized Sedan		

Features

Powerful Yet Smooth 1.6L DOHC Engine, 121Hp, Great Fuel Efficiency, ABS, Twin Airbags, Climatic Control Aircon, Power Flipping Mirrors With Indicators [View specs of the Hyundai Avante \(2007-2011\)](#)

Accessories

Leather Seats, Sports Rims, Good Tyres, Icy Cold Aircon, Solar Film, Alarm, Reverse Sensors, Pioneer Audio, Door Visors, 70:30 Collapsible Rear Seats.

Description

Extremely Good Condition Avante 1.6A Up For Grabs! Shiny Black! Low Documented Mileage With Receipts To Show! Solid Condition Both Inside Out! Look At Photos First, Then Inspect Personally! Great No Frills Run-Abouts Vehicle Less The High Maintenance Costs! Comfortable! Big On Space! Responsive Drive! New 5-Yr COE Renewal Option Available At \$32,900! Hurry, Inquire/View Now! No Regrets For Sure!

Category

PAFF Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Posted on: 15-Oct-2019 | Last Updated on: 15-Oct-2019
[Compare](#)



Location Map

Price Chart

[Click on the point to view the vehicle](#)

[Shortlist](#)

[Compare](#)

[Add note](#)

[Report Error](#)

[More Actions](#)

Seller Information

Auto Quest Singapore

11 vehicles for sale. 2 sold in past 3 mths

1 Bukit Batok Crescent #04-51

WCEGA Plaza

Tel: 68539919

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 065H

Vehicle Details

Vehicle No.: SJY5497S

Vehicle to be Exported: No

Intended Deregistration Date: 15 Nov 2019

Vehicle Make: HYUNDAI

Vehicle Model: AVANTE 1.6 AT ABS D/AB 2WD 4DR

Primary Colour: Silver

Manufacturing Year: 2010

Engine No.: G4FC9U817093

Chassis No.: KMH DU41BMAU986776

Maximum Power Output: 89.7 kW (120 bhp)

Open Market Value: \$11,520.00

Original Registration Date: 14 Sep 2010

First Registration Date: 14 Sep 2010

Transfer Count: 1

Actual ARF Paid: \$11,520.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Sep 2020

PARF Rebate Amount: \$5,760.00

Intended COE Rebate Details

COE Expiry Date: 13 Sep 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$33,089.00

COE Rebate Amount: \$2,743.00

Total Rebate Amount: \$8,503.00

The information contained herein is correct as at 15 Nov 2019

OK

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

31-12-19

Date Of Accident : 13-11-2019

OUR REF : SJY 5497S/T/19

JOYRIDE CAR RENTAL PTE LTD

1 Kaki Bukit Ave 6

#02-34 (Auto Bay @ KB)

Singapore 417883

Lkk - Mercedes

Date In/Out: 13/11/19 to 19/11/19

Not about
about
2/5 \$3600
Schy.
15/11/19

ESTIMATE BILL ON VEH. NO. : SJY 5497S

MODEL : HYUNDAI AVANTE

CHASSIS NO: KMHU41BMAU986776

LIST ITEM

Head Lamp RH		scryene	486.10	—
Head Lmap Lower Bracket		NA	39.80	X
Front Bumper Fascia		Dis	428.60	—
Front Bumper Side Retainer RH		one	42.00	—
Front Bumper Attachment Clips		na	41.40	X
Front Bumper Reinforcement		but	253.80	—
Front Bumper Sponge		toin	125.80	—
Front Bumper Clips	10pcs @ 6.50	na	65.00	—
Fog Lamp Bracket - RH		na	95.40	X
Fog Lamp RH		one	288.10	—
Fog Lamp Cover - RH		17	29.50	X
Front Fender RH		but	396.70	—
Front Fender Emblem "VVTi"		na	28.00	—
Front Fender Splash Shield		toin	53.50	—
Front Fender Splash Shield Clips	8pcs @ 6.50	na	52.00	—
Wiper Washer Tank		ice	48.60	—
Wiper Washer Tank Motor		one/ange	65.00	✓
Wiper Washer Tank Motor Bush		na	8.00	✓
Front Support Panel		one	716.80	—
Radiator Spare Tank		na	47.50	—

	3,311.60
Less Discount 20%:	662.32
	2,649.28

SPECIAL NETT ITEM

Sport Rim Assy (Front RH)

cu 600.00 ⁴⁰⁰

LABOUR CHARGE

Towing

11 80.00 X

To check wiring system

50.00 20

To tuff coat affected areas

180.00 30

To remove & refix radiator & top up coolant

180.00

To remove & refix air con condensor & top up gas

180.00 } 100

To check & adjust computer wheel alignment

120.00 80

To remove & refix front RH sport rim & contact wheel balancing

11 120.00 X


To respray affected areas

1,300.00 800

To renew damaged parts, straighten & repair bumper spoile, front RH door, front RH wheel housing panel and aligned all parts

1,100.00 600

	6,559.28
GST 7%:	459.15
AMOUNT DUE:	7,018.43



P-3105-8
2484.40

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19020286/UYD3N2

Date: 29/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756MKF

Claimant Vehicle No : SJY5497S

Insured Vehicle No : SML5512P

Date of Loss: 13/11/2019

Nature of Claim: TP

Claim No: 611753

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY5497S

Make & Model: HYUNDAI AVANTE, 1.6 ABS D/AB 2WD (A)

Engine No: G4FC9U817093

Reg. Date: 14/09/2010 (Man. Year: 2010)

Chassis No: KMHU41BMAU986776

Colour: Silver

Odometer: 148419 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17

Rear Tyre Size: 215/45R17

Front Left Side: Dayton 6 mm

Rear Left Side: Dayton 6 mm

Front Right Side: Dayton 6 mm

Rear Right Side: Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,249.28	2,884.40	364.88	11.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	1,630.00	1,680.00	50.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,559.28	4,514.40	2,044.88	31.18
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	6,559.28	3,600.00	2,959.28	45.12
+ GST 7.00/7.00% (S\$)	459.15	252.00	207.15	45.12
Nett Amount (S\$)	7,018.43	3,852.00	3,166.43	45.12

INSPECTION

Date of Assignment: 14/11/2019

Date Inspected: 15/11/2019

Inspected At:

Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jan 2020)

Parts: 143 HYUNDAI AVANTE 1.6 ABS D/AB 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJY5497S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP RH	Scratched/Cracked	486.10 FL	*486.10 FL
2	1		*HEAD LAMP LOWER BRACKET	Not fitted	39.80 FL	*- FL
3	1		*FRONT BUMPER FASCIA	Distorted	428.60 FL	*428.60 FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	42.00 FL	*42.00 FL
5	1		*FRONT BUMPER ATTACHMENT CLIPS	Not Necessary	41.40 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	253.80 FL	*253.80 FL
7	1		*FRONT BUMPER SPONGE	Torn	125.80 FL	*125.80 FL
8	10		*FRONT BUMPER CLIPS	Necessary	65.00 FL	*65.00 FL
9	1		*FOG LAMP BRACKET-RH	Not Necessary	95.40 FL	*- FL
10	1		*FOG LAMP RH	Cracked	288.10 FL	*288.10 FL
11	1		*FOG LAMP COVER-RH	Not Necessary	29.50 FL	*- FL
12	1		*FRONT FENDER RH	Buckled	396.70 FL	*396.70 FL
13	1		*FRONT FENDER EMBLEM VVTI	Necessary	28.00 FL	*28.00 FL
14	1		*FRONT FENDER SPLASH SHIELD	Torn	53.50 FL	*53.50 FL
15	8		*FRONT FENDER SPLASH SHIELD CLIPS	Necessary	52.00 FL	*52.00 FL
16	1		*WIPER WASHER TANK	Deformed	48.60 FL	*48.60 FL
17	1		*WIPER WASHER TANK MOTOR	Cracked/Damaged	65.00 FL	*65.00 FL
18	1		*WIPER WASHER TANK MOTOR BUSH	Necessary	8.00 FL	*8.00 FL
19	1		*FRONT SUPPORT PANEL	Cracked	716.80 FL	*716.80 FL
20	1		*RADIATOR SPARE TANK	Deformed	47.50 FL	*47.50 FL
21	1		*SPORT RIM ASSY (FRONT RH)	Cut	600.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,911.60	3,505.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	662.32	621.10
Total Parts (\$\$)	3,249.28	2,884.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	80.00	0.00
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	30.00
4	TO REMOVE & REFIX RADIATOR & TOP UP COOLANT }	New	180.00	100.00
5	TO REMOVE & REFIX AIR CON CONDENSOR & TOP UP GAS }	New	180.00	0.00
6	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT	New	120.00	80.00
7	TO REMOVE & REFIX FRONT RH SPORT RIM & CONTACT WHEEL BALANCING	New	120.00	0.00
8	TO RESPRAY AFFECTED AREAS	New	1,300.00	800.00
9	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR BUMPER SPOILER,FRONT RH DOOR,FRONT RH WHEEL HOUSING PANEL AND ALIGNED ALL PARTS	New	1,100.00	600.00
Gross Labour Cost (\$\$)			3,310.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >