

ASS. REC. BY:

REF: CS/CTI/19020287/Kyd3n2

Special Instruction:

Survey: connected

ASSIGNMENT (Office)

Meitimen

From (Person): Tan Kah Leong

of CTI

Date/Time: 14/11/19 @ 5:30pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 6984Z

Insured: GWS192S

at Workshop n/s Yee Auto

Tel: 6457 2625

of 160 Sin Ming Drive # 02-17

Policy No: DMCVSN/536/219044

Claim No: SNM19D205380C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:37am @ 15/11/19

Person Contacted: winnie

Vehicle IN / OUT

Date/Time	Action/Instruction	Follow up
	SKH 6984Z - NA / CTI / 19020123/24	done 12/11/19
	GWS192S - NA / CTI / 19020123/24	Done: 12/11/19
9/13	LI Sing & 455d email & confirm (Red #11064-20, 70%)	

ASSIGNMENT

From: _____ Date: 15/11/19

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SK4 6984Z

at Workshop m/s: Yee Auto

of 160 Sin Ming Drive # 02-17

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vch: vehicle In.

Veh No: SK11 6984Z yr Regn: 01 / 13

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: M C180 cc: 1595

Colour: white AC: Insured / Std / NI / NA

Sp Reading: 75481 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W00 2043312G 027754

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STB A/Rim or _____

Tyre Size: F: _____ R: 225/45 ER17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____


Front	Rear
R/Bal. 5 mm	R/Bal. 6 mm
L/Bal. 5 mm	L/Bal. 6 mm
D.O.A. 12/11/19	D.O.I. 15/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision: _____



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
RECEIVED 10 MAR 2020	

Date/Time, File Pass to? : Prel. Report

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 3

Date/Time, File Return to? 10/3/20 Stypist

Add Fee: : Site Insp (\$) _____

: Interview (\$) _____

: Tech. Insp (\$) _____

: Wash and (\$) _____

Survey Fee:	
Transportation:	
S + P + J	
Phone:	
Other:	
TOTAL:	220

Report Format: _____

Lang Code: USJG \$4550/

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Est Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2019		14 Nov 2019 17:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	ONG BEE PENG, ID: 56919795G		
Vehicle Reg. No.:	SKH6984Z	Date of Loss:	12/11/2019 16:00 - :59
Claim Type:	TP / SNM19D205380C02	Policy/Cover Note No.:	DMCVSN15361219044
Vehicle Reg. No. (Insured):	GW51925	Policy No. (Claimant):	S119V00012/VPC/R05
		Excess:	S\$0.00
Repairer:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6457 2625		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/11/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 14 November 2019 5:24 PM
To: bonnie kwok; assignments
Subject: RE: OUR REF: SNM19D205380/GW5192S/TKL & YOUR REF: SKH6984Z - PRI - Acc Inv: SKH 6984 Z & GW 5192 S ON 12 NOVEMBER 2019

WITHOUT PREJUDICE

Dear June,

We refer to your email dated 14.11.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Thursday, November 14, 2019 5:14 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205380/GW5192S/TKL & YOUR REF: SKH6984Z - PRI - Acc Inv: SKH 6984 Z & GW 5192 S ON 12 NOVEMBER 2019

Dear Kah Leong,

We refer to your email dated 14 November 2019

Our client has no objection of appointing the motor surveyor Kenneth Kong stated in your said list to conduct the joint pre-repair survey as a single joint expert.

Regards,

June

On Thu, 14 Nov 2019 at 15:21, Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com> wrote:

Without Prejudice

Dear June,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, November 13, 2019 5:26 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; litigation@bonniekwok.com

Subject: OUR REF: SNM19D205380/GW5192S/TKL & YOUR REF: SKH6984Z - PRI - Acc Inv: SKH 6984 Z & GW 5192 S
ON 12 NOVEMBER 2019

Dear Kah Leong

Please conduct PRS –SKN6984Z soonest possible

File with officer-in-charge –Tan Kah Leong- DID 6389 6193.

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok [<mailto:litigation@bonniekwok.com>]

Sent: Wednesday, 13 November, 2019 4:45 PM

To: Claims Dept of CTI

Subject: PRI - Acc Inv: SKH 6984 Z & GW 5192 S ON 12 NOVEMBER 2019

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SKH 6984 Z at M/s Yee Auto Pte Ltd, 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722. Contact number 6457 5768.

Regards,

June

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	795G
Vehicle Details	
Vehicle No.:	SKH6984Z
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	27491030027726
Chassis No.:	WDD2043312G027754
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$35,604.00
Original Registration Date:	08 Jan 2013
First Registration Date:	08 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$30,604.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2023
PARF Rebate Amount:	\$18,362.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$68,000.00
COE Rebate Amount:	\$20,345.00
Total Rebate Amount:	\$38,707.00

The information contained herein is correct as at 10 Jan 2020

OK



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5788 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Estimate No: ES1900116

Date: 13 Nov 2019

Policy No:

Veh Reg No: SKH6984Z

Make/Model: MERCEDES BEN C 180

Chassis No: WDD2043312G027754

Engine No: 27491030027726

Reg. Date: 08/01/2013

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 12/11/2019

Not Authorized

61 Day @ 4550k

Recovery After Party

4 days

Estimate Repair Cost to Vehicle No :SKH6984Z

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00 X	60.00
Spare Parts				
2 REAR BOOT LID <i>1720</i>	2,530.20	1 PC	2,530.20 ✓	
3 REAR BOOT LID CHROME MOULDING	280.10	1 PC	280.10 X	
4 REAR BOOT LID EMBLEM 'C180'	98.50	1 PC	98.50 ✓	
5 REAR BOOT LID EMBLEM 'MERCEDES STAR'	120.00	1 PC	120.00 ✓	
6 REAR BOOT LID HINGE - LH	220.00	1 PC	220.00 X	
7 REAR BOOT LID HINGE - RH	220.00	1 PC	220.00 X	
8 REAR BOOT LID LOCK	355.00	1 PC	355.00 X	
9 REAR BOOT LID TRIMBOARD	480.00	1 PC	480.00 X	
10 REAR BOOT LID TRIMBOARD CLIP	80.00	1 SET	80.00 X	
11 REAR BOOT LID WEATHERSTRIP	265.00	1 PC	265.00 X	
12 REAR BUMPER <i>1500</i>	1,896.10	1 PC	1,896.10 ✓	
13 REAR BUMPER BOTTOM BRACKET - LH	56.50	1 PC	56.50 X	
14 REAR BUMPER BOTTOM BRACKET - RH	56.50	1 PC	56.50 ✓	
15 REAR BUMPER CENTRAL MOULDING	249.90	1 PC	249.90 ✓	
16 REAR BUMPER CHROME SIDE MOULDING - LH	185.00	1 PC	185.00 ✓	
17 REAR BUMPER CHROME SIDE MOULDING - RH	185.00	1 PC	185.00 ✓	
18 REAR BUMPER CLIPS	80.00	1 SET	80.00 ✓	
19 REAR BUMPER INNER GARNISH	288.10	1 PC	288.10 ✓	
20 REAR BUMPER REINFORCEMENT	588.00	1 PC	588.00 ✓	
21 REAR BUMPER REINFORCEMENT BRACKET - LH	155.00	1 PC	155.00 X	
22 REAR BUMPER REINFORCEMENT BRACKET - RH	155.00	1 PC	155.00 X	
23 REAR BUMPER SIDE BRACKET (TOP) - LH	85.00	1 PC	85.00 X	
24 REAR BUMPER SIDE BRACKET (TOP) - RH	85.00	1 PC	85.00 X	
25 REAR BUMPER SIDE RETAINER - LH	105.90	1 PC	105.90 X	
26 REAR BUMPER SIDE RETAINER - RH	105.90	1 PC	105.90 X	
27 REAR BUMPER TOWING COVER	65.00	1 PC	65.00 X	
28 REAR EMBLEM 'TG-TRONIC'	120.00	1 PC	120.00 ✓	
29 REAR END PANEL	710.50	1 PC	710.50 X	
30 REAR END PANEL GARNISH	240.00	1 PC	240.00 X	
31 REAR TAILLAMP - RH	813.00	1 PC	813.00 X	
32 REVERSE SENSORS (4PCS)	450.00	1 SET	450.00 X	

11,324.20 11,324.20

Labour

108



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 12/11/2019

Estimate No: ES1900116
Date: 13 Nov 2019
Policy No:
Veh Reg No: SKH6984Z
Make/Model: MERCEDES BEN C 180
Chassis No: WDD2043312G027754
Engine No: 27491030027726
Reg. Date: 08/01/2013

Estimate Repair Cost to Vehicle No :SKH6984Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
33 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	500
34 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,600.00	1 JOB	1,600.00	500
35 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	30
36 TO COMPUTER RESET.	480.00	1 JOB	480.00	X
37 TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	20
			4,230.00	4,230.00
			Total	SS 15,614.20
			Add GST @ 7%	1,092.99
			Total Amount Payable	SS 16,707.19

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND SEVEN HUNDRED AND SEVEN AND CENTS NINETEEN ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020287/KYD3N2
Date: 11/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN15361219044
Claimant Vehicle No: SKH6984Z Insured Vehicle No: GW5192S
Date of Loss: 12/11/2019 Nature of Claim: TP Claim No: SNM19D205380C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH6984Z
Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491030027726
Reg. Date: 08/01/2013 (Man. Year: 2012) Chassis No: WDD2043312G027754
Colour: White Odometer: 75481 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17 Rear Tyre Size: 225/45ZR17
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	11,384.20	4,671.90	6,712.30	58.96	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,230.00	1,050.00	3,180.00	75.18	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	15,614.20	5,721.90	9,892.30	63.35	
Approved Total (Overridden) (S\$)		4,550.00			
	(S\$)	15,614.20	4,550.00	11,064.20	70.86
	+ GST 7.00/7.00% (S\$)	1,092.99	318.50	774.49	70.86
	Nett Amount (S\$)	16,707.19	4,868.50	11,838.69	70.86

INSPECTION

Date of Assignment: 14/11/2019
Date Inspected: 15/11/2019 Inspected At: Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN MING
AUTOCITY
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2020)
Parts: 143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKH6984Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	2,530.20 F	*1,720.00 FL
2	1		*REAR BOOT LID CHROME MOULDING	Serviceable	280.10 F	*- FL
3	1		*REAR BOOT LID EMBLEM C180	Necessary	98.50 F	*98.50 FL
4	1		*REAR BOOT LID EMBLEM MERCEDES STAR	Necessary	120.00 F	*120.00 FL
5	1		*REAR BOOT LID HINGE-LH	Repair	220.00 F	*- FL
6	1		*REAR BOOT LID HINGE-RH	Repair	220.00 F	*- FL
7	1		*REAR BOOT LID LOCK	Repair	355.00 F	*- FL
8	1		*REAR BOOT LID TRIMBOARD	Serviceable	480.00 F	*- FL
9	1		*SET REAR BOOT LID TRIMBOARD CLIP	Not Necessary	80.00 F	*- FL
10	1		*REAR BOOT LID WEATHERSTRIP	Serviceable	265.00 F	*- FL
11	1		*REAR BUMPER	Buckled/Cracked	1,896.10 F	*1,500.00 FL
12	1		*REAR BUMPER BOTTOM BRACKET-LH	Serviceable	56.50 F	*- FL
13	1		*REAR BUMPER BOTTOM BRACKET-RH	Cracked	56.50 F	*56.50 FL
14	1		*REAR BUMPER CENTRAL MOULDING	Necessary	249.90 F	*249.90 FL
15	1		*REAR BUMPER CHROME SIDE MOULDING-LH	Necessary	185.00 F	*185.00 FL
16	1		*REAR BUMPER CHROME SIDE MOULDING-RH	Necessary	185.00 F	*185.00 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	80.00 F	*80.00 FL
18	1		*REAR BUMPER INNER GARNISH	Cracked	288.10 F	*288.10 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	588.00 F	*588.00 FL
20	1		*REAR BUMPER REINFORCEMENT BRACKET-LH	Repair	155.00 F	*- FL
21	1		*REAR BUMPER REINFORCEMENT BRACKET-RH	Repair	155.00 F	*- FL
22	1		*REAR BUMPER SIDE BRACKET (TOP)-LH	Serviceable	85.00 F	*- FL
23	1		*REAR BUMPER SIDE BRACKET (TOP)-RH	Serviceable	85.00 F	*- FL
24	1		*REAR BUMPER SIDE RETAINER-LH	Serviceable	105.90 F	*- FL
25	1		*REAR BUMPER SIDE RETAINER-RH	Serviceable	105.90 F	*- FL
26	1		*REAR BUMPER TOWING COVER	Serviceable	65.00 F	*- FL
27	1		*REAR EMBLEM TG-TRONIC	Necessary	120.00 F	*120.00 FL
28	1		*REAR END PANEL	Repair	710.50 F	*- FL
29	1		*REAR END PANEL GARNISH	Serviceable	240.00 F	*- FL
30	1		*REAR TAILLAMP-RH	Serviceable	813.00 F	*- FL
31	1		*SET REVERSE SENSORS (4 PCS)	Serviceable	450.00 F	*- FL
32	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	11,384.20	5,191.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	519.10
Total Parts (\$\$)	11,384.20	4,671.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,800.00	500.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,600.00	500.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	200.00	30.00
4	TO COMPUTER RESET	New	480.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	150.00	20.00
Gross Labour Cost (S\$)			4,230.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >