

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 13/11/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGV6663Z	Ashes.	
MODEL	: TOYOTA ESTIMA 2.4A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 13-Nov-19
		TIME	: 11:30HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER SIDE RETAINER RH <i>Nec</i>	1	\$ 110.00	\$ 110.00
2	HEADLAMP (HID)RH <i>cracked.</i>	1	\$ 1,985.50	\$ 1,985.50
3	FRONT FENDER RH <i>Repair</i>	1	\$ 720.00	\$ 720.00
4	FRONT FENDER EMBLEM 'VVT-I' <i>Nec</i>	1	\$ 90.00	\$ 90.00
5	FRONT FENDER INNER COWLING <i>Nec</i>	1	\$ 280.00	\$ 280.00

2140.5

TOTAL PRICE \$ 3,185.50

1605.37

LESS 25% \$ 796.38

SUB TOTAL PRICE \$ 2,389.13

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER <i>Replaced</i>	1	\$ 1,600.00	\$ 1,600.00
2	FRONT BUMPER CLIPS(SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00
3	FRONT FENDER INNER COWLING CLIPS(SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00

1220

TOTAL \$ 1,640.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00	300
---	---	-------------	-----

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	400
3	TUFF COAT	\$ 120.00	X
4	WIRING CHECK	\$ 80.00	30

TOTAL 730 \$ 2,200.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,029.13

TOTAL LABOUR COS : \$ 2,200.00

TOTAL REPAIR COS : \$ 6,229.13

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Ly
H/S 13/11/19.
04 Days.

Total: 3555.37
H/S: 2.8/12

P: +2,140.50
-25%
= 1,605.38
S/N +1,220.00
L: + 730.00
= 3,555.38
-20%
H/S: +2,800

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: