



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Malakar Rina	Cust No/Name	/Malakar Rina
3 CARMEN TERRACE	Reg No/Reg Date	SKT2993K / 29/05/201
459682	Date In/Mileage	/ 0
Contact No Mobile: 96345034	Chassis No	KNAFX411MF5448499
	Engine No	G4FGFH776524
	Make/Model	KIA/FORTE K3 1.6 A EX W/ LED & D.BR
	Colour/Trim	4SS / WK


Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	15/11/2019/ 09:35	QUK	282 / Kevin Leong	61940			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550 1100.00
TO RENEW REAR BUMPER, REAR BUMPER LOWER & AFFECTED AREA								420 840.00
E PNT98000								120 150.00
PAINT WORK ON REAR BUMPER PANEL								X 40.00
E PNT88000								80.00
TO REMOVE & INSTALL REAR PARKING ASSIST								180.00
M SUNDRY								20 50.00
TO APPLY BODY SEALANT								
A 54900099								
CHECK ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
SUNDRIES								
M COVER-RR BUMPER,UPR					1.00	234.00	00.00	234.00
M COVER-RR BUMPER					1.00	768.00	00.00	768.00
M COVER-RR BPR UNDER?					1.00	42.00	00.00	42.00
M BEAM-RR BUMPER					1.00	365.00	00.00	365.00
M BRACKET-RR BEAM LWR MTG					1.00	5.00	00.00	5.00
M BRACKET-RR BEAM LWR,CTR					1.00	5.00	00.00	5.00
M BRACKET-RR BEAM LWR MTG					1.00	5.00	00.00	5.00
M BRACKET-RR RAIL UPR MTG,LH					1.00	4.00	00.00	4.00
M BRACKET-RR RAIL UPR MTG,RH					1.00	4.00	00.00	4.00
M STAY-RR BUMPER LH					1.00	75.00	00.00	75.00
M STAY-RR BUMPER RH					1.00	75.00	00.00	75.00
M BRACKET-RR BUMPER SIDE MTG,LH					1.00	33.00	00.00	33.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

SURVEYOR NAME: Rasul - 40 20010568

SURVEYOR SIGNATURE: 

DATE: 20/07/2020 @ 1110

REMARKS: 3 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

Date: 1.00 234.00 00.00 234.00  
 1.00 768.00 00.00 768.00  
 1.00 42.00 00.00 42.00  
 1.00 365.00 00.00 365.00  
 1.00 5.00 00.00 5.00  
 1.00 5.00 00.00 5.00  
 1.00 5.00 00.00 5.00  
 1.00 4.00 00.00 4.00  
 1.00 4.00 00.00 4.00  
 1.00 75.00 00.00 75.00  
 1.00 75.00 00.00 75.00  
 1.00 33.00 00.00 33.00

SURVEYOR NAME: RASUL - 4p 200w68

SURVEYOR SIGNATURE: [Signature]

DATE: 20/07/2020 @ 1110

REMARKS: 3 days

Confirm &amp; accepted by

Remy before paint

7% GST on      **Nett**      4,055.00  
                          4055.00      283.85

**Total Payable** 4,338.85

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.