

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKU6080M/1911148

15th November 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

: Date: 15th November 2019

Date of Accident

Location

Third Party Claim Vehicle No

Repair Cost For Vehicle No

: Paya Lebar Road

: SBJ 9800 Y

: SKU 6080 M Toyota Vellfire

Not Allowed
Wkph before painting
18/11/19
3 day.

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Headlamp assy LH <i>SCR</i>	1	4,198.90	\$ 4,198.90
2	Front bumper fascia <i>Deep CW</i>	1	1,380.00	\$ 1,380.00
3	Front bumper clips <i>nu</i>	1set	85.00	\$ 85.00
4	Front bumper side retainer LH <i>11</i>	1	980.20	\$ 980.20
5	Front bumper fog lamp chrome LH	1	299.10	\$ 299.10
6	Front fender LH <i>n</i>	1	997.60	\$ 997.60
7	Front fender cowling LH	1	265.70	\$ 265.70
8	Front fender cowling clips LH <i>11</i>	1	39.00	\$ 39.00
9	Front quarter glass moulding LH <i>11</i>	1	346.60	\$ 346.60
10	Front quarter glass sealant (s/net) <i>11</i>	1	40.00	\$ 40.00
				\$ 8,632.10

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front fender LHL, remove & install all damage parts, straighten & re-align body	\$ 980.00 <i>400</i>
Tuff-kote on damage parts	<i>11</i> \$ 40.00 <i>X</i>
Spray painting on damage parts	\$ 1,080.00 <i>400</i>
Remove & refix rear front quarter glass	<i>11</i> \$ 100.00 <i>X</i>
Check all lighting after repairs	\$ 45.00 <i>20</i>
Computerize wheel alignment	\$ 180.00 <i>60</i>
Labour Charge	\$ 2,425.00
Total Amount	\$ 11,057.10

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.