

Surveyor:

MARCUS

DOI: 18.11.2019

Date / Time: 18/11/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. PC 7262J

Claim No. :

Name of Insured

Policy No. :

Insured Tel No.

HP:

Make / Model :

Excess Sec II :SS

D.O.A : 18/11/2019

Place of Accident :

Is driver the owner?

(YES) (NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Driver Tel No. :

(V/L) YES (NO)

Insured Liability :

%

Final ? Yes / No

GBE 1814L

INSRS:
WSP: FASTECH
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
	GBE 1814L -X	Non-Reporting ltr (1st):	
	PC 7262J - CS/CTI19017319/Ksd3n2; DOA: 30.09.2019	Non-Reporting ltr (2nd):	
	- NA/INC19011564/h4; DOA: 6.5.19	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
17-12-19	FILE PROC TO TPA TO PREPARE REPORT.	Call OI:	17.12.19
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☐
		LTA / GIA :	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:		Post-Repair Photos:		☐		☐	
					Others:		☐		☐	
FINALIZATION		Date/Time:	Confirm with:		Confirm by: GCS					
Repair Cost:		45	SS 4,500	(4 days) Reduction:	72 %	Email ☒		Call ☐		
FINAL SETTLEMENT		Date/Time: 02.03.20	Confirm with: JAMES		Email ☐		Call ☐			
Final Liability:		% 100	(Agreed / Assessed) BOLA S/N No.:		31	If NO or B 28, Ass. Lia :				
Repair Cost:		with	SS4,815.00	DID REPAIR ENDED TP.						
Loss of Rental (LOR):		SS 240.00	(3 days) x		450	COPY SENT 24/3/2020				
Loss of Use (LOU):		SS -	(5 x days)							
Loss of Income (LOI):		SS -	(5 x days)							
LOR only ☒		LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]					
GIA/LTA Search		SS 2.00								
Medical:		SS -								
Disbursement:		SS -	(e.g. Tow/ Independent)							
Legal Cost		SS -								
Total:		SS 5,051.00	Global Sum SS:							
FINAL PAYMENT		Date/Time: 02.03.20	Confirm with: JAMES		Email ☒		Call ☐			
Payee 1:		SS 5,051.00	Name 1:		FASTECH AUTO PTE LTD.					
Payee 2: (Strike if N.A.)		SS	Name 2:							
Payee 3: (Strike if N.A.)		SS	Name 3:							

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBE 18146
 at Workshop m/s PC 72623
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bol. or Market Value: 386
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: GBE 18146 Yr Regn: 9.15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CM
 Make: Nissan NV200 cc 1461
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: -129076 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VSKYBAM 2020097389
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nit / S/Rim / STD A/Rim or
 Tyre Size: F: 175/70R14
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 18/11/19 D.O.I. 18/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/11/19 1/5 + 4500 contained with Ahr.

(RED: + 11,458.30 70%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Form:

Temp. Form / L.B.J.:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Wheel Align %

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE. 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM19D205522
Our ref: CC6/CTI19020384/Uea3

Date: 04/12/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBE 1814L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/11/2019 at the premises of M/s Fastech Auto Pte Ltd - Kaki Bukit and have the following to report:-

Workshop Estimate Amount	: S\$	15,928.20
Revised Estimate Amount	: S\$	4,500.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	4,500.00

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Enjoy 1.99% p.a. (EIR 3.77% p.a.) on your pre-owned car loan & FREE QVIA Dashcam

Apply now

NV200

Price Range

Depreciation

2015

Vehicle Type

Submit

Advanced Search

Home » Used Cars » The Car Enthusiast Pte Ltd » Nissan NV200 1.6A

Nissan NV200 1.6A

Overview	Financial	Accessories	Similar	Research	Photos	Map
Price	\$39,800		Fuel Type	Petrol		
Depreciation	\$6,890 /yr View models with similar depre		Reg Date	26-Aug-2015 (5yrs 9mths 7days COE left)		
Mileage	81,284 km (19.2k /yr)		Manufactured	2015		
Road Tax	N.A.		Transmission	Auto		
Dereg Value	\$22,434 as of today (change)		OMV	\$14,436		
COE	\$38,863		ARF	\$722		
Engine Cap	1,597 cc		No. of Owners	1		
Curb Weight	1,220 kg					
Type of Vehicle	Van					

Features
View specs of the Nissan NV200 (2011)

Description
1 Owner Only! Well Maintained, Excellent Condition! Bank Or In House Loan Available. Call For More Enquiries!

Category
-

Status
Available


Resources



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



Click on the point to view the vehicle

Shortlist

Report Error

Compare

More Actions

Add note

Posted on: 15-Nov-2019 | Last Updated on: 15-Nov-2019

Upfront Payment		» more Financial info
Transfer Fee	\$25	
Down Payment	\$3,980 (change)	Maximum 90% Loan
1st Instalment	\$621	Based on 3.4% interest rate
Compare		

Seller Information

The Car Enthusiast Pte Ltd

17 vehicles for sale, 18 sold in past 3 mths

1 Bukit Batok Crescent #04-25

WCEGA Plaza

Tel: 66848470

sgcarmart.com

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Enjoy 1.99% p.a. (EIR 3.77% p.a.) on your pre-owned car loan & FREE QVIA Dashcam

Apply now
or apply.

NV200

Price Range

Depreciation

2015

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Car (S) Pte Ltd » Nissan NV200 1.5M

Nissan NV200 1.5M

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price	\$36,800	Lifespan	27-Aug-2035
Depreciation	\$6,370 /yr View models with similar depre	Reg Date	28-Aug-2015 (5yrs 9mths 9days COE left)
Mileage	77,067 km (18.2k /yr)	Manufactured	2015
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$11,353 as of today <i>(change)</i>	OMV	\$20,266
COE	\$19,649	ARF	\$1,014
Engine Cap	1,461 cc	No. of Owners	1
Curb Weight	1,280 kg		
Type of Vehicle	Van		

Features

Reverse Camera, Reverse Sensor, Road Tax Till 02/2020! [View specs of the Nissan NV200 \(2011\)](#)

Description

Owner's Personal Transportation Vehicle From Home To Workplace Only! 1 Owner Unit With Genuine Low Mileage, Extremely Well Maintained. Kindly Contact Us For More Enquiry!

Category

Premium Ad Car

Status

Available

Resources

Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Posted on: 18-Nov-2019 | Last Updated on: 18-Nov-2019

Upfront Payment

Compare

» more Financial info

Seller Information

Car (S) Pte Ltd

95 vehicles for sale. 105 sold in past 3 mths

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	472G

Vehicle Details

Vehicle No.:	GBE1814L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Nov 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	K9KC400D054473
Chassis No.:	VSKYBAM20Z0097389
Maximum Power Output:	-
Open Market Value:	\$20,122.00
Original Registration Date:	22 Sep 2015
First Registration Date:	22 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$1,007.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	21 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$50,002.00
COE Rebate Amount:	\$29,402.00
Total Rebate Amount:	\$29,402.00

The information contained herein is correct as at 18 Nov 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	472G
Vehicle Details	
Vehicle No.:	GBE1814L
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	K9KC400D054473
Chassis No.:	VSKYBAM20Z0097389
Maximum Power Output:	-
Open Market Value:	\$20,122.00
Original Registration Date:	22 Sep 2015
First Registration Date:	22 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$1,007.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$50,002.00
COE Rebate Amount:	\$29,402.00
Total Rebate Amount:	\$29,402.00

The information contained herein is correct as at 18 Nov 2019

OK

not Adhuan
18/11/19 4/5 = 4500 4dy.

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
S'PORE 417883 TEL 67457158

VEHICLE No:GBE 1814L

NETT ITEM

1PC	REAR BACK DOOR N/S	606.50	1281.10	\$1,610.10	—
1PC	REAR BACK DOOR 'NV 200' EMBLEM N/S	all	77.90	\$205.30	—
1PC	REAR BACK DOOR REAR LOGO N/S	all		\$66.80	—
1PC	REAR BACK DOOR OUTER HANDLE N/S	11		\$168.50	X
1PC	REAR BACK DOOR LOWER LOCK N/S	11	185.50	\$299.30	—
1PC	REAR BACK DOOR INNER TRIM N/S	11		\$625.10	X
1SET	REAR BACK DOOR INNER TRIM CLIPS N/S	11		\$25.00	X
1PC	REAR BACK DOOR O/S	11	960.90	\$1,615.10	—
1PC	REAR BACK DOOR 'DCI' EMBLEM O/S	all		\$66.80	—
1PC	REAR BACK DOOR LOWER LOCK O/S	11		\$299.30	X
1PC	REAR BACK DOOR INNER RUBBER O/S	11		\$288.50	X
1PC	REAR BACK DOOR INNER TRIM O/S	11		\$605.10	X
1SET	REAR BACK DOOR INNER TRIM CLIPS O/S	11		\$30.00	X
1PC	REAR BUMPER	11	624.60	\$822.30	—
2PCS	REAR BUMPER REFLECTORS @\$60.00	11		\$120.00	X
1PC	REAR BUMPER SPONGE	11	84.00	\$288.00	—
2PCS	REAR BUMPER SIDE HOLDERS @\$95.00	11		\$190.00	X
2PCS	TAILLAMPS @\$480.00	11		\$960.00	X
1PC	REAR END PANEL	11	510.80	\$655.20	—
1PC	REAR END PANEL TOP GARNISH	11		\$311.30	X
1PC	REAR END PANEL WEATHERSTRIP	11		\$366.50	X
1PC	REAR FLOOR PANEL	11		\$1,420.00	X
				11838.20	3820.60
	S.NETT				
1PC	REAR BACK DOOR GLASS SEALANT N/S	all		\$50.00	40
1PC	70KM/H STICKER	all		\$20.00	10
1PC	REAR BACK DOOR GLASS SEALANT O/S	all		\$50.00	40
1PC	6 PAX STICKER	all		\$20.00	10
1SET	REAR BUMPER REVERSE SENSOR	11		\$280.00	200
1SET	REAR BUMPER CLIPS	all		\$30.00	✓
1SET	REAR FLOOR PANEL INSULATOR	11		\$180.00	X
	TO CHECK WIRING			\$80.00	30
	TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00	50
	TO DISMANTLE & REFIX BOTH BACK DOOR GLASS			\$300.00	200
	TO DISMANTLE & REFIX BOTH BACK DOOR MECHANISM			\$200.00	100
	TO DISMANTLE & REFIX REAR EXHAUST	11		\$100.00	X
	TO SPRAY RUST PROOFING			\$120.00	80
	TO CONDUCT CHASSIS ALIGNMENT	11		\$380.00	X
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,500.00	600
	TO PUTTY & SPRAY PAINTING			\$1,500.00	800
	TOTAL			\$15,920.20	

5621.54

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 13 December, 2019 6:45 PM
To: Tan Kah Leong
Cc: Asher Sng (LKKAUTO); Admin A
Subject: RE: OUR REF: SNM19D205522-PC7262J-TKL- Accident Involving PC7262J (OI : CTI - TBA) AND GBE1814L (TP : LKK REF - CC6/CTI19020384/Uea3) on 18/11/2019
Attachments: TP ESTIMATE-MARKED.pdf; Preliminary Advice.pdf; OI GIA REPORT.PDF
Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

CTI ref : SNM19D205522
LKK ref : CC6/CTI19020384/Uea3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: GBE 1814L

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- OI GIA report

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 22 November, 2019 9:12 AM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: RE: OUR REF: SNM19D205522-PC7262J-TKL- Accident Involving PC7262J (OI : CTI - TBA) AND GBE1814L (TP : LKK REF - CC6/CTI19020384/Uea3) on 18/11/2019

Without Prejudice

Dear Mei Kwan,

Subject: Direct Settlement - Accident Involving PC7262J (OI : CTI - TBA) AND GBE1814L (TP : LKK REF - CC6/CTI19020384/Uea3) on 18/11/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBE 1814L at M/s Fastech Auto Pte Ltd - Kaki Bukit on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CT119020384/Uea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 25-03-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 7262J	Veh. Inspected	GBE 1814L	
Policy No.	DMB1SN3035141900	Coverage (\$)	0.00	
Claim No.	SNM19D205522	Excess (\$)	0.00	
Assign From		Assign Date	18/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VSKYBAM20Z0097389	Colour	BLACK	
Odometer	129076	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	DUNLOP	5 mm	
L/H Front Tyre	175/70 R14	DUNLOP	5 mm	
R/H Rear Tyre	175/70 R14	DUNLOP	5 mm	
L/H Rear Tyre	175/70 R14	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/11/2019	Inspection Date	18/11/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 1814L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BACK DOOR N/S	BADLY DENTED	1,610.10	1,281.10
1	REAR BACK DOOR "NV200" EMBLEM N/S	NECESSARY	205.30	79.90
1	REAR BACK DOOR REAR LOGO N/S	NECESSARY	66.80	66.80
1	REAR BACK DOOR OUTER HANDLE N/S	NOT NECESSARY	168.50	-
1	REAR BACK DOOR LOWER LOCK N/S	TWISTED / JAMMED	299.30	145.50
1	REAR BACK DOOR INNER TRIM N/S	NOT NECESSARY	625.10	-
1	SET REAR BACK DOOR INNER TRIM CLIPS N/S	NOT NECESSARY	25.00	-
1	REAR BACK DOOR O/S	DENTED	1,615.10	960.90
1	REAR BACK DOOR "DCI" EMBLEM O/S	NECESSARY	66.80	66.80
1	REAR BACK DOOR LOWER LOCK O/S	NOT NECESSARY	299.30	-
1	REAR BACK DOOR INNER RUBBER O/S	NOT NECESSARY	288.50	-
1	REAR BACK DOOR INNER TRIM O/S	NOT NECESSARY	605.10	-
1	SET REAR BACK DOOR INNER TRIM CLIPS O/S	NOT NECESSARY	30.00	-
1	REAR BUMPER	DENTED / DEFORMED	822.30	624.80
2	REAR BUMPER REFLECTORS @\$60.00	NOT NECESSARY	120.00	-
1	REAR BUMPER SPONGE	TORN	288.00	84.00
2	REAR BUMPER SIDE HOLDERS @\$95.00	NOT NECESSARY	190.00	-
2	TAILLAMPS @\$480.00	NOT NECESSARY	960.00	-
1	REAR END PANEL	DENTED / BENT	655.20	510.80
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	311.30	-
1	REAR END PANEL WEATHERSTRIP	NOT NECESSARY	366.50	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,420.00	-
	LESS 10% DISCOUNT		-	-382.06
			11,038.20	3,438.54
SPECIAL NETT ITEMS				
1	REAR BACK DOOR GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	REAR BACK DOOR GLASS SEALANT O/S (SN)	NECESSARY	50.00	40.00
1	6PAX STICKER (SN)	NECESSARY	20.00	10.00

Report Ref No. CC6/CTI19020384/Uea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	180.00	-
			630.00	330.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX BOTH BACK DOOR GLASS.		300.00	200.00
	TO DISMANTLE & REFIX BOTH BACK DOOR MECHANISM.		200.00	100.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		120.00	80.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,500.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			4,260.00	1,860.00
GRAND TOTAL			15,928.20	5,628.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC6/CT119020384/Uea3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.