

KK
Attan Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singn
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No:
Date:
Policy No:
Veh Reg No:
Make/Model:

0 * C
498 * 1 +
149 * +
21 * +
304 * +
737 * 1 =
1,709 * 2 *
1,709 * 2 *
75 * %
1,281 * 9 *
0 * C

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 06/11/2019
TP Veh Reg No: SLH2592K

Not Notarized
Respray Bepalim
3 days

Chassis No:
Engine No:
Reg. Date:

250 * +
280 * =
530 * *

Estimate Repair Cost to Vehicle No :GBH4851

Description	U/Price	Quantit		
List Price				
1 FRONT BUMPER	498.10	1 P		
2 FRONT BUMPER RH RETAINER	149.00	1 P		
3 FRONT BUMPER CLIPS	3.50	6 P		
4 FRONT BUMPER REINFORCEMENT	304.00	1 PC	21.00	
5 RH HEADLAMP	737.10	1 PC	304.00	
			737.10	
			1,709.20	
	Less 25%		427.30	1,281.90
Labour				
6 REMOVE & REFIX FRT BUMPER, HEADLAMP, FRT BUMPER REINFORCEMENT & REALIGN THE SAME	400.00	1 LA	400.00	2501
7 PUTTY & RESPRAY ON FRT BUMPER, REINFORCEMENT	400.00	1 LA	400.00	280
			800.00	800.00

Total S\$ 2,081.90
Add GST @ 7% 145.73
Total Amount Payable S\$ 2,227.63

Handwritten calculation:
\$1209.20
427.30

\$1281.90
530

\$1811.90 ✓ dk

For Cheng Hoe Motor Pte Ltd

[Signature]
AUTHORISED SIGNATURE

