

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 5750K

DATE : 16/11/2019

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (LH) X (R)			\$ 2,256.40
	Front Door Glass (LH) SCR			\$ 228.20
	Front Door Outer Handle (LH) SCR X (R)			\$ 36.30
	Front Door Outer Moulding (LH) SCR			\$ 47.10
	Front Door Mirror Assy (LH) Br			\$ 670.00
	Rear Door (LH) BUC			\$ 2,201.10
	Rear Door Glass (LH) xnn			\$ 200.20
	Rear Door Outer Moulding (LH) xnn			\$ 35.80
	Rear Door Outer Handle (LH) SCR			\$ 36.30
	Front Windscreen Moulding nec			\$ 113.30
	Front Windscreen Pillar Inner(LH/RH) xnn			\$ 310.70
	Front Windscreen Enforcement(LH/RH) xnn			\$ 1,163.30
	Frt DOOR outer chrome garnish DD			
	SUB TOTAL			\$ 7,298.70
	LESS 20%			\$ 1,459.74
	DISCOUNTED TOTAL			\$ 8,758.44
	Front Door Comfort Logo (LH) nec			\$ 75.00
	Front Door Advertisement Logo (LH) nec			\$ 100.00
	Rear Door Tel No. Sticker (LH/RH) nec			\$ 10.00
	Front Windscreen Sealant nec			\$ 46.00
				\$ 231.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	TOTAL LABOUR			\$ 2,170.00
	ESTIMATE TOTAL			\$ 11,159.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CMMV

Ching

2636.54

1630

Ram (LKR)
886227784
Ramaswami@LKRauto.com
get repair photo
3 repair days
45
45 = \$3600
3 repair days