Tech, Invs (5)

Westend (S)

11

Report Formst:

Lump Tum H.B.J: (3)

Nivitha (LKK Auto)

From:

Claims Dept <claims@premiumauto.com.sg>

Sent:

Friday, 15 November 2019 6:01 PM

To:

'assignments'; 'Admin-D (LKKAuto)'; 'SUR'

Cc:

'Claims Dept'

Subject:

OD CLAIM FOR SKK 392 E

Attachments:

SKK 392 E - 15112019.pdf

Dear all.

Kindly arrange survey on 19/11/2019@10am owner waiting.

Attached GIA report for your kind reference.

Thank you.

Best Regards, Tony Foong Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323. d. +65 67689911

e.mailto:claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Shiau Chan (LKKAuto)

From:

Claims Dept <claims@premiumauto.com.sg>

Sent:

Wednesday, 4 December 2019 6:46 PM

To:

'Claims Dept'; 'Nadaraja, Deebanalnadaraja'; Shiau Chan (LKKAuto)

Cc:

'Lim, Sheng Yang'; 'Parthiban, Theerthan'; 'Mohd Rizal, Nur Mariah Huibrechts';

boojohnny@gmail.com; Adrian Ling (LKKAuto)

Subject:

RE: - AIG RE: OD CLAIM FOR SKK 392 E, DOA= 15/11/2019

Attachments:

SKK 392 E - REPORTING ONLY.PDF

Dear all,

Kindly be inform, owner decided withdraw claim.

Attached GIA report (Reporting only) for your kind reference.

We will proceed to close file.

Thank you.

Best Regards, Tony Foong Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911
e.mailto:claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Friday, 22 November 2019 7:55 AM

To: 'Nadaraja, Deebanalnadaraja'; 'Shiau Chan (LKKAuto)'; 'assignments'; 'SUR'

Cc: 'Lim, Sheng Yang'; 'Parthiban, Theerthan'; 'Mohd Rizal, Nur Mariah Huibrechts'; 'Claims Dept'

Subject: RE: - AIG - RE: RE: OD CLAIM FOR SKK 392 E, DOA= 15/11/2019

Dear Deeban,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	15/11/2019 15:31
Date Of Accident	15/11/2019 13:40
Exact Location Of Accident	PIE BEFORE KALLANG WAY EXIT 13 TWDS CHANGI
Country/State of Loss	SINGAPORE
. D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKK392E
Insured/Policyholder	MOST AND MANY SAME AND
Name Of Registered Owner	LEAH-DIANE WARDEN XIU YU
NRIC No	S9613700A
Email Address	LEAH.DWARDEN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92977849
Alternative Phone No	OTHERS-92977849
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	The second secon
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800156533
Cover Note Number	03/01/2019 TO 02/01/2020
Driver	the state of the s
Name of Driver	LEAH-DIANE WARDEN XIU YU
NRIC No	S9613700A
Date Of Birth	20/04/1996
Occupation	INDOOR
Date Of Driving Pass	25/05/2015
Driving Experience	4 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92977849
Fax Number	

OTHERS-92977849

LEAH.DWARDEN@GMAIL.COM

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours: Monday to Friday, 09:00 - 17:00 UEN: \$66\$\$0020G / GST Reg. No.: M400017735

Address

Contact (Tel)

Email Address

Date of Accident

Place of Accident

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: Original Report No : MKFS19151242 _Vehicle Registration No: SKK392E Name(as shown in NRIC): LEAH-DIANE WARDEN XIU YU_NRIC/FIN/Passport No : S9613700A (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate : 60c eng neo avenue singapore 289542 Mobile No. : 92977849 . leah.dwarden@gmail.com : 15/11/2019 _Time of Accident : 1340hrs pie before kallang way exit 13 twds changi

(B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Insurance Company: AIG Asia Pacific Insurance Pte. Ltd.

		
	1	

LEAH-DIANE WARDEN XIU YU

To amend add in police report.

Policyholder / Driver's Signature Date:

Reporting Centre Personnel's Signature

Name: NRIC/FINNo.:

Date: 18/11/2019

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours : Monday to Friday, 09:00 – 17:00 UEN: 566550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

		AI	DDENDUM	
(A)	PARTICULARS OF PE	RSONMAKINGTHEAME	NDMENTS:	
	Original Report No	1	Vehicle Registration N	o: SKK392E
	Name(as shown in NRIC)	: LEAH-DIANE WARDE	N XIU YU_NRIC/FIN/Passport No	: S9613700A
	(*Vehicle Driver / Ve	ehicle Owner) (*) Please de	elete as appropriate	
	Address	: 60c eng neo avenue s	ingapore 289542	Singapore()
	Contact (Tel)	:	Mobile No. : 9297784	9
	Email Address	leah.dwarden@gmail.	com	
	Date of Accident	: 15/11/2019	Time of Accident :13	40hrs
	Place of Accident	. PIE BEFORE KALLAN	NG WAY EXIT 13 TWDS CHANG	31
		. AIG ASIA PACIFIC	INSURANCE PTE LTD	7
	To amend from ow	vn damage claim to acci	dent reporting only.	
				1
			1 Table 1	
			K 5/2	
			17 Sept. 15 cm	
			- 4	
	<u> </u>			1
			19	100
	h	-	The state of the s	100 mg
	Policyholder / Driver	r's Signature	Reporting Centre P	ersonnel's Signature

NRIC/FIN No .:

Date: 04/12/2019

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 21 November 2019 11:54 AM

To:

Claims Dept; assignments; SUR

Subject:

RE: OD CLAIM FOR SKK 392 E

Dear Tony,

Instructed by our client, please proceed to repair the insured vehicle SKK 392E (Excess \$800).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com> Sent: Wednesday, 20 November 2019 5:58 PM

To: Claims Dept <claims@premiumauto.com.sg>; assignments <assignments@lkkauto.com>; SUR

<sur@lkkauto.com>

Subject: RE: OD CLAIM FOR SKK 392 E

Dear Tony,

Please be informed that we are still pending for insurance's mandate approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>

Sent: Wednesday, 20 November 2019 5:56 PM

To: 'Claims Dept' <<u>claims@premiumauto.com.sg</u>>; assignments <<u>assignments@lkkauto.com</u>>; Admin-D (LKKAuto)

<admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: OD CLAIM FOR SKK 392 E

Dear all,

Any update on repair approval?

Thank you.

Best Regards,

Claim Audit

Vo.	On	Audit	Remarks	By
	15 Nov 2019 16:38	Clm Veh Model Changed		[] Merimen Administrato
	15 Nov 2019 16:38	Clm Created	Reg No: SKK392E, Policy No: 1800156533, Acct Date: 2019/11/15, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte, Ltd. (SG), Ins.Status => Notification. Cr eated from SAS:MKFS19151242	[1] Merimen Administrato
3	20 Nov 2019 07:59	Clm Registration Modified	Acct Time:13:40:00->13:00:00,	[I] Lim, Sheng Yang
4	20 Nov 2019 08:23	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Nivitha Govindasam
5	20 Nov 2019 08:23	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Nivitha Govindasam
6	20 Nov 2019 08:23	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasam
7	20 Nov 2019 08:23	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/11/29	[A] Nivitha Govindasam
8	20 Nov 2019 08:23	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasam
9	20 Nov 2019 08:23	Clm Registration Modified	Rep:1137->200611.	[A] Nivitha Govindasam
10	20 Nov 2019 08:23	Clm Veh Model Changed	(202153) AUDI A4 2.0 TFSI QU S-TRONIC (A).	[A] Nivitha Govindasam
11	20 Nov 2019 08:23	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Nivitha Govindasam
12	20 Nov 2019 10:03	Adj Rpt Initiated		[A] SHIAU CHAN
13	20 Nov 2019 10:03	Clm Dtl Modified	JPJ Reg. Date: -> 2019/01/03.	[A] SHIAU CHAN
14	20 Nov 2019 10:03	Clm Details Notified		[A] SHIAU CHAN
15	20 Nov 2019 10:43	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/11/29	[A] SHIAU CHAN
16	20 Nov 2019 10:43	Adj Mandate Request	Cur.Req:32903.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	20 Nov 2019 11:56	Clm Registration Modified	Init.Est.:->5,000 - 6,000.	[I] Abu Kassim, Noo Mariesa
18	21 Nov 2019 10:32	Clm Registration Modified	Excess: -> 800.00. Excess Waived: -> 800.00. 2F Remarks: -> Not Applicable. GS T: -> 7.00.	
19	21 Nov 2019 10:32	Label Added	(20226):Coverage Confirmed.	[A] Merimer Administrato
20	21 Nov 2019 11:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/11/29. Mandate Remarks: Re-inspection to be d one for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	21 Nov 2019 11:07	Adj Mandate Set	Approved:24999.00:Re-inspection to be done for damage check and supplementar y items / labour, Reinsp:Yes.	[I] Koh, Victor-CK

ACTIVITY

No record

2350848	20 Nov 2019	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants	LKK Auto Consultants	SKK392E		11.77
Bill Ref No	Bill Date	Bill Type	Асс Туре	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Foo, Chit Yan

Date: 20 Nov 2019

Preliminary Advice

Vehicle No

: SKK392E

Accident Date

: 15/11/2019

Make

: AUDI A4

Policy No.

: 1800156533

Assignment Date

: 20/11/2019

Excess

: \$\$0.00

Date of Inspection : 19/11/2019

Est. Duration of Repair

: 11.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

:S\$	48,502.00
:S\$	24,999.00
:S\$	7,904.00
:S\$	32,903.00
	:S\$:S\$


:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	57,718.00
Salvage Value	:S\$	
Margin for Repair	:S\$	102,282.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

	ACCIDENT STATEMENT
Date Of Report	15/11/2019 15:31
Date Of Accident	15/11/2019 13:40
Exact Location Of Accident	PIE BEFORE KALLANG WAY EXIT 13 TWDS CHANGI
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKK392E
Insured/Policyholder	
Name Of Registered Owner	LEAH-DIANE WARDEN XIU YU
NRIC No	S9613700A
Email Address	LEAH.DWARDEN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92977849
Alternative Phone No	OTHERS-92977849
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Exact Purpose for which vehicle was being used at time of accident	TO THOME (NAV)
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE, LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800156533
Cover Note Number	03/01/2019 TO 02/01/2020
Oriver	
Name of Driver	LEAH-DIANE WARDEN XIU YU
NRIC No	S9613700A
Date Of Birth	20/04/1996
Occupation	INDOOR
Pate Of Driving Pass	25/05/2015
Priving Experience	4 YEARS AND 5 MONTHS
Gender	FEMALE
fobile Number	(LOCAL) +65-92977849

LEAH.DWARDEN@GMAIL.COM

OTHERS-92977849

Address

60C ENG NEO AVENUE SINGAPORE 289542

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Foreign Vehicle Registration Number

VAD5288 (PRIVATE CAR)

Number of vehicles (including own vehicle)

involved in the accident

4

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

VAD5288

Vehicle Make/Model/Colour

TOYOTA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

YEOW SIOW QUAN

NRIC/Passport Number

971020-01-5085

Contact Number

010-9001588

Address

NO 36 JLN PERMAS 1/8 BANDAR BARU PERMAS JAYA 81750 MASAI

JOHOR MALAYSIA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBG4824C

Vehicle Make/Model/Colour

TOYOTA DYNA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SHC1868X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

TAN KOON CHUAN

NRIC/Passport Number

S1546244B

Contact Number

91839149

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 15/11/19

4-29 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: \5 11/14

15/11/19 4-29/m Reporting Centre Personnel's Signature

NRIC/FIN No.:

Accident Sketch Plan Pg. 1

		A constant of the same of the
		A: SEK 392 E
		B: VAD 5288
_		C: CTB9 48
Pie _	DD BAIGED	D- SHC 1868
_		
DESCRIBE CIRCUMSTANC	CES OF THE ACCIDENT	
collision, I proce	eded to exchange particulars a	ealised it was a 4-vehicle chain
Unfortunately, the	lorny in Bont of me did not ctop	p, and proceeded to drive off-
Unfortunately, the	lorny in Bont of me did not stop	p, and proceeded to drive off-
Unfortunately, the	larry in Boart of me did not stop	p, and proceeded to drive off. INSURER: ALC
Unfortunately, the	larry in Board of me did not stop	p, and proceeded to drive off
Unfortunately, the	lorny in Bont of me did not stop	INSURER: : A1GT VEHICLE: SFF 392F
Unfortunately, the	larry in Board of me did not stop	INSURER: : A1GT VEHICLE: SFF 392E DOA:
DECLARATION	larry in front of me did not stop	INSURER: : A+C= VEHICLE: SFK-392E DOA: CLAIM TYPE:
DECLARATION	lorny in Bond of me did not stop	INSURER: : A+C= VEHICLE: SFK-392E DOA: CLAIM TYPE:
DECLARATION	larry in front of me did not stop	INSURER: : A+C= VEHICLE: SFK-392E DOA: CLAIM TYPE:

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER)	: Lech - Diene warden Xiv yo
VEHICLE NUMBER	: = + 391E
DATE/TIME OF ACCIDENT	: 15/11/2019 @ 13x16/15
PLACE OF ACCIDENT	: pie before tollors how exit 13
THIRD PARTY VEHICLE (IF ANY)	: pie before tollorg han exit 13 : VAD 5088, GBHH80HE tube chansi SHC 1868+
BEFORE THE ACCIDENT?	OURNEY AND WHERE WAS THE INTENDED DESTINATION
ACCIDENT? IF YES, DID THE TRA ON YOU? IF YES, WHAT IS THE RE	ON AND THE EXTENSIVENESS OF THE DAMAGES TO ALL
WERE YOU OR YOUR PASSENGER TAKEN TO THE TRAFFIC POLICE I	/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU FOR INVESTIGATION?
10	

Page 6 of 27

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	700A
Vehicle Details	
Vehicle No.:	SKK392E
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CVK071281
Chassis No.:	WAUZZZF40KN000823
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,763.00
Original Registration Date:	03 Jan 2019
First Registration Date:	03 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$39,269.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jan 2029
PARF Rebate Amount:	\$29,451.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jan 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,001.00
COE Rebate Amount:	\$28,267.00
Total Rebate Amount:	\$57,718.00

The information contained herein is correct as at 20 Nov 2019

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323

Fax No

: 6841 1183

Reference

: PA/OD/1367/2019/NS

WIP: 19473

Date

18-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Ms Leah - Diane Warden Xiu Yu

Address

60C Eng Neo Avenue

Singapore 289542

Telephone

HP +65 92977849

Type of Claim

Own Damage Claims

Policy No.

1800156533

Vehicle No

SKK 392 E

Model Code

A4 Sedan 2.0 TFSI 8W

Model / Year

: Jan-19

Engine No

CVK 071281

Chassis No

WAUZZZF40KN000823

Mileage

:

:

Date In **Estimated By**

Johnny Boo / Allan Wu

Accident Date

15-Nov-19

Place of Accident

PIE Before Kallang Way Exit 13 Towards Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKK 392 E

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	
2	To remove and reinstall aircond condender, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	7
3	To dismantle and renew front bumper, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 4,900.00	1500 (without lock (acrier) 2750 (with lock
4	To respray front bumper and bonnet.		\$ 2,000.00	1100 Carrier)
	SUB TOTAL LABOUR CHARGES	:	\$ 8,580.00	

Telefax

Estimated Labour Charges for Accident Vehicle. SKK 392 E

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
5	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	
6	To dismantle and renew rear bumper. To repair lid. Reorganise rear crash management components. Reinstall all parts removed.		\$ 1,750.00	500
7	To respray rear bumper and rear lid.		\$ 2,000.00	1100
8	To carry out diagnostic check	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 12,882.00	

Telefax

Material List for Accident Vehicle Regn No. SKK 392 E

			Damaged Parts	& Prices
S/N	Parts Description		S/Nett	Remarks
1	FRONT BUMPER 7		\$ 1,999.00	
2	FRONT BUMPER FIXING PARTS		\$ 531.00 +	
3	FRONT BUMPER GRILLE - CENTRE SANCE M		\$ 178.00 +	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE / ~ ~		\$ 191.00 ←	
5	RADIATOR GRILLE Coule d		\$ 1,227.00	<
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH No-l M	2	\$ 246.00 4.	
7	FRONT BUMPER CARRIER		\$ 733.00 ?	
8	FRONT BUMPER FOAM FILLER PIECE		\$ 113.00 7	
9	FRONT BUMPER COVER		\$ 116.00	
10	CAUTION SIGN STICKER 2	NEC	\$ 13.00 —	
11	AIRCON STICKER	NEC	\$ 7.00 -	
12	EXTERNAL TEMPERATURE SENSOR 7		\$ 54.00 ?	
13	TEMPERATURE SENSOR BRACKET		\$ 17.00 ?	
14	LOCK CARRIER BRACKET		\$ 125.00 7	
15	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 52.00	
16	HORN - LH HIGH TONE 2,		\$ 37.00 A	
17	HORN - RH LOW TONE TM M		\$ 262.00 4	
18	SRING SHACKLE - LH / RH Nec -	2	\$ 52.00 4	
19	FRONT PARKING AID SENSOR - INNER / OUTER 2	2	\$ 462.00 +	
20	FRONT PARKING AID SEAL RING	4	\$ 12.00 t	
	SUB TOTAL SPARE PARTS CHARGES		\$ 6,427.00	

Telefax

Material List for Accident Vehicle Regn No. SKK 392 E

c /h:				Damaged Parts 8	
5/N_	Parts Description			S/Nett	Remarks
21	BONNET Distorted		\$	2,554.00	
22	BONNET ATTACHMENT PARTS ?		\$	373.00	
23	BONNET LID HINGE - LH / RH / / ←	2	\$	554.00 +	
24	BONNET IMPACT PROTECTION - CENTRE / LH / 14 /4 L	3	\$	75.00	
25	BONNET GAS FILLED STRUT	2	\$	217.00 +	
26	BONNET STRIKER - LH / RH ?	2	\$	92.00 ?	
27	BONNET LID LOCK ?	2	\$	391.00 7	
28	BONNET BOWDEN CABLE - CENTRE		\$	53.00	
29	BONNET RELEASE CABLE		\$	53.00 ⁷	
30	BONNET RELEASE LEVER		\$	12.00 7	
31	BONNET LID LOCK CABLE 7		\$	67.00 7	
32	BONNET SOUND ABSORBER 🖟 ~		\$	311.00 ×	
33	LED HEADLIGHT - LH / RH Lt	2	\$	14,174.00	
34	HEADLIGHT CORRUGATED PIPE Me		\$	83.00 ±	
35	LOCK CARRIER		\$	928.00	
36	COOLANT REGULATOR SUPPORT	2	\$	69.00 ?	
37	AIRCON CONDENSER		\$	568.00 7	
38	PRESSURE RELIEF VALVE		\$	48.00 7	
39	REFRIGERANT LINE PRESSURE SENDER ?		\$	175.00	
40	RADIATOR HE -		\$	676.00 +	
	SUB TOTAL SPARE PARTS CHARGES		-	21,473.00	

Telefax

Material List for Accident Vehicle Regn No. SKK 392 E

				Damaged Part	
S/N	Parts Description		_	S/Nett	Remarks
41	READY MIX COOLANT	4	\$	165.00 ?	
42	RADIATOR AIR GUIDE - LH / RH 7	2	\$	50.00 +	
43	RADIATOR AIR GUIDE - LH / RH	2	\$	22.00 -	
44	RADIATOR AIR GUIDE - UPPER		\$	15.00	
45	RADIATOR AIR GUIDE - LOWER		\$	19.00 7	
46	AIR INTAKE AIR DUCT		\$	19.00 7	
47	AIR INTAKE AIR GUIDE		\$	48.00 7	
48	AIR INTAKE AIR FILTER		\$	339.00 +	
49	AIR INTAKE AIR MASS METRE LUC L		\$	533.00 ⊀	
50	AIR INTAKE HOSE ALL M		\$	85.00 +	
51	REAR BUMPER Regis		\$	2,491.00 1	
52	REAR BUMPER FIXING PARTS 2		\$	416.00 +	
53	REAR BUMPER SECURING STRIP		\$	203.00 ₺	
54	REAR BUMPER SPOILER Cut		\$	227.00 -	
55	REAR BUMPER TRIM		\$	265.00 ⊀.	
56	REAR BUMPER BRACKET - LH / RH 2	2	\$	212.00 *	
57	REAR LIGHT REFLECTOR - LH / RH	2	\$	76.00 t	
58	LED LICENSE PLATE LIGHT HE am	2	\$	191.00	
59	REAR BUMPER CARRIER 2		\$	819.00 /	
60	REAR BUMPER CARRIER 2 REAR BUMPER SEAL	2	\$	25.00 ₹	
	SUB TOTAL SPARE PARTS CHARGES	:	<u> </u>	6,220.00	

Telefax

Material List for Accident Vehicle Regn No. SKK 392 E

				Damaged Parts	& Prices
S/N	Parts Description			S/Nett	Remarks
61	REAR BUMPER HOLDING STRAP - LH / RH 2	2	s	152.00	
62	REAR BUMPER GUIDE SECTION - LH / RH	uln 2	\$	40.00 +	
63	REAR PARKING AID SENSOR - INNER / OUTER	2	\$	462.00 +	
64	REAR PARKING AID SEAL RING	4	\$	12.00 *	
65	AUDI EMBLEM 2		\$	113.00 -	_
66	A4 INSCRIPTION Man		\$	87.00	
67	REAR CROSS PANEL TRIM		\$	154.00 4	
68	FRONT NO PLATE New	S/N	\$	40.00 +	
69	REAR NO PLATE Dented	S/N	\$	40.00 -	
70	SUNDRIES ?		\$	400.00	7
	TOTAL SPARE PARTS CHARGES	\$	\$	35,620.00	
	TOTAL LABOUR CHARGES	i .	\$	12,882.00	
	GRAND TOTAL	;	\$	48,502.00 %	
	All charges are not inclusive of GST.				

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultents Honde notify the Repairer of the following:

- . Tomesurvey new ministration administration
- To display carried parts: guing resurvey
- Parts pode an engine in continuation
- Third party are the second of the Frequence basis
- * No regular add a second to be seen
- Supraction the islandation resurveyed and
 Is subject to final eight valifrom insurance Company

concilledged by Repairer

Signature:

Date

the Anthonised, US Duys. (Without Lock Carrier)

Please Note

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Adrian hin

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager

Allan Wu Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adi Assigned	Adj-Rpt		Ad) Subr	nitted	Ins Auth'ed	Status		
Main	20 Nov 2019	Lac Sharring	20 Nov 2019 08:23 Edit Adj Rpt	S\$24,999.0 Edit Estimate	227	S\$24,99 View Rp	577 C		Pendin Report Cancel	Martin Million Phil	
	Main	Re	ference	CI	laim (Details		Docume	nts	Show A	ui
CLAIM SU	BFOLDER DE	TAILS		Charles and Charles		No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other pa	[Create	ed by insurer]			
Insured:	LEAH-DIA	NE WARDEN XI	YU, ID: 5961	13700A, Tel:	+659	2977849,	, Email:	leah.dwarden@g	mail.com		
Vehicle Reg No.:		J. Carlo			Date	of Loss:	15/11/2 [10 Mor	019 13:00 - :59 oths and 12 Days	From LTA R	eg Date (Man Y	r)]
Claim Type:	OD / 29	59393351SG				y/Cover No.:	180015	0156533 (Comprehensive)			
					Exce	The second second	S\$800.0	Contract processing and the second second second			
Repairer:	Premium	Automobiles Pto	Ltd (UBI) 55 I	Ubi Road 1, 40	8699	Ubi - Tel:	6768982	28/9827/9911			
Handling Insurer:	Deebanalr	Pacific Insuranci adaraja.Nadaraja	@aig.com								
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Har	dled by A	DRIAN	LING] [Final	Rpt due	29/11/2019]	
Driver/Cust dian:	LEAH-DIA	NE WARDEN XIU Y	U (23 / Female)	, NRIC: 596	51370	OA, Tel:	+65929	77849 Email: leal	n.dwarden@	gmail.com	
	TED MAIL RE								View All	Compose Case	Mail
AIG_SG AIG_SG	(21/11/2019) (21/11/2019)	: Alert - Adj Man : SKK392E / OD	date Approved / 15/11/2019	(S\$24999.0 / Coverage	0) - S & Exc	KK392E ess upda	- Claim ate	Handler: Nadara	aja, D		
ALL ASSO	CIATED TA	sks⊟					View A	All Search Tasks			plete
Due Dat	e Priority	Type Task	Group Sub	ject Hand	ler	Assign	ed By	Completed (On Cre	ated On D	one

Claim Documents

*SKK392E (2959393351SG) OD Nov 15 2019 1:00PM [LEAH-DIANE WARDEN XIU YU] Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio Video			View	View in Brow	/ser ▼
Vid	eo		1 per	page ▼	•
No.	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	15/11/19 16:03	Video - Accident [Linked Accident Report Documents]	0	Load MP4	
2	15/11/19 16:03	Video - Accident [Linked Accident Report Documents]	0	Load MP4	
Ass	essment Reports		1 per	page V	
Vo.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	- P.	Thumbnail	-
1	20/11/19 10:43	Adjuster Immediate Advice	0	Load HTM	
Dhe	stoc/Images		2 nor	page ▼	•
	otos/Images	True and Company to the Mark	3 per		
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Thumbnail Load JPG	Prin
1	20/11/19 09:59	General View			-
2	20/11/19 09:59	General View	0	Load JPG	•
3	20/11/19 09:59	Chassis Number	0	Load JPG	•
4	20/11/19 09:59	General View	0	Load JPG	(4)
5	20/11/19 09:59	General View	0	Load JPG	•
6	20/11/19 09:59	General View	0	Load JPG	•
7	20/11/19 09:59	General View	0	Load JPG	•
В	20/11/19 09:59	General View	0	Load JPG	•
9	20/11/19 09:59	General View	0	Load JPG	1
10	20/11/19 09:59	General View	0	Load JPG	•
11	20/11/19 09:59	General View	0	Load JPG	•
12	20/11/19 09:59	General View	0	Load JPG	4
13	20/11/19 09:59	General View	0	Load JPG	(e)
14	20/11/19 09:59	General View	0	Load JPG	•
15	20/11/19 09:59	General View	0	Load JPG	4
16	20/11/19 09:59	General View	0	Load JPG	•
17	20/11/19 09:59	General View	0	Load JPG	•
18	20/11/19 09:59	General View	0	Load JPG	•
19	20/11/19 09:59	General View	0	Load JPG	•
20	20/11/19 09:59	General View	0	Load JPG	•
21	20/11/19 09:59	General View	0	Load JPG	•
22	20/11/19 09:59	General View	0	Load JPG	•
	Paris Management	August and a state of the state	0	Load JPG	•
23	20/11/19 09:59	General View General View	0	Load JPG	2
24			0	Load JPG	•
25	20/11/19 09:59	General View General View	0	Load JPG	•
26	20/11/19 09:59			(-00)	
27	20/11/19 09:59	General View	0	Load JPG	•
28	20/11/19 09:59	General View		Load JPG	-
29	20/11/19 09:59	General View	0	Load JPG	V
30	20/11/19 09:59	General View	0	Load JPG	•
31	20/11/19 09:59	General View	0	Load JPG	2
32	20/11/19 09:59	General View	0	Load JPG	•
33	20/11/19 09:59	General View	0	Load JPG	

Vid	/ideo		1 per	page ▼	•
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
34	20/11/19 09:59	General View	0	Load JPG	•
35	20/11/19 09:59	General View	0	Load JPG	•
36	20/11/19 09:59	General View	0	Load JPG	•
37	20/11/19 09:59	General View	0	Load JPG	•
38	20/11/19 09:59	General View	0	Load JPG	•
39	20/11/19 09:59	General View	0	Load JPG	•
40	20/11/19 09:59	General View	0	Load JPG	•
41	20/11/19 09:59	General View	0	Load JPG	•
42	20/11/19 09:59	General View	0	Load JPG	•
43	20/11/19 09:59	General View	0	Load JPG	•
44	20/11/19 09:59	General View	0	Load JPG	•
45	20/11/19 09:59	General View	0	Load JPG	•
Doc	cumentation		1 per	page ▼	Y
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/11/19 09:57	Singapore Accident Statement	0	Load PDF	
2	20/11/19 09:58	Certificate of Insurance	0	Load PDF	
3	20/11/19 09:58	Driver's Driving License	0	Load PDF	
4	20/11/19 09:58	ESTIMATE	0	Load PDF	
5	20/11/19 10:08	INTERVIEW FORM	0	Load PDF	
6	05/12/19 10:29	ADDENDUM GIA REPORT	0	Load PDF	

Linked Accident Report Documents

			View	View in Brow	/ser ▼
Vide	80		1 per	page 🔻	•
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	15/11/19 16:03	Video - Accident	0	Load MP4	
2	15/11/19 16:03	Video - Accident	0	Load MP4	
Ass	essment Reports		1 per	page 🔻	•
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	15/11/19 16:37	Accident Statement	0	Load HTM	0.500.00
2	18/11/19 10:17	Addendum Sheet	0	Load TIFF	
3	18/11/19 10:18	Accident Statement Addm. #1	0	Load HTM	
4	04/12/19 13:45	Addendum Sheet	0	Load TIFF	-
5	04/12/19 13:45	Accident Statement Addm, #2	0	Load HTM	
Pho	tos/Images		3 per	page ▼	•
No:	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	15/11/19 16:32	Accident Photo	0	Load JPG	•
2	15/11/19 16:32	Accident Photo	0	Load JPG	•
3	15/11/19 16:32	Accident Photo	0	Load JPG	•
4	15/11/19 16:32	Accident Photo	0	Load JPG	•
5	15/11/19 16:32	Accident Photo	0	Load JPG	•
6	15/11/19 16:32	Accident Photo	0	Load JPG	€
7	15/11/19 16:32	Accident Photo	0	Load JPG	•
8	15/11/19 16:32	Accident Photo	0	Load JPG	•
9	15/11/19 16:32	Accident Photo	0	Load JPG	V
10	15/11/19 16:32	Accident Photo	0	Load JPG	€
11	15/11/19 16:32	Accident Photo	0	Load JPG	•
12	15/11/19 16:32	Accident Photo	0	Load JPG	•
13	15/11/19 16:32	Accident Photo	0	Load JPG	(4)
14	15/11/19 16:32	Accident Photo	0	Load JPG	•
15	15/11/19 16:32	Accident Photo	0	Load JPG	•
16	15/11/19 16:35	Accident Photo	0	Load JPG	•
17	15/11/19 16:35	Accident Photo	0	Load JPG	•

Vid	ideo		1 per	page ▼	1
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Prin
18	15/11/19 16:35	Accident Photo	0	Load JPG	•
19	15/11/19 16:35	Accident Photo	0	Load JPG	2
Doc	Documentation		1 per	page ▼	•
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	15/11/19 16:34	Accident Sketch Plan	0	Load TIF	
2	15/11/19 16:34	aig interview form	0	Load TIF	
3	15/11/19 16:34	Identification Card	•	Load TIF	
4	15/11/19 16:34	certificate of insurance	0	Load TIF	
5	15/11/19 16:37	Accident Sketch Plan	0	Load TIF	
6	18/11/19 10:17	police report	0	Load JPG	•
7	18/11/19 10:17	police report	0	Load JPG	•
8	18/11/19 10:17	police report	0	Load JPG	•

Documents Checklist

OCUMENTS CHECKLIST	Reset Save Print
here are no document checklists configured.	
Dur Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #08-16

Singapore 079120

Our File No:

CC3/AIG19020522/AQD3S2

Date:

OD

05/12/2019

REFERENCE

Insured/Claimant: Date of Loss:

LEAH-DIANE WARDEN XIU YU

15/11/2019

Policy No:

1800156533

Nature of Claim:

Claim No:

2959393351SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKK392E

Make & Model:

AUDI A4, 2.0 TFSI QU S-TRONIC (A)

03/01/2019 (Man. Year: 2018)

Chassis No: Odometer:

Engine No:

CVK071281 WAUZZZF40KN000823

14557 km

Reg. Date: Colour:

White

Engine Capacity: Market Value/New Car Price:

1984 cc

\$\$160,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

245/40 R18

Rear Tyre Size:

245/40 R18

Front Left Side: Front Right Side: Falken 6 mm Falken 6 mm Rear Left Side: Rear Right Side: Falken 6 mm Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		35,620.00	18,517.00	17,103.00	48.02
Miscellaneous Items		0.00	0.00	0.00	
Labour		12,882.00	6,482.00	6,400.00	49.68
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	48,502.00	24,999.00	23,503.00	48.46
	- Excess (S\$)	800,00	800.00	0.00	0.00
	(S\$)	47,702.00	24,199.00	23,503.00	49.27
	+ GST 7.00/7.00% (S\$)	3,339.14	1,693.93	1,645.21	49.27
	Nett Amount (S\$)	51,041.14	25,892.93	25,148.21	49.27

INSPECTION

Date of Assignment:

20/11/2019

Date Inspected:

19/11/2019

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

11.0 days

Adjuster: ADRIAN LING Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Inspected At:

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$7,904.00 NETT)

REPAIR DETAILS

Recomme	nded	Parts
Reconnine	nucu	raito

		nmende Part No. P		Condition	Repairer's	Amount
1	1		FRONT BUMPER	*Check	1,999.00 FS	*-FS
2	1		FRONT BUMPER FIXING PARTS	Not Necessary	531.00 FS	*-FS
3	1		FRONT BUMPER GRILLE - CENTRE	Not Necessary	178.00 FS	*-FS
1	1		FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	191.00 FS	*-FS
	-8			Cracked	1,227.00 FS	*1,227.00 FS
5	1		RADIATOR GRILLE	Not Necessary	246.00 FS	*-FS
6	2		FRONT BUMPER AIR GUIDE GRILLE - LH /RH	*Check	733.00 FS	*-FS
7	1		FRONT BUMPER CARRIER FRONT BUMPER FOAM FILLER PIECE	*Check	113.00 FS	*-FS
В	1			*Check	116.00 FS	*-FS
9	1		FRONT BUMPER COVER	Necessary	13.00 FS	*13.00 FS
10	1		CAUTION SIGN STICKER		7.00 FS	*7.00 FS
11	1		AIRCON STICKER	Necessary	54.00 FS	*-FS
12	1		EXTERNAL TEMPERATURE SENSOR	*Check		*-FS
13	1		TEMPERATURE SENSOR BRACKET	*Check	17.00 FS	10.65
14	1		LOCK CARRIER BRACKET	*Check	125.00 FS	*-FS
15	2		FRONT BUMPER SUPPORT - LH / RH	*Check	52.00 FS	*-FS
16	1		HORN - LH HIGH TONE	Not Necessary	37.00 FS	*-FS
17	1		HORN - RH LOW TONE	Not Necessary		*-FS
18	2		SRING SHACKLE - LH / RH	Not Necessary	52.00 FS	*-FS
19	2		FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary		*-FS
20	4		FRONT PARKING AID SEAL RING	Not Necessary	12.00 FS	*-FS
21	1		BONNET	Distorted	2,554.00 FS	*2,554.00 FS
22	1		BONNET ATTACHMENT PARTS	*Check	373.00 FS	*- FS
23	2		BONNET LID HINGE - LH / RH	Not Necessary	554.00 FS	*- FS
24	3		BONNET IMPACT PROTECTION - CENTRE / LH RH	Necessary	75.00 FS	*75.00 FS
25	2		BONNET GAS FILLED STRUT	Not Necessary	217.00 FS	*-FS
26	2		BONNET STRIKER - LH / RH	*Check	92.00 FS	*-FS
27	2		BONNET LID LOCK	*Check	391.00 FS	*-FS
28	1		BONNET BOWDEN CABLE - CENTRE	*Check	53.00 FS	*-FS
29	1		BONNET RELEASE CABLE	*Check	53.00 FS	*-FS
	1		BONNET RELEASE CABLE BONNET RELEASE LEVER	*Check	12.00 FS	*-FS
30				*Check	67.00 FS	*-FS
31	1		*BONNET LID LOCK CABLE	Not Necessary	311.00 FS	*-FS
32	1		*BONNET SOUND ABSORBER			*14,174.00 FS
33	2		*LED HEADLIGHT - LH / RH	Cut		
34	1		*HEADLIGHT CORRUGATED PIPE	Not Necessary	83.00 FS	*-FS
35	1		LOCK CARRIER	*Check	928.00 FS	*-FS
36	2	,	*COOLANT REGULATOR SUPPORT	*Check	69.00 FS	*-FS
37	1		*AIRCON CONDENSER	*Check	568.00 FS	*-FS
38	1		*PRESSURE RELIF VALVE	*Check	48.00 FS	*-FS
39	1	1	REFRIGERANT LINE PRESSURE SENDER	*Check	175.00 FS	*-FS
40	1		*RADIATOR	Not Necessary		*-FS
41	4		*READY MIX COOLANT	*Check	165,00 FS	*-FS
42	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	50,00 FS	*-FS
43	2	,	*RADIATOR AIR GUIDE - LH / RH	Not Necessary	22.00 FS	*-FS
44	1	9	*RADIATOR AIR GUIDE - UPPER	*Check	15.00 FS	*-FS
45	1		*RADIATOR AIR GUIDE - LOWER	*Check	19.00 FS	*-F8
46	1		*AIR INTAKE AIR DUCT	*Check	19.00 FS	*-F8
47	1		*AIR INTAKE AIR GUIDE	*Check	48.00 FS	*-FS
48	1		*AIR INTAKE AIR FILTER	Not Necessary	339.00 FS	*-F8
49	1		*AIR INTAKE AIR MASS METRE	Not Necessary		*-F5
50	1		*AIR INTAKE HOSE	Not Necessary		*-F5
51	1		*REAR BUMPER	Repair	2,491.00 FS	*-F\$
52	1		*REAR BUMPER FIXING PARTS	Not Necessary		
53	1		*REAR BUMPER SECURING STRIP	Not Necessary		
			*REAR BUMPER SPOILER	Cut	227.00 FS	
54	1					
55	1		*REAR BUMPER TRIM	Not Necessary	200.00 FS	- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	212.00 FS	*-FS
57	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	76.00 FS	*-FS
58	2		*LED LICENCE PLATE LIGHT	Not Necessary	191.00 FS	*-FS
59	1		*REAR BUMPER CARRIER	Not Necessary	819.00 FS	*-FS
60	2		*REAR BUMPER SEAL	Not Necessary	25.00 FS	*-FS
61	2		*REAR BUMPER HOLDING STRAP - LH / RH	Not Necessary	152.00 FS	*- FS
62	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	40.00 FS	*-FS
63	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	462.00 FS	*-FS
64	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*-FS
65	1		*AUDI EMBLEM	Necessary	113.00 FS	*113.00 FS
66	1		*A4 INSCRIPTION	Necessary	87.00 FS	*87.00 FS
67	1		*REAR CROSS PANEL TRIM	Not Necessary	154.00 FS	*-FS
68	1		*FRONT NO PLATE	Not Necessary	40.00 FS	*-FS
69	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS
70	1		*SUNDRIES	*Check	400.00 FS	*-FS
F=Fr	anchise	part. S=Spo	Nett.	Total Parts (S\$)	35,620.00	18,517.00
					-	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Pacar	nman	hah	labour
RECOL	ппеп	aea	Lannin

Amount	Repairer's	Lab.Type	Particulars	No
			pour Items	Lab
480.00	480.00	New	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	1
0.00	1,200.00	New	TO REMOVE AND REINSTALL AIRCOND CONDENSER, RADIATOR AND CHARGED AIR COOLER. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (*Check)	2
2,750.00	4,900.00	New	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	3
1,100.00	2,000.00	New	TO RESPRAY FRONT BUMPER AND BONNET.	4
360.00	360.00	New	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	5
500.00	1,750.00	New	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LID. RE- ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	6
1,100.00	2,000.00	New	TO RESPRAY REAR BUMPER AND REAR LID.	7
192.00	192.00	New	TO CARRY OUT DIAGNOSTIC CHECK.	8
6,482.00	12,882.00	Cost (S\$)	Gross Labour	

< END OF ESTIMATES >